

OWNER: LATITUDE 33 AVIATION, LLC
ADDRESS: 2100 PALOMAR AIRPORT ROAD
 CARLSBAD CA 92011
PHONE: 760-985-3610
FAX:

OPERATOR: LATITUDE 33 AVIATION, LLC
ADDRESS: 2100 PALOMAR AIRPORT ROAD
 CARLSBAD CA 92011
PHONE: 760-985-3610
FAX:

ANALYST: ANDREY KORSUKOV
EMAIL: AKORSUKOV@CAMPSYSTEMS.COM

+1-514-636-2016 (DIRECT)
 514-636-2020 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 50500283/N600GF **MODEL:** EMB-505 - PHENOM 300 **MANUFACTURER:** EMBRAER

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	28-OCT-2015	958.7 A/C HRS	as of 15-AUG-2019	A/C HRS	as of ___/___/___
INSERVICE DATE:	28-OCT-2015	591 AFL	as of 15-AUG-2019	AFL	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-DG-0578/PW535E **MODEL:** PW535E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 28-OCT-2015		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	958.7 ENG. HRS	as of 15-AUG-2019	ENG. HRS	as of ___/___/___
0 ENC		591 ENC	as of 15-AUG-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-DG-0581/PW535E **MODEL:** PW535E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 28-OCT-2015		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	958.7 ENG. HRS	as of 15-AUG-2019	ENG. HRS	as of ___/___/___
0 ENC		591 ENC	as of 15-AUG-2019	ENC	as of ___/___/___



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00-	INFORMATION							
00100	AIRCRAFT REGISTRATION-FAR 47.40							
	PKG 88	MOS	36	-6m		10-NOV-2016	30-NOV-2019	
		HRS/MSC				300.2		
	REF:	AFL				235		
CHAPTER 05-	TIME LIMITS/MAINTENANCE CHECKS							
05-30-01	600 FH MAINTENANCE PACKAGE							
+								
	PKG 1	MOS				06-NOV-2017		
		HRS/MSC	600	+30/-30		547.6	1147.6	1177.6
	REF: SMR 05-30-01	AFL				370		
05-30-02	600 FH/12 MO MAINTENANCE PACKAGE							
+								
	PKG 2	MOS	12	+30d/-30d		15-NOV-2018	15-NOV-2019	15-DEC-2019
		HRS/MSC	600	+30/-30		800.3	1400.3	1430.3
	REF: SMR 05-30-02	AFL				507		
05-30-10	1200 FH MAINTENANCE PACKAGE							
+								
	PKG 10	MOS				28-OCT-2015		
		HRS/MSC	1200	+30/-30		0	1200	1230
	REF: SMR 05-30-10	AFL				0		
05-30-12	1200 FH/24 MO MAINTENANCE PACKAGE							
+								
	PKG 12	MOS	24	+30d/-30d		06-NOV-2017	06-NOV-2019	06-DEC-2019
		HRS/MSC	1200	+30/-30		547.6	1747.6	1777.6
	REF: SMR 05-30-12	AFL				370		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-20	1800 FH MAINTENANCE PACKAGE							
+	PKG 20	MOS				28-OCT-2015		
		HRS/MSC	1800	+30/-30		0	1800	1830
	REF: SMR 05-30-20	AFL				0		
05-30-40	3000 FH MAINTENANCE PACKAGE							
+	PKG 40	MOS				28-OCT-2015		
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-40	AFL				0		
05-30-41	3000 FH/48 MO MAINTENANCE PACKAGE							
+	PKG 41	MOS	48	+30d/-30d		28-OCT-2015	28-OCT-2019	27-NOV-2019
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-41	AFL				0		
05-30-42	3000 FH/60 MO MAINTENANCE PACKAGE							
+	PKG 42	MOS	60	+1m/-1m		28-OCT-2015	31-OCT-2020	28-NOV-2020
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-42	AFL				0		
05-30-45	4800 FH MAINTENANCE PACKAGE							
+	PKG 45	MOS				28-OCT-2015		
		HRS/MSC	4800	+30/-30		0	4800	4830
	REF: SMR 05-30-45	AFL				0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-50	6000 FH MAINTENANCE PACKAGE								
+	PKG 50	MOS					28-OCT-2015		
		HRS/MSC	6000	+30/-30			0	6000	6030
	REF: SMR 05-30-50	AFL					0		
05-30-53	6000 FH/96 MO MAINTENANCE PACKAGE								
+	PKG 53	MOS	96	+30d/-30d			28-OCT-2015	28-OCT-2023	27-NOV-2023
		HRS/MSC	6000	+30/-30			0	6000	6030
	REF: SMR 05-30-53	AFL					0		
05-30-60	7800 FH MAINTENANCE PACKAGE								
+	PKG 60	MOS					28-OCT-2015		
		HRS/MSC	7800	+30/-30			0	7800	7830
	REF: SMR 05-30-60	AFL					0		
05-30-65	12000 FH MAINTENANCE PACKAGE								
+	PKG 65	MOS					28-OCT-2015		
		HRS/MSC	12000	+30/-30			0	12000	12030
	REF: SMR 05-30-65	AFL					0		
05-30-80	12 MO MAINTENANCE PACKAGE								
+	PKG 80	MOS	12	+30d/-30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
		HRS/MSC					800.3		
	REF: SMR 05-30-80	AFL					507		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-81 +	24 MO MAINTENANCE PACKAGE								
	PKG 81	MOS	24				07-NOV-2017	07-NOV-2019	07-DEC-2019
		HRS/MSC					547.6		
	REF: SMR 05-30-81	AFL					370		
05-30-82	36 MO MAINTENANCE PACKAGE								
	PKG 82	MOS	36				15-NOV-2018	30-NOV-2021	15-DEC-2021
		HRS/MSC					800.3		
	REF: SMR 05-30-82	AFL					507		
05-30-83 +	48 MO MAINTENANCE PACKAGE								
	PKG 83	MOS	48				28-OCT-2015	28-OCT-2019	27-NOV-2019
		HRS/MSC					0		
	REF: SMR 05-30-83	AFL					0		
05-30-84 +	60 MO MAINTENANCE PACKAGE								
	PKG 84	MOS	60				28-OCT-2015	28-OCT-2020	27-NOV-2020
		HRS/MSC					0		
	REF: SMR 05-30-84	AFL					0		
05-30-87 +	120 MO MAINTENANCE PACKAGE								
	PKG 87	MOS	120				28-OCT-2015	28-OCT-2025	27-NOV-2025
		HRS/MSC					0		
	REF: SMR 05-30-87	AFL					0		



Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							
	PKG 90	MOS	120			28-OCT-2015	31-OCT-2025	27-NOV-2025
		HRS/MSC				0		
	REF: SMR 05-30-90	AFL				0		

ENGINE NO. 1	Model : PW535E	Serial # PCE-DG-0578	Part # PW535E					
051254	NO. 1 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
+								
	PKG 1	MOS	12	+30d		15-NOV-2018	15-NOV-2019	15-DEC-2019
		HRS/MSC	600	+10%		800.3	(1400.3) 1400.3	1460.3
	REF: MM 05-20-00	ENC				507		

ENGINE NO. 2	Model : PW535E	Serial # PCE-DG-0581	Part # PW535E					
051254	NO. 2 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
+								
	PKG 1	MOS	12	+30d		15-NOV-2018	15-NOV-2019	15-DEC-2019
		HRS/MSC	600	+10%		800.3	(1400.3) 1400.3	1460.3
	REF: MM 05-20-00	ENC				507		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00-	INFORMATION								
00200	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MONITORING REQUIREMENTS	MOS					07-JUL-2017 475.8	07-NOV-2019 M	
	REF:	HRS/MSC AFL	DUE						
00300 (s)	TCAS II VERSION 7.1 SOFTWARE UPGRADE FOR OPERATION IN EUROPEAN AIRSPACE	MOS					28-OCT-2015 6.4 4		
	REF:	HRS/MSC AFL	-						
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705	HRS/MSC AFL	-						
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705-1	HRS/MSC AFL	-						
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160822	HRS/MSC AFL	-						
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161022	HRS/MSC AFL	-						



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016	MOS		TSI:0			(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122	HRS/MSC - AFL		TSI:0 TSI:0					
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122-1	HRS/MSC - AFL							
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161202	HRS/MSC - AFL							
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
EM55-190218A	REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019	MOS							
REQUIREMENT CHANGE FORMS	REF: RCF EM55	HRS/MSC - AFL							
ENROLLMENT DOCUMENTS	ENROLLMENT DOCUMENTATION ARCHIVE (SEE REMARKS)	MOS						28-OCT-2015	
	REF:	HRS/MSC - AFL						0 0	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05-	TIME LIMITS/MAINTENANCE CHECKS								
05-50-01	LIGHTNING STRIKE-GENERAL VISUAL INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		
05-50-02	HARD LANDING/OFF TEMPERATURE-INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		
05-50-06	LANDING GEAR DOWN OVERSPEED -INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		
05-50-10	HIGH ENERGY STOP CONDITION INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		
05-50-11	LANDING GEAR FREE-FALL CONDITION- INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		
05-50-12	OVERHEATED WHEELS-INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		
05-50-13	WHEEL OVERSPEED-INSPECTION								
		MOS					28-OCT-2015		
		HRS/MSC -					0		
	REF:	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-14	TIRE TREAD FAILURE-INSPECTION	MOS					28-OCT-2015		
	REF:	HRS/MSC - AFL					0 0		
05-50-15	TIRE BURST WITH LANDING GEAR FULLY RETRACTED-INSPECTION	MOS					28-OCT-2015		
	REF:	HRS/MSC - AFL					0 0		
05-50-16	ON-GROUND GALE EVENTS-INSPECTION	MOS					28-OCT-2015		
	REF:	HRS/MSC - AFL					0 0		
05-50-18	LOAD FACTOR EXCEEDANCE -INSPECTION/CHECK	MOS					28-OCT-2015		
	REF:	HRS/MSC - AFL					0 0		
+ H140-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE						PKG		
	PKG 87	MOS	120	+30d/-30d	TSI:0		28-OCT-2015		
	REF: AMM 05-42-00	HRS/MSC AFL			TSI:0 TSI:0		0 0		
+ H242-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE						PKG		
	PKG 87	MOS	120	+30d/-30d	TSI:0		28-OCT-2015		
	REF: AMM 05-42-00	HRS/MSC AFL			TSI:0 TSI:0		0 0		
+ H430-001 (s)	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS						PKG		
	PKG 84	MOS	60	+30d/-30d	TSI:0		28-OCT-2015		
	REF: AMM 05-46-00	HRS/MSC AFL			TSI:0 TSI:0		0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ H700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
		HRS/MSC					0		
	REF: AMM 05-47-00	AFL					0		
+ H700-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
		HRS/MSC					0		
	REF: AMM 05-47-00	AFL					0		
+ H700-003 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
		HRS/MSC					0		
	REF: AMM 05-47-00	AFL					0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
+ 05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS								
		MOS					28-OCT-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE								
		MOS					28-OCT-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED								
		MOS					28-OCT-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-810	NO. 1 ENGINE - ENGINE IMMERSION IN WATER	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-811	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-812	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-813	NO. 1 ENGINE - LOSS OF OIL	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-814	NO. 1 ENGINE - CHIP DETECTOR LIGHT "ON"	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		



Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									
+ 05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-810	NO. 2 ENGINE - ENGINE IMMERSION IN WATER								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-811	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-812	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-814	NO. 2 ENGINE - CHIP DETECTOR LIGHT "ON"	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN	MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
+ 05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL								
		MOS		TSI:0			28-OCT-2015		
		HRS/MSC	A/R	TSI:0			0		
	REF: MM 05-50-00	ENC		TSI:0			0		
CHAPTER 21-	AIR CONDITIONING								
21-01-01	RH INSC ILLUM PANEL								
	441-44843-001	MOS		TSN:0			28-OCT-2015		
	1103	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY								
	1300250-9	MOS		TSN:0			28-OCT-2015		
	857	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY								
	1300250-9	MOS		TSN:0			28-OCT-2015		
	861	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
21-20-05	GROUND COOLING FAN								
	1133660-3	MOS		TSN:0			28-OCT-2015		
	429	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
+ 21-21-02-001 (s)	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE						PKG		
	PKG 50	MOS					28-OCT-2015		
		HRS/MSC	6000	+30/-30			0		
	REF: AMM 21-21-02	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-21-02-001 (s)	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE PKG 50	MOS					PKG 28-OCT-2015		
	REF: AMM 21-21-02	HRS/MSC AFL	6000	+30/-30			0 0		
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR 100000-77 29036	MOS					28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C				0 0		
21-23-03	RAM AIR VALVE 505-18030-403 0000840972	MOS					28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C				0 0		
+ 21-23-03-002 (s)	OPERATIONAL CHECK OF RAM AIR VALVE POSITION PKG 50	MOS					PKG 28-OCT-2015		
	REF: AMM 21-23-03	HRS/MSC AFL	6000	+30/-30			0 0		
+ 21-23-03-003 (s)	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION PKG 1	MOS					PKG 06-NOV-2017		
	REF: AMM 21-23-03	HRS/MSC AFL	600				547.6 370		
+ 21-23-04-001 (s)	OPERATIONAL CHECK OF RAM AIR CHECK VALVES PKG 50	MOS					PKG 28-OCT-2015		
	REF: AMM 21-23-04	HRS/MSC AFL	6000	+30/-30			0 0		
+ 21-23-05-001 (s)	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN PKG 10	MOS					PKG 28-OCT-2015		
	REF: AMM 21-23-05	HRS/MSC AFL	1200	+30/-30			0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-24-01-001 (s)	OPERATIONAL CHECK OF IFE COOLING FAN PKG 50 REF: AMM 21-24-01	MOS HRS/MSC AFL	6000	+15/-30			PKG 28-OCT-2015 0 0		
+ 21-31-00-002 (s)	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600	+30/-30			PKG 06-NOV-2017 547.6 370		
+ 21-31-00-003 (s)	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE) PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600	+30/-30			PKG 06-NOV-2017 547.6 370		
+ 21-31-00-004 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 21-31-00-005 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
21-31-01	(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT 2119286-9 2119286-01036 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		
+ 21-31-01-001	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) 2119286-9 2119286-01036 REF: AMM 21-31-01	MOS HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0	6000	6030

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-02	OUTFLOW VALVE 103922-1 103922-00309 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 21-31-02-001	RESTORATION (REPAIR) OF OUTFLOW VALVE 103922-1 103922-00309 REF: AMM 21-31-02	MOS HRS/MSC AFL	7200	+30/-30 TSI:0 TSI:0			28-OCT-2015 0 0	7200	7230
21-31-03	NEGATIVE PRESSURE RELIEF (NPR) VALVE 130664-2 34163-0667 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 21-31-03-001 (s)	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
21-31-04	PRESSURE RELIEF (PRV) VALVE 103918-2 103918-00393 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 21-31-04-001 (s)	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
21-52-01	CDM - COMPRESSOR 1133640-5 462 REF: AMM 21-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-52-01-001	DETAILED INSPECTION OF VCS COMPRESSOR DRIVE MODULE	MOS					06-NOV-2017		
	REF: AMM 21-52-01	HRS/MSC O/C					547.6		
		AFL					370		
+ 21-52-01-002 (s)	DISCARD OF COMPRESSOR DRIVE MODULE BELT						PKG		
	PKG 20	MOS		TSI:0			28-OCT-2015		
	REF: AMM 21-52-01	HRS/MSC 1800	+30/-30	TSI:0			0		
		AFL		TSI:0			0		
+ 21-52-01-003 (s)	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION						PKG		
	PKG 1	MOS					06-NOV-2017		
	REF: AMM 21-52-01	HRS/MSC 600	+30/-30				547.6		
		AFL					370		
+ 21-52-01-004	RESTORATION (OVERHAUL) CDM - COMPRESSOR								
	1133640-5	MOS		TSI:0			28-OCT-2015		
	462	HRS/MSC 2000	+30/-30				0	2000	2030
	REF: AMM 21-52-01	AFL		TSI:0			0		
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE								
	1133860-4	MOS		TSN:0			28-OCT-2015		
	454	HRS/MSC O/C		TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
+ 21-52-03-001 (s)	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES						PKG		
	PKG 1	MOS					06-NOV-2017		
	REF: AMM 21-52-03	HRS/MSC 600	+30/-30				547.6		
		AFL					370		
21-52-04	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER								
	1133850-104	MOS		TSR:0			11-MAY-2017		
	582	HRS/MSC O/C		TSR:0			423.6		
	REF: See Workcard	AFL		TSR:0			299		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-52-06-001 (s)	SERVICING OF VCS REFRIGERANT FLUID PKG 2	MOS	12				PKG 15-NOV-2018 800.3 507		
	REF: AMM 12-17-00	HRS/MSC AFL	600						
21-52-08	AIR CONDITION CONDENSER ASSEMBLY 1133760-2	MOS		TSN:0			28-OCT-2015 0 0		
	400	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								
+ 21-52-08-001 (s)	GENERAL VISUAL INSPECTION OF VCS CONDENSER PKG 10	MOS					PKG 28-OCT-2015 0 0		
	REF: AMM 21-52-08	HRS/MSC AFL	1200	+30/-30					
21-52-09	AIR CONDITION MIX FLOW CONDENSER FAN 1133720-4	MOS		TSN:0			28-OCT-2015 0 0		
	435	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								
21-52-10	AIR CONDITION BLEED AIR HEAT EXCHANGER 1320260-2	MOS		TSN:0			28-OCT-2015 0 0		
	395	HRS/MSC AFL	O/C	TSN:0 TSN:0					
	REF: See Workcard								
+ 21-61-00-001 (s)	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM PKG 1	MOS					PKG 06-NOV-2017 547.6 370		
	REF: AMM 21-61-00	HRS/MSC AFL	600	+30/-30					
21-61-01	ECS TEMPERATURE CONTROLLER 1300670-6	MOS		TSN:0			25-MAR-2016 114.4 79		
	00472	HRS/MSC AFL	O/C	TSN:111.8 TSN:76					
	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 2919 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 2924 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 2899 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 2897 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 21-61-06-001 (s)	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR PKG 50 REF: AMM 21-61-06	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
CHAPTER 22- AUTO FLIGHT									
22-11-00	GMC 715 GUIDANCE PANEL 011-01430-00 15900875 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d			15-NOV-2018 800.3 507	15-NOV-2019	15-DEC-2019
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-11-00-001	FUNCTIONAL CHECK ELEVATOR	GSA 81	LOW TORQUE	AUTOPILOT SERVO					
		MOS	12	+30d/-30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
AIRWORTHINESS	REF: AMM 22-11-00	HRS/MSC AFL					800.3 507		
+ 22-11-00-001	FUNCTIONAL CHECK RUDDER	GSA 81	LOW TORQUE	AUTOPILOT SERVO					
		MOS	12	+30d/-30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
AIRWORTHINESS	REF: AMM 22-11-00	HRS/MSC AFL					800.3 507		
+ 22-11-00-001	FUNCTIONAL CHECK TAIL CONE	GSA 80	HIGH SPEED	AUTOPILOT SERVO					
		MOS	12	+30d/-30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
AIRWORTHINESS	REF: AMM 22-11-00	HRS/MSC AFL					800.3 507		
+ 22-11-00-002 (s)	LUBRICATION OF SERVO ACTUATORS						PKG		
	PKG 12	MOS	24	+30d/-30d			06-NOV-2017		
	REF: AMM 22-11-00	HRS/MSC AFL	1200	+30/-30			547.6 370		
+ 22-11-00-003 (s)	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE						PKG		
	PKG 42	MOS	60	+1m/-1m			28-OCT-2015		
	REF: AMM 22-11-00	HRS/MSC AFL	3000	+30/-30			0 0		
22-11-01	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO								
	011-00877-21	MOS			TSN:0		28-OCT-2015		
	1A0006413	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO								
	011-00878-20	MOS			TSN:0		28-OCT-2015		
	1A1012473	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-02	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1012476 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
22-11-03	AILERON GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK013120 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 22-11-04-001	FUNCTIONAL CHECK OF AUTOPILOT AILERON SERVO CABLE REF: AMM 22-11-04	MOS HRS/MSC AFL	O/C				28-OCT-2015 0		
22-11-06	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK013116 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 22-11-07-001	FUNCTIONAL CHECK OF AUTOPILOT ELEVATOR SERVO CABLE REF: AMM 22-11-07	MOS HRS/MSC AFL	O/C				28-OCT-2015 0		
22-11-09	RUDDER GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK013121 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 22-11-10-001	FUNCTIONAL CHECK OF AUTOPILOT RUDDER SERVO CABLE REF: AMM 22-11-10	MOS HRS/MSC AFL	O/C				28-OCT-2015 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-12	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT 011-01904-00 1GK013327 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 22-11-13-001	FUNCTIONAL CHECK OF AUTOPILOT VENTRAL RUDDER SERVO CABLE REF: AMM 22-11-13	MOS HRS/MSC AFL	O/C				28-OCT-2015 0		
CHAPTER 23- COMMUNICATIONS									
23-10-01	VHF ANTENNA S65-8280-41 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
23-10-03	VHF 3 ANTENNA S65-8280-41 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
23-50-01	LEFT GMA 1347D AUDIO PANEL 011-01257-20 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
23-50-02	COPILOT HEADSET 025-250-015 00203254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
23-50-02	PILOT HEADSET 025-250-015 00203248 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-50-03	HAND MICROPHONE 85-03-12369-04 371876 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 23-51-00-001 (s)	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE PKG 40 REF: AMM 23-51-00	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
23-51-01	RIGHT GMA 1347D AUDIO PANEL 011-01257-20 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
23-51-05	LEFT CONTROL PANEL 441-40943-002 1336 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
23-51-05	RIGHT CONTROL PANEL 441-40943-002 1338 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 23-61-00-001 (s)	FUNCTIONAL CHECK OF STATIC DISCHARGERS PKG 83 REF: AMM 23-61-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
CHAPTER 24-	ELECTRICAL POWER								
24-01-01	LEFT CONSOLE CONTROL PANEL 441-40929-002 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01	NO. 1 ENGINE STARTER/GENERATOR 400SG180Q S00100XL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
24-31-01	NO. 2 ENGINE STARTER/GENERATOR 400SG180Q S00098XL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:25 TSN:547.6 TSN:370			06-NOV-2017 547.6 370		
+ 24-31-01-001	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S00100XL REF: AMM 24-31-01	MOS HRS/MSC AFL	1200	+30/-30 TSI:0 TSI:0			28-OCT-2015 0 0	1200	1230
+ 24-31-01-001	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) 400SG180Q S00098XL REF: AMM 24-31-01	MOS HRS/MSC AFL	1200	+30/-30 TSI:0 TSI:0			28-OCT-2015 0 0	1200	1230
+ 24-31-01-002	DETAILED INSPECTION NO. 1 ENGINE STARTER/GENERATOR STARTER GENERATOR BRUSHES - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S00100XL REF: AMM 24-31-01	MOS HRS/MSC AFL	600	+30/-30			06-NOV-2017 547.6 370	1147.6	1177.6
+ 24-31-01-002	DETAILED INSPECTION NO. 2 ENGINE STARTER/GENERATOR STARTER GENERATOR BRUSHES - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) 400SG180Q S00098XL REF: AMM 24-31-01	MOS HRS/MSC AFL	600	+30/-30			06-NOV-2017 547.6 370	1147.6	1177.6

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS		TSI:0				28-OCT-2015	
	S00100XL	HRS/MSC	N/A	TSI:0				0	
	REF: AMM 24-31-01	AFL		TSI:0				0	
+ 24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS		TSI:0				28-OCT-2015	
	S00098XL	HRS/MSC	N/A	TSI:0				0	
	REF: AMM 24-31-01	AFL		TSI:0				0	
+ 24-31-01-004	DETAILED INSPECTION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS						14-OCT-2016	
	S00100XL	HRS/MSC	N/A					291.3	
	REF: AMM 24-31-01	AFL						229	
+ 24-31-01-004	DETAILED INSPECTION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS						14-OCT-2016	
	S00098XL	HRS/MSC	N/A					291.3	
	REF: AMM 24-31-01	AFL						229	
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT								
	CG301A-11	MOS		TSN:0				28-OCT-2015	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: See Workcard	AFL		TSN:0				0	
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT								
	CG301A-11	MOS		TSN:0				28-OCT-2015	
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0				0	
	REF: See Workcard	AFL		TSN:0				0	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF LH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60	TSI:0 TSI:0 TSI:0			PKG 28-OCT-2015 0 0		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF RH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60	TSI:0 TSI:0 TSI:0			PKG 28-OCT-2015 0 0		
24-36-01	AFT MAIN BATTERY 7638-48P G03009790 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:10 TSN:191.2 TSN:102			13-MAY-2019 892.4 554		
24-36-01	FORWARD MAIN BATTERY 7639-34 G03012354 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:4 TSN:0 TSN:0			15-NOV-2018 800.3 507		
+ 24-36-01-003	DISCARD AFT MAIN BATTERY 7638-48P G03009790 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			10-JUL-2018 701.2 452	10-JUL-2020 1052	09-AUG-2020 1082
+ 24-36-01-003	DISCARD FORWARD MAIN BATTERY 7639-34 G03012354 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			15-NOV-2018 800.3 507	15-NOV-2020 1107	15-DEC-2020 1137
+ 24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7638-48P G03009790 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7639-34 G03012354 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
+ 24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015) 7638-48P G03009790 REF: AMM 24-36-01	MOS HRS/MSC AFL	6	+30d/-30d			13-MAY-2019 892.4 554	13-NOV-2019	13-DEC-2019
+ 24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015) 7639-34 G03012354 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			15-NOV-2018 800.3 507	15-NOV-2019	15-DEC-2019
+ 24-36-02-001 (s)	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2) PKG 50 REF: AMM 24-36-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
24-54-05	28 VDC / 115 VAC STATIC INVERTER AS-24-0026-001 0792 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		08-JUL-2016 219.1 157		
24-65-01	LEFT POWER DISTRIBUTION BOX SX7EG20-3 0337 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
24-65-02	RIGHT POWER DISTRIBUTION BOX SX7EG21-3 0311 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-65-04	NOSE POWER DISTRIBUTION BOX SX7EG22-3 0305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 25- EQUIPMENT/FURNISHINGS									
25-11-01	COPILOT SEAT 1429-621AK SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-11-01	PILOT SEAT 1429-521AK SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 25-11-01-001 (s)	DETAILED INSPECTION COPILOT SEAT PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
+ 25-11-01-001 (s)	DETAILED INSPECTION PILOT SEAT PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
+ 25-11-01-002 (s)	DETAILED INSPECTION OF COCKPIT SEAT BELTS PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
25-21-01	PAX 6 - LH FWD FACE SEAT 403174-1B1E SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-01	PAX 7 - RH FWD FACE SEAT 403174-2B1E SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 25-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER SEATS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
+ 25-21-01-002 (s)	DETAILED INSPECTION OF PASSENGER SEAT BELTS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
+ 25-21-02-001 (s)	DETAILED INSPECTION DIVAN PN PKG 40 SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
+ 25-21-02-002 (s)	DETAILED INSPECTION DIVAN SEAT BELTS PN PKG 40 SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
25-21-03	PAX 4 - LH FWD FACE SEAT 403174-1B1E SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-21-03	PAX 5 - RH FWD FACE SEAT 403174-4B1E SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-04	SEAT, PAX-EAGLE LEFT-HAND 403174-3B1E SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 25-21-04-001	RESTORATION (DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY (OVERHAUL) OF SEAT BELT AIRBAG SYSTEM REF: AMM 25-21-04 OverHaul Date:31-MAR-2015	MOS HRS/MSC AFL	84	TSI:0 TSI:0			31-MAR-2015	31-MAR-2022	
+ 25-43-01-001 (s)	DETAILED VISUAL INSPECTION BELTED TOILET UNIT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
+ 25-43-01-002 (s)	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
25-60-01	EMERGENCY LOCATOR TRANSMITTER S1821502-02 LX1100157829 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:12 TSN:291.3 TSN:229			14-OCT-2016 291.3 229		
25-60-03	ELT ANTENNA S65-8282-406 401-2659 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY S1820506-01C SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM S1821502-02 LX1100157829 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				13-MAY-2019 892.4 554	13-MAY-2020	
+ 25-61-00-002	GENERAL VISUAL INSPECTION EMERGENCY LOCATOR TRANSMITTER OF EMERGENCY LOCATOR TRANSMITTER S1821502-02 LX1100157829 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				13-MAY-2019 892.4 554	13-MAY-2020	
+ 25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY S1820506-01C SN-UNKNOWN REF: AMM 25-61-04	MOS HRS/MSC AFL	DUE				28-OCT-2015	30-JUN-2021 M	
+ 25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE PN SN-UNKNOWN REF: AMM 25-61-07	MOS HRS/MSC AFL	N/A						
+ 25-62-01	FIRST AID KIT 019708-0005L SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		TSN:1 TSN:0 TSN:0		25-JAN-2019 834 520		
+ 25-62-01-001	VISUAL CHECK FIRST AID KIT 019708-0005L SN-UNKNOWN REF: AMM 25-62-01	MOS HRS/MSC AFL	DUE				25-JAN-2019 834 520	31-AUG-2020 M	
25-62-02 (s)	COPILOT LIFE VEST 66601-505 L2650894 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
25-62-02 (s)	DIVAN NO. 1 LIFE VEST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02 (s)	DIVAN NO. 2 LIFE VEST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 1 PASSENGER LIFE VEST 66601-105 L2897835 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 2 PASSENGER LIFE VEST 66601-105 L2935088 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 3 PASSENGER LIFE VEST 66601-105 L2940616 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 4 PASSENGER LIFE VEST 66601-105 L3046879 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 5 PASSENGER LIFE VEST 66601-105 L3046880 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 6 PASSENGER LIFE VEST 66601-105 L3046881 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	NO. 7 PASSENGER LIFE VEST 66601-105 L3046882 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02 (s)	NO. 8 PASSENGER LIFE VEST 66601-105 L3046886 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	PILOT LIFE VEST 66601-505 L2650891 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
25-62-02 (s)	TOILET PAX LIFE VEST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST 66601-505 L2650894 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST 66601-105 L2897835 REF: AMM 25-62-02 OVERHAUL	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST 66601-105 L2935088 REF: AMM 25-62-02 OVERHAUL	MOS HRS/MSC AFL	N/A						

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST 66601-105 L2940616 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST 66601-105 L3046879 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST 66601-105 L3046880 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST 66601-105 L3046881 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST 66601-105 L3046882 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST 66601-105 L3046886 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001 (s)	RESTORATION (OVERHAUL) OF PILOT LIFE VEST 66601-505 L2650891 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF TOILET LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02-002	LIFE VEST - PASSENGER - DISCARD 66601-105 L2861648 REF:	MOS HRS/MSC AFL	120	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	28-OCT-2025	
+ 25-62-02-003 (s)	DISCARD COPILOT LIFE VEST 66601-505 L2650894 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003 (s)	DISCARD DIVAN NO. 1 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-003 (s)	DISCARD DIVAN NO. 2 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-003 (s)	DISCARD NO. 1 PASSENGER LIFE VEST 66601-105 L2897835 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003 (s)	DISCARD NO. 2 PASSENGER LIFE VEST 66601-105 L2935088 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003 (s)	DISCARD NO. 3 PASSENGER LIFE VEST 66601-105 L2940616 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003 (s)	DISCARD NO. 4 PASSENGER LIFE VEST 66601-105 L3046879 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-003	DISCARD NO. 5 PASSENGER LIFE VEST 66601-105 L3046880 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-003 (s)	DISCARD NO. 6 PASSENGER LIFE VEST 66601-105 L3046881 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003 (s)	DISCARD NO. 7 PASSENGER LIFE VEST 66601-105 L3046882 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003	DISCARD NO. 8 PASSENGER LIFE VEST 66601-105 L3046886 REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-003 (s)	DISCARD PILOT LIFE VEST 66601-505 L2650891 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C						
+ 25-62-02-003	DISCARD TOILET PAX LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-04-001 (s)	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER PKG 81 REF: AMM 25-62-04	MOS HRS/MSC AFL	24	+30d/-30d			PKG 07-NOV-2017 547.6 370		
25-64-52-01	HOT JUG ELECTRICAL CONNECTOR AC16707 8002131044 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		10-MAY-2016 157.5 111		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252070	SEAT, PAX-EAGLE RIGHT-HAND 403174-4B1E SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 26- FIRE PROTECTION									
26-11-01	LEFT ENGINE FIRE DETECTOR 3951-49-565/215C-5.1M SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
26-11-01	RIGHT ENGINE FIRE DETECTOR 3951-49-565/215C-5.1M SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 26-11-01-001 (s)	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			28-OCT-2015 0 0		
+ 26-11-01-001 (s)	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			28-OCT-2015 0 0		
+ 26-11-01-002 (s)	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			28-OCT-2015 0 0		
+ 26-11-01-002 (s)	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			28-OCT-2015 0 0		
26-15-01	MODEL 602 SMOKE DETECTOR 8930-223B60L014 24049 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE 33000073-1 71209A1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL REF: AMM 26-21-00	MOS HRS/MSC AFL	2400	+30/-30			28-OCT-2015 0 0	2400	2430
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL 441-42702-002 1123 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 26-21-03-001	FUNCTIONAL CHECK ENGINE FIRE EXTINGUISHER BOTTLE OF ENGINE EXTINGUISHING BOTTLE 33000073-1 71209A1 REF: AMM 26-21-03 HydroCheck Date: 31-JAN-2015	MOS HRS/MSC AFL	120				31-JAN-2015	31-JAN-2025	
+ 26-21-05-001 (s)	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) PKG 20 REF: AMM 26-21-05	MOS HRS/MSC AFL	1800	+30/-30			PKG 28-OCT-2015 0 0		
26-21-07	NO. 1 CARTRIDGE 30903962-1/30903963-1 0059RL REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		
26-21-07	NO. 2 CARTRIDGE 30903963-1 1602RL REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-21-07-001	DISCARD NO. 1 CARTRIDGE 30903962-1/30903963-1 0059RL REF: AMM 26-21-07 Manufacture Date: 28-OCT-2015	MOS HRS/MSC AFL	120				28-OCT-2015	28-OCT-2025	
	LIFE LIMIT								
+ 26-21-07-001	DISCARD NO. 2 CARTRIDGE 30903963-1 1602RL REF: AMM 26-21-07	MOS HRS/MSC AFL	120				28-OCT-2015 0 0	28-OCT-2025	
	LIFE LIMIT				TSI:0 TSI:0				
+ 26-21-09-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING PKG 20 REF: AMM 26-21-09	MOS HRS/MSC AFL	1800	+30/-30			PKG 28-OCT-2015 0 0		
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 A25950172 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 A25950142 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		
+ 26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 A25950172 REF: AMM 26-24-01	MOS HRS/MSC AFL	12				13-MAY-2019	13-MAY-2020	
+ 26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 A25950142 REF: AMM 26-24-01	MOS HRS/MSC AFL	12				13-MAY-2019	13-MAY-2020	
+ 26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 A25950172 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-JAN-2014	01-JAN-2026	



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 A25950142 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-JAN-2014	01-JAN-2026	
+ 26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 A25950172 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-003	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 A25950142 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A				28-OCT-2015 0 0		
+ 26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 A25950172 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 A25950142 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
CHAPTER 27- FLIGHT CONTROLS									
+ 27-004	ROLL TRIM ACTUATOR 470500-1005 0319 REF: See Workcard	MOS HRS/MSC AFL	12000				28-OCT-2015 0 0	12000	
LIFE LIMIT				TSN:0 TSN:0 TSN:0					
+ 27-005	YAW TRIM ACTUATOR 470600-1005 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000				28-OCT-2015 0 0	12000	
LIFE LIMIT				TSN:0 TSN:0 TSN:0					
+ 27-006	PITCH TRIM ACTUATOR 467500-1003 0330 REF: See Workcard	MOS HRS/MSC AFL	35000				28-OCT-2015 0 0	35000	
LIFE LIMIT				TSN:0 TSN:0 TSN:0					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-007	LEFT SPOILER ACTUATOR 456800-1003 0626 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		35000
LIFE LIMIT									
+ 27-007	RIGHT SPOILER ACTUATOR 456800-1003 0629 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		35000
LIFE LIMIT									
+ 27-009	RUDDER BOOSTER ACTUATOR 9125-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		35000
LIFE LIMIT									
27-01-01	LEFT CONTROL WHEEL 83912139 00904 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-01-01	RIGHT CONTROL WHEEL 83912141 00861 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-01-02	LH PEDAL ASSEMBLY 505-15420-427 0000837080 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 27-01-03-001 (s)	LUBRICATION OF ROTARY BALL SPLINE PKG 81 REF: AMM 12-21-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 07-NOV-2017 547.6 370		
+ 27-010	LEFT TOGGLE LINK 456870-1001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		35000
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-010	RIGHT TOGGLE LINK 456870-1001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-011	STICK PUSHER ACTUATOR 9124-1 0327T REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-012	POWER DRIVE UNIT 467700-1003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-013	LEFT FLAP POSITION SENSOR UNIT 457310-1001 0683 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-013	RIGHT FLAP POSITION SENSOR UNIT 457310-1001 0685 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-014	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1247 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-014	LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1270 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								
+ 27-014	RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1264 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
	LIFE LIMIT								



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-014	RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1267 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	35000	
LIFE LIMIT									
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL 462900-1015 0858 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 27-03-01-002 (s)	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 27-03-01-003 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR AIRWORTHINESS	MOS HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0	6000	6030
27-04-01	TRIM ACTUATOR CONTROLLER 475200-1009 0357 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 27-04-01-001 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 27-04-01-002 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-11-00-001 (s)	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42	MOS	60	+1m/-1m			PKG 28-OCT-2015		
	REF: AMM 27-11-00	HRS/MSC AFL	3000	+30/-30			0 0		
27-11-01	LEFT AILERON 505-14717-401 0000844228 REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-11-01	RIGHT AILERON 505-14718-401 0000845190 REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
+ 27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION	MOS	60	+1m/-1m			06-NOV-2017	06-NOV-2022	06-DEC-2022
	REF: AMM 27-11-02	HRS/MSC AFL	3000	+30/-30			547.6 370	3547.6	3577.6
+ 27-11-02-002 (s)	DETAILED INSPECTION OF AILERON CONTROL CABLES PKG 42	MOS	60	+1m/-1m			PKG 28-OCT-2015		
	REF: AMM 27-11-02	HRS/MSC AFL	3000	+30/-30			0 0		
+ 27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-14-03	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-14-02	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-14-03	LEFT AILERON TAB 505-14630-403 SN-UNKNOWN REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-21-00-001 (s)	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42	MOS	60	+1m/-1m			PKG 28-OCT-2015		
	REF: AMM 27-21-00	HRS/MSC AFL	3000	+30/-30			0 0		
27-21-01	RUDDER ASSEMBLY 505-39084-413 0000844220 REF: See Workcard	MOS			TSN:0		28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
+ 27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION	MOS	60	+1m/-1m			06-NOV-2017	06-NOV-2022	06-DEC-2022
	REF: AMM 27-21-02	HRS/MSC AFL	3000	+30/-30			547.6 370	3547.6	3577.6
+ 27-21-02-002 (s)	DETAILED INSPECTION OF RUDDER CONTROL CABLES PKG 42	MOS	60	+1m/-1m			PKG 28-OCT-2015		
	REF: AMM 27-21-02	HRS/MSC AFL	3000	+30/-30			0 0		
+ 27-23-00-001 (s)	OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM PKG 1	MOS	600	+30/-30			PKG 06-NOV-2017		
	REF: AMM 27-23-00	HRS/MSC AFL					547.6 370		
+ 27-24-02-001	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH	MOS	6000	+30/-30			28-OCT-2015	6000	6030
AIRWORTHINESS	REF: AMM 27-24-03	HRS/MSC AFL					0 0		
+ 27-24-02-002	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM	MOS	6000	+30/-30			28-OCT-2015	6000	6030
AIRWORTHINESS	REF: AMM 27-24-02	HRS/MSC AFL					0 0		
27-24-03	RUDDER TRIM TAB 505-10450-401 0000844651 REF: See Workcard	MOS			TSN:0		28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-26-01	VENTRAL RUDDER 505-07540-417 0000844092 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 27-31-00-001 (s)	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-31-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 28-OCT-2015 0 0		
27-31-01	LEFT ELEVATOR 505-11082-401 0000842497 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-31-01	RIGHT ELEVATOR 505-11170-406 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			06-NOV-2017 547.6 370	06-NOV-2022 3547.6	06-DEC-2022 3577.6
+ 27-31-02-002 (s)	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES PKG 42 REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3000	+30/-30			PKG 28-OCT-2015 0 0		
27-31-03	LEFT ELEVATOR TAB 505-11084-401 0000844202 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-31-03	RIGHT ELEVATOR TAB 505-11082-402 0000862024 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-31-03-001 (s)	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH PKG 50	MOS					PKG 28-OCT-2015		
	REF: AMM 27-31-03	HRS/MSC AFL	6000	+30/-30			0 0		
+ 27-31-03-002 (s)	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM PKG 50	MOS					PKG 28-OCT-2015		
	REF: AMM 27-31-03	HRS/MSC AFL	6000	+30/-30			0 0		
+ 27-36-03-001 (s)	OPERATIONAL CHECK OF PUSHER CUTOFF SWITCH PKG 12	MOS	24	+30d/-30d			PKG 06-NOV-2017		
	REF: AMM 27-36-03	HRS/MSC AFL	1200	+30/-30			547.6 370		
+ 27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-41-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-40-00	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-41-01-003 (s)	LUBRICATION OF PITCH TRIM ACTUATOR PKG 83	MOS	48	+30d/-30d			PKG 28-OCT-2015		
	REF: AMM 12-21-00	HRS/MSC AFL					0 0		
+ 27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-41-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-41-01-005 (s)	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES PKG 83	MOS	48				PKG 28-OCT-2015		
	REF: AMM 12-18-00	HRS/MSC AFL					0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-41-01-006 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP PKG 50	MOS					PKG 28-OCT-2015		
	REF: AMM 27-41-01	HRS/MSC AFL	6000	+30/-30			0 0		
+ 27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 27-51-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 27-51-01-001 (s)	LUBRICATION OF FLAP ACTUATORS BALL SCREWS PKG 83	MOS	48	+30d/-30d			PKG 28-OCT-2015		
	REF: AMM 12-21-00	HRS/MSC AFL					0 0		
+ 27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-51-01-002	DETAILED VISUAL INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-51-01-002	DETAILED VISUAL INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
+ 27-51-01-005 (s)	SERVICING OF FLAP ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48				28-OCT-2015		
	REF: AMM 12-18-00	HRS/MSC AFL					0 0		
+ 27-51-01-900-801-01	LEFT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
	475100-1013	HRS/MSC	1800	TSN:0			0	1800	
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
+ 27-51-01-900-801-02	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					29-SEP-2016		
	475100-1013	HRS/MSC	7200	TSN:11			285.9	7200	
LIFE LIMIT	REF: See Workcard	AFL		TSN:285.9 TSN:224			224		
+ 27-51-01-900-801-03	LEFT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
	475000-2013	HRS/MSC	7200	TSN:0			0	7200	
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
+ 27-51-01-900-801-04	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
	475000-2013	HRS/MSC	7200	TSN:0			0	7200	
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		
+ 27-51-01-900-801-05	LEFT NO. 1 INBOARD FLAP ACTUATOR	MOS					28-OCT-2015		
	475000-1013	HRS/MSC	7200	TSN:0			0	7200	
LIFE LIMIT	REF: See Workcard	AFL		TSN:0			0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-51-01-900-801-06	RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 1270 REF: See Workcard	MOS HRS/MSC AFL	7200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	7200	
LIFE LIMIT									
27-51-05	LEFT INBOARD FLAP 505-14334-401 0000839523 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-51-05	LEFT OUTBOARD FLAP 505-14349-401 0000844515 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-51-05	RIGHT INBOARD FLAP 505-14334-402 0000837850 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
27-51-05	RIGHT OUTBOARD FLAP 505-14349-402 0000844252 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 27-51-06-001 (s)	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-001 (s)	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-001 (s)	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-51-06-001 (s)	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-001 (s)	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-001 (s)	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-002 (s)	DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-002 (s)	DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 28-OCT-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83	MOS	48	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 27-51-06	HRS/MSC AFL					0 0		
+ 27-51-06-900-801-05	LEFT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007	MOS		TSN:0			28-OCT-2015 0		
	SSW0630	HRS/MSC	35000	TSN:0			0		35000
	LIFE LIMIT REF: See Workcard	AFL		TSN:0			0		
+ 27-51-06-900-801-06	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007	MOS		TSN:0			28-OCT-2015 0		
	SSW0639	HRS/MSC	35000	TSN:0			0		35000
	LIFE LIMIT REF: See Workcard	AFL		TSN:0			0		
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER 780501-9	MOS		TSN:0			28-OCT-2015 0		
	1627	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
+ 27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL	MOS					28-OCT-2015		
	REF: NDT PART 6 27-64-00	HRS/MSC	17500						17500 M
	AIRWORTHINESS	AFL	14000						14000 M
+ 27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL	MOS					28-OCT-2015		
	REF: NDT PART 5 27-64-00	HRS/MSC	17500						17500 M
	AIRWORTHINESS	AFL	14000						14000 M
+ 27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL	MOS					28-OCT-2015		
	REF: NDT PART 7 27-64-00	HRS/MSC	17500						17500 M
	AIRWORTHINESS	AFL	14000						14000 M

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-65-00-001 (s)	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM PKG 50 REF: AMM 27-60-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 27-65-01-001 (s)	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU) PKG 50 REF: AMM 27-65-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR 456896-1001 149262 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR 456896-1001 152714 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR 456897-1001 151489 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR 456897-1001 151492 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
271010	ACTUATOR,- ELECTROMECHANICAL PITCH TRIM 467500-1003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
271020	FLIGHT CONTROL ELECTRONICS 462900-1015 0864 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271030	AILERON TAB ACTUATOR 470500-1005 0325 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
272010	RUDDER SPRING ACTUATOR-HYDRO 9125-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
272030	RUDDER TAB ACTUATOR 470600-1005 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
275030	LEFT FLAP ACTUATOR,INBD #1 475000-1009 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
275035	RIGHT FLAP ACTUATOR,INBD #1 475000-1009 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
275040	LEFT FLAP ACTUATOR,OUTBD #2 475000-2009 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
275045	RIGHT FLAP ACTUATOR,OUTBD #2 475000-209 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
275050	LEFT FLAP ACTUATOR,OUTBD #3 475100-1009 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275055	RIGHT FLAP ACTUATOR,OUTBD #3 475100-1009 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
275090	FLAP POWER DRIVE UNIT 467700-1003 0348 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
276060	MULTIFUNCTION SPOILER POWER CONTROL UNIT 4568000-1003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
276080	SPOILER TOGGLE LINK ASSEMBLY 456870-1001 0702 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
276090	SPOILER TOGGLE LINK ASSEMBLY 456870-1001 0726 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 28- FUEL									
+ 28-11-00-001 (s)	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS PKG 80 REF: AMM 28-11-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 15-NOV-2018 800.3 507		
28-11-05	LEFT WING WATER DRAIN VALVE L83A13-628 J19043 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-11-05	RIGHT WING WATER DRAIN VALVE L83A13-628 J19038 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-11-07	LEFT WING DUMP VALVE V98A32-001 J20095 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-11-07	RIGHT WING DUMP VALVE V98A32-001 J20088 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 28-12-01-001 (s)	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA PKG 2 REF: AMM 28-12-01	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE L87-19-001P2 D95244 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:84 TSN:0 TSN:0			20-JUN-2019 944.7 575		
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE L87-19-001P2 J98732 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:17 TSN:0 TSN:0			20-JUN-2019 944.7 575		
+ 28-12-03-001 (s)	OPERATIONAL CHECK LEFT FLOAT VENT VALVE PKG 50 REF: AMM 28-12-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 20-JUN-2019 944.7 575		
+ 28-12-03-001 (s)	OPERATIONAL CHECK RIGHT FLOAT VENT VALVE PKG 50 REF: AMM 28-12-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 20-JUN-2019 944.7 575		
28-21-02	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 G42009 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-02	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 G42016 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-03	LEFT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 G38379 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-03	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 G43256 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-05	LEFT WING JET PUMP FEED LINE T99A19-602 G42825 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-05	RIGHT WING JET PUMP FEED LINE T99A19-602 G42824 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-07	LEFT 0.75 SHUTOFF VALVE B97-15-601 J22242 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-07	RIGHT 0.75 SHUTOFF VALVE B97-15-601 J22240 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM REF: AMM 28-21-07	MOS HRS/MSC AFL	600	+30/-30			06-NOV-2017 547.6 370	1147.6	1177.6
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM	MOS					06-NOV-2017		
AIRWORTHINESS	REF: AMM 28-21-07	HRS/MSC AFL	600	+30/-30			547.6 370	1147.6	1177.6
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR D97C00-644P2 C702031 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
28-21-08	LEFT WING 28 VDC SOV ACTUATOR D97C00-644P2 C702033 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR D97C00-644P2 C702035 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
28-21-09	LEFT WING SCAVENGER JET PUMP T99A19-603 G42364 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
28-21-09	RIGHT WING SCAVENGER JET PUMP T99A19-603 G42366 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE B97H19-608P2 H67235 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
+ 28-21-10-001 (s)	OPERATIONAL CHECK OF FUEL XFEED VALVE PKG 65 REF: AMM 28-21-10	MOS HRS/MSC AFL	12000	+30/-30			PKG 28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 J20825 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 J14437 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-21-13	INSC ILLUM PANEL 441-42621-002 1304 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P3 J22871 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P3 J22872 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 28-23-04-001 (s)	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER PKG 40 REF: AMM 28-23-05	MOS HRS/MSC AFL	3000	+30/-30			PKG 28-OCT-2015 0 0		
28-23-09	FUEL PORT AND CAP K97-63-613 J19447 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 1 LEFT PROBE 765896-1-0 765896IN00739 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01	NO. 1 RIGHT PROBE 765896-1-0 765896IN00733 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 2 LEFT PROBE 765873-1-0 765873IN00751 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 2 RIGHT PROBE 765873-1-0 765873IN00756 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 3 LEFT PROBE 765874-1-0 765874IN00766 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 3 RIGHT PROBE 765874-1-0 765874IN00768 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 4 LEFT PROBE 765875-1-0 765875IN00754 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-01	NO. 4 RIGHT PROBE 765875-1-0 765875IN00770 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT 738742-1-4 738790IN00840 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-43-01	TEMPERATURE SENSOR 798840-1-0 04254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 28-43-01-001 (s)	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR PKG 50 REF: AMM 28-43-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
28-45-01	LEFT PRESSURE SWITCH D98C07-611 1381 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
28-45-01	RIGHT PRESSURE SWITCH D98C07-611 1384 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 29- HYDRAULIC POWER									
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR 3032763-003 MX781150 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX785790 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX785675 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 29-12-02-001 (s)	VISUAL CHECK OF MANIFOLD/ RESERVOIR PKG 2 REF: AMM 29-12-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-12-02-002 (s)	OPERATIONAL CHECK LEFT PKG 53 REF: AMM 29-10-00	EDP CHECK VALVE MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			PKG 28-OCT-2015 0 0		
+ 29-12-02-002 (s)	OPERATIONAL CHECK RIGHT PKG 53 REF: AMM 29-10-00	EDP CHECK VALVE MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			PKG 28-OCT-2015 0 0		
29-12-04.1	HYDRAULIC SYSTEM FILTER ELEMENT PRESSURE SIDE. UNK SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
29-12-04.2	HYDRAULIC SYSTEM FILTER ELEMENT RETURN SIDE. 3032408-329 US00013818 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-SEP-2016 275.3 214		
29-15-03	CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 0860231003/DAP00106-01 11172-2 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 29-15-03-001 (s)	SERVICING CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 0860231003/DAP00106-01 PKG 2 11172-2 REF: AMM 12-13-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE 3032428-001 AA511657 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE 3032428-001 AA511658 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-15-04-001	OPERATIONAL CHECK LEFT ENGINE HYDRAULIC SHUT-OFF VALVE	MOS	48	+30d/-30d			28-OCT-2015	28-OCT-2019	27-NOV-2019
AIRWORTHINESS	REF: AMM 29-15-04	HRS/MSC AFL	3000	+30/-30			0 0	3000	3030
+ 29-15-04-001	OPERATIONAL CHECK RIGHT ENGINE HYDRAULIC SHUT-OFF VALVE	MOS	48	+30d/-30d			28-OCT-2015	28-OCT-2019	27-NOV-2019
AIRWORTHINESS	REF: AMM 29-15-04	HRS/MSC AFL	3000	+30/-30			0 0	3000	3030
29-15-05	PRIORITY VALVE 2217-0001-401 00309 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
+ 29-31-02-001 (s)	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE PKG 53 REF: AMM 29-31-02	MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30	TSI:0 TSI:0 TSI:0		28-OCT-2015 0 0	PKG	
CHAPTER 30-	ICE AND RAIN PROTECTION								
30-01-01	MD INSC ILLUM PANEL 441-43233-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
+ 30-12-00-001 (s)	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM PKG 50 REF: AMM 30-10-00	MOS HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0	PKG	
+ 30-12-01-001 (s)	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS PKG 50 REF: AMM 30-12-01	MOS HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0	PKG	
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-3 0306 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-4 0308 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-1-399 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
30-12-05	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8205-7-474 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-1-264 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-1-400 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
30-12-05	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8205-7-849 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-1-388 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 30-12-05-001 (s)	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-12-05-001 (s)	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 50	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 30-12-05								
+ 30-12-05-002 (s)	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 50	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 30-12-05								
+ 30-12-05-002 (s)	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 50	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 30-12-05								
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0001013	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
	REF: See Workcard								
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0001017	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
	REF: See Workcard								
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 8172-9-363	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
	REF: See Workcard								
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 8172-9-350	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
	REF: See Workcard								
+ 30-21-03-001 (s)	BORESCOPE INSPECTION OF PICCOLO TUBE PKG 50	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 30-21-03								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-21-04-001 (s)	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS PKG 20	MOS					PKG 28-OCT-2015		
	REF: AMM 30-21-00	HRS/MSC AFL	1800	+30/-30			0 0		
+ 30-31-00-002 (s)	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING PKG 81	MOS	24	+30d/-30d			PKG 02-NOV-2017		
	REF: AMM 30-30-00	HRS/MSC AFL					547.6 370		
+ 30-41-01-001	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING	MOS					15-NOV-2018		
	REF: AMM 30-41-01	HRS/MSC AFL	O/C				800.3 507		
+ 30-41-01-002 (s)	DISCARD OF WINDSHIELD RAIN REPELLENT COATING PKG 80	MOS	12		TSI:0		PKG 28-OCT-2015		
	REF: AMM 30-41-01	HRS/MSC AFL			TSI:0 TSI:0		0 0		
+ 30-42-00-001 (s)	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM PKG 1	MOS					PKG 06-NOV-2017		
	REF: AMM 30-42-00	HRS/MSC AFL	600	+30/-30			547.6 370		
30-42-01	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-2 02836	MOS			TSN:0		28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
30-42-01	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-2 02837	MOS			TSN:0		28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
CHAPTER 31-	INDICATING/RECORDING SYSTEMS								
31-30-02	CVDR ACCELEROMETER 3001-01-111 1214-DTW1555	MOS			TSN:0		28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-30-03	REAR CVDR IMPACT SWITCH 5930-4-000 6683 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 31-31-00-002 (s)	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) PKG 80 REF: AMM 31-31-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 15-NOV-2018 800.3 507		
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER 5003-6100-50 001038295 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY REF: AMM 31-31-03 Expiry Date: 28-OCT-2015	MOS HRS/MSC AFL	DUE				28-OCT-2015	28-OCT-2021 M	
31-31-09	CVDR CONTROL PANEL 441-42635-002 0673 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
31-33-01	FDR - FLIGHT DATA RECORDER 2100-2044-00 000990135 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-JUL-2017 475.8		
+ 31-33-03-001	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED) REF: AMM 31-33-03 Expiry Date: 28-OCT-2015	MOS HRS/MSC AFL	DUE				28-OCT-2015	28-OCT-2021 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-33-04	FORWARD CVDR IMPACT SWITCH 5930-4-000 6853 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A	TSI:0 TSI:0 TSI:0			28-OCT-2015 0 0		
+ 31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A	TSI:0 TSI:0 TSI:0			28-OCT-2015 0 0		
31-40-01	LH DCU UNIT 011-01457-00 16905963 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
31-40-01	RH DCU UNIT 011-01457-00 16906305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-40 2DC001695 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-MAY-2019 892.4 554		
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-40 2DC001094 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-MAY-2019 892.4 554		
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL 441-42627-001 1295 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-42-00-001 (s)	OPERATIONAL CHECK OF HSDB SWITCH REVERSION PKG 50	MOS					PKG		
	REF: AMM 31-42-00	HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0		
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46719866 REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46719883 REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46719983 REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
31-61-00	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) MFD AMLCD DISPLAY 011-01440-10 1F1105001 REF: See Workcard	MOS					28-OCT-2015		
		HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
+ 31-61-00-001 (s)	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40	MOS					PKG		
	REF: AMM 31-61-00	HRS/MSC AFL	3000	+30/-30			28-OCT-2015 0 0		
+ 31-61-00-001 (s)	OPERATIONAL CHECK MFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40	MOS					PKG		
	REF: AMM 31-61-00	HRS/MSC AFL	3000	+30/-30			28-OCT-2015 0 0		
+ 31-61-00-001 (s)	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40	MOS					PKG		
	REF: AMM 31-61-00	HRS/MSC AFL	3000	+30/-30			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-01	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 1F1100615 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
31-61-01	NO. 2 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 1F1105002 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 32- LANDING GEAR									
+ 32-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF MAIN LANDING GEAR POLYURETHANE FILMS PKG 1 REF: AMM 32-00-20	MOS HRS/MSC AFL	600				PKG 06-NOV-2017 547.6 370		
+ 32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING 2317-1201-503/2317-1225-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
+ 32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING 2317-1201-504/2317-1225-502 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
+ 32-003	LEFT PINTLE PIN 2317-1101-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
+ 32-003	RIGHT PINTLE PIN 2317-1101-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
+ 32-004	LEFT PINTLE PIN 2317-1102-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-004	RIGHT PINTLE PIN 2317-1102-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1545434/009 REF: See Workcard	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		15300
LIFE LIMIT									
+ 32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 154543/014 REF: See Workcard	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		15300
LIFE LIMIT									
+ 32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-406 00295 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-405 00299 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-405 00299 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-406 00301 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		15300
LIFE LIMIT									
+ 32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		15300
LIFE LIMIT									
+ 32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1551571/006 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1551571/005	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-104	LEFT MAIN LANDING GEAR TRAILING ARM 2317-1501-001/2317-1513-501 SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-105	RIGHT MAIN LANDING GEAR TRAILING ARM 2317-1501-002/2317-1513-502 SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 SN-UNKNOWN	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
+ 32-11-00-001 (s)	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR PKG 2	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		
	REF: AMM 32-11-00								



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-00-002	RESTORATION (OVERHAUL) OF LEFT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00 Restoration Date:28-OCT-2015	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			28-OCT-2015	28-OCT-2025	27-NOV-2025 12000 M 12030
+ 32-11-00-002	RESTORATION (OVERHAUL) OF RIGHT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00 Restoration Date:28-OCT-2015	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			28-OCT-2015	28-OCT-2025	27-NOV-2025 12000 M 12030
+ 32-11-00-003 (s)	LUBRICATION OF MAIN LANDING GEAR PKG 2 REF: AMM 12-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			15-NOV-2018 800.3 507		
+ 32-11-02-900-801-05	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000		TSN:0 TSN:0 TSN:0		(EBT)		12005
+ 32-11-02-900-801-06	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000		TSN:0 TSN:0 TSN:0		(EBT)		12005
+ 32-11-02-900-801-07	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000		TSN:0 TSN:0 TSN:0		(EBT)		12005
+ 32-11-02-900-801-08	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000		TSN:0 TSN:0 TSN:0		(EBT)		12005

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-02-900-801-13	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-11-02-900-801-14	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-11-02-900-801-15	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-11-02-900-801-16	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-11-03-004 (s)	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER PKG 2 REF: AMM 12-14-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00639 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-404 00640 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		16800
LIFE LIMIT									
+ 32-21-00-001 (s)	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR PKG 2 REF: AMM 32-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-00-002	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR								
	PN	MOS	120	+30d/-30d			28-OCT-2015	28-OCT-2025	27-NOV-2025
	SN-UNKNOWN	HRS/MSC		TSI:0			0		
OVERHAUL	REF: AMM 32-21-00	AFL	12000	+30/-30			0	12000	12030
+ 32-21-00-003 (s)	LUBRICATION OF NOSE LANDING GEAR						PKG		
	PKG 2	MOS	12	+30d/-30d			15-NOV-2018		
		HRS/MSC	600	+30/-30			800.3		
	REF: AMM 12-21-00	AFL					507		
32-21-02	NLG RETRACTION ACTUATOR								
	2117-1000-401	MOS					28-OCT-2015		
	00311	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
32-21-03	NLG DOWNLOCK ACTUATOR								
	2117-2000-401	MOS					28-OCT-2015		
	00314	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
+ 32-21-05-004 (s)	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER						PKG		
	PKG 2	MOS	12	+30d/-30d			15-NOV-2018		
		HRS/MSC	600	+30/-30			800.3		
	REF: AMM 12-14-03	AFL					507		
+ 32-21-06-005 (s)	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER						PKG		
	PKG 2	MOS	12	+30d/-30d			15-NOV-2018		
		HRS/MSC	600	+30/-30			800.3		
	REF: AMM 32-21-06	AFL					507		
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR								
	2117-3000-409	MOS					28-OCT-2015		
	00652	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR								
	2117-3000-409	MOS					28-OCT-2015		
	00657	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3031-001/2117-3034-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3031-001/2117-3034-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
32-31-01	LANDING GEAR CONTROL LEVER 827101-13 0131 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE 7342-1 0317T REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-31-05	LH MLG UPLOCK BOX ASSY 2617-1000-401 00604 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-31-05	NLG UPLOCK BOX ASSY 2617-1000-401 00610 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-31-05	RH MLG UPLOCK BOX ASSY 2617-1000-402 00303 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12005
LIFE LIMIT									
+ 32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1/GA2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:0 TSN:0 TSN:0			(EBT)		10505
LIFE LIMIT									
+ 32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1/GA2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:0 TSN:0 TSN:0			(EBT)		10505
LIFE LIMIT									
+ 32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	28000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		28000
LIFE LIMIT									
+ 32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	28000	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		28000
LIFE LIMIT									
+ 32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM REF: AMM 32-35-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			06-NOV-2017 547.6 370	06-NOV-2019 1747.6	06-DEC-2019 1777.6
AIRWORTHINESS									
+ 32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES REF: AMM 32-35-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			06-NOV-2017 547.6 370	06-NOV-2019 1747.6	06-DEC-2019 1777.6
AIRWORTHINESS									
32-35-02	CENTER FUSELAGE FREE FALL VALVE 7343-2 0298T REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-400	NOSE LANDING GEAR SHOCK STRUT 2317-5100-403 00309 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT 2310-1144-005 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT 2310-1173-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN 2317-5105-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN 2317-5105-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING 2317-5301-503/2317-5316-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER 2117-4000-403 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE 2317-5101-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
+ 32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
+ 32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN 2317-6003-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
+ 32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE 2310-1165-001 1548247/003 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
32-41-00	BRAKE CONTROL UNIT DAP00100-10 229950105 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-APR-2017 394.7 286		
+ 32-41-00-001 (s)	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM PKG 50 REF: AMM 32-41-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 19-JAN-2018 583.2 388		
32-41-01	BRAKE CONTROL UNIT TRAY DAP00134-01 1135 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		
32-41-02	LH BRAKE PEDAL TRANSDUCER Q3008 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-02	RH BRAKE PEDAL TRANSDUCER Q3008 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-41-02-001 (s)	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 50 REF: AMM 32-41-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 32-41-02-001 (s)	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 50 REF: AMM 32-41-02	MOS HRS/MSC AFL	6000	+30/-30	TSI:0 TSI:0 TSI:0		PKG 28-OCT-2015 0 0		
+ 32-41-02-002 (s)	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		
+ 32-41-02-002 (s)	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 15-NOV-2018 800.3 507		
32-41-06	LH MLG WHEEL SPEED TRANSDUCER DAP00103-01 081NX REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-41-06	RH MLG WHEEL SPEED TRANSDUCER DAP00103-01 078NX REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-41-07	BRAKE CONTROL MODULE DAP00101-02 026PB REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN 57675-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
+ 32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT 2310-1183-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
+ 32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK 2317-5191-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT									
+ 32-43-00-001 (s)	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM PKG 50 REF: See Workcard	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 32-43-01-001 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM PKG 50 REF: AMM 32-43-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
32-43-02	PRESSURE SWITCH DAP00108-01 019NX REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR DAP00106-01 306 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-43-05	EMERGENCY/PARKING BRAKE VALVE DAP00107-01 085PA REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-43-06	PRESSURE TRANSDUCER DAP00109-01 8067-3-92 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-43-08	THERMAL RELIEF VALVE DAP00110-01 329 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE DAP00202-01 409 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE 2216-0001-401 00650 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE REF: AMM 32-43-11	MOS HRS/MSC AFL	600	+30/-30			06-NOV-2017 547.6 370	1147.6	1177.6
AIRWORTHINESS									
32-45-00	LH MAIN WHEEL AND TIRE ASSY 505-19517-611 5167KR REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:6 TSR:0 TSR:0			05-JUL-2018 698.5 450		
32-45-00	NOSE WHEEL AND TIRE ASSY 505-19601-605 5116PA REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			15-NOV-2018 800.3 507		
32-45-00	RH MAIN WHEEL AND TIRE ASSY 505-19517-611 5029QK REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-JAN-2018 583.2 388		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-01	LEFT MAIN WHEEL DAP00098-02 5167KR REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:6 TSR:0 TSR:0			05-JUL-2018 698.5 450		
32-45-01	RIGHT MAIN WHEEL DAP00098-02 5029QK REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-JAN-2018 583.2 388		
32-45-01-002	SPECIAL DETAIL INSPECTION LH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-611 5167KR REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C						
32-45-01-002	SPECIAL DETAIL INSPECTION RH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-611 5029QK REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C						
+ 32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5167KR REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C						
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5029QK REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500	TSI:0 TSI:0			19-JAN-2018 583.2 388	1888	
32-45-02	LEFT MAIN WHEEL TIRE 258K63-2 72892693 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-JUL-2018 698.5 450		
32-45-02	RIGHT MAIN WHEEL TIRE 258K63-2 52582620 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-AUG-2016 261.1 202		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-03	LH MLG HUB CAP DAP00131-02 087NY REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-45-03	RH MLG HUB CAP DAP0031-02 207PA REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-45-11	NOSE WHEEL DAP00099-01 5116PA REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:3 TSO:0 TSO:0			15-NOV-2018 800.3 507		
32-45-11-002	SPECIAL DETAIL INSPECTION NOSE WHEEL AND TIRE ASSY (NDT) OF NOSE LANDING GEAR WHEEL ASSEMBLY 505-19601-605 5116PA REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				15-NOV-2018 800.3 507		
+ 32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY DAP00099-01 5116PA REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500				15-NOV-2018 800.3 507		2007
32-45-12	NOSE TIRE 156K23B1 80272459 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-NOV-2018 800.3 507		
32-45-21	LH MLG CARBON BRAKE ASSY DAP00097-03 5210PA REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-45-21	RH MLG CARBON BRAKE ASSY DAP00097-04 5096KC REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			19-JAN-2018 583.2 388		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-500	NOSE LANDING GEAR SHOCK ABSORBER 2317-5170-403 00315 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK 2317-5221-001/2317-5227-501 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING 2317-5113-005 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER 2317-5231-503/2317-5237-501 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
32-600	NOSE LANDING GEAR DRAG BRACE 2317-6000-403 00309 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-601	NOSE LANDING GEAR UPPER DRAG BRACE 2317-6101-501/2317-6114-501 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-602	NOSE LANDING GEAR LOWER DRAG BRACE 2317-6201-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
+ 32-604	NOSE LANDING GEAR DRAG BRACE PIN 2317-6003-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	11200	
32-61-01	LH WING PROXIMITY SWITCH 80-057-01 40794 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH 80-057-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 1 NLG PROXIMITY SWITCH 80-057-01 40805 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH 80-057-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH 80-057-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 2 NLG PROXIMITY SWITCH 80-057-01 40814 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH 80-057-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH 80-057-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH 80-057-01 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-61-01	RH WING PROXIMITY SWITCH 80-057-01 40795 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
32-700	NOSE LANDING GEAR LOCKING STAY 2317-6500-403 00304 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 32-701	NOSE LANDING GEAR UPPER LOCKING STAY 2317-6521-003 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
+ 32-702	NOSE LANDING GEAR LOWER LOCKING STAY 2317-6531-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
+ 32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		11200
LIFE LIMIT			11200						
326100X	TRANSDUCER-PEDAL POSITION, RUDDER CONTROL, FORWARD FUSELAGE Q3008 134384 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
326130	TRANSDUCER-PEDAL, RUDDER CONTROL, FORWARD FUSELAGE Q3008 134396 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 33-	LIGHTS								
33-01-01	OVERHEAD LIGHTS CONTROL PANEL 441-43246-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-12-01	COCKPIT DIMMER 81-01760-002 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-12-02	INSC ILLUM - TEST PANEL 505-62239-401 S9312366 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-NOV-2018 800.3 507		
33-42-01	LH LWR FWD TAXI LIGHT ASSY 81017-5 000470 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-42-01	RH LWR FWD TAXI LIGHT ASSY 81017-6 000475 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-47-01	LEFT LANDING LIGHT ASSY 84017-5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-47-01	RIGHT LANDING LIGHT ASSY 84017-5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-48-00	LEFT NO. 1 NAVIGATION LIGHT 84004-7 000768 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-48-00	LEFT NO. 2 NAVIGATION LIGHT 84015-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000770 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT 84015-2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 33-48-00-001 (s)	DISCARD LEFT NO. 1 NAVIGATION LIGHT 84004-7 PKG 65 000768 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30 TSI:0 TSI:0 TSI:0			28-OCT-2015 0 0		PKG
+ 33-48-00-001 (s)	DISCARD LEFT NO. 2 NAVIGATION LIGHT 84015-1 PKG 65 SN-UNKNOWN REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30 TSI:0 TSI:0 TSI:0			28-OCT-2015 0 0		PKG

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-48-00-001 (s)	DISCARD RIGHT NO. 1 NAVIGATION LIGHT 84004-7 PKG 65 000770 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-48-00-001 (s)	DISCARD RIGHT NO. 2 NAVIGATION LIGHT 84015-2 PKG 65 SN-UNKNOWN REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30	TSI:0 TSI:0 TSI:0		PKG 28-OCT-2015 0 0		
+ 33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30	TSI:0 TSI:0 TSI:0		PKG 28-OCT-2015 0 0		
33-49-00	NO. 1 STROBE LIGHT 84036-3 000378 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
33-49-00	NO. 2 STROBE LIGHT 84036-4 000384 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-49-00-001 (s)	DISCARD NO. 1 STROBE LIGHT 84036-3 PKG 60 000378 REF: AMM 33-49-00	MOS HRS/MSC AFL	7800	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-49-00-001 (s)	DISCARD NO. 2 STROBE LIGHT 84036-4 PKG 60 000384 REF: AMM 33-49-00	MOS HRS/MSC AFL	7800	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 28-OCT-2015 0 0		
+ 33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 28-OCT-2015 0 0		
33-52-01	LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001182 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSR:0 25-FEB-2018 599.7 396		
33-52-01	RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 001309 REF: See Workcard	MOS HRS/MSC AFL	O/C				TSN:0 14-DEC-2017 559.4 377		
+ 33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001182 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d			25-JAN-2019 834 520	25-JAN-2020	24-FEB-2020
+ 33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001309 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d	-42		25-JAN-2019 834 520	14-DEC-2019	13-JAN-2020

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001182 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
+ 33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001309 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
+ 33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001182 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
+ 33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 001309 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
+ 33-52-17-001 (s)	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED) PKG 12 REF: AMM 33-52-17	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 28-OCT-2015 0 0		
331030	PANEL - INSC ILLUM-LIGHTING ASSY 441-44443-001 1124 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
331050	LED LIGHT DIMMER AS-33-0038-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
331060	LED LIGHT DIMMER AS-33-0038-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331070	LED EMERGENCY FLOODLIGHT ASD-33-0069-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
332020	LED INTERNAL EMERGENCY FLOODLIGHT AS-33-0069-003 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
332030	BATTERY EMERGENCY -NICAD 6VDC 5AH 3400-22-10 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
332040	BATTERY EMERGENCY -NICAD 6VDC 5AH 3400-22-10 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
335010	BATTERY EMERGENCY NICAD 6VDC,5AH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	7800	+30/-30 TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	7800	7830
335020	BATTERY EMERGENCY NICAD 6VDC,5AH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	7800	+30/-30 TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0	7800	7830
CHAPTER 34-	NAVIGATION								
34-00-03	NO.1 IASP SMART PROBE 2015L-4B 0846 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-00-03	NO.2 IASP SMART PROBE 2015L-4B 0848 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-10-01	RADIO ALTIMETER 066-01153-0101 KRA405B-16357 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA S67-2002-45 553-7013 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA S67-2002-45 553-7024 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT C16786DA01 C16786013292 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 34-11-00-001	FUNCTIONAL CHECK IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001) C16786DA01 C16786013292 REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+30d/-30d			02-NOV-2017 547.6 370	02-NOV-2019	02-DEC-2019
34-11-02	PITOT/STATIC PROBE 0856UT4 292394 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001) 0856UT4 292394 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+30d/-30d			06-NOV-2017 547.6 370	06-NOV-2019	06-DEC-2019

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-15-00-001 (s)	FUNCTIONAL CHECK OF AIR DATA SYSTEM PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 02-NOV-2017 547.6 370		
+ 34-15-00-002 (s)	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 07-NOV-2017 547.6 370		
+ 34-15-00-003 (s)	DETAILED INSPECTION OF IASP PKG 81 REF: AMM 34-15-07	MOS HRS/MSC AFL	24	+30d/-30d			PKG 02-NOV-2017 547.6 370		
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42029089 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42029108 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-20-02	LEFT MAGNETOMETER 011-00870-10 1CM014291 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-20-02	RIGHT MAGNETOMETER 011-00870-10 1CM014354 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-23-00	MAGNETIC COMPASS KCA0120W 4120115 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-23-00-001	FUNCTIONAL CHECK KCA0120W 4120115 REF: AMM 34-23-00	MAGNETIC COMPASS MOS HRS/MSC AFL	OF 24	STANDBY COMPASS +30d/-30d			06-NOV-2017 547.6 370	06-NOV-2019	06-DEC-2019
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA S65-247170 173-4359 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE S65-247170 173-4987 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-40-01	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER 011-00987-00 47768435 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 12462 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-40-02	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 12477 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA 011-01768-00 1DP005906 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-40-04	TCAS II UNIT 9003500-55905 TSE02418 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-JAN-2018 583.2 388		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-40-05	TCAS II TOP ANTENNA 7514060-902 ANE45895 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-43-02	LOWER TCAS L BAND ANTENNA S65-5366-7L 261-117479 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA S65-5366-7L 261-118316 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-02	TOP XPDR L BAND ANTENNA S65-5366-7L 261-118307 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-03	KN 63 DISTANCE MEASURING UNIT 066-01070-0001 38071 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-05	PHASING COUPLER SSPD-113-10 8231 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-06	MARKER BEACON ANTENNA S35-1000-2 102-11200 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-10	GSR 56 IRIDIUM UNIT 011-02268-00 1NZ006110 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-11	IRIDIUM SATCOM ANTENNA S67-1575-109 430-13875 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-12	GDL 59 DATALINK MANAGEMENT UNIT 011-01746-00 1EJ005590 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-13	WI-FI - DATALINK ANTENNA S65-5366-71S SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-14	ADF ANTENNA 622-7383-001 43P47M REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-50-15	ADF UNIT 622-7382-101 4KGYC REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-51-02	NO. 1 DME L BAND ANTENNA S65-5366-7L 261-118199 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-52-00	NO. 1 TRANSPONDER 9006000-55000 NXE09681 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			15-NOV-2018 800.3 507		
34-52-00	NO. 2 TRANSPONDER 7510700-951 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM 9006000-55000 NXE09681 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				18-OCT-2018	31-OCT-2020	
+ 34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM 7510700-951 SN-UNKNOWN REF: AMM 34-52-00	MOS HRS/MSC AFL	24				02-NOV-2017	30-NOV-2019	
34-52-04	LOWER COAXIAL UNIT D2-729B005 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-52-04	UPPER COAXIAL UNIT D2-729B005 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-53-01	ADF MOUNTING TRAY 622-5212-001 42N7TX REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL 011-01428-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 35- OXYGEN									
+ 35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			15-NOV-2018 800.3 507	15-NOV-2021 2600.3	15-DEC-2021 2630.3
AIRWORTHINESS	REF: AMM 35-00-00								
+ 35-01-00-001 (s)	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION PKG 84 REF: AMM 35-01-02	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-01-02	OXYGEN CYLINDER TRANSDUCER 4441125-000 8054-8-532 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH P24151 0364 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-01-06	OXYGEN SYSTEM CONTROL PANEL 441-40945-002 0683 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-01-07	COCKPIT SENSOR P24099 0719 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-01-09	ALTITUDE COMPENSATING REGULATOR 4421135-001 00569 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-01-10	LOW PRESSURE OXYGEN VALVE 4421132-109 00726 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-02-01	OXYGEN CYLINDER 4441122-077 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	C/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER ASSEMBLY 4441122-077 SN-UNKNOWN REF: AMM 35-02-01	MOS HRS/MSC AFL	60				28-OCT-2015	28-OCT-2020	

HydroCheck Date: 28-OCT-2015

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-02-01-003	DISCARD OF OXYGEN CYLINDER 4441122-077 SN-UNKNOWN REF: AMM 35-02-01 Manufacture Date: 28-OCT-2015	MOS HRS/MSC AFL	180				28-OCT-2015	28-OCT-2030	
+ 35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX REF: AMM 35-11-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			15-NOV-2018 800.3 507	15-NOV-2019 1400.3	15-DEC-2019 1430.3
35-11-01	COPILOT OXYGEN MASK STOWAGE BOX 1186F6-23 01553 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:6 TSR:0 TSR:0		15-NOV-2018 800.3 507		
35-11-01	PILOT OXYGEN MASK STOWAGE BOX 1186F6-23 01369 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
35-11-02	LEFT CREW OXYGEN MASK 174232-93 37949 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
35-11-02	RIGHT CREW OXYGEN MASK 174232-93 37950 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
+ 35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 37949 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A				28-OCT-2015 0 0		
+ 35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 37950 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A				28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK 174232-93 37949 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30	TSI:0		31-JAN-2015	31-JAN-2021 3600 M	02-MAR-2021 3630
+ 35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK 174232-93 37950 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30	TSI:0		31-JAN-2015	31-JAN-2021 3600 M	02-MAR-2021 3630
+ 35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 37949 REF: AMM 35-11-02	MOS HRS/MSC AFL	600	+30/-30			06-NOV-2017 547.6 370	1147.6	1177.6
+ 35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 37950 REF: AMM 35-11-02	MOS HRS/MSC AFL	600	+30/-30			19-JAN-2018 583.2 388	1183.2	1213.2
+ 35-11-04-001 (s)	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED) PKG 82 REF: AMM 35-11-04	MOS HRS/MSC AFL	36	+1m/-1m			PKG 15-NOV-2018 800.3 507		
+ 35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			15-NOV-2018 800.3 507	15-NOV-2021 2600.3	15-DEC-2021 2630.3
AIRWORTHINESS									
+ 35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			15-NOV-2018 800.3 507	15-NOV-2021 2600.3	15-DEC-2021 2630.3
AIRWORTHINESS									
35-21-01	AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER 4411071-112 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER 4411071-112 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-112 4411072-012-00918 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-112 4411072-112-00591 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:8 TSN:0 TSN:0			15-NOV-2018 800.3 507		
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411071-112 4411071-112-00262 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-NOV-2018 800.3 507		
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-112 4411072-012-00951 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 35-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS PKG 82 REF: AMM 35-21-01	MOS HRS/MSC AFL	36	+1m/-1m			PKG 15-NOV-2018 800.3 507		
+ 35-31-01	PBE - PROTECTIVE BREATHING EQUIPMENT MR-10022NEMB E1403535 DISCARD REF: See Workcard	MOS HRS/MSC AFL	126	+30d/-30d	TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0	28-APR-2026	28-MAY-2026
352325	50 CUBIC FOOT OXYGEN CYLINDER ASSY. 4441122-050 699926803 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

CHAPTER 36- PNEUMATIC

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-01-01	PNEUMATIC INSC ILLUM PANEL 441-42633-002 1293 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-3 0325 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-4 0316 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 36-11-01-001 (s)	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER PKG 50 REF: AMM 36-11-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 36-11-01-002 (s)	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-00	MOS HRS/MSC AFL	600	+30/-30			PKG 06-NOV-2017 547.6 370		
+ 36-11-02-001 (s)	DETAILED INSPECTION OF BLEED LINE WATER DRAINS PKG 12 REF: AMM 36-11-02	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 06-NOV-2017 547.6 370		
36-11-03	AMS CONTROLLER SYLZ-53632-205 0369A REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-04	NO. 1 ENGINE FAN AIR VALVE RYLB-53527-1 0615 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-04	NO. 2 ENGINE FAN AIR VALVE RYLB-53527-1 0625 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 36-11-04-001 (s)	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER PKG 50 REF: AMM 36-11-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
36-11-05	LH INCONEL 625 BLEED PRE-COOLER 10965000-105 T0296 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-05	RH INCONEL 625 BLEED PRE-COOLER 10964000-105 T0301 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-06	CROSS BLEED VALVE RYLB-53506-1 0311 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 36-11-06-001 (s)	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-06	MOS HRS/MSC AFL	600	+30/-30			PKG 06-NOV-2017 547.6 370		
+ 36-11-06-002 (s)	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER PKG 50 REF: AMM 36-11-06	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 8236-12-67 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 8236-12-95 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTU3736 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTW5560 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTW6406 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTW6409 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 36-11-08-001 (s)	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 36-11-08-001 (s)	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 36-11-08-001 (s)	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 36-11-08-001 (s)	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 28-OCT-2015 0 0		
+ 36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS REF: AMM 36-21-01	MOS HRS/MSC AFL	6000	+30/-30			28-OCT-2015 0 0	6000	6030
AIRWORTHINESS									
CHAPTER 38- WATER/WASTE									
38-33-07	WASTE DRAIN VALVE 0218-0032-1 227005 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
CHAPTER 44- CABIN SYSTEMS									
44-12-07	3-CHANNEL AUDIO AMPLIFIER 0700-005 15020009 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
44-21-09	IFE INSC ILLUM PANEL 441-42725-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
44-21-11	XM RECEIVER 0500-200 15010157 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
44-21-13	XM HEAD CONTROL 0500-300 14020246 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-21-15	AUDIO VOLUME CONTROLLER 0700-008 14120403 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-21-17	IR RECEIVER WITH CONNECTOR 0500-006 15010308 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-21-19	IR REMOTE CONTROLLER 0500-028 15030082 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-21-21	WIRELESS AUDIO TRANSMITTER 0700-009 15050330 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-21-23	NO. 1 WIRELESS HEADPHONE 0500-100 15050029 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER 0604-001 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-22-02	LEFT AFT CABIN SPEAKER AS-23-0211 0346 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-NOV-2018 800.3 507		
44-22-02	LEFT FORWARD CABIN SPEAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-22-02	RIGHT AFT CABIN SPEAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-22-02	RIGHT FORWARD CABIN SPEAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-22-03	10.4 INCH FOLD DOWN MONITOR- 1043-306 15020133 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
44-32-01	ATG5000 TRANSCEIVER P15864-02 1586400217040 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-SEP-2018 769.2 489		
444030	SUPPORT ASSY IFE 505-29230-401 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 52-	DOORS								
52-00-00	KEY LOCK KIT 505-09736-901 8MA000151CM REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 52-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			28-OCT-2015 0 0	PKG	
+ 52-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			28-OCT-2015 0 0	PKG	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 52-10-20-001 (s)	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL								
	PKG 12	MOS	24	+30d/-30d			PKG		
	REF: AMM 52-10-20	HRS/MSC AFL	1200	+30/-30			06-NOV-2017 547.6 370		
+ 52-11-00-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM								
	PKG 41	MOS	48	+30d/-30d			PKG		
	REF: AMM 52-11-00	HRS/MSC AFL	3000	+30/-30			28-OCT-2015 0 0		
+ 52-11-00-003 (s)	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH								
	PKG 2	MOS	12	+30d/-30d			PKG		
	REF: AMM 52-11-23	HRS/MSC AFL	600				15-NOV-2018 800.3 507		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-13-21-001	DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED)								
	500-09890-001	MOS		TSI:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	N/A	TSI:0			0		
	REF: AMM 52-13-21	AFL		TSI:0			0		
52-13-21-001-U1	DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR								
	500-09892-005	MOS		TSN:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	6000	+30/-30	TSN:0		0	6000	6030
	REF:	AFL		TSN:0			0		
52-13-22	MAIN DOOR BALANCING MECHANISM								
	500-09890-001	MOS		TSN:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
+ 52-13-22-001	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE								
	500-09890-001	MOS					06-NOV-2017		
	SN-UNKNOWN	HRS/MSC	O/C				547.6		
	REF: AMM 52-13-22	AFL					370		
52-13-22-004 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES								
	PKG 40	MOS		TSI:0			28-OCT-2015		
	REF: AMM 52-13-22	HRS/MSC	3000	+30/-30	TSI:0		0		
		AFL		TSI:0			0		
+ 52-13-23-001 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED)								
	500-09890-001 PKG 50	MOS		TSI:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	6000	+30/-30	TSI:0		0		
	REF: AMM 52-13-23	AFL		TSI:0			0		
52-20-00	EMERGENCY DOOR								
	500-09700-439	MOS		TSN:0			28-OCT-2015		
	0000840201	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
+ 52-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR STRUCTURE								
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 52-20-00	HRS/MSC					0		
		AFL					0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-20-01-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: See Workcard								
+ 52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS	REF: NDT PART 5 52-20-00								
+ 52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS	REF: NDT PART 5 52-20-00								
+ 52-20-20-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM PKG 41	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 52-20-20								
+ 52-20-21-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR RUBBER SEAL PKG 12	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 06-NOV-2017 547.6 370		
	REF: AMM 52-20-21								
+ 52-31-20-001 (s)	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM PKG 41	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 52-31-20								
+ 52-32-20-001 (s)	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM PKG 41	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			PKG 28-OCT-2015 0 0		
	REF: AMM 52-32-20								
521010	MAIN DOOR ASSEMBLY 505-09910-441 SN-UNKNOWN	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
	REF:								

CHAPTER 53- FUSELAGE

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS PKG 1 REF: AMM 53-00-20	MOS HRS/MSC AFL	600				PKG 06-NOV-2017 547.6 370		
+ 53-05-00-001 (s)	DETAILED INSPECTION OF FUSELAGE DRAINS PKG 84 REF: AMM 53-05-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 53-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 53-10-00-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 53-10-00-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES), FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-10-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 53-10-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 53-10-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	0 0				0 0		
+ 53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	15000 12000				28-OCT-2015		15000 M 12000 M
+ 53-10-07-02-901	DETAILED INSPECTION OF WHEEL WHEEL STRUCTURE. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	15000 12000				28-OCT-2015		15000 M 12000 M
+ 53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WHEEL STRUCTURE.								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	15000 12000				28-OCT-2015		15000 M 12000 M
53-14-00	NOSE RADOME 5190-102-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
+ 53-20-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	0 0				0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL							
+ 53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE	MOS	120	+30d/-30d			28-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 53-20-00								
+ 53-20-05-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE	MOS	120	+30d/-30d			28-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 53-20-00								
+ 53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-06-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		
+ 53-20-06-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 90	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		
+ 53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	8750 7000					8750 M 7000 M	
+ 53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE	MOS	60	+30d/-30d	TSI:0		28-OCT-2015		
	PKG 90	HRS/MSC			TSI:0		0		
	REF: GENERIC NO REF	AFL			TSI:0		0		
+ 53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-10-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS	MOS	120	+30d/-30d			28-OCT-2015		
	PKG 90	HRS/MSC					0		
	REF: NDT PART 5 53-20-00	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
+ 53-30-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
+ 53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL PKG 90	MOS	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL							
+ 53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	12500 10000					12500 M 10000 M	
+ 53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES PKG 90	MOS	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL							



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	10000 8000					10000 M 8000 M	
+ 53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	12500 10000					12500 M 10000 M	
+ 53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 53-30-07-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-30-07-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00								
+ 53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL	MOS HRS/MSC AFL	17500				28-OCT-2015		17500 M 14000 M
AIRWORTHINESS	REF: NDT PART 5 53-30-00		14000						
+ 53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL	MOS HRS/MSC AFL	17500				28-OCT-2015		17500 M 14000 M
AIRWORTHINESS	REF: NDT PART 5 53-30-00		14000						
+ 53-30-08-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00								
+ 53-30-08-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00								
5300000	EMB 505 AIRPLANE STRUCTURE LIMITATION	MOS HRS/MSC AFL	5000				28-OCT-2015 0 0		5000
	REF:								
531010	FORWARD FUSELAGE ASSY 505-01000-437 0000840996	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
	REF:								
531015	CENTER FUSELAGE ASSY 505-03500-463 0000838371	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
	REF:								

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
531020	CTL FUSE JUNCTION ASSY 505-03600-463 0000837860 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
531025	REAR FUSELAGE ASSY 505-06000-445 0000838372 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 54- NACELLES/PYLONS									
+ 54-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS PKG 1 REF: AMM 54-51-20	MOS HRS/MSC AFL	600				PKG 06-NOV-2017 547.6 370		
+ 54-50-00-001 (s)	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE PKG 90 REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 54-50-00-002 (s)	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX PKG 90 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 54-50-01-01-901	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 54-50-02-01-901	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 54-50-03-001 (s)	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE. PKG 84 REF: NDT PART 5 54-52-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-03-01-901	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-52-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-52-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-52-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 54-50-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES PKG 87								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	120 +30d/-30d				PKG 28-OCT-2015 0 0		
+ 54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 54-55-00	MOS HRS/MSC AFL	15000 12000				28-OCT-2015		15000 M 12000 M
+ 54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
+ 54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	15000 12000				28-OCT-2015		15000 M 12000 M
+ 54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	15000 12000				28-OCT-2015		15000 M 12000 M

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 55- STABILIZERS									
+ 55-00-00-001 (s)	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS						PKG		
	PKG 1	MOS					06-NOV-2017		
	REF: AMM 55-00-20	HRS/MSC	600				547.6		
		AFL					370		
55-10-00	HORIZONTAL STABILIZER (COMPLETION)								
	505-10700-403	MOS		TSN:0			28-OCT-2015		
	0000842220	HRS/MSC	O/C	TSN:0			0		
	REF: GENERIC NO REF	AFL		TSN:0			0		
+ 55-10-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC					0		
		AFL					0		
+ 55-10-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC					0		
		AFL					0		
+ 55-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC					0		
		AFL					0		
+ 55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC	17500						17500 M
		AFL	14000						14000 M
+ 55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC	17500						17500 M
		AFL	14000						14000 M

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN						PKG		
	PKG 87	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0 0		
+ 55-10-03-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0 0		
+ 55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-10-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-10-05-001 (s)	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-05-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 55-10-05-02-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
+ 55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10-08-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 55-10-00								
+ 55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-09-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 55-10-00								
+ 55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								
+ 55-10-10-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TRIM-TAB FITTINGS PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 55-10-00								
+ 55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS	REF: NDT PART 5 55-10-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 55-20-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY PKG 87 REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL REF: NDT PART 6 55-20-00	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 8 55-20-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-20-04-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MASS-BALANCE WEIGHT ATTACHMENTS						PKG		
	PKG 87	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
+ 55-20-04-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
+ 55-22-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB						PKG		
	PKG 87	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-22-00	HRS/MSC AFL					0 0		
55-30-00	VERTICAL STABILIZER								
	505-10100-415	MOS				TSN:0	28-OCT-2015		
	0000845780	HRS/MSC	O/C			TSN:0	0		
	REF: GENERIC NO REF	AFL				TSN:0	0		
+ 55-30-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		
+ 55-30-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		
+ 55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-03-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS						PKG		
	PKG 87	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		
+ 55-30-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX						PKG		
	PKG 87	MOS	120	+30d/-30d			28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL					0 0		
+ 55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING	MOS	60	+30d/-30d			28-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-30-00								
+ 55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER	MOS	60	+30d/-30d			28-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-30-00								
+ 55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-30-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING	MOS	120	+30d/-30d			28-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-30-00								
+ 55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-40-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX PKG 87 REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 55-40-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS PKG 87 REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 55-40-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY PKG 87 REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL								
		MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 55-42-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 55-42-00	HRS/MSC AFL					0 0		
CHAPTER 56-	WINDOWS								
56-10-00	LEFT GLASS, HEATED WINDSHIELD ASSY, (LH)								
	NP-195301-3	MOS			TSN:0		28-OCT-2015		
	14346H8129	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
56-10-00	RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH)								
	NP-195301-4	MOS			TSN:0		28-OCT-2015		
	14349H8266	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
+ 56-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF SIDE WINDOW						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 56-12-00	HRS/MSC AFL					0 0		
+ 56-10-01-002	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS								
		MOS					06-NOV-2017		
	REF: AMM 56-10-00	HRS/MSC AFL	1200	+30/-30			547.6 370	1747.6	1777.6
+ 56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE						PKG		
	PKG 90	MOS	120	+30d/-30d	TSI:0		28-OCT-2015		
	REF: NDT PART 5 56-10-00	HRS/MSC AFL			TSI:0 TSI:0		0 0		
+ 56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE						PKG		
	PKG 90	MOS	120	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 56-10-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d TSI:0 TSI:0 TSI:0			PKG 28-OCT-2015 0 0		
+ 56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d TSI:0 TSI:0 TSI:0			PKG 28-OCT-2015 0 0		
+ 56-10-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL AIRWORTHINESS	MOS HRS/MSC AFL	17500 14000				28-OCT-2015	17500 M 14000 M	
56-12-00	LEFT ACRYLIC SIDE WINDOW NP-195302-3 15023H1406 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-12-00	RIGHT ACRYLIC SIDE WINDOW NP-195302-4 14262H9287 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 1 WINDOW TRANSPARENCY 14024 2310083 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 10 WINDOW TRANSPARENCY 14024 2450794 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 11 WINDOW TRANSPARENCY 14024 24507947 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	NO. 2 WINDOW TRANSPARENCY 14024 2436219 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 3 WINDOW TRANSPARENCY 14024 2436238 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 4 WINDOW TRANSPARENCY 14024 2436241 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 5 WINDOW TRANSPARENCY 14024 2436246 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 6 WINDOW TRANSPARENCY 14024 2436253 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 7 WINDOW TRANSPARENCY 14024 2436254 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 8 WINDOW TRANSPARENCY 14024 2436258 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
56-20-00	NO. 9 WINDOW TRANSPARENCY 14024 2436259 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 56-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PASSENGER WINDOW PANELS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 56-20-00								
CHAPTER 57- WINGS									
+ 57-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF WINGLET POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	600				PKG 06-NOV-2017 547.6 370		
	REF: AMM 57-35-21								
+ 57-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00								
+ 57-10-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00								
+ 57-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: See Workcard								
+ 57-10-01-01-901	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
AIRWORTHINESS	REF: NDT PART 5 57-10-00								
+ 57-10-02-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00								
+ 57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL	MOS HRS/MSC AFL	17500 14000				28-OCT-2015		17500 M 14000 M
AIRWORTHINESS	REF: NDT PART 5 57-10-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR PKG 90	MOS	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-04-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR PKG 84	MOS	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-20-00	HRS/MSC AFL							
+ 57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL PKG 87	MOS	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-10-07-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 84	MOS	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
+ 57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-11-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE	MOS	60	+30d/-30d			PKG 28-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-10-00								
+ 57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-11-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	12500 10000					12500 M 10000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 57-50-00	HRS/MSC					0		
		AFL					0		
+ 57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL						28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS						17500 M	
		HRS/MSC	17500					14000 M	
		AFL	14000						
+ 57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL						28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS						11250 M	
		HRS/MSC	11250					9000 M	
		AFL	9000						
+ 57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL						28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS						17500 M	
		HRS/MSC	17500					14000 M	
		AFL	14000						
+ 57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL						28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS						17500 M	
		HRS/MSC	17500					14000 M	
		AFL	14000						
+ 57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL						28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	MOS						17500 M	
		HRS/MSC	17500					14000 M	
		AFL	14000						
+ 57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL						28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	MOS						17500 M	
		HRS/MSC	17500					14000 M	
		AFL	14000						

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-50-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK	MOS	60	+30d/-30d			28-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-20-00								
+ 57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-52-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP	MOS	120	+30d/-30d			28-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-52-00								



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-52-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP PKG 84 REF: NDT PART 5 57-52-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 57-52-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL REF: NDT PART 5 57-52-00	MOS HRS/MSC AFL	17500	14000			28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL REF: NDT PART 5 57-52-00	MOS HRS/MSC AFL	17500	14000			28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 57-52-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL REF: NDT PART 5 57-52-00	MOS HRS/MSC AFL	17500	14000			28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL REF: NDT PART 6 57-52-00	MOS HRS/MSC AFL	11250	9000			28-OCT-2015	11250 M 9000 M	
AIRWORTHINESS									
+ 57-52-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL REF: NDT PART 5 57-52-00	MOS HRS/MSC AFL	17500	14000			28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									
+ 57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL REF: NDT PART 6 57-52-00	MOS HRS/MSC AFL	17500	14000			28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-53-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP PKG 90 REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 57-53-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP PKG 84 REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
+ 57-53-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 57-53-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						
+ 57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL REF: NDT PART 6 57-53-00	MOS HRS/MSC AFL	11250				28-OCT-2015	11250 M 9000 M	
AIRWORTHINESS			9000						
+ 57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL REF: NDT PART 5 57-53-00	MOS HRS/MSC AFL	17500				28-OCT-2015	17500 M 14000 M	
AIRWORTHINESS			14000						

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-53-04-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-53-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-60-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON PKG 87	MOS	120	+30d/-30d			PKG 28-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL							
+ 57-60-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON TAB PKG 84	MOS	60	+30d/-30d			PKG 28-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL							
+ 57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL	MOS					28-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000					17500 M 14000 M	
+ 57-70-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS						PKG		
	PKG 84	MOS	60	+30d/-30d			28-OCT-2015		
	REF: NDT PART 5 57-70-00	HRS/MSC AFL					0 0		

CHAPTER 70- STANDARD PRACTICES - ENGINES

ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E

700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION	MOS					28-OCT-2015		
		HRS/MSC ENC	A/R				0 0		
	REF: MM 70-00-00								

ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E

700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION	MOS					28-OCT-2015		
		HRS/MSC ENC	A/R				0 0		
	REF: MM 70-00-00								

CHAPTER 71- POWER PLANT

71-11-00-001 (s)	GENERAL VISUAL INSPECTION OF UPPER MID COWL						PKG		
	PKG 50	MOS					28-OCT-2015		
	REF: AMM 71-11-00	HRS/MSC AFL	6000	+30/-30			0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0922 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK1855 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK1797 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0926 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK1800 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK1844 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
+ 71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY	MOS HRS/MSC AFL	6000 6000				28-OCT-2015		6000 M 6000 M
AIRWORTHINESS	REF: AMM 71-20-00								
+ 71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL	MOS HRS/MSC AFL	3600				28-OCT-2015 0		3600 M
AIRWORTHINESS	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY	MOS					28-OCT-2015		
AIRWORTHINESS	REF: AMM 71-20-00	HRS/MSC AFL	6000 6000						6000 M 6000 M
+ 71-31-00-001 (s)	DETAILED INSPECTION OF PYLON FIREWALL SEAL PKG 20	MOS					28-OCT-2015		
	REF: AMM 71-31-00	HRS/MSC AFL	1800 +30/-30				0 0		
71-60-01	LEFT ENGINE AIR INLET 505-36900-401 SN-UNKNOWN	MOS					28-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0		
71-60-01	RIGHT ENGINE AIR INLET 505-43430-405 CPI440	MOS					06-NOV-2017		
	REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			547.6 370		
71EN1	NO. 1 ENGINE	MOS					28-OCT-2015		
71.EN1	PCE-DG-0578	HRS/MSC AFL	E/C	TSO:219.1 TSO:157			0 0		
71EN2	NO. 2 ENGINE	MOS					28-OCT-2015		
71.EN2	PCE-DG-0581	HRS/MSC AFL	E/C	TSO:219.1 TSO:157			0 0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS					28-OCT-2015		
	REF: MM 70-00-00	HRS/MSC ENC	A/R	TSI:0 TSI:0 TSI:0			0 0		
+ 71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12				13-MAY-2019	13-MAY-2020	
	REF: MM 71-00-00	HRS/MSC ENC	630				892.4 554	(1522.4) 1522.4	

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				15-NOV-2018	15-NOV-2019	
	REF: MM 72-00-02	HRS/MSC	630				800.3	(1430.3)	1430.3
		ENC					507		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS		TSl:0			28-OCT-2015		
	REF: MM 70-00-00	HRS/MSC	A/R	TSl:0			0		
		ENC		TSl:0			0		
+ 71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12				13-MAY-2019	13-MAY-2020	
	REF: MM 71-00-00	HRS/MSC	630				892.4	(1522.4)	1522.4
		ENC					554		
+ 72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				15-NOV-2018	15-NOV-2019	
	REF: MM 72-00-02	HRS/MSC	630				800.3	(1430.3)	1430.3
		ENC					507		
CHAPTER 72- ENGINE									
720001	ENGINE ASSEMBLY, TURBOFAN, PW535E, STAINLESS STEEL								
	3072913-01	MOS		TSN:0			28-OCT-2015		
	PCE-DG00578	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
720002	ENGINE ASSEMBLY, TURBOFAN, PW535E, STAINLESS STEEL								
	3072913-01	MOS		TSN:0			28-OCT-2015		
	PCE-DG00581	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
+ 72-00-00-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA								
	PKG 1	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	REF: MM 72-00-00	HRS/MSC	600	+10%			800.3	(1400.3)	1400.3
		ENC					507		1460.3

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-212-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-803	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-804	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-805	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-806	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-807	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-808	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-809	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	MOS					20-MAR-2015		
	REF: MM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 72-00-00-280-818	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	MOS	120	+1m			20-MAR-2015	20-MAR-2025	20-APR-2025
	REF: MM 72-00-00	HRS/MSC ENC					0 0		
+ 72-00-00-280-820	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
+ 72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					06-NOV-2017		
	REF: MM 72-00-00	HRS/MSC ENC	BF/F				547.6 370		
+ 72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS	MOS					28-OCT-2015		
	REF: MM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 720010	NO. 1 ENGINE - OVERHAUL	MOS	5000	+100			20-MAR-2015	(5000) 5000	5100
	REF: GENERIC NO REF	HRS/MSC ENC					0 0		
+ 720060	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS	2500	+50			20-MAR-2015	(2500) 2500	2550
	REF: MM 72-00-00	HRS/MSC ENC					0 0		
722001	NO. 1 ENGINE - OIL PUMP	MOS					20-MAR-2015		
	3073477-02	HRS/MSC	O/C				0		
	SN-UNKNOWN	ENC					0		
	REF: See Workcard						0		

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY 3073356-01 PKAAA597717	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		30000					(30000) 30000	
+ 723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A003LOHC	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: See Workcard		15000					(15000) 15000	
+ 723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1D4447	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		15000					(15000) 15000	
+ 723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 ADO3KKY6	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
+ 723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 EAAD00P250	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
+ 723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A003LLDH	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
+ 723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A003LFBF	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
+ 724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A003LAOF	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			20-MAR-2015 0 0		
LIFE LIMIT	REF: See Workcard		10000					(10000) 10000	

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A003FW75	MOS HRS/MSC		TSN:0 TSN:0			20-MAR-2015 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	13500	TSN:0			0	(13500) 13500	
727008	NO. 1 ENGINE - HIGH POWER SHUTDOWN	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		
727010	NO. 1 ENGINE - SUSPECTED FOD INSPECTION	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		
727011	NO. 1 ENGINE - WINDMILLING IN FLIGHT	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		
727012	NO. 1 ENGINE - LIGHTNING STRIKE	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		
727013	NO. 1 ENGINE - FUEL FILTER CONTAMINATION-INSPECTION	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		
727014	NO. 1 ENGINE - EXPOSED TO FIRE EXTINGUISHING AGENT	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		
727015	NO. 1 ENGINE - INCORRECT SHUTDOWN OF ENGINE ON THE GROUND	MOS HRS/MSC -					20-MAR-2015 0		
	REF:	ENC					0		



Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727016	NO. 1 ENGINE - HEAVY LANDING	MOS					20-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
727017	NO. 1 ENGINE - SUSTAINED RUN AT OIL TEMPS OUTSIDE LIMITS	MOS					20-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									
+ 72-00-00-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
+ 72-00-00-212-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
+ 72-00-00-212-803	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
+ 72-00-00-212-804	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
+ 72-00-00-212-805	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
+ 72-00-00-212-806	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-212-807	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-808	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-212-809	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR REF: MM 72-00-00	MOS HRS/MSC ENC	A/R				27-MAR-2015 0 0		
+ 72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) REF: MM 72-00-00	MOS HRS/MSC ENC	120	+1m			27-MAR-2015 0 0	27-MAR-2025	27-APR-2025
+ 72-00-00-280-820	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL REF: MM 72-00-00	MOS HRS/MSC ENC	BF/F				06-NOV-2017 547.6 370		
+ 72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS REF: MM 72-00-00	MOS HRS/MSC ENC	A/R				28-OCT-2015 0 0		

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720010	NO. 2 ENGINE - OVERHAUL	MOS					27-MAR-2015		
	REF: GENERIC NO REF	HRS/MSC ENC	5000	+100			0 0	(5000) 5000	5100
+ 720060	NO. 2 ENGINE - HOT SECTION INSPECTION	MOS					27-MAR-2015		
	REF: MM 72-00-00	HRS/MSC ENC	2500	+50			0 0	(2500) 2500	2550
722001	NO. 2 ENGINE - OIL PUMP	MOS					27-MAR-2015		
	3073477-02	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: See Workcard			TSN:0					
+ 723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY	MOS					27-MAR-2015		
	3073356-01	HRS/MSC		TSN:0			0		
	PKAAA597714	ENC	30000	TSN:0			0	(30000) 30000	
	REF: GENERIC NO REF			TSN:0					
LIFE LIMIT									
+ 723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR	MOS					27-MAR-2015		
	3073311-01	HRS/MSC		TSN:0			0		
	A003L7M9	ENC	15000	TSN:0			0	(15000) 15000	
	REF: See Workcard			TSN:0					
LIFE LIMIT									
+ 723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR	MOS					27-MAR-2015		
	3073292-01	HRS/MSC		TSN:0			0		
	TXA1D4533	ENC	15000	TSN:0			0	(15000) 15000	
	REF: GENERIC NO REF			TSN:0					
LIFE LIMIT									
+ 723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR	MOS					27-MAR-2015		
	3072981-01	HRS/MSC		TSN:0			0		
	AOO3L350	ENC	13500	TSN:0			0	(13500) 13500	
	REF: GENERIC NO REF			TSN:0					
LIFE LIMIT									
+ 723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR	MOS					27-MAR-2015		
	3056210-01	HRS/MSC		TSN:0			0		
	EAAD000P522	ENC	13500	TSN:0			0	(13500) 13500	
	REF: GENERIC NO REF			TSN:0					
LIFE LIMIT									

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A003LNX5	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			27-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
+ 723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A003LNNH	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			27-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
+ 724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A003LHDL	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			27-MAR-2015 0 0		
LIFE LIMIT	REF: See Workcard		10000					(10000) 10000	
+ 724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A003L3LP	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			27-MAR-2015 0 0		
LIFE LIMIT	REF: GENERIC NO REF		13500					(13500) 13500	
727008	NO. 2 ENGINE - HIGH POWER SHUTDOWN	MOS HRS/MSC ENC					27-MAR-2015 0 0		
REF:									
727010	NO. 2 ENGINE - SUSPECTED FOD INSPECTION	MOS HRS/MSC ENC					27-MAR-2015 0 0		
REF:									
727011	NO. 2 ENGINE - WINDMILLING IN FLIGHT	MOS HRS/MSC ENC					27-MAR-2015 0 0		
REF:									
727012	NO. 2 ENGINE - LIGHTNING STRIKE	MOS HRS/MSC ENC					27-MAR-2015 0 0		
REF:									

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727013	NO. 2 ENGINE - FUEL FILTER CONTAMINATION-INSPECTION								
		MOS					27-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
727014	NO. 2 ENGINE - EXPOSED TO FIRE EXTINGUISHING AGENT								
		MOS					27-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
727015	NO. 2 ENGINE - INCORRECT SHUTDOWN OF ENGINE ON THE GROUND								
		MOS					27-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
727016	NO. 2 ENGINE - HEAVY LANDING								
		MOS					27-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
727017	NO. 2 ENGINE - SUSTAINED RUN AT OIL TEMPS OUTSIDE LIMITS								
		MOS					27-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
CHAPTER 73- ENGINE FUEL AND CONTROL									
73-21-01	LEFT FADEC								
	3073593-08	MOS					28-OCT-2015		
	2014100010	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
73-21-01	RIGHT FADEC								
	3073593-08	MOS					28-OCT-2015		
	2015020012	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER								
	8TJ300AAB2	MOS					28-OCT-2015		
	DTW4969	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 DTW6195 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
+ 72-00-00-280-819	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 	(5000) 5000	M 5100
+ 73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900		TSI:0 TSI:0		(EBT) 	(9900) 9900	
+ 73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d			15-NOV-2018 800.3 507	15-NOV-2019	15-DEC-2019
+ 73-10-05-960-801	NO. 1 ENGINE - DISCARD FUEL THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			06-NOV-2017 547.6 370	(1147.6) 1147.6	1207.6
+ 73-10-07-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT PN SN-UNKNOWN REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 	(5000) 5000	M 5100

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-20-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
73-20-10-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000 M 5100	
73-20-20-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000 M 5100	
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0			(5000) 5000 M 5100	
+ 73-30-02-212-801	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
730007	NO. 1 ENGINE - EMERGENCY FUEL SHUT-OFF PIN DIMENSIONAL CHECK-ONE TIME REF:	MOS HRS/MSC ENC	-				20-MAR-2015 0 0		
730010	NO. 1 ENGINE - FUEL METERING UNIT- INSPECTION REF:	MOS HRS/MSC ENC	-				20-MAR-2015 0 0		
730011	NO. 1 ENGINE - FUEL FLOW MANIFOLD AND FUEL NOZZLES REF:	MOS HRS/MSC ENC	-				20-MAR-2015 0 0		

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
730013	NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER INSPECTION	MOS					20-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
731005	NO. 1 ENGINE - FUEL FILTER	MOS		TSN:0			06-NOV-2017		
	PN	HRS/MSC	O/C	TSN:0			547.6		
	SN-UNKNOWN	ENC		TSN:0			370		
	REF: GENERIC NO REF								
731015	NO. 1 ENGINE - ELECTRONIC ENGINE CONTROL	MOS					20-MAR-2015		
	REF:	HRS/MSC -					0		
		ENC					0		
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH	MOS		TSN:0			28-OCT-2015		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: GENERIC NO REF								
732040	NO. 1 ENGINE - FUEL SHUT-OFF CABLE	MOS		TSN:0			28-OCT-2015		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	ENC		TSN:0			0		
	REF: See Workcard								

ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E

+ 72-00-00-280-819	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	PKG 1	HRS/MSC	600	+10%			800.3	(1400.3) 1400.3	1460.3
	REF: MM 72-00-00	ENC					507		
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES	MOS		TSI:0			(EBT)		
	REF: GENERIC NO REF	HRS/MSC	5000	+100	TSI:0			(5000) 5000	M 5100
		ENC		TSI:0					
+ 73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES	MOS		TSI:0			(EBT)		
	REF: MM 73-10-04	HRS/MSC		TSI:0				(9900) 9900	
		ENC	9900						

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d			15-NOV-2018 800.3 507	15-NOV-2019	15-DEC-2019
+ 73-10-05-960-801	NO. 2 ENGINE - DISCARD FUEL THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			06-NOV-2017 547.6 370	(1147.6) 1147.6	1207.6
+ 73-10-07-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT PN SN-UNKNOWN REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000	M 5100
+ 73-20-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
73-20-10-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000	M 5100
73-20-20-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000	M 5100
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0			(5000) 5000	M 5100

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-30-02-212-801	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	REF: MM 73-30-02	HRS/MSC ENC	600	+10%			800.3 507	(1400.3) 1400.3	1460.3
730007	NO. 2 ENGINE - EMERGENCY FUEL SHUT-OFF PIN DIMENSIONAL CHECK-ONE TIME	MOS					27-MAR-2015		
	REF:	HRS/MSC ENC	-				0 0		
730010	NO. 2 ENGINE - FUEL METERING UNIT- INSPECTION	MOS					27-MAR-2015		
	REF:	HRS/MSC ENC	-				0 0		
730011	NO. 2 ENGINE - FUEL FLOW MANIFOLD AND FUEL NOZZLES	MOS					27-MAR-2015		
	REF:	HRS/MSC ENC	-				0 0		
730013	NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER INSPECTION	MOS					27-MAR-2015		
	REF:	HRS/MSC ENC	-				0 0		
731005	NO. 2 ENGINE - FUEL FILTER PN SN-UNKNOWN	MOS					06-NOV-2017		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			547.6 370		
731015	NO. 2 ENGINE - ELECTRONIC ENGINE CONTROL	MOS					27-MAR-2015		
	REF:	HRS/MSC ENC	-				0 0		
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN	MOS					28-OCT-2015		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			0 0		



Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732040	NO. 2 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
CHAPTER 74- IGNITION									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
74-00-01-750-801 (s)	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 600				PKG 15-NOV-2018 800.3 507		
+ 74-10-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER PN PKG 1 SN-UNKNOWN REF: MM 74-10-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 74-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR PN-UNKNOWN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG 15-NOV-2018 800.3 507		
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR PN-UNKNOWN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG 15-NOV-2018 800.3 507		
+ 74-20-02-960-801	NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				25-FEB-2018 599.7 396		

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 74-20-02-960-801	NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSI:0 TSI:0 TSI:0			25-FEB-2018 599.7 396		
+ 742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-FEB-2018 599.7 396		
+ 742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			25-FEB-2018 599.7 396		
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-02 NNA16440200 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-MAY-2019 892.4 554		
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-01 NNA16370060 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-MAY-2019 892.4 554		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									
74-00-01-750-801 (s)	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 600				PKG 15-NOV-2018 800.3 507		
+ 74-10-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER PN PKG 1 SN-UNKNOWN REF: MM 74-10-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 74-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3



Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR PN-UNKNOWN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS	12				PKG 15-NOV-2018 800.3 507		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR PN-UNKNOWN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS	12				PKG 15-NOV-2018 800.3 507		
+ 74-20-02-960-801	NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS	O/C				25-FEB-2018 599.7 396		
+ 74-20-02-960-801	NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS	O/C	TSI:0			25-FEB-2018 599.7 396		
+ 742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS	O/C	TSN:0			25-FEB-2018 599.7 396		
+ 742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS	O/C	TSN:0			25-FEB-2018 599.7 396		
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD 3127401-01 NNA1740057 REF: See Workcard	MOS	O/C	TSN:0			13-MAY-2019 892.4 554		
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-02 NNA16440215 REF: See Workcard	MOS	O/C	TSN:0			13-MAY-2019 892.4 554		

CHAPTER 75- AIR

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
+ 75-30-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1	MOS	12	+30d			15-NOV-2018	15-NOV-2019	15-DEC-2019
	REF: MM 75-30-01	HRS/MSC ENC	600	+10%			800.3	(1400.3) 1400.3	1460.3
+ 75-30-01-212-802	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR PN	MOS					(EBT)		
	SN-UNKNOWN	HRS/MSC	5000	+100	TSI:0			(5000) 5000	M 5100
	REF: MM 75-30-01	ENC			TSI:0				
75-30-01-212-803	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE PN	MOS					(EBT)		
	SN-UNKNOWN	HRS/MSC	5000	+100	TSI:0			(5000) 5000	M 5100
	REF:	ENC			TSI:0				
+ 75-30-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER PN	MOS					(EBT)		
	SN-UNKNOWN	HRS/MSC	5000	+100	TSI:0			(5000) 5000	M 5100
	REF: GENERIC NO REF	ENC			TSI:0				
+ 75-30-20-212-801	NO. 1 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN	MOS					(EBT)		
	SN-UNKNOWN	HRS/MSC	5000	+100	TSI:0			(5000) 5000	M 5100
	REF: GENERIC NO REF	ENC			TSI:0				
750010	NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR PN	MOS					28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	ENC			TSN:0		0		
753020	NO. 1 ENGINE - BOV TORQUE MOTOR PN	MOS					28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	ENC			TSN:0		0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 75-30-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1 REF: MM 75-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: MM 75-30-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000 M 5100	
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000 M 5100	
+ 75-30-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000 M 5100	
+ 75-30-20-212-801	NO. 2 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT)	(5000) 5000 M 5100	
750010	NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
753020	NO. 2 ENGINE - BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		
CHAPTER 76-	ENGINE CONTROLS								
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY 6990010-11 1689 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		28-OCT-2015 0 0		



Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 77- ENGINE INDICATING									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E									
+ 77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM	MOS	36	+30d			16-APR-2018	20-MAR-2021	19-APR-2021
		HRS/MSC	1800	+100			636	(2436) 2436	2536
	REF: MM 77-20-02	ENC					412		
+ 77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT	MOS					(EBT)		
	PN	HRS/MSC	5000	+100				(5000) 5000	M 5100
	SN-UNKNOWN	ENC							
	REF: GENERIC NO REF								
774020	NO. 1 ENGINE - DATA COLLECTION UNIT-INSPECTION	MOS					20-MAR-2015		
		HRS/MSC	-				0		
	REF:	ENC					0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									
+ 77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM	MOS	36	+30d			16-APR-2018	27-MAR-2021	26-APR-2021
		HRS/MSC	1800	+100			636	(2436) 2436	2536
	REF: MM 77-20-02	ENC					412		
+ 77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT	MOS					(EBT)		
	PN	HRS/MSC	5000	+100				(5000) 5000	M 5100
	SN-UNKNOWN	ENC							
	REF: GENERIC NO REF								
774020	NO. 2 ENGINE - DATA COLLECTION UNIT-INSPECTION	MOS					27-MAR-2015		
		HRS/MSC	-				0		
	REF:	ENC					0		
CHAPTER 79- OIL									
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR								
	APTE-478A-1000-270D	MOS					28-OCT-2015		
	00600	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR APTE-478A-1000-270D 00581 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
791020	MAIN OIL TEMPERATURE (MOT) SENSOR ATS-9-800 011315-1 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
791040	MAIN OIL TEMPERATURE (MOT) SENSOR ATS-9-800 011315-5 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		

ENGINE NO. 1 Model : PW535E Serial # PCE-DG-0578 Part # PW535E

+ 79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 	(5000) 5000 M 5100	
+ 79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 	(5000) 5000 M 5100	
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 	(5000) 5000 M 5100	
+ 79-20-01-960-801	NO. 1 ENGINE - DISCARD OIL THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			06-NOV-2017 547.6 370	(1147.6) 1147.6 1207.6	
+ 79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP COLLECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 	(5000) 5000 M 5100	

Status Report

ENGINE#1: S/N PCE-DG-0578

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-30-01-212-801	NO. 1 ENGINE - EXAMINE THE CHIP DETECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 79-30-01-770-801	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
+ 79-30-02-210-801	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
79-30-03-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 79-30-20-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
790000	NO. 1 ENGINE - OIL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		
793005	NO. 1 ENGINE - OIL CHIP COLLECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		
793020	NO. 1 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		



Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			28-OCT-2015 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG-0581 Part # PW535E									
+ 79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 0	(5000) 5000	M 5100
+ 79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 0	(5000) 5000	M 5100
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 0	(5000) 5000	M 5100
+ 79-20-01-960-801	NO. 2 ENGINE - DISCARD OIL THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			06-NOV-2017 547.6 370	(1147.6) 1147.6	1207.6
+ 79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP COLLECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 0	(5000) 5000	M 5100
+ 79-30-01-212-801	NO. 2 ENGINE - EXAMINE THE CHIP DETECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100	TSI:0 TSI:0 TSI:0		(EBT) 0	(5000) 5000	M 5100
+ 79-30-01-770-801	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

ENGINE#2: S/N PCE-DG-0581

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

958.7 HRS, 591 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-30-02-210-801	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			15-NOV-2018 800.3 507	15-NOV-2019 (1400.3) 1400.3	15-DEC-2019 1460.3
79-30-03-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) TSI:0 TSI:0 TSI:0	(5000) 5000 M 5100	
+ 79-30-20-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) TSI:0 TSI:0 TSI:0	(5000) 5000 M 5100	
790000	NO. 2 ENGINE - OIL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		
793005	NO. 2 ENGINE - OIL CHIP COLLECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		
793020	NO. 2 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				28-OCT-2015 0 0		

CHAPTER ---	GENERAL								
+ Z210-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			28-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z210-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: See Workcard								
+ Z220-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-41-00								
+ Z220-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: See Workcard								
+ Z230-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-42-00								
+ Z230-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-42-00								
+ Z240-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-42-00								
+ Z240-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-42-00								
+ Z310-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-43-00								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z310-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-43-00								
+ Z320-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-43-00								
+ Z320-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-43-00								
+ Z330-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-44-00								
+ Z330-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-44-00								
+ Z340-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-44-00								
+ Z340-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-44-00								
+ Z410-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
	REF: AMM 05-46-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500283 (N600GF): 958.7 HRS, 591 AFL as of 15-Aug-2019

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 16-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z410-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ Z430-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 28-OCT-2015 0 0		
+ Z430-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE PKG 84 REF: AMM 05-46-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
+ Z500-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS PKG 84 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
+ Z500-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS PKG 84 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		
+ Z700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY PKG 84 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 28-OCT-2015 0 0		