



# Status Report

## EMB-505 - PHENOM 300 S/N 50500037 N312FL

**OWNER:** LATITUDE 33 AVIATION, LLC  
**ADDRESS:** 2056 PALOMAR AIRPORT ROAD  
 CARLSBAD CA 92011  
**PHONE:**  
**FAX:** 760-278-2168

**OPERATOR:** LATITUDE 33 AVIATION, LLC  
**ADDRESS:** 2056 PALOMAR AIRPORT ROAD  
 CARLSBAD CA 92011  
**PHONE:**  
**FAX:** 760-278-2168

**ANALYST:** ANDREY KORSUKOV  
**EMAIL:** AKORSUKOV@CAMPSYSTEMS.COM

+1-514-636-2016 (DIRECT)  
 514-636-2020 (OFFICE)  
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)  
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** 50500037/N312FL      **MODEL:** EMB-505 - PHENOM 300      **MANUFACTURER:** EMBRAER

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 21-SEP-2011	1676.7 A/C HRS	as of 22-SEP-2020	A/C HRS	as of ___/___/___
	1083 AFL	as of 22-SEP-2020	AFL	as of ___/___/___

**ENGINE NO. 1 SERIAL/PART:** PCE-DG0064/A3072913-01      **MODEL:** PW535E      **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 10-DEC-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	1 A/C HRS	1676.7 ENG. HRS	as of 22-SEP-2020	ENG. HRS	as of ___/___/___
ENC		1083 ENC	as of 22-SEP-2020	ENC	as of ___/___/___

**ENGINE NO. 2 SERIAL/PART:** PCE-DG0063/A3072913-01      **MODEL:** PW535E      **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 10-DEC-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	1 A/C HRS	1676.7 ENG. HRS	as of 22-SEP-2020	ENG. HRS	as of ___/___/___
ENC		1083 ENC	as of 22-SEP-2020	ENC	as of ___/___/___



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>							
05-30-01	800 FH MAINTENANCE PACKAGE							
	PKG 1	MOS				14-APR-2019		
		HRS/MSC	800	+30/-30	26.5	1206.8	<b>2033.3</b>	2063.3
	REF: SMR 05-30-01	AFL				793		
05-30-10	1600 FH MAINTENANCE PACKAGE							
	PKG 10	MOS				27-JUN-2017		
		HRS/MSC	1600	+30/-30		840.6	<b>2440.6</b>	2470.6
	REF: SMR 05-30-10	AFL				558		
05-30-20	2400 FH MAINTENANCE PACKAGE							
	PKG 20	MOS				21-SEP-2011		
		HRS/MSC	2400	+30/-30		0	<b>2400</b>	2430
	REF: SMR 05-30-20	AFL				0		
05-30-40	3200 FH MAINTENANCE PACKAGE							
	PKG 40	MOS				21-SEP-2011		
		HRS/MSC	3200	+30/-30		0	<b>3200</b>	3230
	REF: SMR 05-30-40	AFL				0		
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE							
+	PKG 42	MOS	60	+1m/-1m		27-MAY-2016	<b>27-MAY-2021</b>	27-JUN-2021
		HRS/MSC	3200	+30/-30		688.1	<b>3888.1</b>	3918.1
	REF: SMR 05-30-42	AFL				478		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-50	5600 MAINTENANCE PACKAGE							
	PKG 50	MOS				21-SEP-2011		
		HRS/MSC	5600	+30/-30		0		5600
	REF: SMR 05-30-50	AFL				0		5630
05-30-60	6400 FH MAINTENANCE PACKAGE							
	PKG 60	MOS				21-SEP-2011		
		HRS/MSC	6400	+30/-30		0		6400
	REF: SMR 05-30-60	AFL				0		6430
05-30-80	12 MO MAINTENANCE PACKAGE							
	PKG 80	MOS	12	+30d/-30d	24	05-MAY-2020	29-MAY-2021	28-JUN-2021
		HRS/MSC				1528.2		
	REF: SMR 05-30-80	AFL				990		
05-30-81	24 MO MAINTENANCE PACKAGE							
	PKG 81	MOS	24	+30d/-30d	-30	27-JUN-2019	28-MAY-2021	27-JUN-2021
		HRS/MSC				1275.4		
	REF: SMR 05-30-81	AFL				845		
05-30-82	36 MO MAINTENANCE PACKAGE							
	PKG 82	MOS	36	+1m/-1m		05-MAY-2020	05-MAY-2023	05-JUN-2023
		HRS/MSC				1528.2		
	REF: SMR 05-30-82	AFL				990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-83	48 MO MAINTENANCE PACKAGE							
	PKG 83	MOS	48			27-JUN-2017	27-JUN-2021	27-JUL-2021
		HRS/MSC		+30d/-30d		840.6		
	REF: SMR 05-30-83	AFL				558		
05-30-84	60 MO MAINTENANCE PACKAGE							
	PKG 84	MOS	60			27-MAY-2016	27-MAY-2021	26-JUN-2021
		HRS/MSC		+30d/-30d		688.1		
	REF: SMR 05-30-84	AFL				478		
05-30-87	120 MO MAINTENANCE PACKAGE							
	PKG 87	MOS	120			21-SEP-2011	21-SEP-2021	21-OCT-2021
		HRS/MSC		+30d/-30d		0		
	REF: SMR 05-30-87	AFL				0		
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							
	PKG 90	MOS	120			21-SEP-2011	21-SEP-2021	21-OCT-2021
		HRS/MSC		+30d/-30d		0		
	REF: SMR 05-30-90	AFL				0		

ENGINE NO.	Model	Serial #	PCE-DG0064	Part #	A3072913-01
051254	PW535E	PCE-DG0064	A3072913-01	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION	
	PKG 1	MOS	12	+30d	05-MAY-2020
		HRS/MSC	800	+10%	1528.2
	REF: MM 05-20-00	ENC			990
					(2328.2) 2328.2
					04-JUN-2021
					2408.2

ENGINE NO.	Model	Serial #	PCE-DG0063	Part #	A3072913-01
------------	-------	----------	------------	--------	-------------

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							
	PKG 1	MOS	12			05-MAY-2020	<b>05-MAY-2021</b>	04-JUN-2021
		HRS/MSC	800	+30d		1528.2	<b>(2328.2) 2328.2</b>	2408.2
	REF: MM 05-20-00	ENC		+10%		990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
00-CUS-0701	RENEWAL OF AIRCRAFT REGISTRATION								
		MOS						31-OCT-2021	M
	REF:	HRS/MSC	DUE						
		AFL							
EM55-160520	REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16								
		MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF EM55-160520	HRS/MSC	-						
		AFL							
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM								
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF EM55-160705	HRS/MSC	-						
		AFL							
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM								
		MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF EM55-160705-1	HRS/MSC	-						
		AFL							
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
		MOS							
<b>REQUIREMENT CHANGE FORMS</b>	REF: RCF EM55-160822	HRS/MSC	-						
		AFL							



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EM55-161022</b>	MOS HRS/MSC - AFL							
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EM55-161122</b>	MOS HRS/MSC - AFL					(EBT)		
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EM55-161122-1</b>	MOS HRS/MSC - AFL							
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EM55-161202</b>	MOS HRS/MSC - AFL							
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EM55</b>	MOS HRS/MSC - AFL					(EBT)		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	-------------	------------	---------------------------	--------------

EM55-190218A REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019

REQUIREMENT CHANGE FORMS

REF: RCF EM55

MOS  
HRS/MSC -  
AFL

## ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01

E53E-160530 NO. 1 ENGINE - REVIEW PW535E MM REV 11.0

REQUIREMENT CHANGE FORMS

REF: RCF E53E

MOS  
HRS/MSC -  
ENC

(EBT)

## ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01

E53E-160530 NO. 2 ENGINE - REVIEW PW535E MM REV 11.0

REQUIREMENT CHANGE FORMS

REF: RCF E53E

MOS  
HRS/MSC -  
ENC

(EBT)

## CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

H140-001 (s) EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE

PKG 87

MOS 120 +30d/-30d  
HRS/MSC  
AFL

REF: AMM 05-42-00

PKG

H242-001 (s) INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE

PKG 87

MOS 120 +30d/-30d  
HRS/MSC  
AFL

REF: AMM 05-42-00

PKG

21-SEP-2011  
0  
0

H430-001 INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS

PKG 84

MOS 60 +30d/-30d  
HRS/MSC  
AFL

REF: AMM 05-46-00

24

05-MAY-2020 29-MAY-2025 28-JUN-2025  
1528.2  
990





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H700-001	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS								
	PKG 84	MOS	60	+30d/-30d		24	05-MAY-2020	29-MAY-2025	28-JUN-2025
	REF: AMM 05-47-00	HRS/MSC AFL					1528.2 990		
H700-002	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS								
	PKG 84	MOS	60	+30d/-30d		24	05-MAY-2020	29-MAY-2025	28-JUN-2025
	REF: AMM 05-47-00	HRS/MSC AFL					1528.2 990		
H700-003	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING								
	PKG 84	MOS	60	+30d/-30d		24	05-MAY-2020	29-MAY-2025	28-JUN-2025
	REF: AMM 05-47-00	HRS/MSC AFL					1528.2 990		
<b>ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01</b>									
+ 05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS								
		MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC A/R ENC					0 0		
+ 05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE								
		MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC A/R ENC					0 0		
+ 05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED								
		MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC A/R ENC					0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-810	NO. 1 ENGINE - ENGINE IMMERSION IN WATER	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-811	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-812	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-813	NO. 1 ENGINE - LOSS OF OIL								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-814	NO. 1 ENGINE - CHIP DETECTOR LIGHT "ON"								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION								
		MOS					23-SEP-2010		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	MOS					23-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-823	NO. 1 ENGINE - FUEL CONTAMINATION	MOS					23-SEP-2010		
<b>UNSCHEDULED MAINTENANCE CHECK</b>	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
<b>ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01</b>									
+ 05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-810	NO. 2 ENGINE - ENGINE IMMERSION IN WATER	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-811	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS					21-SEP-2010		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-812	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	
+ 05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	
+ 05-50-00-210-814	NO. 2 ENGINE - CHIP DETECTOR LIGHT "ON"	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	
+ 05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	
+ 05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	
+ 05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	
+ 05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R					0	
		ENC						0	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-823	NO. 2 ENGINE - FUEL CONTAMINATION	MOS						21-SEP-2010	
	REF: MM 05-50-00	HRS/MSC	A/R				0		
	UNSCHEДУLED MAINTENANCE CHECK	ENC					0		

## CHAPTER 08 LEVELING AND WEIGHING

8-0001-1	PERFORM WEIGHT AND BALANCE CHECK (FAR 91.423 OR 135.185)	MOS	36					13-NOV-2018	25-NOV-2021 M
	REF: GENERIC NO REF	HRS/MSC					1071.9		
		AFL					701		

## CHAPTER 21 AIR CONDITIONING



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-01-01	RH INSC ILLUM PANEL 441-42629-002 1035 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-20-01	AVIONICS BLOWER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-20-02	AVIONICS/DISPLAY COOLING FAN PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 201 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-JUN-2012 106.5 88		
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 130 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-JUN-2012 106.5 88		
21-20-05	GROUND COOLING FAN 1133660-3 308 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-MAY-2015 633.3 448		
21-21-02-001 (s)	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE PKG 60 REF: AMM 21-21-02	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-21-02-001 (s)	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE PKG 60 REF: AMM 21-21-02	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR 100000-77 25039 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
21-23-03	RAM AIR VALVE 505-18030-403 0000624594 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
21-23-03-002 (s)	OPERATIONAL CHECK OF RAM AIR VALVE POSITION PKG 60 REF: AMM 21-23-03	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
21-23-03-003 (s)	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION PKG 1 REF: AMM 21-23-03	MOS HRS/MSC AFL	800				PKG 14-APR-2019 1206.8 793		
21-23-04-001 (s)	OPERATIONAL CHECK OF RAM AIR CHECK VALVES PKG 60 REF: AMM 21-23-04	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
21-23-05-001 (s)	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN PKG 10 REF: AMM 21-23-05	MOS HRS/MSC AFL	1600	+30/-30			PKG 27-JUN-2017 840.6 558		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-24-01-001 (s)	OPERATIONAL CHECK OF IFE COOLING FAN PKG 60 REF: AMM 21-24-01	MOS HRS/MSC AFL	6400	+15/-30			PKG 21-SEP-2011 0 0		
21-31-00-002 (s)	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		
21-31-00-003 (s)	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE) PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		
21-31-00-004 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
21-31-00-005 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
21-31-01	(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT 2119286-5 2119286-00635 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:1 N:0 N:0		15-NOV-2011 26.7 18		
21-31-01-001	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) 2119286-5 2119286-00635 REF: AMM 21-31-01	MOS HRS/MSC AFL	5600	+30/-30			15-NOV-2011 26.7 18	5626.7	5656.7



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-02	OUTFLOW VALVE 103922-1 103922-00033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-31-02-001	RESTORATION (REPAIR) OF OUTFLOW VALVE 103922-1 103922-00033 REF: AMM 21-31-02	MOS HRS/MSC AFL	7200	+30/-30			21-SEP-2011 0 0	7200	7230
21-31-03	NEGATIVE PRESSURE RELIEF (NPR) VALVE 130664-2 34163-0265 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-31-03-001 (s)	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-03	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
21-31-04	PRESSURE RELIEF (PRV) VALVE 103918-2 103918-00080 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-31-04-001 (s)	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-04	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
21-41-01	BHS SHUT-OFF VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-41-04	RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-52-01	CDM - COMPRESSOR 1133640-5 175 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-JUL-2018 1036 668		
21-52-01-002	DISCARD OF COMPRESSOR DRIVE MODULE BELT  REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			27-JUN-2017 840.6 558	2840.6	2870.6
21-52-01-003 (s)	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION PKG 1 REF: AMM 21-52-01	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		
21-52-01-004	RESTORATION (OVERHAUL) CDM - COMPRESSOR 1133640-5 175 REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			04-JAN-2015 513.6 356	2513.6	2543.6
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE 1133860-4 137 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			58 25		
21-52-03-001 (s)	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES PKG 1 REF: AMM 21-52-03	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-04	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER 1133850-104 397 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-52-06-001 (s)	SERVICING OF VCS REFRIGERANT FLUID PKG 80 REF: AMM 12-17-00	MOS HRS/MSC AFL	12				PKG 05-MAY-2020 1528.2 990		
21-52-08	AIR CONDITION CONDENSER ASSEMBLY 1133760-2 154 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-52-08-001 (s)	GENERAL VISUAL INSPECTION OF VCS CONDENSER PKG 10 REF: AMM 21-52-08	MOS HRS/MSC AFL	1600	+30/-30			PKG 27-JUN-2017 840.6 558		
21-52-09	AIR CONDITION MIX FLOW CONDENSER FAN 1133720-3 164 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-52-10	AIR CONDITION BLEED AIR HEAT EXCHANGER 1320260-2 150 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-61-00-001 (s)	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM PKG 1 REF: AMM 21-61-00	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-01	ECS TEMPERATURE CONTROLLER 1300670-6 00131 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-MAY-2013 270.6 185		
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1244 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1292 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1185 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH 1300450-10 1299 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
21-61-06-001 (s)	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR PKG 60 REF: AMM 21-61-06	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
215207-0101	RECEIVER 1134275-12 8004905424 REF:	MOS HRS/MSC AFL	O/C				05-JUL-2013		

## CHAPTER 22 AUTO FLIGHT

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-00	GMC 715 GUIDANCE PANEL 011-01430-00 15900415 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO  REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		24	05-MAY-2020 1528.2 990	29-MAY-2021	28-JUN-2021
<b>AIRWORTHINESS</b>									
22-11-00-001	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO  REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		24	05-MAY-2020 1528.2 990	29-MAY-2021	28-JUN-2021
<b>AIRWORTHINESS</b>									
22-11-00-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO  REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		24	05-MAY-2020 1528.2 990	29-MAY-2021	28-JUN-2021
<b>AIRWORTHINESS</b>									
22-11-00-001	FUNCTIONAL CHECK TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO  REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d		24	05-MAY-2020 1528.2 990	29-MAY-2021	28-JUN-2021
<b>AIRWORTHINESS</b>									
22-11-00-002 (s)	LUBRICATION OF SERVO ACTUATORS PKG 80 REF: AMM 22-11-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
22-11-00-003 (s)	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE PKG 42 REF: AMM 22-11-00	MOS HRS/MSC AFL	60	+1m/-1m +30/-30			PKG 27-MAY-2016 688.1 478		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-01	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO 011-00877-21 1A0005570 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1006040 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-02	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1005999 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-02	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1006018 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-03	AILERON GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK005599 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-06	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK005489 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
22-11-09	RUDDER GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK005494 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-12	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT 011-01904-00 1GK005567 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>CHAPTER 23 COMMUNICATIONS</b>									
23-10-01	VHF ANTENNA S65-8280-41 322-2419 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-11-01	PS440 HF CONTROL DISPLAY UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-11-02	REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-11-03	KPA 1052 POWER AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-11-04	HF ANTENNA COUPLER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-12-02	BOTTOM VHF 2 ANTENNA S65-8280-41 322-2441 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-21-01	SELCAL CSD DECODER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-50-01	LEFT GMA 1347D AUDIO PANEL 011-01257-20 17106176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-50-02	COPILOT HEADSET 026-55-999-0131 00200189 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-50-02	PILOT HEADSET 026-55-999-0131 00200188 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-50-03	HAND MICROPHONE 85-03-12369-04 245887 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-50-04	COCKPIT SPEAKER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-50-05	CDVR MICROPHONE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-51-00-001 (s)	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE PKG 40 REF: AMM 23-51-00	MOS HRS/MSC AFL	3200	+30/-30			PKG 24-JAN-2012 57.6		
23-51-01	RIGHT GMA 1347D AUDIO PANEL 011-01257-20 17106196 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-51-05	LEFT CONTROL PANEL 441-40943-002 0531 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-51-05	RIGHT CONTROL PANEL 441-40943-002 0738 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
23-61-00-001 (s)	FUNCTIONAL CHECK OF STATIC DISCHARGERS PKG 83 REF: AMM 23-61-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
<b>CHAPTER 24 ELECTRICAL POWER</b>									
24-01-01	LEFT CONSOLE CONTROL PANEL 441-40929-002 0322 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
24-31-01	NO. 1 ENGINE STARTER/GENERATOR 400SG180Q S01125XL REF: See Workcard	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			14-APR-2019 1206.8 793		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01	NO. 2 ENGINE STARTER/GENERATOR MG103C-4 0716 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-APR-2015 628.2 431		
24-31-01-001	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S01125XL REF: AMM 24-31-01	MOS HRS/MSC AFL	800	+30/-30			14-APR-2019 1206.8 793	2006.8	2036.8
24-31-01-001	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) MG103C-4 0716 REF: AMM 24-31-01	MOS HRS/MSC AFL	800	+30/-30			10-APR-2015 628.2 431	1828.2 M	1858.2
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) 400SG180Q S01125XL REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A						
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017) MG103C-4 0716 REF: AMM 24-31-01	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT CG301A-12 389 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-MAY-2015 633.3 448		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT CG301A-12 406 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-MAY-2015 633.3 448		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF LH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60				PKG 07-JUN-2019 1263.3 836		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF RH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60				PKG 07-JUN-2019 1263.3 836		
24-36-01	AFT MAIN BATTERY 7638-48P G03088580 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-MAY-2020 1528.2 990		
24-36-01	FORWARD MAIN BATTERY 7639-34 G03087442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-MAY-2020 1528.2 990		
24-36-01-003	DISCARD AFT MAIN BATTERY 7638-48P G03088580 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			05-MAY-2020 1528.2 990	<b>05-MAY-2022</b> <b>1590</b>	04-JUN-2022 1620
24-36-01-003	DISCARD FORWARD MAIN BATTERY 7639-34 G03087442 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			05-MAY-2020 1528.2 990	<b>05-MAY-2022</b> <b>1590</b>	04-JUN-2022 1620

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7638-48P G03088580 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7639-34 G03087442 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015) 7638-48P G03088580 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			05-MAY-2020 1528.2 990	05-MAY-2021	04-JUN-2021
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015) 7639-34 G03087442 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			05-MAY-2020 1528.2 990	05-MAY-2021	04-JUN-2021
24-36-02-001 (s)	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2) PKG 60 REF: AMM 24-36-02	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
24-54-05	28 VDC / 115 VAC STATIC INVERTER AS-24-0026-001 0325 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-SEP-2011 0 0		
24-65-00	W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-65-01	LEFT POWER DISTRIBUTION BOX SX7EG20-1 0051 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
24-65-02	RIGHT POWER DISTRIBUTION BOX SX7EG21-1 0057 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
24-65-04	NOSE POWER DISTRIBUTION BOX SX7EG22-1 0058 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									
25-11-01	COPILOT SEAT 1429-621DE 1173-1429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-11-01	PILOT SEAT 1429-521DE 1194-1429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-11-01-001 (s)	DETAILED INSPECTION COPILOT SEAT PKG 20 REF: AMM 25-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 29-MAY-2015 633.3 448		
25-11-01-001 (s)	DETAILED INSPECTION PILOT SEAT PKG 20 REF: AMM 25-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 29-MAY-2015 633.3 448		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-01-002 (s)	DETAILED INSPECTION OF COCKPIT SEAT BELTS PKG 20 REF: AMM 25-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 29-MAY-2015 633.3 448		
25-21-01	PAX 1 - RH AFT FACE SEAT 403174-8I2FZ 48473 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-01	PAX 2 - LH AFT FACE SEAT 403174-5I2FZ 48468 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-01	PAX 3 - RH AFT FACE SEAT 403174-6I2FZ 48470 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-01	PAX 6 - LH FWD FACE SEAT 403174-7I2FZ 48472 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-01	PAX 7 - RH FWD FACE SEAT 403174-8I2FZ 48474 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER SEATS PKG 20 REF: AMM 25-21-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 29-MAY-2015 633.3 448		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-01-002 (s)	DETAILED INSPECTION OF PASSENGER SEAT BELTS PKG 20 REF: AMM 25-21-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 29-MAY-2015 633.3 448		
25-21-02	DIVAN PN NOT INSTALLED SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-02-001	DETAILED INSPECTION DIVAN PN NOT INSTALLED SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	N/A				29-MAY-2015 633.3 448		
25-21-02-002	DETAILED INSPECTION DIVAN SEAT BELTS PN NOT INSTALLED SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	N/A				29-MAY-2015 633.3 448		
25-21-03	PAX 4 - LH FWD FACE SEAT 403174-512FZ 48469 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-03	PAX 5 - RH FWD FACE SEAT 403174-612FZ 48471 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-21-04-001	RESTORATION (DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY (OVERHAUL) OF SEAT BELT AIRBAG SYSTEM REF: AMM 25-21-04	MOS HRS/MSC AFL	N/A				21-SEP-2011		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-43-01-001 (s)	DETAILED VISUAL INSPECTION BELTED TOILET UNIT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3200	+30/-30			PKG 29-MAY-2015 633.3 448		
25-43-01-002 (s)	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3200	+30/-30			PKG 29-MAY-2015 633.3 448		
25-60-01	EMERGENCY LOCATOR TRANSMITTER S1821502-02 2622275-0044 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:69 N:840.6 N:558			27-JUN-2017 840.6 558		
25-60-03	ELT ANTENNA S65-8282-406 401-1759 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY DK120 AT65045 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2017 840.6 558		
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM S1821502-02 2622275-0044 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				05-DEC-2019 1444 948	05-DEC-2020	
25-61-00-002	GENERAL VISUAL INSPECTION EMERGENCY LOCATOR TRANSMITTER OF EMERGENCY LOCATOR TRANSMITTER S1821502-02 2622275-0044 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				05-MAY-2020 1528.2 990	05-MAY-2021	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY DK120 AT65045 REF: AMM 25-61-04	MOS HRS/MSC AFL	72					31-JUL-2022 M	
25-61-05	CS144-A ELT/NAV INTERFACE MODULE S1825502-02 TM0000016654 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			16-NOV-2011 26.7 18		
+ 25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE S1825502-02 TM0000016654 REF: AMM 25-61-07	MOS HRS/MSC AFL	N/A						
25-62-01	FIRST AID KIT 019708-0005L 8009451078 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	N:2 N:0 N:0			26-APR-2019 1217.4 807		
25-62-01-001	VISUAL CHECK FIRST AID KIT 019708-0005L 8009451078 REF: AMM 25-62-01	MOS HRS/MSC AFL	DUE				26-APR-2019 1217.4 807	29-OCT-2020 M	
25-62-02	COPILOT LIFE VEST 63600-105 L1345350 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 1 PASSENGER LIFE VEST 63600-105 L1435349 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02	NO. 2 PASSENGER LIFE VEST 63600-105 L1435346 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 3 PASSENGER LIFE VEST 63600-105 L1435353 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 4 PASSENGER LIFE VEST 63600-105 L1420960 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 5 PASSENGER LIFE VEST 63600-105 L1435348 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 6 PASSENGER LIFE VEST 63600-105 L1435345 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 7 PASSENGER LIFE VEST 63600-105 L1435345 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
25-62-02	NO. 8 PASSENGER LIFE VEST 63600-105 L1435345 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02	PILOT LIFE VEST 63600-105 L1435351 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2011 12.6 13		
+ 25-62-02-001	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST 63600-105 L1345350 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST 63600-105 L1435349 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST 63600-105 L1435346 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST 63600-105 L1435353 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST 63600-105 L1420960 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST 63600-105 L1435348 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST 63600-105 L1435345 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST 63600-105 L1435345 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST 63600-105 L1435345 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST 63600-105 L1435351 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				21-SEP-2011	21-SEP-2021	
<b>OVERHAUL</b>									
25-62-04-001 (s)	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER PKG 81 REF: AMM 25-62-04	MOS HRS/MSC AFL	24	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
25-66-01	LIFE RAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
25-66-01-001	RESTORATION LIFE RAFT (OVERHAUL) PN SN-UNKNOWN REF: AMM 25-66-01	MOS HRS/MSC AFL	N/A						

## CHAPTER 26 FIRE PROTECTION

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-11-01	LEFT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 44176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
26-11-01	RIGHT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 44177 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
26-11-01-001 (s)	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1600	+30/-30			PKG 27-JUN-2017 840.6 558		
26-11-01-001 (s)	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1600	+30/-30			PKG 27-JUN-2017 840.6 558		
26-11-01-002 (s)	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR PKG 1 REF: AMM 26-11-01	MOS HRS/MSC AFL	800	+30/-30			PKG 27-JUN-2017 840.6 558		
26-11-01-002 (s)	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR PKG 1 REF: AMM 26-11-01	MOS HRS/MSC AFL	800	+30/-30			PKG 27-JUN-2017 840.6 558		
26-15-01	MODEL 602 SMOKE DETECTOR 8930-223B60L014 215448 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-MAY-2013 270.6 185		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE 33000073-1 93358A1 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-MAY-2020 1528.2 990		
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL  REF: AMM 26-21-00	MOS HRS/MSC AFL	2400	+30/-30			21-SEP-2011 0 0	2400	2430
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL 441-42702-002 0289 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
26-21-03-001	FUNCTIONAL CHECK ENGINE FIRE EXTINGUISHER BOTTLE OF ENGINE EXTINGUISHING BOTTLE 33000073-1 93358A1 REF: AMM 26-21-03	MOS HRS/MSC AFL	120				05-MAY-2020 1528.2 990	05-MAY-2030	
26-21-05-001 (s)	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) PKG 20 REF: AMM 26-21-05	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
26-21-07	NO. 1 CARTRIDGE 30903962-1 1676YH REF: See Workcard	MOS HRS/MSC AFL	O/C				05-MAY-2020 1528.2 990		
26-21-07	NO. 2 CARTRIDGE 30903963-1 1528YJ REF: See Workcard	MOS HRS/MSC AFL	O/C				05-MAY-2020 1528.2 990		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-07-001	DISCARD NO. 1 CARTRIDGE 30903962-1 1676YH <b>REF:</b> AMM 26-21-07	MOS HRS/MSC AFL	120					29-SEP-2024 M	
<b>LIFE LIMIT</b>									
26-21-07-001	DISCARD NO. 2 CARTRIDGE 30903963-1 1528YJ <b>REF:</b> AMM 26-21-07	MOS HRS/MSC AFL	120				05-MAY-2020 1528.2 990	29-SEP-2024 M	
<b>LIFE LIMIT</b>									
26-21-09-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING PKG 20 <b>REF:</b> AMM 26-21-09	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-500634 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		27-JUN-2017 840.6 558		
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-814366 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-500634 <b>REF:</b> AMM 26-24-01	MOS HRS/MSC AFL	12				05-MAY-2020	05-MAY-2021	
26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-814366 <b>REF:</b> AMM 26-24-01	MOS HRS/MSC AFL	12				05-MAY-2020	05-MAY-2021	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-500634 REF: AMM 26-24-01	MOS HRS/MSC AFL	144					27-JUN-2029 M	
26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-814366 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-APR-2010	01-APR-2022	
26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-500634 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
26-24-01-003	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-814366 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-500634 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 X-814366 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
<b>CHAPTER 27</b>	<b>FLIGHT CONTROLS</b>								
+ 27-001	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1009 0097 REF: See Workcard	MOS HRS/MSC AFL	1800				21-SEP-2011 0 0	1800	
<b>LIFE LIMIT</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-001	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1009 0098	MOS HRS/MSC	1800				21-SEP-2011 0		1800
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-002	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2009 0201	MOS HRS/MSC	1800				21-SEP-2011 0		1800
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-002	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2009 0181	MOS HRS/MSC	1800				21-SEP-2011 0		1800
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-003	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0218	MOS HRS/MSC	1800				21-SEP-2011 0		1800
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-003	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0197	MOS HRS/MSC	1800				21-SEP-2011 0		1800
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
27-004	ROLL TRIM ACTUATOR 470500-1005 0062	MOS HRS/MSC	12000		N:0 N:0		21-SEP-2011 0		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL			N:0		0		
27-005	YAW TRIM ACTUATOR 470600-1005 0051	MOS HRS/MSC	12000		N:0 N:0		21-SEP-2011 0		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL			N:0		0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-006	PITCH TRIM ACTUATOR 467500-1003 0054	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-007	LEFT SPOILER ACTUATOR 456800-1003 0107	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-007	RIGHT SPOILER ACTUATOR 456800-1003 0108	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR SYLC-53058 1362	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-JUL-2014 399.1 267		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-009	RUDDER BOOSTER ACTUATOR 9125-3 0050T	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-01-01	LEFT CONTROL WHEEL 83912139 00460	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-01-01	RIGHT CONTROL WHEEL 83912140 00463	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-01-02	LH PEDAL ASSEMBLY 505-15420-415 0000619784 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-01-02	RH PEDAL ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-01-03-001 (s)	LUBRICATION OF ROTARY BALL SPLINE PKG 81 REF: AMM 12-21-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
27-010	LEFT TOGGLE LINK 456870-1001 0095 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
27-010	RIGHT TOGGLE LINK 456870-1001 0094 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
27-011	STICK PUSHER ACTUATOR 9124-1 0035T LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	35000	R:0 N:31746 R:0 R:0			22-MAR-2012 63.9 40	3317.9	
27-012	POWER DRIVE UNIT 467700-1003 0060 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-013	LEFT FLAP POSITION SENSOR UNIT 457310-1001 0112	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
27-013	RIGHT FLAP POSITION SENSOR UNIT 457310-1001 0117	MOS HRS/MSC AFL	35000	N:0 N:0 N:0			21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 27-014	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0079	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 27-014	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0157	MOS HRS/MSC AFL	35000				21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 27-014	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0159	MOS HRS/MSC AFL	35000				21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 27-014	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0088	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 27-014	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0156	MOS HRS/MSC AFL	35000				21-SEP-2011 0 0	35000	
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-014	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS					21-SEP-2011		
	SSW0158	HRS/MSC	35000				0		35000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-015	DISCARD LEFT CENTER FLAP FLEXIBLE	2 SHAFT							
	457360-1007	MOS					21-SEP-2011		
	SSW0079	HRS/MSC	35000				0		35000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-015	DISCARD LEFT INBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS					21-SEP-2011		
	SSW0157	HRS/MSC	N/A				0		
	<b>REF: See Workcard</b>	AFL					0		
+ 27-015	DISCARD LEFT OUTBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS					21-SEP-2011		
	SSW0159	HRS/MSC	N/A				0		
	<b>REF: See Workcard</b>	AFL					0		
+ 27-015	DISCARD RIGHT CENTER FLAP FLEXIBLE	2 SHAFT							
	457360-1007	MOS					21-SEP-2011		
	SSW0088	HRS/MSC	35000				0		35000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL					0		
+ 27-015	DISCARD RIGHT INBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS					21-SEP-2011		
	SSW0156	HRS/MSC	N/A				0		
	<b>REF: See Workcard</b>	AFL					0		
+ 27-015	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE	1 SHAFT							
	457360-1005	MOS					21-SEP-2011		
	SSW0158	HRS/MSC	N/A				0		
	<b>REF: See Workcard</b>	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-016	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1009 0097 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 27-016	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1009 0098 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 27-017	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2009 0201 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 27-017	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2009 0181 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 27-018	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0218 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 27-018	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0197 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL 462900-1017 0323 REF: See Workcard	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0		27-JUN-2017 840.6 558		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL 462900-1017 0453 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2017 840.6 558		
27-03-01-002 (s)	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
27-03-01-003 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR REF: AMM 27-03-01	MOS HRS/MSC AFL	6000	+30/-30			21-SEP-2011 0 0	6000	6030
<b>AIRWORTHINESS</b>									
27-04-01	TRIM ACTUATOR CONTROLLER 475200-1005 0030 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-JUN-2019 1263.3 836		
27-04-01-001 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
27-04-01-002 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-11-00-001 (s)	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-11-00	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 27-MAY-2016 688.1 478		
27-11-01	LEFT AILERON 505-14683-4003 0000553140 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-11-01	RIGHT AILERON 505-14667-4003 0000628212 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30		24	05-MAY-2020 1528.2 990	<b>29-MAY-2025</b> <b>4728.2</b>	29-JUN-2025 4758.2
27-11-02-002 (s)	DETAILED INSPECTION OF AILERON CONTROL CABLES PKG 42 REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 27-MAY-2016 688.1 478		
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY REF: AMM 27-14-03	MOS HRS/MSC AFL	6000	+30/-30			21-SEP-2011 0 0	<b>6000</b>	6030
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM REF: AMM 27-14-02	MOS HRS/MSC AFL	6000	+30/-30			21-SEP-2011 0 0	<b>6000</b>	6030



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-14-03	LEFT AILERON TAB 505-14679-4003 0000549705 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-21-00-001 (s)	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-21-00	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 27-MAY-2016 688.1 478		
27-21-01	RUDDER ASSEMBLY 505-10500-417 0000634658 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION REF: AMM 27-21-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30	24		05-MAY-2020 1528.2 990	<b>29-MAY-2025</b> <b>4728.2</b>	29-JUN-2025 4758.2
27-21-02-002 (s)	DETAILED INSPECTION OF RUDDER CONTROL CABLES PKG 42 REF: AMM 27-21-02	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 27-MAY-2016 688.1 478		
27-23-00-001 (s)	OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM PKG 10 REF: AMM 27-23-00	MOS HRS/MSC AFL	1600	+30/-30			PKG 14-APR-2019 1206.8 793		
27-24-02-001	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH REF: AMM 27-24-03	MOS HRS/MSC AFL	6000	+30/-30			21-SEP-2011 0 0	<b>6000</b>	6030
<b>AIRWORTHINESS</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-24-02-002	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-24-02</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-24-03	RUDDER TRIM TAB 505-10450-401 0000628209 <b>REF: See Workcard</b>	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-26-01	VENTRAL RUDDER 505-07540-415 0000636054 <b>REF: See Workcard</b>	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-31-00-001 (s)	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 <b>REF: AMM 27-31-00</b>	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30			PKG 27-MAY-2016 688.1 478		
27-31-01	LEFT ELEVATOR 505-39054-4003 0000629759 <b>REF: See Workcard</b>	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-31-01	RIGHT ELEVATOR 505-39054-4004 0000629756 <b>REF: See Workcard</b>	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION  <b>REF: AMM 27-31-02</b>	MOS HRS/MSC AFL	60 3200	+1m/-1m +30/-30		24	05-MAY-2020 1528.2 990	<b>29-MAY-2025</b> <b>4728.2</b>	29-JUN-2025 4758.2



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-02-002 (s)	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES PKG 42 REF: AMM 27-31-02	MOS HRS/MSC AFL	60 3200	+30/-30			PKG 27-MAY-2016 688.1 478		
27-31-03	LEFT ELEVATOR TAB 505-11050-4003 0000629757 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-31-03	LEFT HAND ELEVATOR ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-31-03	RIGHT ELEVATOR TAB 505-11050-4004 0000629754 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
27-31-03-001 (s)	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH PKG 50 REF: AMM 27-31-03	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
27-31-03-002 (s)	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM PKG 50 REF: AMM 27-31-03	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
27-36-03-001 (s)	OPERATIONAL CHECK OF PUSHER CUTOFF SWITCH PKG 10 REF: AMM 27-36-03	MOS HRS/MSC AFL	1600	+30/-30			PKG 27-JUN-2019 1275.4 845		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-41-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-40-00</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-41-01-003 (s)	LUBRICATION OF PITCH TRIM ACTUATOR						PKG		
	PKG 83	MOS	48	+30d/-30d			27-JUN-2017		
	<b>REF: AMM 12-21-00</b>	HRS/MSC AFL					840.6 558		
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-41-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-41-01-005 (s)	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48				27-JUN-2017		
	<b>REF: AMM 12-18-00</b>	HRS/MSC AFL					840.6 558		
27-41-01-006 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP						PKG		
	PKG 50	MOS					21-SEP-2011		
	<b>REF: AMM 27-41-01</b>	HRS/MSC AFL	5600	+30/-30			0 0		
27-43-02	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL								
	PN	MOS			N:0		21-SEP-2011		
	SN-UNKNOWN	HRS/MSC	O/C		N:0		0		
	<b>REF: GENERIC NO REF</b>	AFL			N:0		0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 27-51-00</b>	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
27-51-01-001 (s)	LUBRICATION OF FLAP ACTUATORS BALL SCREWS PKG 83	MOS	48	+30d/-30d			27-JUN-2017		
	<b>REF: AMM 12-21-00</b>	HRS/MSC AFL					840.6 558		
27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-51-01-002	DETAILED VISUAL INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-51-01-002	DETAILED VISUAL INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: AMM 27-51-01</b>	HRS/MSC AFL	6000	+30/-30			0 0	<b>6000</b>	6030
27-51-01-005 (s)	SERVICING OF FLAP ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48				27-JUN-2017		
	<b>REF: AMM 12-18-00</b>	HRS/MSC AFL					840.6 558		
27-51-01-900-801-01	LEFT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
	475100-1009	HRS/MSC	H/T		N:0		0		
	0097	AFL			N:0		0		
	<b>REF: See Workcard</b>				N:0		0		
27-51-01-900-801-02	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
	475100-1009	HRS/MSC	H/T		N:0		0		
	0098	AFL			N:0		0		
	<b>REF: See Workcard</b>				N:0		0		
27-51-01-900-801-03	LEFT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
	475000-2009	HRS/MSC	H/T		N:0		0		
	0201	AFL			N:0		0		
	<b>REF: See Workcard</b>				N:0		0		
27-51-01-900-801-04	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					21-SEP-2011		
	475000-2009	HRS/MSC	H/T		N:0		0		
	0181	AFL			N:0		0		
	<b>REF: See Workcard</b>				N:0		0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-01-900-801-05	LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0218 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-01-900-801-06	RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1009 0197 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-05	LEFT INBOARD FLAP 505-14401-4003 0000629197 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-05	LEFT OUTBOARD FLAP 505-14361-4003 0000629180 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-05	RIGHT INBOARD FLAP 505-14401-4004 0000629194 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-05	RIGHT OUTBOARD FLAP 505-14361-4004 0000629176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-06-001 (s)	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-001 (s)	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-001 (s)	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-001 (s)	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-001 (s)	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-001 (s)	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 27-51-06	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2017 840.6 558		
27-51-06-900-801-01	RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0158 REF: See Workcard	MOS HRS/MSC AFL	H/T		N:0 N:0 N:0		21-SEP-2011 0 0		
27-51-06-900-801-02	RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0156 REF: See Workcard	MOS HRS/MSC AFL	H/T		N:0 N:0 N:0		21-SEP-2011 0 0		
27-51-06-900-801-03	LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0159 REF: See Workcard	MOS HRS/MSC AFL	H/T		N:0 N:0 N:0		21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-900-801-04	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW0157 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-06-900-801-05	LEFT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0079 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			21-SEP-2011 0 0		
27-51-06-900-801-06	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0088 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			21-SEP-2011 0 0		
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER 780501-9 1141 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL  REF: NDT PART 6 27-64-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL  REF: NDT PART 5 27-64-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 7 27-64-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
27-65-00-001 (s)	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM PKG 60	MOS					21-SEP-2011		
	<b>REF: AMM 27-60-00</b>	HRS/MSC	6400	+30/-30			0		
		AFL					0		
27-65-01-001 (s)	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU) PKG 60	MOS					21-SEP-2011		
	<b>REF: AMM 27-65-00</b>	HRS/MSC	6400	+30/-30			0		
		AFL					0		
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR 456896-1001	MOS					21-SEP-2011		
	865987	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR 456896-1001	MOS					21-SEP-2011		
	866004	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR 456897-1001	MOS					21-SEP-2011		
	865963	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR 456897-1001	MOS					21-SEP-2011		
	867265	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 28</b>	<b>FUEL</b>								
28-11-00-001 (s)	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS PKG 80	MOS	12	+30d/-30d			PKG 05-MAY-2020 1528.2 990		
	REF: AMM 28-11-00	HRS/MSC AFL							
28-11-05	LEFT WING WATER DRAIN VALVE L83A13-628	MOS		N:0			21-SEP-2011		
	E54579	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
28-11-05	RIGHT WING WATER DRAIN VALVE L83A13-628	MOS		N:0			08-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			633.3		
	REF: See Workcard	AFL		N:0			448		
28-11-07	LEFT WING DUMP VALVE V98A32-001	MOS		N:0			21-SEP-2011		
	E89214	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
28-11-07	RIGHT WING DUMP VALVE V98A32-001	MOS		N:0			21-SEP-2011		
	E51553	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
28-12-01-001 (s)	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA PKG 1	MOS	800	+30/-30			PKG 05-MAY-2020 1528.2 990		
	REF: AMM 28-12-01	HRS/MSC AFL							
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE L87-19-001P2	MOS		N:0			21-SEP-2011		
	E54266	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE L87-19-001P2 E54259 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK LEFT FLOAT VENT VALVE PKG 60 REF: AMM 28-12-03	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK RIGHT FLOAT VENT VALVE PKG 60 REF: AMM 28-12-03	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
28-21-01	LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-01	RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-02	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 E61510 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-02	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 E61515 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-03	LEFT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 E70002 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-03	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 E70004 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-05	LEFT WING JET PUMP FEED LINE T99A19-602 E62404 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-05	RIGHT WING JET PUMP FEED LINE T99A19-602 E62403 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-07	LEFT 0.75 SHUTOFF VALVE B97-15-601 E54633 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-07	RIGHT 0.75 SHUTOFF VALVE B97-15-601 E51416 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM  REF: AMM 28-21-07	MOS HRS/MSC AFL	600	+30/-30		26.5	14-APR-2019 1206.8 793	1833.3	1863.3
<b>AIRWORTHINESS</b>									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM	MOS					14-APR-2019		
<b>AIRWORTHINESS</b>	<b>REF: AMM 28-21-07</b>	HRS/MSC AFL	600	+30/-30		26.5	1206.8 793	<b>1833.3</b>	1863.3
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR	MOS					21-SEP-2011		
	D97C00-644P2	HRS/MSC	O/C	N:0			0		
	C70835	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0			0		
28-21-08	LEFT WING 28 VDC SOV ACTUATOR	MOS					21-SEP-2011		
	D97C00-644P2	HRS/MSC	O/C	N:0			0		
	C70840	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0			0		
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR	MOS					21-SEP-2011		
	D97C00-644P2	HRS/MSC	O/C	N:0			0		
	C70837	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0			0		
28-21-09	LEFT WING SCAVENGER JET PUMP	MOS					21-SEP-2011		
	T99A19-603	HRS/MSC	O/C	N:0			0		
	E61767	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0			0		
28-21-09	RIGHT WING SCAVENGER JET PUMP	MOS					21-SEP-2011		
	T99A19-603	HRS/MSC	O/C	N:0			0		
	E61769	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0			0		
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE	MOS					21-SEP-2011		
	B97H19-608P2	HRS/MSC	O/C	N:0			0		
	E62665	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-10-001	OPERATIONAL CHECK OF FUEL XFEED VALVE  REF: AMM 28-21-10	MOS HRS/MSC AFL	12000	+30/-30			21-SEP-2011 0 0	12000	12030
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE  L96-13-001 E58098 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE  L96-13-001 E58105 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
28-21-13	INSC ILLUM PANEL  441-42621-002 1039 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
28-23-01	REFUEL CONTROL PANEL  742388-1-2 742388IN00104 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE  L94E31-653P2 E67166 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE  L94E31-653P2 E67167 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-23-04-001 (s)	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER PKG 40 REF: AMM 28-23-05	MOS HRS/MSC AFL	3200	+30/-30			PKG 29-MAY-2015 633.3 448		
28-23-07	LEFT HIGH LEVEL SENSOR 722860-2-0 0183 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-23-07	RIGHT HIGH LEVEL SENSOR 722860-2-0 2208 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-JUL-2018 1036 668		
28-23-09	FUEL PORT AND CAP K97-63-613 E58214 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-01	NO. 1 LEFT PROBE 765896-1-0 765896IN00159 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-01	NO. 1 RIGHT PROBE 765896-1-0 765896IN00207 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-01	NO. 2 LEFT PROBE 765873-1-0 765873IN00167 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01	NO. 2 RIGHT PROBE 765873-1-0 765873IN00176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-01	NO. 3 LEFT PROBE 765874-1-0 765874IN00181 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-01	NO. 3 RIGHT PROBE 765874-1-0 765874IN01302 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-JUN-2019 1263.3 836		
28-41-01	NO. 4 LEFT PROBE 765875-1-0 765875IN00177 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-01	NO. 4 RIGHT PROBE 765875-1-0 765875IN00175 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT 738742-1-3 738790IN00371 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-43-01	TEMPERATURE SENSOR 798840-1-0 02238 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-43-01-001 (s)	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR PKG 60 REF: AMM 28-43-01	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
28-45-01	LEFT PRESSURE SWITCH D98C07-611 0514 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
28-45-01	RIGHT PRESSURE SWITCH D98C07-611 0526 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>CHAPTER 29 HYDRAULIC POWER</b>									
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR 3032763-003 MX765704 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-MAY-2013 270.6 185		
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX741787 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX744480 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
29-12-02-001 (s)	VISUAL CHECK OF MANIFOLD/ RESERVOIR PKG 80 REF: AMM 29-12-02	MOS HRS/MSC AFL	12	+30d/-30d			PKG 05-MAY-2020 1528.2 990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-02-002 (s)	OPERATIONAL CHECK LEFT EDP CHECK VALVE PKG 50 REF: AMM 29-10-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 27-JUN-2019 1275.4 845		
29-12-02-002 (s)	OPERATIONAL CHECK RIGHT EDP CHECK VALVE PKG 50 REF: AMM 29-10-00	MOS HRS/MSC AFL	5600	+30/-30			PKG 27-JUN-2019 1275.4 845		
29-15-03	CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR 0860231003 60231-2313 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
29-15-03-001 (s)	SERVICING CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR 0860231003 PKG 80 60231-2313 REF: AMM 12-13-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 05-MAY-2020 1528.2 990		
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE 3032428-001 AA225141 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE 3032428-001 AA226481 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
29-15-04-001	OPERATIONAL CHECK LEFT ENGINE HYDRAULIC SHUT-OFF VALVE REF: AMM 29-15-04	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30		-29	27-JUN-2019 1275.4 845	29-MAY-2023 4275.4	28-JUN-2023 4305.4
<b>AIRWORTHINESS</b>									



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-15-04-001	OPERATIONAL CHECK RIGHT ENGINE HYDRAULIC SHUT-OFF VALVE	MOS	48	+30d/-30d		-29	27-JUN-2019	29-MAY-2023	28-JUN-2023
<b>AIRWORTHINESS</b>	<b>REF: AMM 29-15-04</b>	HRS/MSC AFL	3000	+30/-30			1275.4 845	4275.4	4305.4
29-15-05	PRIORITY VALVE 2217-0001-401 00041 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
29-31-02-001 (s)	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE PKG 50 REF: AMM 29-31-02	MOS HRS/MSC AFL	5600	+30/-30			27-JUN-2019 1275.4 845		PKG
<b>CHAPTER 30 ICE AND RAIN PROTECTION</b>									
30-01-01	MD INSC ILLUM PANEL 441-43234-002 1002 REF: See Workcard	MOS HRS/MSC AFL	O/C		R:0 R:0 R:0		18-NOV-2011 28.1 19		
30-12-00-001 (s)	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM PKG 60 REF: AMM 30-10-00	MOS HRS/MSC AFL	6400	+30/-30			21-SEP-2011 0 0		PKG
30-12-01-001 (s)	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS PKG 60 REF: AMM 30-12-01	MOS HRS/MSC AFL	6400	+30/-30			21-SEP-2011 0 0		PKG



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-3 0055 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-4 0055 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7612-4-539 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-05	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7612-4-563 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7612-4-541 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7612-4-546 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-05	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7612-4-564 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 7612-4-64 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 60 REF: AMM 30-12-05	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0000073 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0000069 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 7717-4-123 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 7623-3-193 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
30-21-02-001	FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER  REF: AMM 30-21-02	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0	12000	
30-21-02-001	FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER  REF: AMM 30-21-02	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0	12000	
30-21-03-001 (s)	BORESCOPE INSPECTION OF PICCOLO TUBE PKG 50 REF: AMM 30-21-03	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
30-21-04-001 (s)	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS PKG 20 REF: AMM 30-21-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
30-31-00-002	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING PKG 81 REF: AMM 30-30-00	MOS HRS/MSC AFL	24	+30d/-30d		-29	27-JUN-2019 1275.4 845	29-MAY-2021	28-JUN-2021



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-41-01-002 (s)	DISCARD OF WINDSHIELD RAIN REPELLENT COATING PKG 80 REF: AMM 30-41-01	MOS HRS/MSC AFL	12				PKG 05-MAY-2020 1528.2 990		
30-41-01-003 (s)	FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE PKG 80 REF: AMM 30-41-01	MOS HRS/MSC AFL	12				PKG 21-SEP-2011 0 0		
30-42-00-001 (s)	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		
30-42-01	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-4 02447 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		29-MAY-2015 633.3 448		
30-42-01	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-4 02445 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		29-MAY-2015 633.3 448		
30-81-02	LEFT NOSE ICE DETECTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
<b>CHAPTER 31 INDICATING/RECORDING SYSTEMS</b>									
31-30-02	CVDR ACCELEROMETER 3001-01-111 0510-16492 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-30-03	REAR CVDR IMPACT SWITCH 5930-4-000 4838 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-31-00-002	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) PKG 80 REF: AMM 31-31-00	MOS HRS/MSC AFL	12	+30d/-30d			05-MAY-2020 1528.2 990	05-MAY-2021	04-JUN-2021
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER 2100-3083-50 000700014 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-31-03	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON DK120 AT65045 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2017 840.6 558		
31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DK120 AT65045 REF: AMM 31-31-03 DISCARD	MOS HRS/MSC AFL	DUE				27-JUN-2017 840.6 558	31-MAY-2024 M	
31-31-09	CVDR CONTROL PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-33-01	FDR - FLIGHT DATA RECORDER PN NOT INSTALLED SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-33-03	FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON PN NOT INSTALLED SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-33-03-001	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED) PN NOT INSTALLED SN-UNKNOWN REF: AMM 31-33-03	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
31-33-04	FORWARD CVDR IMPACT SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A				29-MAY-2015 633.3 448		
31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A				29-MAY-2015 633.3 448		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-40-01	LH DCU UNIT 011-01457-00 16905286 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-40-01	RH DCU UNIT 011-01457-00 16905277 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-01 15W013779 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-01 15W012225 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL 441-42627-001 1036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-42-00-001 (s)	OPERATIONAL CHECK OF HSDB SWITCH REVERSION PKG 60 REF: AMM 31-42-00	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
31-50-01	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46712036 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46712029 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46712038 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-61-00	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) MFD AMLCD DISPLAY 011-01440-10 18T005654 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3200	+30/-30			21-SEP-2011 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3200	+30/-30			21-SEP-2011 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3200	+30/-30			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-01	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 18T005588 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-61-01	NO. 2 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01440-10 18T005597 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-61-05	TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-61-06	NO. 1 BARO INSC ILLUMINATED PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
31-61-06	NO. 2 BARO INSC ILLUMINATED PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>CHAPTER 32 LANDING GEAR</b>									
32-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF MAIN LANDING GEAR POLYURETHANE FILMS PKG 1 REF: AMM 32-00-20	MOS HRS/MSC AFL	800				PKG 14-APR-2019 1206.8 793		
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING 2317-1201-503 1310262/001 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			21-SEP-2011 0 0		16800

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING 2317-1201-504 1312174/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-003	LEFT PINTLE PIN 2317-1101-003 1337689/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-003	RIGHT PINTLE PIN 2317-1101-003 1337689/005	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-004	LEFT PINTLE PIN 2317-1102-001 1347559/006	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-004	RIGHT PINTLE PIN 2317-1102-001 1347559/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 1330320/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 1330320/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1339800/002	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	15300	N:0			0	<b>15300</b>	
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1339800/007	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	15300	N:0			0	<b>15300</b>	
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 1337688/002	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 1337688/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 1333587/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 1333587/004	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-10-00	LEFT MAIN LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2011 0		
	<b>REF: AMM 32-11-00</b>	AFL		N:0			0		



## Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00	RIGHT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-405 00039 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-406 00038 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-405 00042 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-406 00043 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1346864/001 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL		N:0 N:0 N:0				21-SEP-2011 0 0	15300
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1346864/002 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL		N:0 N:0 N:0				21-SEP-2011 0 0	15300



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1316236/005	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1316236/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1339763/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1342740/005	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-104	LEFT MAIN LANDING GEAR TRAILING ARM 2317-1501-001 1350600/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM 2317-1501-002 1337190/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 1334307/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



## Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 11334307/005	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	16800	N:0			0	<b>16800</b>	
32-11-00-001 (s)	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR PKG 80	MOS HRS/MSC	12	+30d/-30d			PKG 05-MAY-2020 1528.2		
	<b>REF:</b> AMM 32-11-00	AFL					990		
32-11-00-003	LUBRICATION OF MAIN LANDING GEAR	MOS HRS/MSC	12	+30d/-30d			05-MAY-2020 1528.2	<b>05-MAY-2021</b>	04-JUN-2021
	<b>REF:</b> AMM 12-21-00	AFL	650				990	<b>1640</b>	
32-11-01-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)	MOS HRS/MSC	120	+1m/-1m			(EBT)	<b>21-SEP-2021</b>	21-OCT-2021
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	AFL	12000	+30/-30				<b>12000</b>	12030
32-11-01-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)	MOS HRS/MSC	120	+1m/-1m			(EBT)	<b>21-SEP-2021</b>	21-OCT-2021
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	AFL	12000	+30/-30				<b>12000</b>	12030
32-11-02-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH)	MOS HRS/MSC	120				(EBT)	<b>21-SEP-2021</b>	
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	AFL	12000					<b>12000</b>	
32-11-02-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH)	MOS HRS/MSC	120				(EBT)	<b>21-SEP-2021</b>	
<b>OVERHAUL</b>	<b>REF:</b> GENERIC NO REF	AFL	12000					<b>12000</b>	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-02-900-801-05	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 1341464/001 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			(EBT)		
32-11-02-900-801-06	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1562835/012 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			12-AUG-2015 633.3 448		
32-11-02-900-801-07	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1334280/001 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			(EBT)		
32-11-02-900-801-08	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1334280/004 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			(EBT)		
32-11-02-900-801-13	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1331853/009 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			(EBT)		
32-11-02-900-801-14	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1331853/003 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			(EBT)		
32-11-02-900-801-15	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1551229/001 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			12-AUG-2015 633.3 448		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-02-900-801-16	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 1344474/005 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			(EBT)		
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000				(EBT)	21-SEP-2021	12000
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000				(EBT)	21-SEP-2021	12000
32-11-03-004	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER  REF: AMM 12-14-02	MOS HRS/MSC AFL	12 650	+30d/-30d			05-MAY-2020 1528.2 990	05-MAY-2021	04-JUN-2021 1640
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			(EBT)	21-SEP-2021	21-OCT-2021 12030
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			(EBT)	21-SEP-2021	21-OCT-2021 12030
32-20-01	NOSE LANDING GEAR PN SN-UNKNOWN REF: AMM 32-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00091 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00090 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 1338500/001 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			21-SEP-2011 0 0	16800	
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 1339733/002 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			21-SEP-2011 0 0	16800	
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 1339734/001 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			21-SEP-2011 0 0	16800	
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 1339734/002 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			21-SEP-2011 0 0	16800	
32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 1349271/004 REF: See Workcard	MOS HRS/MSC AFL	16800	N:0 N:0 N:0			21-SEP-2011 0 0	16800	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 1349271/002	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 1332397/007	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 1349271/002	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	16800	N:0			0	<b>16800</b>	
32-21-00-001 (s)	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR PKG 80	MOS HRS/MSC	12	+30d/-30d			PKG 05-MAY-2020 1528.2		
	<b>REF: AMM 32-21-00</b>	AFL					990		
32-21-00-003	LUBRICATION OF NOSE LANDING GEAR	MOS HRS/MSC	12	+30d/-30d			05-MAY-2020 1528.2	<b>05-MAY-2021</b>	04-JUN-2021
	<b>REF: AMM 12-21-00</b>	AFL	650				990	<b>1640</b>	
32-21-01-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY	MOS HRS/MSC	120	+1m/-1m			(EBT)	<b>21-SEP-2021</b>	21-OCT-2021
<b>OVERHAUL</b>	<b>REF: GENERIC NO REF</b>	AFL	12000	+30/-30				<b>12000</b>	12030
32-21-02	NLG RETRACTION ACTUATOR 2117-1000-401 00045	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2011 0		
	<b>REF: See Workcard</b>	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



## Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-03	NLG DOWNLOCK ACTUATOR 2117-2000-401 00045 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-21-04-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			(EBT)  12000	21-SEP-2021  12000	21-OCT-2021  12030
32-21-05-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000	+1m/-1m +30/-30			(EBT)  12000	21-SEP-2021  12000	21-OCT-2021  12030
32-21-05-004	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER  REF: AMM 12-14-03	MOS HRS/MSC AFL	12 650	+30d/-30d			05-MAY-2020 1528.2 990	05-MAY-2021  1640	04-JUN-2021
32-21-06-005 (s)	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER PKG 80 REF: AMM 32-21-06	MOS HRS/MSC AFL	12	+30d/-30d			PKG 05-MAY-2020 1528.2 990		
32-21-09-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY  REF: GENERIC NO REF	MOS HRS/MSC AFL	120 12000				(EBT)  12000	21-SEP-2021  12000	
32-23-03	NLG DOOR - TORQUE TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR 2117-3000-601 00090 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-AUG-2015 633.3 448		
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR 2117-3001-409 00649 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-AUG-2015 633.3 448		
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3031-001 1338799/001 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)	12000	
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3030-403 1365658/001 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)	12000	
+ 32-302	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1562835/012 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 32-302	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 1341464/001 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0	12000	
+ 32-303	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1334280/001 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0	12000	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-303	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1334280/004	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 64307/0008	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 64307/0009	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 1343122/001	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 1343122/002	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 32-306	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1331853/003	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								
+ 32-306	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1331853/009	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0		12000
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-307	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1551229/001 REF: See Workcard	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
+ 32-307	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 1344474/005 REF: See Workcard	MOS HRS/MSC AFL	12000				21-SEP-2011 0 0	12000	
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1334266/005 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)	12000	
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1334266/002 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)	12000	
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1354862/008 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)	12000	
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1354862/007 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)	12000	
32-31-01	LANDING GEAR CONTROL LEVER 827101-7 1040 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE 7342-1 0054T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-31-05	LH MLG UPLOCK BOX ASSY 2617-1000-401 00032 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-31-05	NLG UPLOCK BOX ASSY 2617-1000-401 00082 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-31-05	RH MLG UPLOCK BOX ASSY 2617-1000-402 00037 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			21-SEP-2011 0 0		12000
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1350333/004 REF: See Workcard	MOS HRS/MSC AFL	12000	N:0 N:0 N:0			(EBT)		12000
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA2 00081 REF: See Workcard	MOS HRS/MSC AFL	10500	N:0 N:0 N:0			(EBT)		10500



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA2 00089	MOS HRS/MSC		N:0 N:0					
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	10500	N:0			(EBT)	<b>10500</b>	
+ 32-312	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1334280/001	MOS HRS/MSC	N/A				21-SEP-2011 0		
	<b>REF:</b> See Workcard	AFL					0		
+ 32-312	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3010-001 1334280/004	MOS HRS/MSC	N/A				21-SEP-2011 0		
	<b>REF:</b> See Workcard	AFL					0		
32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT 2117-3029-001 00262	MOS HRS/MSC		N:0 N:0			12-AUG-2015 633.3		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	28000	N:0			448	<b>28448</b>	
+ 32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	AFL	28000	N:0			0	<b>28000</b>	
+ 32-314	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1331853/003	MOS HRS/MSC	N/A				21-SEP-2011 0		
	<b>REF:</b> See Workcard	AFL					0		
+ 32-314	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-001 1331853/009	MOS HRS/MSC	N/A				21-SEP-2011 0		
	<b>REF:</b> See Workcard	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-315	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1551229/001	MOS HRS/MSC					12-AUG-2015 633.3		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	12000				448	<b>12448</b>	
+ 32-315	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-001 1344474/005	MOS HRS/MSC	N/A				21-SEP-2011 0		
	<b>REF: See Workcard</b>	AFL					0		
+ 32-316	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1562835/012	MOS HRS/MSC					12-AUG-2015 633.3		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	12000				448	<b>12448</b>	
+ 32-316	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-001 1341464/001	MOS HRS/MSC	N/A				21-SEP-2011 0		
	<b>REF: See Workcard</b>	AFL					0		
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM  <b>REF: AMM 32-35-00</b>	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30		-29	27-JUN-2019 1275.4 845	<b>29-MAY-2021</b> <b>2475.4</b>	28-JUN-2021 2505.4
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES  <b>REF: AMM 32-35-00</b>	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30		-29	27-JUN-2019 1275.4 845	<b>29-MAY-2021</b> <b>2475.4</b>	28-JUN-2021 2505.4
32-35-02	CENTER FUSELAGE FREE FALL VALVE 7343-2 0051T <b>REF: See Workcard</b>	MOS HRS/MSC AFL	O/C				21-SEP-2011 0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-400	NOSE LANDING GEAR SHOCK STRUT 2317-5100-403 00044 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT 2310-1144-005 1343504/008 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT 2310-1173-001 1337006/003 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN 2317-5105-001 1338505/005 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	
32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN 2317-5105-001 1338505/009 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING 2317-5301-503 1338801/001 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER 2117-4000-403 00046 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE 2317-5101-001 1216129/012	MOS HRS/MSC		N:0 N:0			22-APR-2014 397.5		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			265	<b>11465</b>	
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 1338506/009	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 1338506/004	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN 2317-6003-001 1339757/003	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE 2310-1165-001 1340423/006	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-41-00	BRAKE CONTROL UNIT DAP00100-11 173120034	MOS HRS/MSC	O/C				27-JUN-2019 1275.4		
	<b>REF: See Workcard</b>	AFL					845		
32-41-00-001 (s)	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM PKG 50	MOS HRS/MSC	5600	+30/-30			29-MAY-2015 633.3		
	<b>REF: AMM 32-41-00</b>	AFL					448		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-01	BRAKE CONTROL UNIT TRAY DAP00134-01 0053 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-41-02	LH BRAKE PEDAL TRANSDUCER Q3008 859939 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-41-02	RH BRAKE PEDAL TRANSDUCER Q3008 859949 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
32-41-02-001 (s)	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 60 REF: AMM 32-41-02	MOS HRS/MSC AFL	6400	+30/-30				PKG 21-SEP-2011 0 0	
32-41-02-001 (s)	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 60 REF: AMM 32-41-02	MOS HRS/MSC AFL	6400	+30/-30				PKG 21-SEP-2011 0 0	
32-41-02-002 (s)	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 10 REF: AMM 32-41-02	MOS HRS/MSC AFL	1600	+30/-30				PKG 05-MAY-2020 1528.2 990	
32-41-02-002 (s)	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 10 REF: AMM 32-41-02	MOS HRS/MSC AFL	1600	+30/-30				PKG 05-MAY-2020 1528.2 990	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-06	LH MLG WHEEL SPEED TRANSDUCER DAP00103-01 141JM REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-41-06	RH MLG WHEEL SPEED TRANSDUCER DAP00103-01 140JM REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-41-07	BRAKE CONTROL MODULE DAP00101-02 2JV REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN 57675-1 00266 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0		<b>11200</b>
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT 2310-1183-001 1340426/002 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0		<b>11200</b>
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK 2317-5191-001 1339755/005 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0		<b>11200</b>
32-43-00-001 (s)	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM PKG 50 REF: AMM 32-43-00	MOS HRS/MSC AFL	5600	+30/-30			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-43-01-001 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM PKG 50 REF: AMM 32-43-00	MOS HRS/MSC AFL	5600 +30/-30				PKG 21-SEP-2011 0 0		
32-43-02	PRESSURE SWITCH DAP00108-01 70JK REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR DAP00106-01 036 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-43-05	EMERGENCY/PARKING BRAKE VALVE DAP00107-01 91KL REF: AMM 32-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-AUG-2014 401.4 270		
32-43-06	PRESSURE TRANSDUCER DAP00109-01 7653-2-199 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-43-08	THERMAL RELIEF VALVE DAP00110-01 031 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE DAP00202-01 035 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE 2216-0001-401 00256 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE  REF: AMM 32-43-11	MOS HRS/MSC AFL	600	+30/-30		26.5	14-APR-2019 1206.8 793	1833.3	1863.3
<b>AIRWORTHINESS</b>									
32-45-00	LH MAIN WHEEL AND TIRE ASSY 505-19517-603 5027MA REF: See Workcard	MOS HRS/MSC AFL	O/C				16-OCT-2019 1389.9 923		
32-45-00	NOSE WHEEL AND TIRE ASSY 505-19601-601 5091JS REF: See Workcard	MOS HRS/MSC AFL	O/C	O:47 R:1 O:573.5 R:0 O:345 R:0			14-APR-2019 1206.8 793		
32-45-00	RH MAIN WHEEL AND TIRE ASSY 505-19517-611 5132MS REF: See Workcard	MOS HRS/MSC AFL	O/C				16-OCT-2019 1389.9 923		
32-45-01	LEFT MAIN WHEEL DAP00098-02 5042JN REF: See Workcard	MOS HRS/MSC AFL	O/C				16-OCT-2019 1389.9 923		
32-45-01	RIGHT MAIN WHEEL DAP00098-02 5132MS REF: See Workcard	MOS HRS/MSC AFL	O/C				16-OCT-2019 1389.9 923		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5042JN REF: AMM 32-45-00	MOS HRS/MSC AFL	1500				21-SEP-2011 0 0	1500	
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5132MS REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500				18-APR-2018 998.6 650	2150	
32-45-02	LEFT MAIN WHEEL TIRE 258K63-2 01810312 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-SEP-2020 1676.7 1083		
32-45-02	RIGHT MAIN WHEEL TIRE 258K63-2 01810317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-SEP-2020 1676.7 1083		
32-45-03	LH MLG HUB CAP DAP00131-02 31JL REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-45-03	RH MLG HUB CAP DAP00131-02 32JL REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-45-11	NOSE WHEEL DAP00099-02 5091JS REF: See Workcard	MOS HRS/MSC AFL	O/C	O:47 R:1 O:573.5 R:0 O:345 R:0			14-APR-2019 1206.8 793		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY DAP00099-02 5091JS REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500	I:47 I:573.5 I:345			14-APR-2019 1206.8 793	1948	
32-45-12	NOSE TIRE 156K23B1 80322452 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-APR-2019 1206.8 793		
32-45-21	LH MLG CARBON BRAKE ASSY DAP00097-04 5149RC REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			28-AUG-2019 1356.2 893		
32-45-21	RH MLG CARBON BRAKE ASSY DAP00097-04 5139NP REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			28-AUG-2019 1356.2 893		
32-500	NOSE LANDING GEAR SHOCK ABSORBER 2317-5170-403 00048 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK 2317-5221-001 1334875/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING 2317-5113-005 1334290/004 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0	11200	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER 2317-5231-503 1332456/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	AFL	11200	N:0			0	<b>11200</b>	
32-600	NOSE LANDING GEAR DRAG BRACE 2317-6000-403 00398	MOS HRS/MSC	O/C	N:0 N:0			27-JUN-2017 840.6		
	<b>REF: See Workcard</b>	AFL		N:0			558		
32-601	NOSE LANDING GEAR UPPER DRAG BRACE 2317-6101-501 1339781/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-602	NOSE LANDING GEAR LOWER DRAG BRACE 2317-6201-001 1335694/010	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 1330278/005	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 1330278/001	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
32-604	NOSE LANDING GEAR DRAG BRACE PIN 2317-6003-001 1339757/007	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	LH WING PROXIMITY SWITCH 80-057-01 25249 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH 80-057-01 25223 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 1 NLG PROXIMITY SWITCH 80-057-01 25210 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH 80-057-01 25225 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH 80-057-01 25224 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 2 NLG PROXIMITY SWITCH 80-057-01 25226 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH 80-057-01 25250 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH 80-057-01 25247 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH 80-057-01 25252 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-61-01	RH WING PROXIMITY SWITCH 80-057-01 25246 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-700	NOSE LANDING GEAR LOCKING STAY 2317-6500-403 00044 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
32-701	NOSE LANDING GEAR UPPER LOCKING STAY 2317-6521-003 1328040/010 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0		11200
32-702	NOSE LANDING GEAR LOWER LOCKING STAY 2317-6531-001 1335870/009 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0		11200
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1341028/001 REF: See Workcard	MOS HRS/MSC AFL	11200	N:0 N:0 N:0			21-SEP-2011 0 0		11200

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1341028/002	MOS HRS/MSC		N:0 N:0			21-SEP-2011 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	AFL	11200	N:0			0	<b>11200</b>	
<b>CHAPTER 33 LIGHTS</b>									
33-01-01	OVERHEAD LIGHTS CONTROL PANEL 441-43246-002 1177	MOS HRS/MSC	O/C	R:5 R:0			05-DEC-2019 1444		
	<b>REF: See Workcard</b>	AFL		R:0			948		
33-12-01	COCKPIT DIMMER 81-01760-002 0319	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2011 0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
33-12-02	INSC ILLUM - TEST PANEL 441-42631-002 1070	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2011 0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
33-13-01	LH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY PN	MOS		N:0			21-SEP-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
33-13-01	RH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY PN	MOS		N:0			21-SEP-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-31-02	NOSE (WITH/WITHOUT FDR) W001,ELECTRICAL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-42-01	LH LWR FWD TAXI LIGHT ASSY 81017-3 000077 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-42-01	RH LWR FWD TAXI LIGHT ASSY 81017-4 000017 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-47-01	LEFT LANDING LIGHT ASSY 81017-5 000052 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-47-01	RIGHT LANDING LIGHT ASSY 81017-6 000050 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-48-00	LEFT NO. 1 NAVIGATION LIGHT 84004-7 000089 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-48-00	LEFT NO. 2 NAVIGATION LIGHT 84015-1 000049 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			13-FEB-2015 569.3 386		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000090 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT 84015-2 000042 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-JAN-2016 650 453		
33-48-00-001	DISCARD LEFT NO. 1 NAVIGATION LIGHT 84004-7 000089 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			21-SEP-2011 0 0	12000	12030
33-48-00-001	DISCARD LEFT NO. 2 NAVIGATION LIGHT 84015-1 000049 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			21-SEP-2011 0 0	12000	12030
33-48-00-001	DISCARD RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000090 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			21-SEP-2011 0 0	12000	12030
33-48-00-001	DISCARD RIGHT NO. 2 NAVIGATION LIGHT 84015-2 000042 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			21-SEP-2011 0 0	12000	12030
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
33-49-00	NO. 1 STROBE LIGHT 84036-3 000067 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
33-49-00	NO. 2 STROBE LIGHT 84036-4 000060 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
33-49-00-001	DISCARD NO. 1 STROBE LIGHT 84036-3 000067 REF: AMM 33-49-00	MOS HRS/MSC AFL	8000				21-SEP-2011 0 0	8000	
33-49-00-001	DISCARD NO. 2 STROBE LIGHT 84036-4 000060 REF: AMM 33-49-00	MOS HRS/MSC AFL	8000				21-SEP-2011 0 0	8000	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
33-52-01	LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001500 REF: See Workcard	MOS HRS/MSC AFL	O/C		R:1 R:0 R:0		18-FEB-2019 1163.7 762		
33-52-01	RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 001303 REF: See Workcard	MOS HRS/MSC AFL	O/C		R:1 R:0 R:0		18-FEB-2019 1163.7 762		
33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001500 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d		-76	05-MAY-2020 1528.2 990	18-FEB-2021	20-MAR-2021
33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001303 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d		-76	05-MAY-2020 1528.2 990	18-FEB-2021	20-MAR-2021
33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001500 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001303 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001500 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 001303 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-05	SELF-ILLUMINATED UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
33-52-17-001	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED)  REF: AMM 33-52-17	MOS HRS/MSC AFL	N/A				27-JUN-2017 840.6 558		
<b>CHAPTER 34</b>	<b>NAVIGATION</b>								
34-00-01	ACSS TRANSPONDER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-00-02	TRANSPONDER RF RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-00-03	NO.1 IASP SMART PROBE 2015L-4B 0305 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2019 1275.4 845		
34-00-03	NO.2 IASP SMART PROBE 2015L-4B 0764 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2019 1275.4 845		
34-00-04	SD CARD DATABASE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-10-01	RADIO ALTIMETER 066-01153-0101 KRA405B-11521 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-AUG-2013 308.4 226		
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA S67-2002-45 553-3527 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA S67-2002-45 553-3545 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT C16221APA01 C16221019252 REF: See Workcard	MOS HRS/MSC AFL	O/C				29-MAY-2015 633.3 448		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-001	FUNCTIONAL CHECK IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001)  C16221APA01 C16221019252 REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+30d/-30d		-30	27-JUN-2019 1275.4 845	28-MAY-2021	27-JUN-2021
34-11-02	PITOT/STATIC PROBE  0856UT4 263569 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:93 N:1275.4 N:845			27-JUN-2019 1275.4 845		
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001)  0856UT4 263569 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+30d/-30d			27-JUN-2019 1275.4 845	27-JUN-2021	27-JUL-2021
34-15-00-001 (s)	FUNCTIONAL CHECK OF AIR DATA SYSTEM  PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+30d/-30d			27-JUN-2019 1275.4 845		
34-15-00-002	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS  REF: AMM 34-15-00	MOS HRS/MSC AFL	60	+30d/-30d			27-JUN-2019 1275.4 845	27-JUN-2024	27-JUL-2024
34-15-00-003	DETAILED INSPECTION OF IASP  PKG 81 REF: AMM 34-15-07	MOS HRS/MSC AFL	24	+30d/-30d		-29	27-JUN-2019 1275.4 845	29-MAY-2021	28-JUN-2021



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42014988 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42014903 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-20-02	LEFT MAGNETOMETER 011-00870-00 47516607 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-20-02	RIGHT MAGNETOMETER 011-00870-00 47516600 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-23-00	MAGNETIC COMPASS KCA0120W BE2670310 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-23-00-001	FUNCTIONAL CHECK MAGNETIC COMPASS OF STANDBY COMPASS KCA0120W BE2670310 REF: AMM 34-23-00	MOS HRS/MSC AFL	24	+30d/-30d		-30	27-JUN-2019 1275.4 845	28-MAY-2021	27-JUN-2021
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA S65-247170 173-2500 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE S65-247170 173-2502 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-40-01	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER 011-00987-00 47763281 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 18735 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JUN-2019 1275.4 845		
34-40-02	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 8198 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA 011-00883-20 47203363 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-40-04	TCAS II UNIT 9003500-55904 TSE00637 REF: See Workcard	MOS HRS/MSC AFL	O/C				12-AUG-2015 633.3 448		
34-40-05	TCAS II TOP ANTENNA 7514060-902 ANE34781 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-43-02	LOWER TCAS L BAND ANTENNA S65-5366-10L 258-1927 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-NOV-2011 26.7 18		
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA S65-5366-7L 261-86839 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-02	TOP XPDR L BAND ANTENNA S65-5366-7L 261-86833 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-03	KN 63 DISTANCE MEASURING UNIT 066-01070-0001 34053 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-05	PHASING COUPLER SSPD-113-10 6525 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-06	MARKER BEACON ANTENNA S35-1000-2 102-8670 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-07	MARKER BEACON ANTENNA SPLITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-08	VOR/LOC/GS ANTENNA SPLITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-09	VOR/LOC/GS ANTENNA RF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-50-10	GSR 56 IRIDIUM UNIT 010-00815-00 1NZ005098 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-NOV-2011 26.7 18		
34-50-11	IRIDIUM SATCOM ANTENNA S67-1575-109 449-3570 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-NOV-2011 26.7 18		
34-50-12	GDL 59 DATALINK MANAGEMENT UNIT 010-00666-00 1EJ005127 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-NOV-2011 26.7 18		
34-50-13	WI-FI - DATALINK ANTENNA S65-5366-71S 258-1927 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-NOV-2011 26.7 18		
34-50-14	ADF ANTENNA 622-7383-001 3PHMB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-15	ADF UNIT 622-7382-101 3P9RW REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-51-02	NO. 1 DME L BAND ANTENNA S65-5366-7L 261-87034 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-52-00	NO. 1 TRANSPONDER 9006000-55000 NXE07256 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-APR-2019 1206.8 793		
34-52-00	NO. 2 TRANSPONDER 9006000-55000 NXE08190 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-APR-2019 1206.8 793		
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM 9006000-55000 NXE07256 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				10-APR-2019	<b>10-APR-2021</b>	
34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM 9006000-55000 NXE08190 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				10-APR-2019	<b>10-APR-2021</b>	
34-52-04	LOWER COAXIAL UNIT D2-729B005 563303 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-52-04	UPPER COAXIAL UNIT D2-729B005 562771 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-53-01	ADF MOUNTING TRAY 622-5212-001 3FPFJ REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL 011-01428-00 194005097 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>CHAPTER 35 OXYGEN</b>									
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			05-MAY-2020 1528.2 990	<b>05-MAY-2023</b> <b>3328.2</b>	04-JUN-2023 3358.2
<b>AIRWORTHINESS</b>	REF: AMM 35-00-00								
35-01-00-001 (s)	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION PKG 84 REF: AMM 35-01-02	MOS HRS/MSC AFL	60	+30d/-30d			PKG 24-MAY-2016 688.1 478		
35-01-02	OXYGEN CYLINDER TRANSDUCER 4441125-000 7635-8-95 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH P24151 0025 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-01-06	OXYGEN SYSTEM CONTROL PANEL 441-40945-002 0266 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-01-07	COCKPIT SENSOR P24099 0123 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-01-08	PAX LOW PRESSURE OXYGEN SYSTEM SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-01-09	ALTITUDE COMPENSATING REGULATOR 4421135-001 00007 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-01-10	LOW PRESSURE OXYGEN VALVE 4421132-109 00237 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-02-01	OXYGEN CYLINDER 4441122-050 418078705 REF: See Workcard	MOS HRS/MSC AFL	C/C	N:56 N:688.1 N:478			24-MAY-2016 688.1 478		
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR 4441122-050 418078705 REF: AMM 35-02-01	MOS HRS/MSC AFL	60				13-MAY-2016	13-MAY-2021	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-02-01-003	DISCARD OF OXYGEN CYLINDER 4441122-050 418078705 <b>REF:</b> AMM 35-02-01	MOS HRS/MSC AFL	180				13-MAY-2016	<b>13-MAY-2031</b>	
<b>LIFE LIMIT</b>									
35-02-05	OXYGEN PRESSURE REGULATOR 1423018-019 0314 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX   <b>REF:</b> AMM 35-11-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30	27		05-MAY-2020 1528.2 990	<b>01-JUN-2021</b> <b>2128.2</b>	01-JUL-2021 2158.2
<b>AIRWORTHINESS</b>									
35-11-01	COPILOT OXYGEN MASK STOWAGE BOX 1186F6-23 00529 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-11-01	PILOT OXYGEN MASK STOWAGE BOX 1186F6-23 00525 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
35-11-02	LEFT CREW OXYGEN MASK 174232-93 29019 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:105 N:1531.7 N:995			22-JUN-2020 1531.7 995		
35-11-02	RIGHT CREW OXYGEN MASK 174232-93 29020 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:105 N:1531.7 N:995			22-JUN-2020 1531.7 995		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 29019 REF: AMM 35-11-02	MOS HRS/MSC AFL	24	+30d/-30d		3	22-JUN-2020 1531.7 995	25-JUN-2022	25-JUL-2022
35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 29020 REF: AMM 35-11-02	MOS HRS/MSC AFL	24	+30d/-30d		3	22-JUN-2020 1531.7 995	25-JUN-2022	25-JUL-2022
35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK 174232-93 29019 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30			27-JUN-2017 840.6 558	27-JUN-2023 4440.6	27-JUL-2023 4470.6
35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK 174232-93 29020 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30			27-JUN-2017 840.6 558	27-JUN-2023 4440.6	27-JUL-2023 4470.6
35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 29019 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 29020 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A				21-SEP-2011 0 0		
35-11-04-001 (s)	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED) PKG 82 REF: AMM 35-11-04	MOS HRS/MSC AFL	36	+1m/-1m			PKG 05-MAY-2020 1528.2 990		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE	MOS	36	+30d/-30d			18-JUL-2018	18-JUL-2021 M	17-AUG-2021
<b>AIRWORTHINESS</b>	<b>REF: AMM 35-21-00</b>	HRS/MSC AFL	1800	+30/-30			1036 668	2836	2866
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE	MOS	36	+30d/-30d			18-JUL-2018	18-JUL-2021 M	17-AUG-2021
<b>AIRWORTHINESS</b>	<b>REF: AMM 35-21-00</b>	HRS/MSC AFL	1800	+30/-30			1036 668	2836	2866
35-21-01	AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER	MOS			N:0		21-SEP-2011		
	4411071-001	HRS/MSC	O/C		N:0		0		
	<b>REF: See Workcard</b>	AFL			N:0		0		
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER	MOS			N:0		21-SEP-2011		
	4411071-001	HRS/MSC	O/C		N:0		0		
	<b>REF: See Workcard</b>	AFL			N:0		0		
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS					22-DEC-2016		
	PN-UNKNOWN	HRS/MSC	O/C				773.1		
	<b>REF: See Workcard</b>	AFL					532		
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS			R:0		03-JUL-2014		
	4411072-001	HRS/MSC	O/C		R:0		399.1		
	<b>REF: See Workcard</b>	AFL			R:0		267		
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS			N:2		16-NOV-2011		
	4411072-001	HRS/MSC	O/C						
	4411072-001-00374	AFL							
	<b>REF: See Workcard</b>								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER 4411072-001 4411072-001-00772 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-JUL-2014 399.1 267		
35-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS PKG 82 REF: AMM 35-21-01	MOS HRS/MSC AFL	36	+1m/-1m			PKG 05-MAY-2020 1528.2 990		
<b>CHAPTER 36 PNEUMATIC</b>									
36-01-01	PNEUMATIC INSC ILLUM PANEL 441-42633-002 1082 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-3 0058 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-4 0051 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-01-001 (s)	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER PKG 20 REF: AMM 36-11-01	MOS HRS/MSC AFL	2400	+30/-30			PKG 21-SEP-2011 0 0		
36-11-01-002 (s)	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-00	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-02-001 (s)	DETAILED INSPECTION OF BLEED LINE WATER DRAINS PKG 81 REF: AMM 36-11-02	MOS HRS/MSC AFL	24	+30d/-30d		-30	PKG 27-JUN-2019 1275.4 845		
36-11-03	AMS CONTROLLER SYLZ-53632-203 0072 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-04	NO. 1 ENGINE FAN AIR VALVE RYLB-53527-1 0084 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-04	NO. 2 ENGINE FAN AIR VALVE RYLB-53527-1 0083 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-04-001 (s)	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER PKG 20 REF: AMM 36-11-04	MOS HRS/MSC AFL	2400	+30/-30			PKG 21-SEP-2011 0 0		
36-11-05	LH INCONEL 625 BLEED PRE-COOLER 10965000-105 T0030 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-05	RH INCONEL 625 BLEED PRE-COOLER 10964000-105 T0037 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-06	CROSS BLEED VALVE RYLB-53506-1 0049 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-06-001 (s)	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-06	MOS HRS/MSC AFL	800	+30/-30			PKG 14-APR-2019 1206.8 793		
36-11-06-002 (s)	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER PKG 60 REF: AMM 36-11-06	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 7723-4-20 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 7738-5-86 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 24172 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 24176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 24178 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 24180 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR PKG 60 REF: AMM 36-11-08	MOS HRS/MSC AFL	6400	+30/-30			PKG 21-SEP-2011 0 0		
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS REF: AMM 36-21-01	MOS HRS/MSC AFL	6000	+30/-30			21-SEP-2011 0 0	6000	6030
AIRWORTHINESS									

## CHAPTER 38 WATER/WASTE

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-33-00	TOILET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
38-33-07	WASTE DRAIN VALVE 0218-0032-1 142860 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:16 R:0 R:0			18-SEP-2019 1380.1 910		
<b>CHAPTER 44 CABIN SYSTEMS</b>									
44-12-07	3-CHANNEL AUDIO AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
44-21-03	DC-DC CONVERTER 35-192-00 184 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
44-21-09	IFE INSC ILLUM PANEL 441-42725-001 0141 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
44-21-11	XM RECEIVER XMR050-01 815000323 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-NOV-2011 26.7 18		
44-21-13	XM HEAD CONTROL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-21-15	AUDIO VOLUME CONTROLLER 102029-7 301111 REF: See Workcard	MOS HRS/MSC AFL	O/C					16-NOV-2011 26.7 18	
44-21-17	IR RECEIVER WITH CONNECTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
44-21-19	IR REMOTE CONTROLLER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
44-21-21	WIRELESS AUDIO TRANSMITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
44-21-23	NO. 1 WIRELESS HEADPHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
44-21-23	NO. 2 WIRELESS HEADPHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	
44-21-25	HEADPHONE DISTRIBUTION AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-SEP-2011 0 0	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER 0604-001 0912W003 REF: See Workcard	MOS HRS/MSC AFL	O/C				14-MAR-2012 59.6 38		
44-22-03	NO. 1 10.4 INCH FOLD DOWN MONITOR- PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
44-32-01	ATG5000 TRANSCEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
44-32-03	AIRCELL CONFIGURATION MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
44-32-05	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
442127-0101	LH NO. 1 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
442127-0102	RH NO. 2 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
442127-0103	LH NO. 3 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
442127-0104	RH NO. 4 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
442127-0105	LH NO. 5 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
442127-0106	RH NO. 6 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
<b>CHAPTER 52 DOORS</b>									
52-00-00	KEY LOCK KIT 505-38956-901 000095-00095 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
52-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 87 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
52-10-00-01A	PAX DOOR EQUIPPED MAIN DOOR ASSY 505-09910-451 0000628245 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015 633.3		
	REF: NDT PART 5 52-10-00	HRS/MSC AFL					448		
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 52-10-00	HRS/MSC AFL	17500 14000				0		14000
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 52-10-00	HRS/MSC AFL	17500 14000				0		14000
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 52-10-00	HRS/MSC AFL	17500 14000				0		14000
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 52-10-00	HRS/MSC AFL	17500 14000				0		14000
52-10-20-001 (s)	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL PKG 80	MOS	12	+30d/-30d			PKG 27-JUN-2019 1275.4		
	REF: AMM 52-10-20	HRS/MSC AFL					845		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-11-00-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM PKG 83 REF: AMM 52-11-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
52-11-00-003 (s)	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH PKG 1 REF: AMM 52-11-23	MOS HRS/MSC AFL	800				PKG 05-MAY-2020 1528.2 990		
52-13-00	MAIN DOOR BALANCE ASSY. GEAR SECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		N:0 N:0 N:0		21-SEP-2011 0 0		
52-13-01	MAIN DOOR BALANCE ASSY. PINION SHAFT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T		N:0 N:0 N:0		21-SEP-2011 0 0		
52-13-21-001 (s)	DISCARD OF SECTOR GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED) PN PKG 50 SN-UNKNOWN REF: AMM 52-13-21	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
52-13-22	MAIN DOOR BALANCING MECHANISM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
52-13-22-001	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE PN SN-UNKNOWN REF: AMM 52-13-22	MOS HRS/MSC AFL	O/C				21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-13-22-004 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES PKG 40 REF: AMM 52-13-22	MOS HRS/MSC AFL	3200	+30/-30			PKG 21-SEP-2011 0 0		
52-13-23-001 (s)	DISCARD OF SHAFT PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED) PN PKG 50 SN-UNKNOWN REF: AMM 52-13-23	MOS HRS/MSC AFL	5600	+30/-30			PKG 21-SEP-2011 0 0		
52-20-00	EMERGENCY DOOR 500-09700-433 0000638408 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
52-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR STRUCTURE PKG 90 REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 29-MAY-2015 633.3 448		
52-20-01-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE PKG 90 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 29-MAY-2015 633.3 448		
52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL REF: NDT PART 5 52-20-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-20-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM PKG 83 REF: AMM 52-20-20	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
52-20-21-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR RUBBER SEAL PKG 81 REF: AMM 52-20-21	MOS HRS/MSC AFL	24	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
52-31-20-001 (s)	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM PKG 83 REF: AMM 52-31-20	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
52-32-20-001 (s)	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM PKG 83 REF: AMM 52-32-20	MOS HRS/MSC AFL	48	+30d/-30d			PKG 27-JUN-2019 1275.4 845		
52-71-20	LOWER PAX DOOR MICRO SWITCH ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
52-71-20	UPPER PAX DOOR MICRO SWITCH ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
<b>CHAPTER 53 FUSELAGE</b>									
53-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS PKG 1 REF: AMM 53-00-20	MOS HRS/MSC AFL	800				PKG 14-APR-2019 1206.8 793		



## Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-05-00-001 (s)	DETAILED INSPECTION OF FUSELAGE DRAINS PKG 84 REF: AMM 53-05-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 24-MAY-2016 688.1 478		
53-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
53-10-00-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
53-10-00-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL  REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL  REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-10-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOOUT - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-10-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-10-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-10-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-10-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-10-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



## Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD PKG 90	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 53-10-00	AFL					0		
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 53-10-00	AFL	17500	14000			0		14000
53-10-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015 633.3		
	REF: NDT PART 5 53-10-00	AFL					448		
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL	MOS					21-SEP-2011 0		15000
<b>AIRWORTHINESS</b>	REF: NDT PART 5 53-10-00	AFL	15000	12000			0		12000
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WHEEL STRUCTURE. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - EXTERNAL	MOS					21-SEP-2011 0		15000
<b>AIRWORTHINESS</b>	REF: NDT PART 5 53-10-00	AFL	15000	12000			0		12000
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WHEEL STRUCTURE.	MOS					21-SEP-2011 0		15000
<b>AIRWORTHINESS</b>	REF: NDT PART 5 53-10-00	AFL	15000	12000			0		12000



## Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-14-00	NOSE RADOME 5190-102-1 263 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
53-20-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
53-20-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL REF: NDT PART 5 53-20-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	AFL	14000				0		14000
53-20-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE						PKG		
	PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
		HRS/MSC					0		
	<b>REF: NDT PART 5 53-20-00</b>	AFL					0		
53-20-05-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE						PKG		
	PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
		HRS/MSC					0		
	<b>REF: NDT PART 5 53-20-00</b>	AFL					0		
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	AFL	14000				0		14000
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	AFL	14000				0		14000
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	AFL	14000				0		14000



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-06-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 87	MOS	60	+30d/-30d			29-MAY-2015		
	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC					633.3		
		AFL					448		
53-20-06-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 87,90	MOS	60	+30d/-30d			29-MAY-2015		
	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC					633.3		
		AFL					448		
53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	8750				0	<b>8750</b>	
		AFL	7000				0	<b>7000</b>	





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-20-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE PKG 90	MOS	60	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC					0		
		AFL					0		
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-20-10-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC					0		
		AFL					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-20-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
53-30-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE	MOS	120	+30d/-30d			21-SEP-2011		
	PKG 90	HRS/MSC					0		
	<b>REF: NDT PART 5 53-30-00</b>	AFL					0		
53-30-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES	MOS	120	+30d/-30d			21-SEP-2011		
	PKG 90	HRS/MSC					0		
	<b>REF: NDT PART 5 53-30-00</b>	AFL					0		
53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC					0		
		AFL					0		
53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	12500				0	<b>12500</b>	
		AFL	10000				0	<b>10000</b>	
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
53-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES PKG 90	MOS HRS/MSC AFL	120 +30d/-30d				21-SEP-2011 0 0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>								
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	MOS HRS/MSC AFL	10000 8000				21-SEP-2011 0 0	<b>10000</b> <b>8000</b>	
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	MOS HRS/MSC AFL	12500 10000				21-SEP-2011 0 0	<b>12500</b> <b>10000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-30-07-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC					0		
		AFL					0		
53-30-07-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC					0		
		AFL					0		
53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 53-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-08-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 87 REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
53-30-08-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 90 REF: NDT PART 5 53-30-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
<b>CHAPTER 54 NACELLES/PYLONS</b>									
54-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS PKG 1 REF: AMM 54-51-20	MOS HRS/MSC AFL	800				PKG 14-APR-2019 1206.8 793		
54-50-00-001 (s)	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE PKG 90 REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
54-50-00-002 (s)	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX PKG 90 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
54-50-01-01-901	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL REF: NDT PART 5 54-50-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
<b>AIRWORTHINESS</b>									



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-02-01-901	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-50-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
54-50-03-001 (s)	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE. PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015		
	<b>REF: NDT PART 5 54-52-00</b>	HRS/MSC					633.3		
		AFL					448		
54-50-03-01-901	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-52-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-52-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-52-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
54-50-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES PKG 87	MOS	120	+30d/-30d			PKG 21-SEP-2011		
	<b>REF: NDT PART 5 54-55-00</b>	HRS/MSC					0		
		AFL					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 54-55-00</b>	HRS/MSC AFL	15000 12000				0 0	<b>15000</b> <b>12000</b>	
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-55-00</b>	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-55-00</b>	HRS/MSC AFL	15000 12000				0 0	<b>15000</b> <b>12000</b>	
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 54-55-00</b>	HRS/MSC AFL	15000 12000				0 0	<b>15000</b> <b>12000</b>	
<b>CHAPTER 55</b>	<b>STABILIZERS</b>								
55-00-00-001 (s)	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS						PKG		
	PKG 1	MOS					14-APR-2019		
	<b>REF: AMM 55-00-20</b>	HRS/MSC AFL	800				1206.8 793		
55-10-00	HORIZONTAL STABILIZER (COMPLETION)								
	505-10700-411	MOS					21-SEP-2011		
	0000636256	HRS/MSC	O/C				0		
	<b>REF: GENERIC NO REF</b>	AFL					0		
55-10-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS						PKG		
	PKG 84	MOS	60	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 55-10-00</b>	HRS/MSC AFL					0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING PKG 87 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
55-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS PKG 87 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
55-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 87 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-03-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-05-001 (s)	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS PKG 90	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL					0		
55-10-05-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 55-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
55-10-05-02-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 55-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-08-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-09-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT PKG 87	MOS	120	+30d/-30d			PKG 21-SEP-2011 0 0		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-10-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF ELEVATOR TRIM-TAB FITTINGS PKG 90	MOS	120	+30d/-30d			PKG 21-SEP-2011 0 0		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							



## Status Report

**EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020**

**Owner/Operator: LATITUDE 33 AVIATION, LLC**

**Report Date: 05-OCT-2020**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-10-00</b>	AFL	14000				0		14000
<hr/>									
55-20-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX						PKG		
	PKG 87	MOS	120	+30d/-30d			21-SEP-2011		
		HRS/MSC					0		
	<b>REF: See Workcard</b>	AFL					0		
<hr/>									
55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-20-00</b>	AFL	14000				0		14000
<hr/>									
55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-20-00</b>	AFL	14000				0		14000
<hr/>									
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-20-00</b>	AFL	14000				0		14000
<hr/>									
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-20-00</b>	AFL	14000				0		14000



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY PKG 87	MOS	120	+30d/-30d			21-SEP-2011		
	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	REF: NDT PART 6 55-20-00	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	REF: NDT PART 8 55-20-00	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
55-20-04-001	INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS PKG 84	MOS	60				21-SEP-2011	<b>29-MAY-2021 M</b>	
<b>ALI</b>	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
55-20-04-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS PKG 84	MOS	60				21-SEP-2011	<b>29-MAY-2021 M</b>	
<b>ALI</b>	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
55-22-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB PKG 87	MOS	120	+30d/-30d			21-SEP-2011		
	REF: NDT PART 5 55-22-00	HRS/MSC AFL					0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-00	VERTICAL STABILIZER 505-10100-407 0000636783 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
55-30-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 87 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			29-MAY-2015 633.3 448		
55-30-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			21-SEP-2011 0 0		
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL REF: NDT PART 6 55-30-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	17500 14000	
<b>AIRWORTHINESS</b>									



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC					0		
		AFL					0		
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-03-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS PKG 87	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC					0		
		AFL					0		
55-30-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX PKG 87	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL					0		
55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 55-30-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL							
55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0		14000
55-30-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER PKG 84	MOS	60	+30d/-30d			PKG 21-SEP-2011 0 0		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL							
55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0		14000
55-30-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING PKG 90	MOS	120	+30d/-30d			PKG 21-SEP-2011 0 0		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL							
55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0		14000



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX PKG 87	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0 0		
55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-40-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS PKG 87	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0 0		
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0		17500 14000



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY PKG 87	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0		
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL	MOS					21-SEP-2011 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0	<b>17500</b> <b>14000</b>	
55-40-04-002	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS PKG 84	MOS	60				21-SEP-2011 0	<b>29-MAY-2021 M</b>	
<b>ALI</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0		
55-40-04-003	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS PKG 84	MOS	60				21-SEP-2011 0	<b>29-MAY-2021 M</b>	
<b>ALI</b>	REF: NDT PART 5 55-40-00	HRS/MSC AFL					0		
55-42-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB PKG 90	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 55-42-00	HRS/MSC AFL					0		
<b>CHAPTER 56</b>	<b>WINDOWS</b>								
56-10-00	LEFT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-3	MOS					21-SEP-2011 0		
	10118H4769	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-00	RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-4 10133H6211 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF SIDE WINDOW PKG 84 REF: NDT PART 5 56-12-00	MOS HRS/MSC AFL	60	+30d/-30d			21-SEP-2011 0 0		
56-10-01-002	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS REF: AMM 56-10-00	MOS HRS/MSC AFL	1600	+30/-30			05-MAY-2020 1528.2 990	3128.2	3158.2
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			21-SEP-2011 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			21-SEP-2011 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			21-SEP-2011 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL								
		MOS					21-SEP-2011		
		HRS/MSC	17500				0		17500
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 56-10-00</b>	AFL	14000				0		14000
56-12-00	LEFT ACRYLIC SIDE WINDOW								
	NP-195302-3	MOS		N:0			21-SEP-2011		
	10099H3107	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
56-12-00	RIGHT ACRYLIC SIDE WINDOW								
	NP-195302-4	MOS		N:0			21-SEP-2011		
	10146H7544	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
56-20-00	NO. 1 WINDOW TRANSPARENCY								
	14024	MOS		N:0			21-SEP-2011		
	01882	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
56-20-00	NO. 10 WINDOW TRANSPARENCY								
	14024	MOS		N:0			21-SEP-2011		
	02626	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
56-20-00	NO. 11 WINDOW TRANSPARENCY								
	14024	MOS		N:0			21-SEP-2011		
	03152	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
56-20-00	NO. 2 WINDOW TRANSPARENCY								
	14024	MOS		N:0			21-SEP-2011		
	02495	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	NO. 3 WINDOW TRANSPARENCY 14024 02503 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-20-00	NO. 4 WINDOW TRANSPARENCY 14024 02504 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-20-00	NO. 5 WINDOW TRANSPARENCY 14024 02508 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-20-00	NO. 6 WINDOW TRANSPARENCY 14024 02509 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-20-00	NO. 7 WINDOW TRANSPARENCY 14024 02510 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-20-00	NO. 8 WINDOW TRANSPARENCY 14024 02511 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
56-20-00	NO. 9 WINDOW TRANSPARENCY 14024 02512 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PASSENGER WINDOW PANELS PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 21-SEP-2011 0 0		
REF: NDT PART 5 56-20-00									
<b>CHAPTER 57 WINGS</b>									
57-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF WINGLET POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	800				PKG 14-APR-2019 1206.8 793		
REF: AMM 57-35-21									
57-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX PKG 90	MOS HRS/MSC AFL	60	+30d/-30d			PKG 27-JUN-2017 840.6 558		
REF: NDT PART 5 57-10-00									
57-10-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
REF: NDT PART 5 57-10-00									
57-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
REF: NDT PART 5 57-00-00									
57-10-01-01-901	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-10-00								
57-10-02-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
REF: NDT PART 5 57-10-00									





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-10-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR PKG 90	MOS HRS/MSC AFL	120 +30d/-30d				PKG 21-SEP-2011 0 0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>								
57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-10-04-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR PKG 87	MOS HRS/MSC AFL	60 +30d/-30d				PKG 29-MAY-2015 633.3 448		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>								
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL PKG 87	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 57-10-00	AFL					0		
57-10-07-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 84	MOS	60	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 57-10-00	AFL					0		
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-10-00	AFL	17500				0		14000
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-10-00	AFL	17500				0		14000
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-10-00	AFL	17500				0		14000
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL	MOS					21-SEP-2011 0		17500
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-10-00	AFL	17500				0		14000
57-10-11-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015 633.3		
	REF: NDT PART 5 57-10-00	AFL					448		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



## Status Report

**EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020**

**Owner/Operator: LATITUDE 33 AVIATION, LLC**

**Report Date: 05-OCT-2020**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
<hr/>									
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
<hr/>									
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-10-00</b>	HRS/MSC	12500				0		<b>12500</b>
		AFL	10000				0		<b>10000</b>
<hr/>									
57-50-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS						PKG		
	PKG 87	MOS	60	+30d/-30d			29-MAY-2015		
		HRS/MSC					633.3		
	<b>REF: NDT PART 5 57-50-00</b>	AFL					448		
<hr/>									
57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-50-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
<hr/>									
57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-50-00</b>	HRS/MSC	11250				0		<b>11250</b>
		AFL	9000				0		<b>9000</b>



## Status Report

**EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020**

**Owner/Operator: LATITUDE 33 AVIATION, LLC**

**Report Date: 05-OCT-2020**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS						21-SEP-2011	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-50-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS						21-SEP-2011	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-50-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS						21-SEP-2011	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-50-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS						21-SEP-2011	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-50-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS						21-SEP-2011	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-50-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-50-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK						PKG		
	PKG 84	MOS	60	+30d/-30d				21-SEP-2011	
	<b>REF: NDT PART 5 57-20-00</b>	HRS/MSC					0		
		AFL					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-50-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-50-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-50-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-50-00</b>	HRS/MSC	17500				0	<b>17500</b>	
		AFL	14000				0	<b>14000</b>	
57-52-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP						PKG		
	PKG 90	MOS	120	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 57-52-00</b>	HRS/MSC					0		
		AFL					0		
57-52-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP						PKG		
	PKG 84	MOS	60	+30d/-30d			21-SEP-2011		
	<b>REF: NDT PART 5 57-52-00</b>	HRS/MSC					0		
		AFL					0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-52-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-52-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-52-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-52-00</b>	HRS/MSC	11250				0		<b>11250</b>
		AFL	9000				0		<b>9000</b>
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-52-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL								
		MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-52-00</b>	HRS/MSC	17500				0		<b>17500</b>
		AFL	14000				0		<b>14000</b>



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP PKG 90	MOS	120	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 57-53-00	HRS/MSC AFL					0		
57-53-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP PKG 84	MOS	60	+30d/-30d			PKG 21-SEP-2011 0		
	REF: NDT PART 5 57-53-00	HRS/MSC AFL					0		
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL	MOS					21-SEP-2011 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0	<b>17500</b> <b>14000</b>	
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL	MOS					21-SEP-2011 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0	<b>17500</b> <b>14000</b>	
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL	MOS					21-SEP-2011 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0	<b>17500</b> <b>14000</b>	
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL	MOS					21-SEP-2011 0		
<b>AIRWORTHINESS</b>	REF: NDT PART 6 57-53-00	HRS/MSC AFL	11250 9000				0	<b>11250</b> <b>9000</b>	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-53-00</b>	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-53-00</b>	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-53-00</b>	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					21-SEP-2011		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 6 57-53-00</b>	HRS/MSC AFL	17500 14000				0 0	<b>17500</b> <b>14000</b>	
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON PKG 84	MOS	60				21-SEP-2011	<b>29-MAY-2021 M</b>	
<b>ALI</b>	<b>REF: NDT PART 5 57-60-00</b>	HRS/MSC AFL					0 0		
57-60-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON TAB PKG 87	MOS	60	+30d/-30d			PKG 29-MAY-2015		
	<b>REF: NDT PART 5 57-60-00</b>	HRS/MSC AFL					633.3 448		





## Status Report

**EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020**

**Owner/Operator: LATITUDE 33 AVIATION, LLC**

**Report Date: 05-OCT-2020**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-60-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-60-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-60-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-60-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL								
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-60-00</b>	MOS HRS/MSC AFL	17500 14000				21-SEP-2011 0 0	<b>17500</b> <b>14000</b>	
57-60-04-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF AILERON MASS-BALANCE AND ATTACHMENTS PKG 80,84	MOS HRS/MSC AFL	60 +30d/-30d				21-SEP-2011 0 0	<b>29-MAY-2021</b> M 28-JUN-2021	
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-60-00</b>								
57-70-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS PKG 87	MOS HRS/MSC AFL	60 +30d/-30d				29-MAY-2015 633.3 448		
<b>AIRWORTHINESS</b>	<b>REF: NDT PART 5 57-70-00</b>								



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 70 STANDARD PRACTICES - ENGINES</b>									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01									
700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION							21-SEP-2011	
		MOS						0	
	REF: MM 70-00-00	HRS/MSC A/R						0	
		ENC						0	
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01									
700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION							21-SEP-2011	
		MOS						0	
	REF: MM 70-00-00	HRS/MSC A/R						0	
		ENC						0	
<b>CHAPTER 71 POWER PLANT</b>									
71-11-00-001 (s)	GENERAL VISUAL INSPECTION OF UPPER MID COWL							PKG	
	PKG 50	MOS						21-SEP-2011	
	REF: AMM 71-11-00	HRS/MSC 5600 +30/-30						0	
		AFL						0	
71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR							21-SEP-2011	
	LM-475-SA4	MOS						0	
	LK0246	HRS/MSC O/C						0	
	REF: See Workcard	AFL						0	
71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR							21-SEP-2011	
	LM-475-SA3	MOS						0	
	LK0417	HRS/MSC O/C						0	
	REF: See Workcard	AFL						0	
71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR							21-SEP-2011	
	LM-475-SA3	MOS						0	
	LK0379	HRS/MSC O/C						0	
	REF: See Workcard	AFL						0	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0248 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0385 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK0382 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY	MOS HRS/MSC AFL	6000 6000				21-SEP-2011 0 0	6000 6000	
<b>AIRWORTHINESS</b>	REF: AMM 71-20-00								
71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL	MOS HRS/MSC AFL	3600				21-SEP-2011 0 0	3600	
<b>AIRWORTHINESS</b>	REF: See Workcard								
71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY	MOS HRS/MSC AFL	6000 6000				21-SEP-2011 0 0	6000 6000	
<b>AIRWORTHINESS</b>	REF: AMM 71-20-00								



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-31-00-001 (s)	DETAILED INSPECTION OF PYLON FIREWALL SEAL PKG 20 REF: AMM 71-31-00	MOS HRS/MSC AFL	2400	+30/-30			PKG 27-JUN-2017 840.6 558		
71-60-01	LEFT ENGINE AIR INLET 505-36920-405 143 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-JUN-2013		
71-60-01	RIGHT ENGINE AIR INLET 505-36930-405 043 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:37 R:0 R:0			14-APR-2019 1206.8 793		
71EN1 71.EN1	NO. 1 ENGINE A3072913-01 PCE-DG0064 REF: See Workcard	MOS HRS/MSC AFL	E/C						
71EN2 71.EN2	NO. 2 ENGINE A3072913-01 PCE-DG0063 REF: See Workcard	MOS HRS/MSC AFL	E/C						
<b>ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01</b>									
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS REF: MM 70-00-00	MOS HRS/MSC ENC	A/R				21-SEP-2011 0 0		
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH REF: MM 71-00-00	DAYS HRS/MSC ENC	A/R				18-JUL-2018 1036 682		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS					15-JAN-2016		
	REF: MM 71-00-00	HRS/MSC	A/R						
		ENC							
71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12	+30d			05-MAY-2020	<b>05-MAY-2021</b>	04-JUN-2021
	REF: MM 71-00-00	HRS/MSC	630	+10%			1528.2	<b>(2158.2) 2158.2</b>	2221.2
		ENC					990		
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				05-MAY-2020	<b>05-MAY-2021</b>	
	REF: MM 72-00-02	HRS/MSC	630				1528.2	<b>(2158.2) 2158.2</b>	
		ENC					990		
<b>ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01</b>									
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS					21-SEP-2011		
	REF: MM 70-00-00	HRS/MSC	A/R				0		
		ENC					0		
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH	DAYS					18-JUL-2018		
	REF: MM 71-00-00	HRS/MSC	A/R				1036		
		ENC					682		
71-00-00-760-810	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS					15-JAN-2016		
	REF: MM 71-00-00	HRS/MSC	A/R						
		ENC							
71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12	+30d			05-MAY-2020	<b>05-MAY-2021</b>	04-JUN-2021
	REF: MM 71-00-00	HRS/MSC	630	+10%			1528.2	<b>(2158.2) 2158.2</b>	2221.2
		ENC					990		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION  REF: MM 72-00-02	MOS HRS/MSC ENC	12 630				05-MAY-2020 1528.2 990	05-MAY-2021 (2158.2) 2158.2	
<b>CHAPTER 72 ENGINE</b>									
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01									
+ 72-00-00-000-802	NO. 1 ENGINE - DISCARD GAS GENERATOR CASE 3075417-01 RWA08D477 REF: GENERIC NO REF	MOS HRS/MSC ENC	8200				(EBT)	(8200) 8200	
72-00-00-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			05-MAY-2020 1528.2 990		
72-00-00-212-802 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			05-MAY-2020 1528.2 990		
72-00-00-212-803 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			05-MAY-2020 1528.2 990		
72-00-00-212-804 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			05-MAY-2020 1528.2 990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-805 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-806 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-807 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-808 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-809 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR REF: MM 72-00-00	MOS HRS/MSC ENC	A/R				21-SEP-2011 0 0		
72-00-00-280-818	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES) REF: MM 72-00-00	MOS HRS/MSC ENC	120	+1m			21-SEP-2011 0 0	21-SEP-2021	21-OCT-2021



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-280-820 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES PKG 1	MOS	12	+30d			PKG	05-MAY-2020	
	REF: MM 72-00-00	HRS/MSC	800	+10%			1528.2		
		ENC					990		
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					18-JUL-2018		
	REF: MM 72-00-00	HRS/MSC	BF/F				1036		
		ENC					682		
+ 72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS	MOS					23-SEP-2010		
	REF: MM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-CUS-0701	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF ENGINE INLET CRACK	MOS	3				06-JUL-2020	06-OCT-2020	
	REF:	HRS/MSC					1553.9		
		ENC					1008		
720010	NO. 1 ENGINE - OVERHAUL	MOS					21-SEP-2011		
	REF: GENERIC NO REF	HRS/MSC	5000	+100			0	(5000) 5000	5100
		ENC					0		
720060	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					21-SEP-2011		
	REF: MM 72-00-00	HRS/MSC	2500	+50			0	(2500) 2500	2550
		ENC					0		
721010	NO. 1 ENGINE - GEARBOX	MOS					23-SEP-2010		
	PN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722001	NO. 1 ENGINE - OIL PUMP 3073477-02 EC01A002A945 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY 3073356-01 A002TELN REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	N:0 N:0 N:0			23-SEP-2010 0 0	(30000) 30000	
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A002TFT6 REF: See Workcard	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			23-SEP-2010 0 0	(15000) 15000	
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1C3059 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			23-SEP-2010 0 0	(15000) 15000	
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 A002T5KA REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	N:0 N:0 N:0			23-SEP-2010 0 0	(13500) 13500	
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 A002TY5L REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	N:0 N:0 N:0			23-SEP-2010 0 0	(13500) 13500	
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY 3074676-01 EDA00990N REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723060	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING 3052663-02 FCN318349 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY 3075850-01 A002W1LT REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY 3075417-01 RWA08D477 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A002WAR5 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA331261 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00D323 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 UAAA0504 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 AWE013882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA08476 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAC000C615 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723160	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING 3052670-02 FCN322019 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA331113 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723180	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052616-01 FCN322767 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
723190	NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052634-01 FCN321300 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A002TMP7	MOS HRS/MSC		N:0 N:0			23-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	13500	N:0			0	<b>(13500) 13500</b>	
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A002TFPT	MOS HRS/MSC		N:0 N:0			23-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	13500	N:0			0	<b>(13500) 13500</b>	
724001	NO. 1 ENGINE - INNER COMBUSTION LINER 3075516-01 A002TH11	MOS HRS/MSC	O/C	N:0 N:0			23-SEP-2010 0		
	<b>REF: See Workcard</b>	ENC		N:0			0		
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER 3075522-01 A002TTLX	MOS HRS/MSC	O/C	N:0 N:0			23-SEP-2010 0		
	<b>REF: See Workcard</b>	ENC		N:0			0		
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221819096	MOS HRS/MSC	O/C	N:0 N:0			23-SEP-2010 0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A002TPPE	MOS HRS/MSC		N:0 N:0			23-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	ENC	10000	N:0			0	<b>(10000) 10000</b>	
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A002TEMR	MOS HRS/MSC		N:0 N:0			23-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	13500	N:0			0	<b>(13500) 13500</b>	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX9652 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1059 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1060 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1061 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1071 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1073 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1081 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1084 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1097 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1100 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1101 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDT2875 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1104 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1105 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1112 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1113 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1117 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1125 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1128 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1135 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1141 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1142 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDT2882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1145 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1148 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1152 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1153 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1156 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1158 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1159 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1161 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1173 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1174 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDW7908 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1178 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1183 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY0656 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6398 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6404 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6408 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6419 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6421 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6422 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6423 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1043 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6424 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6426 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6431 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6435 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6438 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6439 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6456 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6465 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6479 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6484 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1044 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6485 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1046 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1054 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1058 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6487 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6488 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6489 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6491 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6501 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6503 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6509 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6514 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6520 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6527 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN320494 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3074832-01 RWA07D552 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 MDAA000A569 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3052263CL01 PDAHNKDK01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAH8HE01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHEKECY01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN318928 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0094543 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0094552 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0094555 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0094564 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726060	NO. 1 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3072949-01 PKAAA313870 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA03D082 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1009768 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1017519 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0096182 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA324813 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY 3075013-01 KYAA007A224 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA005A986 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
793010	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1212 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-000-802	NO. 2 ENGINE - DISCARD GAS GENERATOR CASE 3075417-01 RWA08D480 REF: GENERIC NO REF	MOS HRS/MSC ENC					(EBT)	(8200) 8200	
72-00-00-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-802 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-803 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-804 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-805 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
72-00-00-212-806 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-807 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1	MOS	12	+30d			PKG 05-MAY-2020 1528.2 990		
	REF: MM 72-00-00	HRS/MSC ENC	800	+10%					
72-00-00-212-808 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1	MOS	12	+30d			PKG 05-MAY-2020 1528.2 990		
	REF: MM 72-00-00	HRS/MSC ENC	800	+10%					
72-00-00-212-809 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1	MOS	12	+30d			PKG 05-MAY-2020 1528.2 990		
	REF: MM 72-00-00	HRS/MSC ENC	800	+10%					
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	MOS					21-SEP-2011 0 0		
	REF: MM 72-00-00	HRS/MSC ENC	A/R						
72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	MOS	120	+1m			21-SEP-2011 0 0	21-SEP-2021	21-OCT-2021
	REF: MM 72-00-00	HRS/MSC ENC							
72-00-00-280-820 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES PKG 1	MOS	12	+30d			PKG 05-MAY-2020 1528.2 990		
	REF: MM 72-00-00	HRS/MSC ENC	800	+10%					
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					18-JUL-2018 1036 682		
	REF: MM 72-00-00	HRS/MSC ENC	BF/F						



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS	MOS					21-SEP-2010		
	REF: MM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
72-00-CUS-0701	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF ENGINE INLET CRACK	MOS	3				06-JUL-2020	<b>06-OCT-2020</b>	
	REF:	HRS/MSC					1553.9		
		ENC					1008		
720010	NO. 2 ENGINE - OVERHAUL	MOS					21-SEP-2011		
	REF: GENERIC NO REF	HRS/MSC	5000	+100			0	<b>(5000) 5000</b>	5100
		ENC					0		
720060	NO. 2 ENGINE - HOT SECTION INSPECTION	MOS					21-SEP-2011		
	REF: MM 72-00-00	HRS/MSC	2500	+50			0	<b>(2500) 2500</b>	2550
		ENC					0		
721010	NO. 2 ENGINE - GEARBOX	MOS					21-SEP-2010		
	PN	HRS/MSC	O/C		N:0		0		
	SN-UNKNOWN	ENC			N:0		0		
	REF: GENERIC NO REF				N:0		0		
722001	NO. 2 ENGINE - OIL PUMP	MOS					21-SEP-2010		
	3073477-02	HRS/MSC	O/C		N:0		0		
	EC01A002943	ENC			N:0		0		
	REF: See Workcard				N:0		0		
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY	MOS					21-SEP-2010		
	3073356-01	HRS/MSC			N:0		0		
	A002TELP	ENC	30000		N:0		0	<b>(30000) 30000</b>	
<b>LIFE LIMIT</b>	REF: GENERIC NO REF				N:0		0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A002TAFA	MOS HRS/MSC		N:0 N:0			21-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	ENC	15000	N:0			0	<b>(15000) 15000</b>	
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1C3056	MOS HRS/MSC		N:0 N:0			21-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 15000</b>	
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 A002T5KB	MOS HRS/MSC		N:0 N:0			21-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	13500	N:0			0	<b>(13500) 13500</b>	
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 A002TFT8	MOS HRS/MSC		N:0 N:0			21-SEP-2010 0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	13500	N:0			0	<b>(13500) 13500</b>	
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY 3074676-01 EDA00990B	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2010 0		
	<b>REF: See Workcard</b>	ENC		N:0			0		
723060	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING 3052663-02 FCN318344	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2010 0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY 3075850-01 A002W1LP	MOS HRS/MSC	O/C	N:0 N:0			21-SEP-2010 0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY 3075417-01 RWA08D480 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A002W5N2 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA331264 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00D329 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 UAAA0503 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 AWE013870 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA08485 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAC000C616 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723160	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING 3052670-02 FCN322024 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA331109 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723190	NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052634-01 FCN313030 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A002TMP8 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	N:0 N:0 N:0			21-SEP-2010 0 0	(13500) 13500	
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A002TFPX LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	N:0 N:0 N:0			21-SEP-2010 0 0	(13500) 13500	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724001	NO. 2 ENGINE - INNER COMBUSTION LINER 3075516-01 A002TH12 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER 3075522-01 A002TTLW REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221819051 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A002TPPC REF: See Workcard	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			21-SEP-2010 0 0	(10000) 10000	
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A002TFL7 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	N:0 N:0 N:0			21-SEP-2010 0 0	(13500) 13500	
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDK8834 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1048 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1051 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1057 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1066 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1068 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1069 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1075 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1076 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1079 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1085 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX9638 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1090 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1091 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1095 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1096 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1098 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1102 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1107 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1108 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1110 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1114 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDR3628 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1119 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1123 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1124 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1130 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1131 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1137 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1144 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1149 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1154 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1155 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDW7893 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1163 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1170 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1172 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1181 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6400 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6401 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6410 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6414 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6415 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6428 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1032 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6429 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6436 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6442 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6443 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6447 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6449 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6454 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6458 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6466 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6469 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1033 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6470 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1034 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1039 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDX1045 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6480 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6482 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6499 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6502 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6506 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6507 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6513 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6516 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6517 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3074951-01 HWDY6518 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN321932 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3074832-01 RWA08D130 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 AWE013756 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3052263CL01 PDAHNC9D01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAHNL5Y01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHEHNTW01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
726010	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN318929 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0090793 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0090795 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0091106 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0091107 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	
726060	NO. 2 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3072949-01 PKAAA313867 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA03D075 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1009766 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1010730 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				21-SEP-2010 0 0	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726120	NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0075765 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA324800 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY 3075013-01 KYAA007A222 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA006A842 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
793010	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1183 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
<b>CHAPTER 73</b>	<b>ENGINE FUEL AND CONTROL</b>								
73-21-01	LEFT FADEC 3073593-06 2011050024 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
73-21-01	RIGHT FADEC 3073593-06 2011050023 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 24438 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 29661 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-AUG-2013 308.4 226		
<b>ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01</b>									
72-00-00-280-819 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT)	(9900) 9900	
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d			05-MAY-2020 1528.2 990	05-MAY-2021	04-JUN-2021
73-10-05-960-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	800	+10%		-6.8	14-APR-2019 1206.8	(2000) 2000	2080

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-07-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
+ 73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT 3071682-05 F71511 REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-02-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
73-20-10-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS 3073237-03 ADXBA000268 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-20-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100				(5000) 5000 M 5100	
73-30-02-212-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731002	NO. 1 ENGINE - FLOW DIVIDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731005	NO. 1 ENGINE - FUEL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-APR-2019 1206.8		
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BKM0977 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0624 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA1316 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0303 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0304 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0308 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0316 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0317 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0321 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0323 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLA0623 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 1012300-3-003 2008050002 REF: See Workcard	MOS HRS/MSC ENC	O/C				13-AUG-2013 308.4 226		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F71511 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
732005	NO. 1 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
732006	NO. 1 ENGINE - N1 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS 3073237-03 ADXBA000268 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
732040	NO. 1 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
<b>ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01</b>									
72-00-00-280-819 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 800	+30d +10%			05-MAY-2020 1528.2 990		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES  REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
+ 73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES  REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT)	(9900) 9900	
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT  REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d			05-MAY-2020 1528.2 990	05-MAY-2021	04-JUN-2021
73-10-05-960-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	800	+10%		-6.8	14-APR-2019 1206.8	(2000) 2000	2080
73-10-07-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
+ 73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT 3071682-05 F69443 REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
73-20-02-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-20-10-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS 3073237-03 ADXBA000270 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
73-20-20-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100				(5000) 5000 M	5100
73-30-02-212-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
731002	NO. 2 ENGINE - FLOW DIVIDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		
731005	NO. 2 ENGINE - FUEL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		14-APR-2019 1206.8		
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0270 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0279 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0280 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0271 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0272 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0273 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0274 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0275 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0276 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0277 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DE1BLD0278 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 1012300-3-003 2008090005 REF: See Workcard	MOS HRS/MSC ENC	O/C				13-AUG-2013 308.4 226		
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F69443 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
732005	NO. 2 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
732006	NO. 2 ENGINE - N1 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS 3073237-03 ADXBA000270 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
732040	NO. 2 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

## CHAPTER 74 IGNITION

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01

74-00-01-750-801 (s)	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 800				PKG 05-MAY-2020 1528.2 990		
74-10-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER 500335-1 PKG 1 NNA08144743 REF: MM 74-10-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
74-20-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS	12				PKG 05-MAY-2020 1528.2 990		
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS	12				PKG 05-MAY-2020 1528.2 990		
74-20-02-960-801	NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C				31-MAY-2015 633.3 462		
+ 74-20-02-960-801	NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C				31-MAY-2015 633.3 462		
741001	NO. 1 ENGINE - EXCITER IGNITION 500335-1 NNA08144743 REF: See Workcard	MOS	O/C				03-DEC-2014 501.5 376		
742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C				N:0 23-SEP-2010 0 0		
742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS	O/C				N:0 23-SEP-2010 0 0		





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD 3073141-01 NNA08208577 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD 3073141-02 NNA09079864 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
<b>ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01</b>									
74-00-01-750-801 (s)	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 800				PKG 05-MAY-2020 1528.2 990		
74-10-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER 31J2807-07 PKG 1 NNA10350121 REF: MM 74-10-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
74-20-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS HRS/MSC ENC	12 800				PKG 05-MAY-2020 1528.2 990		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR PN PKG 1 SN-UNKNOWN REF: MM 74-20-02	MOS HRS/MSC ENC	12 800				PKG 05-MAY-2020 1528.2 990		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-02-960-801	NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				31-MAY-2015 633.3 462		
+ 74-20-02-960-801	NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				31-MAY-2015 633.3 462		
741001	NO. 2 ENGINE - EXCITER IGNITION 31J2807-07 NNA10350121 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD 3073141-01 NNA08208582 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD 3073141-02 NNA09079797 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

## CHAPTER 75 AIR

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01									
75-30-01-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1	MOS	12	+30d			PKG	05-MAY-2020	
	REF: MM 75-30-01	HRS/MSC ENC	800	+10%			1528.2 990		
+ 75-30-01-212-802	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: MM 75-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
75-30-01-212-803	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE 3053367-01 AHX016960 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR4490 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER 3071811-01 1317 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
+ 75-30-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1317 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 75-30-20-212-801	NO. 1 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
750010	NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
753002	NO. 1 ENGINE - SERVO COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
753010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX016960 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
753020	NO. 1 ENGINE - BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
<b>ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01</b>									
75-30-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1 REF: MM 75-30-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
+ 75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: MM 75-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE 3053367-01 AHX016959 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR4474 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER 3071811-01 1316 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
+ 75-30-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1316 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 75-30-20-212-801	NO. 2 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
750010	NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
753002	NO. 2 ENGINE - SERVO COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753010	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX016959 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
753020	NO. 2 ENGINE - BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		

## CHAPTER 76 ENGINE CONTROLS

76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY 6990010-11 1269 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
----------	---	-----------------------	-----	-------------------	--	--	-----------------------	--	--

## CHAPTER 77 ENGINE INDICATING

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01

77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM MOS HRS/MSC ENC REF: MM 77-20-02	36 1800	+30d +100				05-MAY-2020 1528.2 990	05-MAY-2023 (3328.2) 3328.2	04-JUN-2023 3428.2
+ 77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT 3075878-01 15036816 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M	5100
774001	NO. 1 ENGINE - DATA COLLECTION UNIT 3075878-01 15036816 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			25-JAN-2016 635.7 452		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM  REF: MM 77-20-02	MOS HRS/MSC ENC	36 1800	+30d +100			05-MAY-2020 1528.2 990	<b>05-MAY-2023</b> (3328.2) 3328.2	04-JUN-2023 3428.2
+ 77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT  3075394-01 DP09-1354 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	<b>(5000) 5000 M</b>	5100
774001	NO. 2 ENGINE - DATA COLLECTION UNIT  3075394-01 DP09-1354 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		
<b>CHAPTER 78 EXHAUST</b>									
78-00-00	LH ENGINE EXHAUST ASSEMBLY  PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
78-00-00	RH ENGINE EXHAUST ASSEMBLY  PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		
<b>CHAPTER 79 OIL</b>									
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR  APTE-478A-1000-270D 00107 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR APTE-478A-1000-270D 00125 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-SEP-2011 0 0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0064 Part # A3072913-01									
+ 79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) 3052640-01 05858039 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER  REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
79-20-01-960-801	NO. 1 ENGINE - DISCARD THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%	-6.8		14-APR-2019 1206.8	(1800) 1800 1860	
+ 79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP COLLECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-30-01-212-801	NO. 1 ENGINE - EXAMINE THE CHIP DETECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units





# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-01-770-801 (s)	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
79-30-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
79-30-03-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-30-20-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
790000	NO. 1 ENGINE - OIL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		
790020	NO. 1 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				29-OCT-2014		
792010	NO. 1 ENGINE - TEMPERATURE SENSOR ATS-9-800 5-18-10-5 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-01 05858039 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
793005	NO. 1 ENGINE - OIL CHIP COLLECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
793010	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1205 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
793020	NO. 1 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-SEP-2010 0 0		
<b>ENGINE NO. 2 Model : PW535E Serial # PCE-DG0063 Part # A3072913-01</b>									
+ 79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) 3052640-01 05858034 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time \*-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER  REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
79-20-01-960-801	NO. 2 ENGINE - DISCARD THE OIL FILTER  PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%	-6.8		14-APR-2019 1206.8	(1800) 1800	1860
+ 79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP COLLECTOR  PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 79-30-01-212-801	NO. 2 ENGINE - EXAMINE THE CHIP DETECTOR  PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
79-30-01-770-801 (s)	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR  PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
79-30-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH  PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 800	+30d +10%			PKG 05-MAY-2020 1528.2 990		
79-30-03-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP  PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-30-20-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
790000	NO. 2 ENGINE - OIL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		
790020	NO. 2 ENGINE - CHANGE OIL  REF: See Workcard	MOS HRS/MSC ENC	A/R				29-OCT-2014		
792010	NO. 2 ENGINE - TEMPERATURE SENSOR ATS-9-800 5-18-10-7 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-01 05858034 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		
793005	NO. 2 ENGINE - OIL CHIP COLLECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		
793010	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR 3052535-02 HA1148 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		21-SEP-2010 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793020	NO. 2 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			21-SEP-2010 0 0		
<b>CHAPTER -- GENERAL</b>									
Z210-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z210-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 29-MAY-2015 633.3 448		
Z220-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
Z220-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 87 REF: AMM 05-41-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z230-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION PKG 84 REF: AMM 05-42-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 21-SEP-2011 0 0		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z230-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-42-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z240-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION PKG 87 REF: AMM 05-42-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z240-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION PKG 84 REF: AMM 05-42-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 21-SEP-2011 0 0		
Z310-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z310-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z320-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z320-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION PKG 87 REF: AMM 05-43-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 29-MAY-2015 633.3 448		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z330-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z330-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z340-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER PKG 84 REF: AMM 05-44-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 21-SEP-2011 0 0		
Z340-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 87 REF: AMM 05-44-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z410-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z410-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 21-SEP-2011 0 0		
Z430-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 25-MAY-2012 105.4 86		



# Status Report

EMB-505 - PHENOM 300 S/N 50500037 (N312FL): 1676.7 HRS, 1083 AFL as of 22-Sep-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 05-OCT-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z430-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE PKG 87 REF: AMM 05-46-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 29-MAY-2015 633.3 448		
Z500-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS PKG 87 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
Z500-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS PKG 87 REF: AMM 05-45-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		
Z700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY PKG 87 REF: AMM 05-47-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 29-MAY-2015 633.3 448		