



Status Report

PC-12/47E S/N 1828 N151MV

OWNER: LATITUDE 33 AVIATION, LLC
ADDRESS: 2056 PALOMAR AIRPORT ROAD
 CARLSBAD CA 92011
PHONE:
FAX: 760-278-2168

OPERATOR: LATITUDE 33 AVIATION, LLC
ADDRESS: 2056 PALOMAR AIRPORT ROAD
 CARLSBAD CA 92011
PHONE:
FAX: 760-278-2168

ANALYST: DAVID VALENCIA
EMAIL: DVALENCIA@CAMPSYSTEMS.COM

+1-631-619-4509 (DIRECT)
 877-411-CAMP (2267) (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 1828/N151MV **MODEL:** PC-12/47E **MANUFACTURER:** PILATUS AIRCRAFT LTD

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	23-OCT-2018	104 A/C HRS	as of 11-AUG-2020	A/C HRS	as of ___/___/___
MANUFACTURER DATE:	31-OCT-2018	79 AFL	as of 11-AUG-2020	AFL	as of ___/___/___
		0 ACH	as of 07-JAN-2020	ACH	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-RY0904/3072955-01 **MODEL:** PT6A-67P **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 27-SEP-2018		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	104 ENG. HRS	as of 11-AUG-2020	ENG. HRS	as of ___/___/___
0 ENC		79 ENC	as of 11-AUG-2020	ENC	as of ___/___/___

PROPELLER NOSERIAL/PART: SA338/HC-E5A-3A **MODEL:** HC-E5A-3A **MANUFACTURER:** HARTZELL PROPELLER INC.

INSTALLED ON 27-SEP-2018		LAST ACTUALS		CURRENT ACTUAL	
0 PROP HRS	0 A/C HRS	104 PROP HRS	as of 11-AUG-2020	PROP HRS	as of ___/___/___



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05200A	JOB SET UP / CLOSE UP PACKAGE							
	PKG 1 in PKG 2,3,4,5,6,7	MOS				24-OCT-2019	PKG	
	REF: AMM 05-20-00	HRS/MSC AFL	A/R			61.5 53		
05401A	300 HOUR INSPECTION							
+	PKG 2	MOS				24-OCT-2019		
	REF: AMM 05-40-01	HRS/MSC AFL	300	+30/-30		61.5 53	361.5	391.5
05402A	300 HOUR OR 12 MONTHS INSPECTION							
+	PKG 3	MOS	12		-1	24-OCT-2019	31-OCT-2020	
	REF: AMM 05-40-01	HRS/MSC AFL	300	+30/-30		61.5 53	361.5	391.5
05403A	600 HOUR INSPECTION							
+	PKG 4	MOS				24-OCT-2019		
	REF: AMM 05-40-01	HRS/MSC AFL	600	+60/-60		61.5 53	661.5	721.5
05404A	600 HOUR OR 12 MONTHS INSPECTION							
+	PKG 5	MOS	12		-1	24-OCT-2019	31-OCT-2020	
	REF: AMM 05-40-01	HRS/MSC AFL	600	+60/-60		61.5 53	661.5	721.5



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05405A	1200 HOUR OR 12 MONTH INSPECTION							
+								
	PKG 6	MOS	12			24-OCT-2019	31-OCT-2020	
		HRS/MSC	1200	+120/-120	-1	61.5	1261.5	1381.5
	REF: AMM 05-40-01	AFL				53		
<hr/>								
05406A	2400 HOUR OR 24 MONTHS INSPECTION							
+								
	PKG 7	MOS	24	+1m/-1m		23-OCT-2018	31-OCT-2020	23-NOV-2020
		HRS/MSC	2400	+60/-60		0	2400	2460
	REF: AMM 05-40-01	AFL				0		
<hr/>								
ENGINE NO. 1 Model : PT6A-67B/-67P Serial # PCE-RY0904 Part # 3072955-01								
057010	NO. 1 ENGINE - MINOR INSPECTION							
+								
	PKG 2	MOS				24-OCT-2019		
		HRS/MSC	300	+10%/-10%		61.5	(361.5) 361.5	391.5
	REF: See Workcard	ENC				53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
+ 00-00/121	CHECK AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS REVIEWED AND COMPLIED WITH AS REQUIRED						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
		HRS/MSC	A/R				61.5		
	REF: GENERIC NO REF	AFL					53		
+ 00-00/122	CHECK CHAPTER 4 AND CHAPTER 5 - OVERHAUL AND REPLACEMENT SCHEDULE AND TIME LIMITED INSPECTION REQUIREMENTS DMS REVIEWED AND ANY ADDITIONAL REQUIREMENTS ARE COMPLIED WITH						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
		HRS/MSC	A/R				61.5		
	REF: GENERIC NO REF	AFL					53		
00-00/481 (s)	CHECK AIRCRAFT FLIGHT MANUAL IS AT THE LATEST REVISION						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
		HRS/MSC	A/R				61.5		
	REF: GENERIC NO REF	AFL					53		
P47E-180917	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL TEMPORARY REVISION NO. 05-05								
		MOS							
		HRS/MSC	-						
	REF: RCF P47E	AFL							
	REQUIREMENT CHANGE FORMS								
P47E-181129	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 20								
		MOS					(EBT)		
		HRS/MSC	-						
	REF: RCF P47E	AFL							
	REQUIREMENT CHANGE FORMS								
P47E-190503	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 21								
		MOS					(EBT)		
		HRS/MSC	-						
	REF: RCF P47E	AFL							
	REQUIREMENT CHANGE FORMS								



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
P47E-191121	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 22	MOS						23-OCT-2018	
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL						0 0	
P47E-200515	REVIEW PC-12/47E AIRCRAFT MAINTENANCE MANUAL REVISION 23	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF P47E	HRS/MSC - AFL							
CHAPTER 04 LIMITATIONS									
+ 040001	AIRCRAFT LIMIT OF VALIDITY								
LIFE LIMIT	PN	MOS		N:0				23-OCT-2018	
	SN-UNKNOWN	HRS/MSC	50000	N:0				0	50000
	REF: GENERIC NO REF	AFL	60000	N:0				0	60000
+ 040005	AIRCRAFT LEFT WING STRUCTURE LIMIT OF VALIDITY								
LIFE LIMIT	PN	MOS		N:0				23-OCT-2018	
	SN-UNKNOWN	HRS/MSC	35000	N:0				0	35000
	REF: GENERIC NO REF	AFL	43000	N:0				0	43000
+ 040005	AIRCRAFT RIGHT WING STRUCTURE LIMIT OF VALIDITY								
LIFE LIMIT	PN	MOS		N:0				23-OCT-2018	
	SN-UNKNOWN	HRS/MSC	35000	N:0				0	35000
	REF: GENERIC NO REF	AFL	43000	N:0				0	43000
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
05-50-01	UNSCHEDULED INSPECTION - CHECK AFTER A HARD LANDING								
		MOS						23-OCT-2018	
		HRS/MSC	A/R					0	
	REF: See Workcard	AFL						0	



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-02	UNSCHEDULED INSPECTION - CHECK AFTER FLIGHT IN SEVERE TURBULENCE OR AFTER SEVERE MANEUVERS	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-03	UNSCHEDULED INSPECTION - CHECK AFTER OVERSPEED WITH FLAPS DOWN	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-04	UNSCHEDULED INSPECTION - CHECK AFTER PROPELLER SUDDEN STOPPAGE OR IMPACT	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-05	UNSCHEDULED INSPECTION - CHECK AFTER A LIGHTNING STRIKE	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-06	UNSCHEDULED INSPECTION - CHECK ALIGNMENT AND SYMMETRY	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-07	GEOMETRY INSPECTION - CHECK FUSELAGE CARRY THRU FRAMES	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-08	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM OPERATING SPEED (VMO/MMO) EXCEEDANCE	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-50-09	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR OPERATING SPEED (VLO) EXCEEDENCE	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-10	UNSCHEDULED INSPECTION - CHECK AFTER MAXIMUM LANDING GEAR EXTENDED SPEED (VLE) EXCEEDENCE	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-11	UNSCHEDULED INSPECTION - TAIL DOWN DAMAGE	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-50-15	UNSCHEDULED INSPECTION - AFTER A FLIGHT THROUGH VOLCANIC ASH OR SMOKE	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
+ 050001	SUPPLEMENTAL STRUCTURAL INSPECTION DOCUMENT (SSID)	MOS					23-OCT-2018		
	REF: AMM 05-10-30	HRS/MSC	N/A				0		
		AFL					0		
+ 050005	AIRCRAFT REGISTRATION - FAR 47.40	MOS					23-OCT-2018	30-NOV-2021 M	
	REF: GENERIC NO REF	HRS/MSC	DUE				0		
		AFL					0		
+ 050010	SUPPLEMENTAL CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) INSPECTION	MOS					23-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC	25000				0	25000	
		AFL	30000				0	30000	

CHAPTER 06 DIMENSIONS AND AREAS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 06-00/119	INSTALL ACCESS PANELS 42AB, 42AT AND 32CT AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,2,3,4,5,6,7 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 06-00/123	REMOVE ACCESS PANELS 42AB, 42AT AND 32CT PKG 1 ,2,3,4,5,6,7 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 06-00/218	OPEN /REMOVE AS NECESSARY TO DO INSPECTION, PANELS 11AL, 11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR, 12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB. MAKE SURE THE ACCESS PANEL DRAIN HOLES ARE CLEAR. PKG 1 ,2,3,4,5,6,7 REF: AMM 06-20-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 06-00/219	CLOSE /INSTALL AS NECESSARY TO CLOSE UP THE INSPECTIOIN THE FOLLOWING PANELS: 11AL,11AR, 11BL, 11BR, 12AZ, 12AB, 12BB, 12BL, 12BR, 12BZ, 12CL, 12CR,12CZ, 12DL, 12DR, 12DZ, 12EL, 12ER, 12EZ, 12FZ, 12HZ, 21GZ, 21JZ, 21PZ, 21QZ, 31AB, 31AL, 31BL, 32AB, 32AL, 32BL, 32BT, 32CL, 33ET, 41AT, 42AT, 42AB, 51KB, 51MB, 51NB, 52KB, 52MB, 52NB, 52OB, 52PB, 52RB, 52TB, 52SB, 61KB, 61MB, 61NB, 62KB, 62MB, 62NB, 62OB, 62PB, 62RB, 62SB, 62TB PKG 1 ,2,3,4,5,6,7 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
CHAPTER 07 LIFTING AND SHORING									
+ 07-10/160	LOWER AIRCRAFT TO THE GROUND, REMOVE JACKS AND DISCONNECT FROM GROUND AS NECESSARY TO CLOSE UP THE INSPECTION PKG 1 ,2,3,4,5,6,7 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 07-10/161	LIFT AIRCRAFT ON JACKS AND CONNECT THE AIRCRAFT TO GROUND AS NECESSARY TO DO THE INSPECTION PKG 1 ,2,3,4,5,6,7 REF: AMM 07-10-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 08 LEVELING AND WEIGHING									
+ 080000	WEIGHT CHECK AIRCRAFT								
08.005		MOS					23-OCT-2018		
	REF: AMM 08-10-00	HRS/MSC	A/R				0		
		AFL					0		
CHAPTER 10 PARKING, MOORING, STORE AND RET TO SERV									
+ 10-10/428 (s)	EXAMINE EXTERNAL PROTECTIVE COVERS - REPLACE IF ANY PART OF THE COVER IS MISSING, DAMAGED, TORN OR DOES NOT INSTALL PROPERLY.						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			61.5		
		AFL					53		
CHAPTER 11 PLACARDS AND MARKINGS									
+ 11-00/220 (s)	EXAMINE PLACARDS AND MARKINGS AND ATTACH NEW PLACARDS IF NECESSARY						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
	REF: See Workcard	HRS/MSC	1200	+10%/-10%			61.5		
		AFL					53		
CHAPTER 12 SERVICING									
+ 12-20/124	WASH AIRCRAFT THE EXTERIOR, INCLUDING THE LANDING GEAR AND FLAP COMPARTMENTS, AS REQUIRED TO PERFORM THE INSPECTION						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
	REF: AMM 12-20-01	HRS/MSC	A/R				61.5		
		AFL					53		
+ 12-20/125	CLEAN WINDSHIELDS AND WINDOWS						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
	REF: AMM 12-20-02	HRS/MSC	A/R				61.5		
		AFL					53		
+ 12-20/126	CLEAN COCKPIT AND CABIN						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
	REF: AMM 12-20-03	HRS/MSC	A/R				61.5		
		AFL					53		
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 00-00/45A	PERFORM CORROSION INSPECTION (INTERNAL)								
20.010	REF: AMM 20-40-00	MOS HRS/MSC AFL	12	+1m/-1m		7	24-OCT-2019 61.5 53	31-OCT-2020	30-NOV-2020
+ 00-00/45B	PERFORM CORROSION INSPECTION (EXTERNAL)								
20.011	REF: AMM 20-40-00	MOS HRS/MSC AFL	6	+10%/-10%		-32	03-JUN-2020 103.6 77	30-NOV-2020	30-NOV-2020
CHAPTER 21 AIR CONDITIONING									
+ 21-20/221 (s)	ECS AND BLEED AIR DUCTS, PIPELINES, EQUIPMENT AND ASSOCIATED CLAMPS IN THE ENGINE COMPARTMENT - EXAMINE						PKG		
	PKG 7	MOS HRS/MSC AFL	24	+10%/-10%			23-OCT-2018 0 0		
	REF: GENERIC NO REF		2400	+10%/-10%					
+ 21-20/317	ECS EMERGENCY SHUT-OFF SYSTEM - CHECK								
		MOS HRS/MSC AFL	12	+10%/-10%		-1	24-OCT-2019 61.5 53	31-OCT-2020 3061.5	29-NOV-2020
AIRWORTHINESS	REF: GENERIC NO REF		3000						
+ 21-30/314	PRESSURIZATION SAFETY VALVE - CHECK FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND								
21.030	PN SN-UNKNOWN REF: AMM 21-30-02	MOS HRS/MSC AFL	N/A				31-OCT-2018 0		
+ 21-30/318	OPERATIONAL TEST PRESSURIZATION DUMP SWITCH								
21.045	REF: AMM 21-30-00	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-30/46	FUNCTIONAL TEST CABIN POSITIVE PRESSURE RELIEF								
21.040	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	N/A				31-OCT-2018 0		
+ 21-30/463	OPERATIONAL TEST CABIN PRESSURIZATION DUMP CONTROL								
	REF: AMM 21-30-00	MOS HRS/MSC AFL	12 600	+10%/-10%	-1		24-OCT-2019 61.5 53	31-OCT-2020 661.5	29-NOV-2020
+ 21-30/464	OPERATIONAL TEST CABIN PRESSURIZATION MANUAL CONTROL								
	REF: AMM 21-30-00	MOS HRS/MSC AFL	12 600	+10%/-10%	-1		24-OCT-2019 61.5 53	31-OCT-2020 661.5	29-NOV-2020
+ 21-30/465	FUNCTIONAL TEST CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE								
	REF: AMM 21-30-00	MOS HRS/MSC AFL	48 4800	+10%/-10%			23-OCT-2018 0 0	31-OCT-2022 4800	17-MAR-2023
+ 21-30/466 (s)	CHECK CABIN PRESSURIZATION POSITIVE PRESSURE RELIEF VALVE FOR CONTAMINATION OF THE VALVE POPPET AND POPPET SEAT, REMOVE AND CLEAN IF CONTAMINATION IS FOUND								
	PKG 7 REF: AMM 21-30-02	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			23-OCT-2018 0 0		
+ 21-30/467	EXAMINE CABIN PRESSURIZATION NEGATIVE PRESSURE RELIEF VALVE								
	REF: AMM 21-30-05	MOS HRS/MSC AFL	48 4800	+10%/-10% +10%/-10%			23-OCT-2018 0 0	31-OCT-2022 4800	17-MAR-2023 5280
+ 21-30/468	FUNCTIONAL TEST CABIN PRESSURIZATION ALTITUDE LIMITING FUNCTION								
	REF: AMM 21-30-00	MOS HRS/MSC AFL	48 4800				23-OCT-2018 0 0	31-OCT-2022 4800	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-30/469	FUNCTIONAL TEST CABIN PRESSURIZATION HIGH CABIN ALTITUDE WARNING								
		MOS	48				23-OCT-2018	31-OCT-2022	
		HRS/MSC	4800				0	4800	
	REF: AMM 21-30-00	AFL					0		
+ 21-40/128 (s)	OPERATIONAL TEST FLIGHT COMPARTMENT FOOT HEATER (IF INSTALLED) THERMAL PROTECTION SWITCH								
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: See Workcard	AFL					53		
+ 21-40/330 (s)	OPERATIONAL TEST CABIN AUXILIARY HEATER THERMAL PROTECTION SWITCH								
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
21.140		HRS/MSC	1200	+10%/-10%			61.5		
	REF: See Workcard	AFL					53		
+ 21-40/331 (s)	FUNCTIONAL TEST UNDERFLOOR (FRONT) ELECTRIC HEATER UNDERFLOOR HEATER THERMAL PROTECTION SWITCH								
	969.67.81.507 PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
21.150	590758	HRS/MSC	1200	+10%/-10%			61.5		
	REF: See Workcard	AFL					53		
+ 21-40/50 (s)	CLEAN WATER SEPARATOR CONDENSER								
	PN PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
21.080	SN-UNKNOWN	HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 21-40-03	AFL					53		
+ 21-40/51	FUNCTIONAL TEST OVERTEMP. BLEEDAIR 1173T083-01 SWITCH OVERTEMPERATURE SWITCH								
	973.81.32.216	MOS	60	+10%/-10%			31-OCT-2018	31-OCT-2023	30-APR-2024
21.130	1286	HRS/MSC	4800	+10%/-10%			0	4800	5280
	REF: AMM 21-40-06	AFL							
+ 21-40/52	FUNCTIONAL TEST OVERTEMP. CONDAIR 1173T08 SWITCH DUCT OVERTEMPERATURE SWITCH								
	973.81.32.214	MOS	60	+10%/-10%			23-OCT-2018	31-OCT-2023	23-APR-2024
21.120	1193	HRS/MSC	4800	+10%/-10%			0	4800	5280
	REF: AMM 21-60-05	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-40/55 (s)	RE-OIL AIR CONDITIONING COLD AIR UNIT						PKG		
21.060	PKG 4	MOS					24-OCT-2019		
	REF: See Workcard	HRS/MSC	600	+10%/-10%			61.5		
		AFL					53		
+ 21-40/56 (s)	INSPECT/CHECK HEAT EXCHANGER MATRIX						PKG		
21.070	PKG 4	MOS					24-OCT-2019		
	REF: AMM 21-40-02	HRS/MSC	600	+10%/-10%			61.5		
		AFL					53		
+ 21-50/223 (s)	EXAMINE VAPOR CYCLE COOLING SYSTEM (IF INSTALLED) THE COOLING UNIT						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%			61.5		
		AFL					53		
+ 21-50/433	CLEAN AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (INCLUDING MOTOR) (IF INSTALLED)								
	959.90.22.140	MOS	12	+1m/-1m		-1	24-OCT-2019	31-OCT-2020	23-NOV-2020
	2216	HRS/MSC	300	+10%/-10%			61.5	361.5	391.5
	REF: AMM 21-40-03	AFL					53		
+ 21-50/461	INSPECT/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CCM P/N 959.90.22.140) (IF INSTALLED)								
	959.90.22.140	MOS					23-OCT-2018		
	2216	HRS/MSC					0		
	REF: AMM 21-50-03	AFL					0		
		ACH	600	+10%/-10%			0	600	660
+ 21-50/462	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE BELT TENSION (CCM P/N 959.90.22.140) (IF INSTALLED)								
	959.90.22.140	MOS					23-OCT-2018		
	2216	HRS/MSC					0		
	REF: AMM 21-50-01	AFL					0		
		ACH	600	+10%/-10%			0	600	660



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50/58	INSPECTION/CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE (CMM P/N 959.90.22.102, 959.90.22.106) (IF INSTALLED)								
21.110	959.90.22.140 2216 REF: AMM 21-50-03	MOS HRS/MSC AFL ACH	N/A				0		
+ 21-50/59	CHECK AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE TENSION OF VAPOR CYCLE COMPRESSOR MOTOR DRIVE BELT (CMM P/N 959.90.22.102, 959.90.22.106) IF INSTALLED								
21.100	959.90.22.140 2216 REF: AMM 21-50-01	MOS HRS/MSC AFL ACH	N/A				0		
210005	OVERPRESSURE SWITCH								
21.340	973.81.15.105 1675 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210010	REFRIGERATION PACK								
21.255	959.90.20.111 2305 REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210015	WATER INJECTOR								
21.370	959.90.20.141 2259 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210020	DUCT TEMP SENSOR								
21.320	959.90.20.121 5305 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210025	PRIM SHUT OFF VALVE								
21.290	959.90.20.132 2278 REF: AMM 21-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210030	HP SHUT OFF VALVE								
21.280	959.90.20.131 2292 REF: AMM 21-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210040	TEMPCONTROL VALVE								
21.310	959.90.20.137 2292 REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210045	AIR-CONDITIONING - COMPRESSOR/CONDENSER MODULE								
21.380	959.90.22.140 2216 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210050	CENTER EVAPORATOR MODULE ASSY								
21.200	959.90.22.121 1167 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210055	RIGHT SIDE EVAPORATOR MODULE ASSY								
21.210	959.90.22.119 1345 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210060	CABIN PRESSURE OUTFLOW VALVE								
21.250	959.90.91.125 65053598-00154 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210065	CABIN PRESSURE RELIEVE VALVE								
21.270	959.90.91.132 58-F0841 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210090	OUTFLOW VALVE CONTROLLER								
21.430	959.90.91.147 65000052-00156 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210115	UNDERFLOOR (FRONT) ELECTRIC HEATER								
21.240	969.67.81.507 590758 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210135	LEFT SIDE EVAPORATOR MODULE ASSY								
21.200	959.90.22.118 1290 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210145	CABIN (REAR) ELECTRIC HEATER								
21.230	969.67.81.507 590766 REF: AMM 21-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210170	OVERPRESSURE SWITCH								
21.340	973.81.15.106 1682 REF: AMM 21-40-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210175	FLOW CONTROL VALVE ACTUATOR								
21.520	959.90.20.162 1914 REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210185	INTEG. ECS CONTROL UNIT								
21.540	959.90.20.129 0884 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210190	FLOOR DUCT TEMP. SENSOR								
21.550	959.90.20.121 5310 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210195	MIDDLE CONSOLE DUCT TEMP. SENSOR								
21.560	959.90.20.121 5308 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210200	FIREWALL 1415-3 SHUT OFF VALVE								
21.570	963.30.11.005 1106 REF: AMM 21-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210205	OVERTEMP. BLEEDAIR 1173T083-01 SWITCH								
21.580	973.81.32.216 1286 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210210	OVERTEMP. CONDAIR 1173T08 SWITCH								
21.590	973.81.32.214 1193 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210215	DUAL FLAPPER 1.5 IN. VALVE CHECK								
21.490	963.30.11.105 1759B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
210220	LH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	963.30.11.106 3169B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210225	RH DUAL FLAPPER 2.5 IN. VALVE CHECK								
21.500	963.30.11.106 3171B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210230	DUAL FLAPPER 2.5 IN. SPANT 15 VALVE CHECK								
21.510	963.30.11.106 3137B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
210235	HEAD LINER DUCT TEMP. SENSOR								
21.600	959.90.20.121 5299 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

CHAPTER 22		AUTO FLIGHT							
+ 22-10/233 (s)	EXAMINE PITCH, ROLL, AND YAW ACTUATORS AND CAPSTAN CONTROL CABLES								PKG
	PKG 7	MOS	24	+10%/-10%				23-OCT-2018	
		HRS/MSC	2400	+10%/-10%				0	
	REF: GENERIC NO REF	AFL						0	
+ 22-10/60	SERVO MOUNT (PITCH) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		7		24-OCT-2019	31-OCT-2020
		HRS/MSC	1000	+10%/-10%				61.5	1061.5
	REF: AMM 22-10-00	AFL						53	1161.5
+ 22-10/60	SERVO MOUNT (ROLL) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		7		24-OCT-2019	31-OCT-2020
		HRS/MSC	1000	+10%/-10%				61.5	1061.5
	REF: AMM 22-10-00	AFL						53	1161.5

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 22-10/60	SERVO MOUNT (YAW) - REMOVE FOR CLUTCH CHECK								
		MOS	12	+1m/-1m		7	24-OCT-2019	31-OCT-2020	30-NOV-2020
		HRS/MSC	1000	+10%/-10%			61.5	1061.5	1161.5
	REF: AMM 22-10-00	AFL					53		
+ 22-20/129 (s)	EXAMINE ANGLE OF ATTACK (AOA) TRANSMITTERS								
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 22-20-02	AFL					53		
+ 22-20/130 (s)	CHECK STICK PUSHER SYSTEM								
	PKG 2	MOS					24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 22-20-00	AFL					53		
+ 22-20/226 (s)	FUNCTIONAL TEST STICK PUSHER SYSTEM								
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 22-20-00	AFL					53		
220045	STICK PUSHER SERVO								
	978.61.11.103	MOS					23-OCT-2018		
22.220	81183	HRS/MSC	O/C				0		
	REF: AMM 22-20-04	AFL					0		
220055	STICK PUSHER CAPSTAN								
	978.61.11.124	MOS					23-OCT-2018		
22.140	81117	HRS/MSC	O/C				0		
	REF: AMM 22-20-06	AFL					0		
220060	STICK SHAKER								
	978.61.11.143	MOS					23-OCT-2018		
22.230	1699	HRS/MSC	O/C				0		
	REF: AMM 22-20-03	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220070	STICK PUSHER								
22.170	975.44.23.104 138866 REF: AMM 22-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
220085	ELEVATOR KSM 375 A/P SERVO MOUNT								
22.280	985.99.12.133 KSM375-B3715 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
220090	RUDDER KSM 375 A/P SERVO MOUNT								
22.280	985.99.12.133 KSM375-B3711 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
220095	AILERON KSM 375 A/P SERVO MOUNT								
22.280	985.99.12.133 KSM375-B3710 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
220100	RUDDER KSA 2700 SERVO								
22.260	985.99.12.275 KSA2700-3766 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
220105	ELEVATOR KSA 2700 SERVO								
22.250	985.99.12.275 KSA2700-3770 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
220110	AILERON KSA 2700 SERVO								
22.240	985.99.12.275 KSA2700-3760 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
220115	KMC 9200 VNAV FLIGHT CONTROLLER								
	985.99.12.204	MOS		N:0			23-OCT-2018		
	KMC9200-2136	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 23 COMMUNICATIONS									
+ 23-10/322 (s)	OPERATIONAL TEST AUDIO CONTROL PANEL EMERGENCY SWITCH						PKG		
	PKG 7	MOS	24	+10%/-10%			23-OCT-2018		
		HRS/MSC	2400	+10%/-10%			0		
	REF: AMM 23-50-00	AFL					0		
+ 23-10/323 (s)	OPERATIONAL TEST EMERGENCY FREQUENCY COMM TUNING SWITCH						PKG		
	PKG 7	MOS	24	+10%/-10%			23-OCT-2018		
		HRS/MSC	2400	+10%/-10%			0		
	REF: AMM 23-12-00	AFL					0		
230005	VHF/NAV SYSTEM I VHF COMM ANTENNA								
	984.81.10.203	MOS		N:0			23-OCT-2018		
23.020	310-32088	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-02	AFL		N:0			0		
230010	VHF/NAV SYSTEM II VHF COMM ANTENNA								
	984.81.10.203	MOS		N:0			23-OCT-2018		
23.030	310-32087	HRS/MSC	O/C	N:0			0		
	REF: AMM 23-12-03	AFL		N:0			0		
230035	CONTROL DISPLAY PS440 UNIT								
	985.99.11.914	MOS		N:0			23-OCT-2018		
23.060	42798	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
230040	IRIDIUM/GPS,S67-1575-109 ANTENNA								
	984.81.10.210	MOS		N:0			23-OCT-2018		
23.070	430-12878	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-57-02	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
230045	NO. 1 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.090	985.99.12.277 4014 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
230050	NO. 2 KTR 2280 MULTI-MODE DIGITAL RADIO								
23.080	985.99.12.277 6008 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
230055	PILOT KMA 29 AUDIO/MARKER PANEL								
23.100	985.99.12.020 Q02343 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
230060	CO-PILOT KMA 29 AUDIO/MARKER PANEL								
23.110	985.99.12.020 Q02349 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
230061	HF ANTENNA ,KAC1052 COUPLER								
	985.99.11.946 KAC1052-8610 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
230063	HF POWER ,KPA1052 AMPLIFIER								
	985.99.11.942 KPA1052-8486 REF: AMM 23-11-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
230065	HF RECEIVER/,KRX1053 EXCITER								
	985.99.11.954 KRX1053-9081 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

CHAPTER 24 ELECTRICAL POWER

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/309	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.437)								
24.210	978.91.23.407 P2785 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 24-30/310	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.437)								
24.026	978.91.23.407 P2786 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 24-30/311	FUNCTIONAL TEST NO. 1 (GCU 1) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.015 AIRWORTHINESS	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-1	24-OCT-2019 61.5 53	31-OCT-2020 3061.5	29-NOV-2020
+ 24-30/311	FUNCTIONAL TEST NO. 2 (GCU 2) GENERATOR CONTROL UNIT OVER AND UNDER-VOLTAGE TRIP PROTECTION								
24.025 AIRWORTHINESS	PN SN-UNKNOWN REF: AMM 71-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-1	24-OCT-2019 61.5 53	31-OCT-2020 3061.5	29-NOV-2020
+ 24-30/312 (s)	EMERGENCY POWER CONTROLLER - OVER/UNDER VOLTAGE TRIP PROTECTION OPERATIONAL TEST								
	PKG 7 REF: AMM 24-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 23-OCT-2018 0 0		
+ 24-30/313 (s)	DC ELECTRICAL SYSTEM - FUNCTIONAL TEST								
	PKG 6 REF: AMM 71-00-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 24-30/339	REMOVE AND SERVICE NO. 1 NICAD BATTERY								
24.060	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-30/339	REMOVE AND SERVICE NO. 2 NICAD BATTERY								
24.061	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 24-30/340	REMOVE/CAPACITY CHECK NO. 1 LEAD ACID BATTERY								
24.010	RG380E/44 40960517 REF: See Workcard	MOS HRS/MSC AFL	6 600	+10%/-10% +10%/-10%			03-JUN-2020 103.6 77	31-DEC-2020 703.6	31-DEC-2020 763.6
+ 24-30/340	REMOVE/CAPACITY CHECK NO. 2 LEAD ACID BATTERY								
24.010	RG380E/44 40960609 REF: AMM 24-30-07	MOS HRS/MSC AFL	6 600	+10%/-10% +10%/-10%			03-JUN-2020 103.6 77	31-DEC-2020 703.6	31-DEC-2020 763.6
	05-10-25 AIRWORTHINESS								
+ 24-30/473 (s)	BRUSH CHECK NO. 1 STARTER GENERATOR (P/N 978.91.23.407)								
	978.91.23.407 PKG 4 P2785 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 24-30/474 (s)	BRUSH CHECK NO. 2 STARTER-GENERATOR (P/N 978.91.23.407)								
	978.91.23.407 PKG 4 P2786 REF: AMM 24-30-01	MOS HRS/MSC AFL	600	+10%/-10%			PKG 24-OCT-2019 61.5 53		
24-30/492	OVERHAUL NO. 1 STARTER GENERATOR								
	978.91.23.407 P2785 REF: AMM 05-10-10	MOS HRS/MSC AFL	1200	+10%/-10%			23-OCT-2018 0 0	1200	1320
	OVERHAUL								



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30/493	OVERHAUL NO. 2 STARTER GENERATOR 978.91.23.407 P2786 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+10%/-10%			23-OCT-2018 0 0	1200	1320
24-30/496	OVERHAUL NO. 1 STARTER GENERATOR 978.91.23.407 P2785 REF: AMM 05-10-10	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
24-30/497	OVERHAUL NO. 2 STARTER GENERATOR 978.91.23.407 P2786 REF: AMM 24-30-01	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 24-40/229 (s)	EXAMINE EXTERNAL POWER UNIT (EPU) RECEPTACLE PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			23-OCT-2018 0 0		
+ 24-50/70 24.050	REMOVE/CAPACITY CHECK EMERGENCY POWER SUPPLY 501-1712-02 83836 REF: AMM 24-52-51	MOS HRS/MSC AFL	12	+10%/-10%			24-OCT-2019 61.5 53	31-OCT-2020	30-NOV-2020
+ 24-60/133 (s)	EXAMINE COCKPIT CIRCUIT BREAKER PANELS AND SWITCH PANELS PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240005	STARTER/GENERATOR 1 VOLTAGE REGULATOR								
24.120	988.21.14.111 P4650 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
240010	GENERATOR 1 300A CONTACTOR								
24.130	974.03.38.113 914 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
240015	GENERATOR 2 300A CONTACTOR								
24.130	974.03.38.113 919 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
240135	NO. 1 LEAD ACID BATTERY								
24.010	RG380E/44 40960517 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:12 N:61.5 N:53			24-OCT-2019 61.5 53		
240140	NO. 2 LEAD ACID BATTERY								
24.010	RG380E/44 40960609 REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:12 N:61.5 N:53			24-OCT-2019 61.5 53		
243010	NO. 2 STARTER-GENERATOR								
24.215	978.91.23.407 P2786 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243020	NO. 1 (GCU 1) GENERATOR CONTROL UNIT								
24.015	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243030	NO. 2 (GCU 2) GENERATOR CONTROL UNIT								
24.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243080	EMERGENCY POWER SUPPLY								
24.050	501-1712-02 83836 REF: AMM 24-52-51	MOS HRS/MSC AFL	O/C				24-OCT-2019 61.5 53		
243100	NO. 1 NICAD BATTERY								
24.060	PN NOT INSTALLED REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243105	NO. 2 NICAD BATTERY								
24.061	PN NOT INSTALLED REF: AMM 24-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243160	NO. 1 STARTER GENERATOR								
24.205	978.91.23.407 P2785 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243170	110 VOLT STATIC ,SS50 INVERTER								
24.220	975.02.15.107 8077 REF: AMM 24-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243175	HALL EFFECT,FE1263 GEN 1 TRANSDUCER								
24.020	975.50.85.111 N4801 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243180	HALL EFFECT,FE1263 GEN 2 TRANSDUCER								
24.020	975.50.85.111 N4796 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
243190	VOLTAGE REGULATOR								
	988.21.14.111 P4665 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
+ 25-10/134 (s)	EXAMINE CREW SEAT BELTS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
	REF: AMM 25-10-01	HRS/MSC AFL	300	+10%/-10%			61.5 53		
+ 25-10/135 (s)	EXAMINE CREW SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED						PKG		
	PKG 2	MOS					24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			61.5 53		
+ 25-10/294	CO-PILOT SEAT BELT								
	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-10/294	CREW SEAT BELTS								
25.030	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 25-10/294	PILOT SEAT BELT								
	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-10/296	REMOVE CREW SEATS AS NECESSARY TO DO INSPECTION PKG 1 ,2,3,4,5,6,7 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 25-10/297	INSTALL CREW SEATS AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,2,3,4,5,6,7 REF: AMM 25-10-01	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 25-10/300 (s)	CREW SEATS - REMOVE CUSHIONS, COVERS AND SHELLS (REF. CMM) AND EXAMINE SEAT. INSTALL CUSHIONS, COVERS AND SHELLS. PKG 6 REF: AMM 25-10-01	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 25-20/136 (s)	EXAMINE PASSENGER SEAT BELTS AND EXTENSIONS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 25-20/137 (s)	EXAMINE PASSENGER SEATS - FOR EXECUTIVE SEATS ONLY, CHECK THE HYDROLOCK REAR ATTACHMENT BOLT FOR SECURITY OF ATTACHMENT PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 25-20/295	NO. 1 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-20/295	NO. 2 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 25-20/295	NO. 3 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 25-20/295	NO. 4 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 25-20/295	NO. 5 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 25-20/295	NO. 6 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
25-20/295	NO. 7 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
25-20/295	NO. 8 PASSENGER SEAT BELT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-20/295	PASSENGER SEAT BELTS								
25.010	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 25-20/298	REMOVE PASSENGER SEATS AS NECESSARY TO DO THE INSPECTION						PKG		
	PKG 1 ,2,3,4,5,6,7 REF: See Workcard	MOS HRS/MSC AFL	A/R				24-OCT-2019 61.5 53		
+ 25-20/299	INSTALL PASSENGER SEATS AS NECESSARY TO CLOSE UP INSPECTION						PKG		
	PKG 1 ,2,3,4,5,6,7 REF: See Workcard	MOS HRS/MSC AFL	A/R				24-OCT-2019 61.5 53		
+ 25-20/302 (s)	EXAMINE PASSENGER SEATS AS FAR AS POSSIBLE WITH SEATS INSTALLED. MOVE THE RECLINE MECHANISM AND SWIVEL FUNCTION (EXECUTIVE SEAT ONLY) THROUGH ITS FULL MOTION AND CHECK FOR CORRECT OPERATION.						PKG		
	PKG 2 REF: GENERIC NO REF	MOS HRS/MSC AFL	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 25-60/231 (s)	OPERATIONAL TEST ELT						PKG		
	985.13.80.882 PKG 3 LX1100691916 REF: See Workcard	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 25-60/232 (s)	EXAMINE ELT INSTALLATION						PKG		
	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
25-60/483	PERFORM EMERGENCY LOCATOR TRANSMITTER PERIODIC INSPECTION ON KANNAD 406 AF ELT. IF INSTALLED								
	985.13.80.882 LX1100691916 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-63/23	ELT BATTERY								
	PN-UNKNOWN	MOS		N:0				01-JUN-2024	M
25.020	SN-UNKNOWN	HRS/MSC	DUE	N:0					
DISCARD	REF: GENERIC NO REF	AFL		N:0					
<hr/>									
+ 25-63/434	DISCARD ELT NAV INTERFACE UNIT SERIAL MEMORY MODULE (IF KANNAD 406 AF NAV INTERFACE UNIT INSTALLED)								
	985.13.80.881	MOS	120	+6m/-6m			23-OCT-2018	31-OCT-2028	23-APR-2029
	LX1100635693	HRS/MSC	16000	+500/-500			0	16000	16500
DISCARD	REF: GENERIC NO REF	AFL					0		
<hr/>									
+ 25-63/477	CLEAN UNDERWATER LOCATOR BEACON (IF INSTALLED)								
	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 25-63-04	AFL					0		
<hr/>									
+ 25-63/478	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON (IF INSTALLED)								
	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 25-63-04	AFL					0		
<hr/>									
+ 25-63/479	FUNCTIONAL TEST UNDERWATER LOCATOR BEACON BATTERY VOLTAGE (IF INSTALLED)								
	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 25-63-04	AFL					0		
<hr/>									
+ 25-63/480	DISCARD UNDERWATER LOCATOR BEACON (IF INSTALLED)								
	PN	MOS					23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	N/A				0		
	REF: AMM 25-63-04	AFL					0		
<hr/>									
250005	REMOTE CONTROL PANEL								
	985.13.80.817	MOS		N:0			23-OCT-2018		
25.070	TM0000146623	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250010	EMERGENCY LOCATOR TRANSMITTER								
25.050	985.13.80.882 LX1100691916 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250021	L/H NO. 1 AFSS PASSENGER SEAT								
25.120	959.30.01.821 63887 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250022	R/H NO. 2 AFSS PASSENGER SEAT								
25.125	959.30.01.822 63888 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250023	L/H NO. 3 FFSS PASSENGER SEAT								
25.130	959.30.01.835 63889 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250024	R/H NO. 4 FFSS PASSENGER SEAT								
25.135	959.30.01.836 63890 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250025	L/H NO. 5 FFSS PASSENGER SEAT								
25.140	959.30.01.837 63891 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
250026	R/H NO. 6 FFSS PASSENGER SEAT								
25.145	959.30.01.838 63892 REF: AMM 25-21-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250027	L/H NO. 7 STANDARD PASSENGER SEAT								
25.150	525.22.12.011 2158 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250028	R/H NO. 8 STANDARD PASSENGER SEAT								
25.155	525.22.12.012 2186 REF: AMM 25-22-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
250630	KANNAD ELT NAV INTERFACE UNIT SERIAL MEMORY (IF KANNAD ELT NAV INTERFACE IS INSTALLED) MODULE								
25.060	985.13.80.881 LX1100635693 REF: AMM 25-63-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
256020	LH BLACK PILOT SEAT								
25.090	959.30.01.165 91857 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
256025	RH BLACK CO-PILOT SEAT								
25.100	959.30.01.166 91741 REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256050	UNDERWATER LOCATOR BEACON								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 25-63-04	AFL		N:0			0		
+ 258010	PERFORM EMERGENCY LOCATOR TRANSMITTER (ELT) 12-MONTHS INSPECTION - FAR 91.207 (D)								
		MOS	12				17-OCT-2019	31-OCT-2020	
25.110		HRS/MSC					61.5		
	REF: AMM 25-63-00	AFL					53		
+ 258020 (s)	RENEW NOAA 406 MHZ ELT REGISTRATION								
		MOS							
		HRS/MSC	DUE						
	REF: GENERIC NO REF	AFL							
CHAPTER 26	FIRE PROTECTION								
+ 26-20/2	CABIN FIRE EXTINGUISHER 1.5 KG								
	PN	MOS							
26.030	SN-UNKNOWN	HRS/MSC	N/A						
	REF: GENERIC NO REF	AFL							
+ 26-20/2	COCKPIT FIRE EXTINGUISHER								
	959.08.06.219	MOS	120	N:0			01-JUN-2018	30-JUN-2028	
26.010	109919	HRS/MSC		N:0					
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0					
	Manufacture Date: 01-JUN-2018								
+ 26-20/24	CABIN FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	N/A						
	REF: GENERIC NO REF	AFL							
+ 26-20/24	COCKPIT FIRE EXTINGUISHER CONTENTS CHECK (EXCEPT MODEL P3APP003010D - P/N 959.08.06.224)								
	959.08.06.219	MOS	12	+1m/-1m	7		24-OCT-2019	31-OCT-2020	30-NOV-2020
26.010	109919	HRS/MSC					61.5		
	REF: GENERIC NO REF	AFL					53		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
260005	FIRE/OVERHEAT DETECTOR									
26.020	975.12.10.012 216105 REF: AMM 26-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
CHAPTER 27 FLIGHT CONTROLS										
+ 27-00/138 (s)	AILERON, ELEVATOR AND RUDDER CONTROLS - OPERATE, MAKE SURE FULL AND FREE TRAVEL						PKG			
	PKG 2	MOS					24-OCT-2019			
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			61.5 53			
+ 27-00/402	EXAMINE - BONDING LEADS TO ALL FLIGHT CONTROL SURFACES									
27.255		MOS					23-OCT-2018			
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0			
+ 27-00/71	FLIGHT CONTROL CABLES INCLUDING AUTO PILOT AND STICK PUSHER CABLES - INSPECTION/CHECK									
27.010		MOS	60	+10%/-10%			31-OCT-2018	31-OCT-2023	30-APR-2024	
	REF: AMM 27-00-00	HRS/MSC AFL	4800	+10%/-10%			0	4800	5280	
+ 27-10/139 (s)	AILERON LH AND RH - EXAMINE AND LUBRICATE THE TRIM HINGES WITH MINIMUM QUANTITY OF CPC (MAT. NO. P10-001)						PKG			
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019			
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			61.5 53			
+ 27-10/234 (s)	AILERON LH AND RH RODS AND LEVERS - EXAMINE. SPRAY PTFE TEFLON SPRAY OKS 571 (OR EQUIVALENT) AROUND THE AILERON PUSHROD GUIDE ROLLER SLEEVES AT ALL THREE LOCATIONS IN EACH WING						PKG			
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019			
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53			
+ 27-10/235 (s)	EXAMINE AILERON ELECTRICAL BONDING STRAPS						PKG			
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019			
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53			



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/236 (s)	AILERON CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 27-10/237 (s)	CHECK AILERON CABLE TENSION						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 27-10-00	AFL					53		
+ 27-10/238 (s)	FUNCTIONAL TEST AILERONS						PKG		
	PKG 7	MOS	24	+10%/-10%			23-OCT-2018		
		HRS/MSC	2400	+10%/-10%			0		
	REF: AMM 27-10-00	AFL					0		
+ 27-10/394	AILERON CONTROL SYSTEM - EXAMINE								
27.155		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 27-10-00	AFL					0		
+ 27-10/395	EDDY CURRENT INSPECTION AILERON CABLE SEGMENT								
27.160		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 27-10-09	AFL					0		
+ 27-10/396	EDDY CURRENT INSPECTION - AILERON CONTROL RODS								
27.165		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 27-00-01	AFL					0		
+ 27-10/397	MAGNETIC PARTICLE INSPECT - AILERON CONTROL RODS								
27.170		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 27-00-01	AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10/398	AILERON BELLCRANKS - EDDY CURRENT AND MAGNETIC PARTICLE INSPECTIONS								
27.175	REF: See Workcard	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 27-10/400	EDDY CURRENT INSPECTION - LEFT WING AILERON HINGE POINTS								
27.215	REF: AMM 57-60-06	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 27-10/400	EDDY CURRENT INSPECTION - RIGHT WING AILERON HINGE POINTS								
	REF: AMM 57-60-06	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 27-10/444	FLIGHT CONTROL CABLES, AILERON								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 27-10-01	AFL	27000	N:0			0	27000	
+ 27-10/445	AUTOPILOT CONTROL CABLE, AILERON								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0	20000	
LIFE LIMIT	REF: AMM 27-10-02	AFL	27000	N:0			0	27000	
+ 27-10/470 (s)	LUBRICATE AILERON CONTROL SYSTEM BEARINGS						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 27-10-00	AFL					53		
+ 27-15/239 (s)	FUNCTIONAL TEST AILERON TRIM						PKG		
	PKG 7	MOS	24	+10%/-10%			23-OCT-2018		
		HRS/MSC	2400	+10%/-10%			0		
	REF: AMM 27-15-00	AFL					0		
+ 27-20/140 (s)	INSPECTION/CHECK RUDDER						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 55-40-00	AFL					53		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/240 (s)	EXAMINE RUDDER STATIC DISCHARGERS PKG 7	MOS	24	+10%/-10%			PKG 23-OCT-2018		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			0 0		
+ 27-20/241 (s)	RUDDER CONTROL - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 6	MOS	12	+10%/-10%			PKG 24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
+ 27-20/243 (s)	CHECK RUDDER CABLE TENSION PKG 6	MOS	12	+10%/-10%			PKG 24-OCT-2019		
	REF: AMM 27-20-00	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
+ 27-20/244 (s)	FUNCTIONAL TEST RUDDER PKG 7	MOS	24	+10%/-10%			PKG 23-OCT-2018		
	REF: AMM 27-20-00	HRS/MSC AFL	2400	+10%/-10%			0 0		
+ 27-20/245 (s)	FUNCTIONAL TEST RUDDER TRIM PKG 7	MOS	24	+10%/-10%			PKG 23-OCT-2018		
	REF: AMM 27-25-00	HRS/MSC AFL	2400	+10%/-10%			0 0		
+ 27-20/246 (s)	EXAMINE RUDDER ELECTRICAL BONDING STRAPS PKG 6	MOS	12	+10%/-10%			PKG 24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
+ 27-20/374	RUDDER CONTROL SYSTEM - EXAMINE	MOS					23-OCT-2018		
27.180	REF: AMM 27-20-00	HRS/MSC AFL	N/A				0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20/375	EDDY CURRENT INSPECTION RUDDER BELLCRANKS								
27.185		MOS					23-OCT-2018		
	REF: AMM 27-20-04	HRS/MSC	N/A				0		
		AFL					0		
+ 27-20/376	EXAMINE RUDDER CABLE QUADRANT SHEAR SPIGOT								
27.190		MOS					23-OCT-2018		
	REF: AMM 27-20-05	HRS/MSC	N/A				0		
		AFL					0		
+ 27-20/430	RUDDER CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED								
		MOS					24-OCT-2019		
	REF: AMM 27-20-00	HRS/MSC	O/C				61.5		
		AFL					53		
+ 27-20/431	FLIGHT CONTROL CABLES, RUDDER RUDDER CONTROL CABLES TENSION - CHECK AFTER REPLACEMENT OF ANY RUDDER CONTROL SYSTEM CABLES (AUTOPILOT AND/OR RUDDER)								
	PN	MOS							
	SN-UNKNOWN	HRS/MSC	A/R				0		
	REF: AMM 27-20-00	AFL							
+ 27-20/446	FLIGHT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-20-01	AFL	27000	N:0			0		27000
+ 27-20/447	AUTOPILOT CONTROL CABLES, RUDDER								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-20-02	AFL	27000	N:0			0		27000
+ 27-30/141 (s)	EXAMINE ELEVATORS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/247 (s)	EXAMINE ELEVATOR ELECTRICAL BONDING STRAPS PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%				61.5 53	
+ 27-30/248 (s)	EXAMINE ELEVATOR STATIC DISCHARGERS PKG 7	MOS	24	+10%/-10%			PKG	23-OCT-2018	
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%				0 0	
+ 27-30/249 (s)	ELEVATOR CONTROLS - EXAMINE THE CONTROL CABLES AND PULLEYS AS FAR AS POSSIBLE. MOVE THE MECHANISM SO THAT YOU CAN SEE ALL PARTS OF THE CABLES AND MAKE SURE THE SAFETY CLIPS ARE FULLY ENGAGED IN THE TURNBUCKLES PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%				61.5 53	
+ 27-30/250 (s)	CHECK ELEVATOR CABLE TENSION PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: AMM 27-30-00	HRS/MSC AFL	1200	+10%/-10%				61.5 53	
+ 27-30/251 (s)	FUNCTIONAL TEST ELEVATOR PKG 7	MOS	24	+10%/-10%			PKG	23-OCT-2018	
	REF: AMM 27-30-00	HRS/MSC AFL	2400	+10%/-10%				0 0	
+ 27-30/333	ELEVATOR CONTROL CABLES TENSION - CHECK FOR NEW FACTORY DELIVERED AIRCRAFT THAT HAVE NOT HAD AN ANNUAL INSPECTION COMPLETED 27.150	MOS						24-OCT-2019	
	REF: AMM 27-30-00	HRS/MSC AFL	O/C					61.5 53	
+ 27-30/334	CHECK FLIGHT CONTROL CABLES, ELEVATOR ELEVATOR CONTROL CABLES TENSION - AFTER REPLACEMENT OF ANY ELEVATOR CONTROL SYSTEM CABLES (AUTOPILOT, STICK PUSHER AND ELEVATOR) PN	MOS							
	REF: AMM 27-30-00	HRS/MSC AFL	A/R					0	



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30/363	ELEVATOR - CONTROL SYSTEM - EXAMINE								
27.195		MOS					23-OCT-2018		
	REF: AMM 27-30-00	HRS/MSC	N/A				0		
		AFL					0		
+ 27-30/364	EDDY CURRENT INSPECTION - ELEVATOR CONTROL RODS								
27.200		MOS					23-OCT-2018		
	REF: AMM 27-00-01	HRS/MSC	N/A				0		
		AFL					0		
+ 27-30/365	MAGNETIC PARTICLE INSPECT - ELEVATOR CONTROL RODS								
27.205		MOS					23-OCT-2018		
	REF: AMM 27-00-01	HRS/MSC	N/A				0		
		AFL					0		
+ 27-30/366	EDDY CURRENT INSPECTION - ELEVATOR CONTROL LEVER								
27.210		MOS					23-OCT-2018		
	REF: AMM 27-30-05	HRS/MSC	N/A				0		
		AFL					0		
+ 27-30/448	FLIGHT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-01	AFL	27000	N:0			0		27000
+ 27-30/449	AUTOPILOT CONTROL CABLES, ELEVATOR								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 27-30-02	AFL	27000	N:0			0		27000
+ 27-30/450	STICK PUSHER CABLES								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000
27-30/514 (s)	EXAMINE - ELEVATOR STOPS						PKG		
	PKG 6	MOS	12	+10%/-10%			23-OCT-2018		
		HRS/MSC	1200	+10%/-10%			0		
	REF: See Workcard	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-40/1	HORIZONTAL STABILIZER TRIM - FUNCTIONAL TEST OF TRIM RUNAWAY AURAL WARNING SYSTEM (FAA CMR)								
27.021		MOS	12	+10%/-10%			24-OCT-2019	31-OCT-2020	29-NOV-2020
AIRWORTHINESS	REF: AMM 27-40-00	HRS/MSC	3000		-1		61.5	3061.5	
		AFL					53		
+ 27-40/142 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM INTERRUPT AND ALTERNATE TRIM SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 27-40-00	AFL					53		
+ 27-40/252 (s)	INSPECTION / CHECK PITCH TRIM ACTUATOR AND ATTACHMENTS						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 27-40-01	AFL					53		
+ 27-40/26	OVERHAUL PITCH TRIM ACTUATOR								
	978.73.14.203	MOS	60				23-OCT-2018	31-OCT-2023	
	1847	HRS/MSC	5000				0	5000	
OVERHAUL	REF: GENERIC NO REF	AFL					0		
+ 27-40/291 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 2	MOS					24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 27-40-00	AFL					53		
+ 27-40/292 (s)	FUNCTIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 27-40-00	AFL					53		
+ 27-40/3	REPLACE PITCH TRIM ACTUATOR								
	978.73.14.203	MOS					23-OCT-2018		
	1847	HRS/MSC	20000				0	20000	
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000				0	27000	
+ 27-40/307	PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL SAFE PLATES AND THEIR ATTACHMENT PARTS (IPC 12-20-00-7)								
	PN	MOS		N:0			23-OCT-2018		
27.036	SN-UNKNOWN	HRS/MSC	10000	N:0			0	10000	
LIFE LIMIT	REF: AMM 27-40-02	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/143	LOWER FLAPS TO 40 DEGREES AS NECESSARY TO DO THE INSPECTION PKG 1 ,2,3,4,5,6,7 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 27-50/144 (s)	EXAMINE FLAPS AND FLAP SUPPORT MECHANISM PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/253 (s)	EXAMINE FLAPS ELECTRICAL BONDING STRAPS PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/254 (s)	EXAMINE FLAP MOTOR, ACTUATORS AND FLEXIBLE DRIVE SHAFTS PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/255 (s)	FUNCTIONAL TEST FLAPS AND ASYMMETRY MONITOR TEST PKG 6 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/28	FLAP POWER DRIVE UNIT 978.73.20.003 27.030 OVERHAUL REF: AMM 27-50-01	MOS HRS/MSC AFL	10000 13500	+500/-500 +500/-500	N:0 N:0 N:0		23-OCT-2018 0 0	10500 13500	
+ 27-50/30	OVERHAUL LEFT INBOARD FLAP ACTUATOR 978.73.20.309 27.040 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			23-OCT-2018 0 0	5500 7500	
+ 27-50/30	OVERHAUL LEFT OUTBOARD FLAP ACTUATOR 978.73.20.309 27.041 OVERHAUL REF: GENERIC NO REF	MOS HRS/MSC AFL	5000 7000	+10%/-10% +500/-500			23-OCT-2018 0 0	5500 7500	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/30	OVERHAUL RIGHT INBOARD FLAP ACTUATOR								
27.050	978.73.20.309	MOS					23-OCT-2018		
OVERHAUL	6660	HRS/MSC	5000	+10%/-10%			0	5000	5500
	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
+ 27-50/30	OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR								
27.051	978.73.20.309	MOS					23-OCT-2018		
OVERHAUL	6662	HRS/MSC	5000	+10%/-10%			0	5000	5500
	REF: GENERIC NO REF	AFL	7000	+500/-500			0	7000	7500
+ 27-50/31	LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.205	MOS		N:0			23-OCT-2018		
DISCARD	S8142	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/31	LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.060	945.02.02.206	MOS		N:0			23-OCT-2018		
DISCARD	S8118	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/31	RIGHT INBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.205	MOS		N:0			23-OCT-2018		
DISCARD	S8143	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/31	RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT								
27.070	945.02.02.206	MOS		N:0			23-OCT-2018		
DISCARD	S8159	HRS/MSC	10000	+500/-500	N:0		0	10000	10500
	REF: AMM 27-50-02	AFL	13500	+500/-500	N:0		0	13500	14000
+ 27-50/386	FLAP MECHANISM - EXAMINE								
27.220		MOS					23-OCT-2018		
	REF: AMM 27-51-00	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/387	EDDY CURRENT INSPECTION - FLAP DRIVE ARM (NOT REMOVED)								
27.225		MOS					23-OCT-2018		
	REF: AMM 27-51-00	HRS/MSC	N/A				0		
		AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/388	EDDY CURRENT INSPECTION FLAP DRIVE ARM (REMOVED)								
27.230		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/389	EDDY CURRENT INSPECTION - LEFT WING FLAP SUPPORT ARM								
27.235		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/389	EDDY CURRENT INSPECTION - RIGHT WING FLAP SUPPORT ARM								
		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/390	EDDY CURRENT INSPECTION - LEFT WING FLAP COVE RIB FITTINGS								
27.240		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/390	EDDY CURRENT INSPECTION - RIGHT WING FLAP COVE RIB FITTINGS								
		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/391	EDDY CURRENT INSPECTION - FLAP AFT LINKS								
27.245		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/392	EDDY CURRENT INSPECTION - FLAP BELLCRANKS								
27.250		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 27-50/4	LEFT INBOARD FLAP ACTUATOR								
27.040	978.73.20.309	MOS					23-OCT-2018		
	6614	HRS/MSC	20000				0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000				0		27000

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/4	LEFT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		N:0			23-OCT-2018		
27.041	6616	HRS/MSC	20000	N:0			0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0		27000
+ 27-50/4	RIGHT INBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		N:0			23-OCT-2018		
27.050	6660	HRS/MSC	20000	N:0			0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0		27000
+ 27-50/4	RIGHT OUTBOARD FLAP ACTUATOR								
	978.73.20.309	MOS		N:0			23-OCT-2018		
27.051	6662	HRS/MSC	20000	N:0			0		20000
DISCARD	REF: AMM 27-50-03	AFL	27000	N:0			0		27000
+ 27-50/414	LEFT HAND FLAP								
	557.50.12.005	MOS		N:0			23-OCT-2018		
57.060	1493M	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
+ 27-50/414	RIGHT HAND FLAP								
	557.50.12.006	MOS		N:0			23-OCT-2018		
57.060	1493M	HRS/MSC	25000	N:0			0		25000
LIFE LIMIT	REF: GENERIC NO REF	AFL	30000	N:0			0		30000
+ 27-50/437	INBOARD FLAP DRIVE ARMS - IN-SITU INSPECTION/CHECK								
		MOS	12	+10%/-10%	-1		24-OCT-2019	31-OCT-2020	29-NOV-2020
AIRWORTHINESS	REF: AMM 27-51-00	HRS/MSC	600	+10%/-10%			61.5	661.5	721.5
		AFL					53		
+ 27-50/443 (s)	SERVICE FLAP UP AND DOWN LIMIT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 12-20-07	AFL					53		
+ 27-50/451	FLAP TENSION RODS								
	PN	MOS		N:0			23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: GENERIC NO REF	AFL	27000	N:0			0		27000

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50/475 (s)	RETRACT FLAPS TO 0 DEGREES TO CLOSE THE INSPECTION PKG 1 ,2,3,4,5,6,7 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 27-50/74 (s)	LUBRICATE LEFT INBOARD FLAP ACTUATOR 978.73.20.309 PKG 3 6614 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/74 (s)	LUBRICATE LEFT OUTBOARD FLAP ACTUATOR 978.73.20.309 PKG 3 6616 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/74 (s)	LUBRICATE RIGHT INBOARD FLAP ACTUATOR 978.73.20.309 PKG 3 6660 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/74 (s)	LUBRICATE RIGHT OUTBOARD FLAP ACTUATOR 978.73.20.309 PKG 3 6662 REF: AMM 27-50-00	MOS HRS/MSC AFL	12 300	+1m/-1m +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 27-50/76	BACKLASH CHECK LEFT INBOARD FLAP ACTUATOR 978.73.20.309 6614 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			23-OCT-2018 0 0	31-OCT-2020 2400 3200	04-JAN-2021 2640 3520
+ 27-50/76	BACKLASH CHECK LEFT OUTBOARD FLAP ACTUATOR 978.73.20.309 6616 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			23-OCT-2018 0 0	31-OCT-2020 2400 3200	04-JAN-2021 2640 3520
+ 27-50/76	BACKLASH CHECK RIGHT INBOARD FLAP ACTUATOR 978.73.20.309 6660 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			23-OCT-2018 0 0	31-OCT-2020 2400 3200	04-JAN-2021 2640 3520

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-50/76	BACKLASH CHECK RIGHT OUTBOARD FLAP ACTUATOR								
27.051	978.73.20.309 6662 REF: AMM 27-50-03	MOS HRS/MSC AFL	24 2400 3200	+10%/-10% +10%/-10% +10%/-10%			23-OCT-2018 0 0	31-OCT-2020 2400 3200	04-JAN-2021 2640 3520
270003	HORIZONTAL TAIL ASSY 555.10.12.037 1665 REF: AMM 55-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270015	ELEVATOR LH ASSY 555.20.12.041 1759 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270023	ELEVATOR RH ASSY 555.20.12.042 1753 REF: AMM 55-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270025	RUDDER TRIM LINEAR ACTUATOR 978.73.18.138 1832 REF: AMM 27-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270033	RUDDER ASSY 555.40.12.040 1493M REF: AMM 55-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270035	FLAP CONTROL AND WARNING UNIT 978.73.20.017 139106 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270045	LH INBOARD TRANSMITTER 978.73.20.021 1810043DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
270050	LH ROTATION TRANSMITTER								
27.120	978.73.20.602 2785 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270060	LH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 1810081DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270070	RH INBOARD TRANSMITTER								
27.100	978.73.20.021 1810053DY REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270075	RH ROTATION,C70016705 TRANSMITTER								
27.120	978.73.20.602 2787 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270080	KTA2810,TRIM ADAPTER								
22.135	985.99.12.249 KTA2810-2574 REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270090	AILERON LINEAR ACTUATOR								
27.140	978.73.18.138 1858 REF: AMM 27-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
270095	RH OUTBOARD TRANSMITTER								
27.110	978.73.20.021 1810071DW REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
274020	PITCH TRIM ACTUATOR								
	978.73.14.203 1847 REF: AMM 27-40-01	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 28 FUEL									
+ 28-10/145 (s)	EXAMINE FUEL TANK FILLER CAPS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 28-10/146 (s)	SAMPLE FUEL - REMOVE A SAMPLE FROM EACH DRAIN VALVE AND EXAMINE FOR WATER						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 28-10/306	OPERATIONAL TEST FUEL CROSS VENT AND OUTWARD CHECK VALVE								
28.029		MOS		+10%/-10%					
		HRS/MSC	2400	+10%/-10%			0	2400	2640
	REF: AMM 28-10-01	AFL							
+ 28-20/147 (s)	OPERATIONAL TEST FUEL TANK VENT VALVE AND FLAME ARRESTOR						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 28-20-07	AFL					53		
+ 28-20/148 (s)	REMOVE/CLEAN FUEL FILTER ELEMENT						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: See Workcard	AFL					53		
+ 28-20/149 (s)	OPERATE FIREWALL SHUTOFF VALVE FUEL EMERG SHUTOFF LEVER AND MAKE SURE FIREWALL SHUTOFF VALVE OPENS AND CLOSES FULLY TO EACH DEAD STOP. MAKE SURE MOVEMENT IS FREE AND CHECK IF INITIAL PULL OUT FORCE AT LEVER OUTER END IS BELOW 10 LBF (4-4.5 N)						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 28-20/150 (s)	EXAMINE ENGINE DRIVEN PUMP						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-20/256 (s)	EXAMINE FUEL SYSTEM COMPONENTS AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED PKG 7	MOS	24	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	2400	+10%/-10%			23-OCT-2018 0 0		
+ 28-20/32	OVERHAUL ENGINE DRIVEN PUMP								
28.010	968.84.51.108 B6272	MOS					23-OCT-2018		
OVERHAUL	REF: AMM 28-20-03	HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		0 0 0	3500	3850
280005	LOW PRESSURE FUEL PUMP								
28.120	968.84.51.108 B6272	MOS					23-OCT-2018		
	REF: AMM 28-20-03	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
280010	FUEL FLOW TRANSMITTER								
28.130	975.35.12.108 AAR0615	MOS					23-OCT-2018		
	REF: AMM 73-30-01	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
280012	FUEL CONTROL MONITORING UNIT								
28.155	975.37.31.336 1012	MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
280015	FIREWALL FUEL, SHUT-OFF VALVE								
28.110	963.87.22.301 4002	MOS					23-OCT-2018		
	REF: AMM 28-20-08	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
280020	MAINTENANCE FUEL SHUT-OFF VALVE								
28.110	963.87.22.301 4003	MOS					23-OCT-2018		
	REF: AMM 28-20-12	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
280025	FUEL FILTER ASSY								
28.025	968.35.21.001 2018FFT939	MOS					23-OCT-2018		
	REF: AMM 28-20-01	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280030	FUEL LOW PRESSURE SWITCH								
28.100	973.81.14.102 3070 REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280035	EJECTOR,TRANSFER LH PUMP								
28.040	968.84.71.104 B6566 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280040	EJECTOR,DELIVERY LH PUMP								
28.030	968.84.71.105 B6274 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280045	FUEL QUANTITY OUTER LH SENSOR								
28.060	975.37.31.253 2835 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280050	FUEL QUANTITY,CENTRAL LH SENSOR								
28.070	975.37.31.252 2783 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280055	FUEL QUANTITY,INNER LH SENSOR								
28.090	975.37.31.251 2759 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280060	FUEL QUANTITY,COLLECTOR LH SENSOR								
28.080	975.37.31.250 2733 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280065	FUEL,BOOSTER LH PUMP								
28.050	968.84.11.405 C1082 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280070	EJECTOR,TRANSFER RH PUMP								
28.040	968.84.71.104 B6568 REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280075	EJECTOR,DELIVERY RH PUMP								
28.030	968.84.71.105 B6276 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280080	FUEL QUANTITY,COLLECTOR RH SENSOR								
28.080	975.37.31.250 2739 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280085	FUEL QUANTITY,INNER RH SENSOR								
28.090	975.37.31.251 2758 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280090	FUEL QUANTITY,CENTRAL RH SENSOR								
28.070	975.37.31.252 2785 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280095	FUEL QUANTITY,OUTER RH SENSOR								
28.060	975.37.31.253 2837 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280100	FUEL,BOOSTER RH PUMP								
28.050	968.84.11.405 C1116 REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280105	TOP CHECK VALVE								
28.150	963.04.23.105 4209 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
280110	BOTTOM CHECK VALVE								
28.150	963.04.23.105 4206 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280115	LH FUEL QUANTITY, TANK HARNESS								
28.140	975.37.31.335 2016 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
280120	RH FUEL QUANTITY, TANK HARNESS								
28.140	975.37.31.335 2018 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
CHAPTER 29 HYDRAULIC POWER									
+ 29-10/151	RETURN LINE FILTER DIFFERENTIAL PRESSURE INDICATOR (IF INSTALLED) - MAKE SURE THAT IT HAS NOT COME OUT. IF INDICATOR FOUND OUT, DO THE INSPECTION/CHECK PROCEDURE								
		MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
	REF: AMM 29-10-04								
+ 29-10/153	RESERVOIR TANK (IF INSTALLED) - MAKE SURE NITROGEN PRESSURE IS CORRECT. PRESSURIZE AS NECESSARY								
		MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
	REF: AMM 29-00-00								
+ 29-10/257	POWER PACK (IF INSTALLED) - EXAMINE SPECIALLY FOR LEAKS AND CRACKS ON THE END PLATES AND WHERE MOTOR IS ATTACHED								
		MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
	REF: GENERIC NO REF								
+ 29-10/258	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.291) (IF INSTALLED)								
	PN SN-UNKNOWN REF: AMM 29-10-02	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-10/259	POWER PACK ELECTRIC MOTOR SHAFT SEAL DRAIN FLUID COLLECTOR BOTTLE (IF INSTALLED) - REMOVE, CLEAN AND RE-INSTALL	MOS						23-OCT-2018	
	REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
+ 29-10/316	HYDRAULIC SYSTEM (IF INSTALLED) - MAKE SURE FLUID LEVEL INDICATOR ON THE RESERVOIR TANK SHOWS FULL. FILL AS NEEDED.	MOS						23-OCT-2018	
	REF: AMM 29-00-00	HRS/MSC AFL	N/A					0 0	
+ 29-10/471	CHECK NITROGEN ACCUMULATOR PRESSURE AND FILL AS NECESSARY (P/N 960.30.01.292)	MOS						23-OCT-2018	
	REF: AMM 29-10-02	PN SN-UNKNOWN HRS/MSC AFL	N/A					0 0	
CHAPTER 30	ICE AND RAIN PROTECTION								
+ 30-10/154 (s)	INSPECTION/CHECK WING AND HORIZONTAL STABILIZER AIRFOIL DE-ICE BOOTS	MOS	12	+10%/-10%			PKG		
	PKG 3	HRS/MSC AFL	300	+10%/-10%				24-OCT-2019 61.5 53	
	REF: AMM 30-10-00								
+ 30-10/155 (s)	OPERATIONAL TEST INERTIAL SEPARATION SYSTEM	MOS	12	+10%/-10%			PKG		
	PKG 5	HRS/MSC AFL	600	+10%/-10%				24-OCT-2019 61.5 53	
	REF: AMM 30-20-00								
+ 30-10/260 (s)	FUNCTIONAL TEST AIRFOIL DE-ICE SYSTEM	MOS	12	+10%/-10%			PKG		
	PKG 6	HRS/MSC AFL	1200	+10%/-10%				24-OCT-2019 61.5 53	
	REF: See Workcard								
+ 30-10/79	APPLY TO AIRFOIL DE-ICERS A SURFACE COATING OF AGE MASTER NO.1	MOS	6	+10%/-10%					
30.010	REF: GENERIC NO REF	HRS/MSC AFL			-32			03-JUN-2020 103.6 77	30-NOV-2020 30-NOV-2020



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-20/156 (s)	EXAMINE ENGINE AIR INTAKE DE-ICE LIP AND LOOK FOR SIGNS OF GAS LEAKS, NONE ARE PERMITTED PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 30-20/261 (s)	EXAMINE AIR BY-PASS DOOR AND OPERATING MECHANISM AND LUBRICATE WITH MINIMUM QUANTITY OF P10-001 PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 30-30/329 (s)	FUNCTIONAL TEST PROBES DE-ICE SYSTEM PKG 5 REF: AMM 30-30-20	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 30-40/262 (s)	OPERATIONAL TEST WINDSHIELD DE-ICE SYSTEM PKG 7 REF: AMM 30-40-00	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 23-OCT-2018 0 0		
+ 30-60/158 (s)	INSPECTION/CHECK PROPELLER DE-ICE SYSTEM PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 24-OCT-2019 61.5 53		
+ 30-60/159 (s)	OPERATIONAL TEST PROPELLER DE-ICE SYSTEM PKG 5 REF: See Workcard	MOS HRS/MSC AFL	12 600	+1m/-1m +30/-30			PKG 24-OCT-2019 61.5 53		
300005	PROP DE-ICE CONTROLLER 968.29.13.227 U4119 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-OCT-2018 0 0		
300010	LPMI LINEAR ACTUATOR 978.73.15.302 F05135 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300015	REGULATOR-RELIEVER ASSY								
30.160	959.89.01.012 N180751 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300020	L606 LOWER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.110	959.89.01.008 N180879 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300025	L605 UPPER SURFACE INBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	959.89.01.008 N180874 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300035	L601 LOWER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.120	959.89.01.008 N180901 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300040	L600 UPPER SURFACE OUTBOARD WING EJECTOR FLOW CONTROL VALVE								
30.130	959.89.01.008 N180902 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300045	EMPENAGE PRESSURE GAGE SWITCH								
30.070	973.81.14.312 9463 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300050	WATER SEPARATOR								
30.060	959.89.01.010 N172244 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300055	DE-ICING SYSTEM TIMER								
30.100	959.89.01.044 UA409 REF: AMM 30-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300060	LEFT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 138980 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300065	RIGHT WINDSHIELD DE ICE CONTROLLER								
30.020	972.81.32.202 138987 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300090	LH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.041 NEN2100 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300095	RH HORIZ STAB DE-ICER BOOT								
30.030	959.89.01.042 NEN6720 REF: AMM 30-16-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300100	RH INBD-WING DE-ICER BOOT								
30.040	959.89.01.038 NEM3080 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300105	RH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.040 NEO0340 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300110	LH AOA PLATE TEMP CONTROLLER								
30.170	975.44.21.418 UG858 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300115	LH INBD-WING DE-ICER BOOT								
30.040	959.89.01.037 NEM0780 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
300120	LH OUTBD-WING DE-ICER BOOT								
30.050	959.89.01.039 NEN5780 REF: AMM 30-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300125	RH AOA PLATE TEMP CONTROLLER								
30.170	975.44.21.418 UG677 REF: AMM 30-30-21	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300130	S601 LOWER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	973.81.14.312 9473 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300135	S600 UPPER SURF.INBD.WING PRESSURE,GAGE SWITCH								
30.180	973.81.14.312 9423 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300140	S602 LOWER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	973.81.14.312 9443 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300145	S603 UPPER SURF.OUTBD.WING PRESSURE,GAGE SWITCH								
30.190	973.81.14.312 9453 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
300150	L602 EMPENAGE EJECTOR FLOW CONTROL VALVE								
30.200	959.89.01.008 N180903 REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

CHAPTER 31 INDICATING/RECORDING SYSTEMS



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 31-00/CFR	TEST/INSPECT COPILOT ALTIMETER (14 CFR 91.411)								
		MOS	24				23-OCT-2018	31-OCT-2020	
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
+ 31-00/CFR	TEST/INSPECT PILOT ALTIMETER (14 CFR 91.411)								
		MOS	24				23-OCT-2018	31-OCT-2020	
		HRS/MSC					0		
	REF: See Workcard	AFL					0		
+ 31-30/421 (s)	OPERATIONAL TEST COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT LDR (IF INSTALLED)						PKG		
	985.99.20.146 PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
	002000194	HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 31-30-01	AFL					53		
310050	DIGITAL CLOCK								
	999.61.11.214	MOS			N:0		23-OCT-2018		
31.040	24474	HRS/MSC	O/C		N:0		0		
	REF: AMM 31-20-12	AFL			N:0		0		
310070	CO-PILOT KMC 2210 DISPLAY CONTROLLER								
	985.99.12.178	MOS			N:0		23-OCT-2018		
31.180	KMC2210-3227	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		
310075	NO. 1 MAU ADVANCED GRAPHIC MODULE								
	985.99.12.051	MOS			N:0		23-OCT-2018		
31.240	1807F679	HRS/MSC	O/C		N:0		0		
	REF: AMM 31-42-00	AFL			N:0		0		
310077	NO. 2 MAU ADVANCED GRAPHIC MODULE								
	985.99.12.051	MOS			N:0		23-OCT-2018		
31.270	1807F680	HRS/MSC	O/C		N:0		0		
	REF: AMM 31-42-00	AFL			N:0		0		
310080	NO. 2 RH MAU SINGLE NETWORK I/F CARD								
	985.99.12.231	MOS			N:0		23-OCT-2018		
31.160	1804L314	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310085	OVERHEAD CONTROL BASIC PANEL								
31.260	972.81.21.155 0869 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310090	KMC2220 MF CONTOLLER								
31.170	985.99.12.189 KMC2220-2257 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310095	PILOT KMC 2210 DISPLAY CONTROLLER								
31.180	985.99.12.178 KMC2210-3229 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310100	NO. 1 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	985.99.12.190 1804R575 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310102	NO. 2 MAU ACTUATOR I/O PROCESSOR MODULE								
31.230	985.99.12.190 1804R576 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310105	MODULAR AVIONICS ,12SLOT UNIT								
31.150	985.99.12.147 18059938 REF: AMM 31-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310110	NO. 1 LH MAU SINGLE NETWORK I/F CARD								
31.160	985.99.12.231 1803L042 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310115	NO. 1 LH MAU POWER SUPPLY MODULE								
31.220	985.99.12.346 18056589 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310120	NO. 2 RH MAU POWER SUPPLY MODULE								
31.220	985.99.12.346 18056622 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310125	MAU DUAL GENERIC I/O MODULE								
31.250	985.99.12.252 18042164 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310130	MAU CUSTOM I/O MODULE DUAL CH UNIT								
31.140	985.99.12.251 18052086 REF: AMM 31-42-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310135	CO-PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.120	985.99.12.371 2890013004 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310140	UPPER MFD KDU 1080 FLAT PANEL DISPLAY								
31.200	985.99.12.371 2890012946 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310145	PILOT PFD KDU 1080 FLAT PANEL DISPLAY								
31.190	985.99.12.371 2890011726 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310150	LOWER MFD KDU 1080 FLAT PANEL DISPLAY								
31.190	985.99.12.371 2890012944 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310155	REV CTL PNL,4-POT DISPLAY								
31.130	972.81.21.120 0238 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310160	NO. 1 LH AIRCRAFT PERSONALITY MODULE								
31.210	985.83.14.204 40830926 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310165	NO. 2 RH AIRCRAFT PERSONALITY MODULE								
31.210	985.83.14.204 40831131 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310167	CC-500 CONTROL UNIT								
31.280	985.99.12.202 42416 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310170	CCD INTERNAL ELECTRICAL ASSEMBLY								
31.290	985.99.12.328 0211 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310175	REAR CENTRE CONS PNL PC-12 47/E								
31.300	972.81.21.154 0867 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310177	MIDDLE CENTRE CONS PANEL								
	972.81.21.146 0847 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310180	COCKPIT AREA MICROPHONE								
	985.99.20.137 001265089 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
310185	COCKPIT VOICE FLIGHT DATA RECORDER (LDR) UNIT								
	985.99.20.146 002000194 REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
310202	VIDEO INTERFACE MODULE 975.95.01.107 13927 REF: AMM 31-60-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
CHAPTER 32 LANDING GEAR									
+ 32-10/162 (s)	LUBRICATE MAIN LANDING GEAR PKG 5 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 32-10/163 (s)	EXAMINE MAIN LANDING GEAR LEGS PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 32-10/164 (s)	EXAMINE MAIN LANDING GEAR COMPARTMENTS PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 32-10/165 (s)	CHECK MAIN LANDING GEAR SHOCK STRUTS NITROGEN PRESSURE PKG 5 REF: AMM 32-10-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 32-10/263 (s)	EXAMINE MAIN LANDING GEAR ELECTRICAL BONDING STRAPS PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 32-10/315	MAIN LANDING GEAR HINGE PIN AND BUSHES INSPECTION/CHECK 32.010 REF: See Workcard	MOS HRS/MSC AFL	12 2400	+1m/-1m +10%/-10%		7	24-OCT-2019 61.5 53	31-OCT-2020 2461.5	30-NOV-2020 2701.5



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/345	LEFT MAIN LANDING GEAR ASSEMBLY								
32.070	532.10.12.055 SI-1194 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 32-10/345	RIGHT MAIN LANDING GEAR ASSEMBLY								
32.070	532.10.12.056 SI-1194 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
+ 32-10/346	LEFT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION								
	REF:	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 32-10/346	RIGHT MLG YOKE FITTING OVERHAUL AND EDDY CURRENT INSPECTION								
32.215	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 32-10/347	LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 32-10/347	RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION								
32.220	REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 32-10/436	EXAMINE MAIN LANDING GEAR SHOCK STRUTS TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
	REF: See Workcard	MOS HRS/MSC AFL	12	+10%/-10%		-1	24-OCT-2019 61.5 53	31-OCT-2020	29-NOV-2020
+ 32-10/438	EXAMINE LEFT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT								
	REF: See Workcard	MOS HRS/MSC AFL	72				23-OCT-2018 0 0	31-OCT-2024	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/438	EXAMINE RIGHT MAIN LANDING GEAR LEG FORWARD ATTACHMENT BOLT AND BUSH AND REAR ATTACHMENT BOLT AND NUT	MOS HRS/MSC AFL	72				23-OCT-2018 0 0	31-OCT-2024	
	REF: See Workcard								
+ 32-10/439	EXAMINE LEFT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				23-OCT-2018 0 0	31-OCT-2024	
	REF: AMM 32-10-00								
+ 32-10/439	EXAMINE RIGHT MAIN LANDING GEAR SPRING PACK ASSEMBLY TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				23-OCT-2018 0 0	31-OCT-2024	
	REF: AMM 32-10-00								
+ 32-10/440	EXAMINE LEFT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				23-OCT-2018 0 0	31-OCT-2024	
	REF: AMM 32-10-00								
+ 32-10/440	EXAMINE RIGHT MAIN LANDING GEAR FOLDING STRUT TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS HRS/MSC AFL	72				23-OCT-2018 0 0	31-OCT-2024	
	REF: AMM 32-10-00								
+ 32-10/441	EXAMINE LEFT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS HRS/MSC AFL	120				23-OCT-2018 0 0	31-OCT-2028	
	REF: AMM 32-10-00								
+ 32-10/441	EXAMINE RIGHT MAIN LANDING GEAR DRAG LINK TOP ATTACHMENT SHEAR BOLT, CAP, BOLT AND NUTS	MOS HRS/MSC AFL	120				23-OCT-2018 0 0	31-OCT-2028	
	REF: AMM 32-10-00								
+ 32-10/80	LUBRICATE LEFT MAIN LANDING GEAR WHEEL BEARINGS	MOS HRS/MSC AFL	12	+1m/-1m		7	24-OCT-2019 61.5 53	31-OCT-2020	30-NOV-2020
	PN SN-UNKNOWN REF: AMM 12-20-06			T/C					

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-10/80	LUBRICATE NOSE WHEEL BEARINGS 959.56.02.302 1831 REF: AMM 12-20-06	MOS HRS/MSC AFL	12 T/C	+1m/-1m		7	24-OCT-2019 61.5 53	31-OCT-2020	30-NOV-2020
+ 32-10/80	LUBRICATE RIGHT MAIN LANDING GEAR WHEEL BEARINGS PN SN-UNKNOWN REF: AMM 12-20-06	MOS HRS/MSC AFL	12 T/C	+1m/-1m		7	24-OCT-2019 61.5 53	31-OCT-2020	30-NOV-2020
+ 32-20/166 (s)	CHECK NOSE LANDING GEAR LEG SHOCK STRUT NITROGEN PRESSURE PKG 5 REF: AMM 32-20-00	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 32-20/167 (s)	LUBRICATE NOSE LANDING GEAR PKG 5 REF: AMM 12-20-04	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 32-20/168 (s)	EXAMINE NOSE LANDING GEAR LEG AND STEERING MECHANISM IN PARTICULAR THE STEERING ROD END (PART NO. 532.20.12.13-4) FOR THE COMPLETE RETENTION OF BEARING INTO THE STEERING ROD END HOUSING. PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 32-20/169 (s)	EXAMINE NOSE LANDING GEAR COMPARTMENT PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 32-20/265 (s)	EXAMINE NOSE LANDING GEAR ELECTRICAL BONDING STRAPS PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 32-20/335	NOSE LANDING GEAR TORQUE TUBE PN 32.190 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC AFL	120 11000 15000	N:0 N:0 N:0			23-OCT-2018 0 0	31-OCT-2028 11000 15000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20/338	INSPECTION/CHECK NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
	PN	MOS					23-OCT-2018		
32.195	SN-UNKNOWN	HRS/MSC	2000				0	2000	
AIRWORTHINESS	REF: AMM 32-20-06	AFL	2500				0	2500	
+ 32-20/403	NOSE LANDING GEAR - OVERHAUL								
	PN	MOS		N:0			23-OCT-2018		
32.200	SN-UNKNOWN	HRS/MSC	25000	+500/-500	N:0		0	25000	25500
OVERHAUL	REF: GENERIC NO REF	AFL	30000	+500/-500	N:0		0	30000	30500
+ 32-20/416	NOSE LANDING GEAR UPPER RIGHT HAND DRAG LINK								
	PN	MOS		N:0			23-OCT-2018		
32.225	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
LIFE LIMIT	REF: AMM 32-20-05	AFL	30000	N:0			0	30000	
+ 32-30/170 (s)	FUNCTIONAL TEST EXTENSION AND RETRACTION SYSTEM AND EMERGENCY EXTENSION SYSTEM						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 32-30-00	AFL					53		
+ 32-30/423	LEFT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	959.56.01.823	MOS		N:0			23-OCT-2018		
	783	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
+ 32-30/423	NOSE LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	959.56.01.824	MOS		N:0			23-OCT-2018		
	395	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
+ 32-30/423	RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL LANDING GEAR ACTUATOR								
	959.56.01.823	MOS		N:0			23-OCT-2018		
	786	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	30000	N:0			0	30000	
+ 32-30/424	OPERATIONAL TEST EMERGENCY GEAR EXTENSION SYSTEM - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS	12	+10%/-10%			24-OCT-2019	31-OCT-2020	29-NOV-2020
		HRS/MSC	2000				61.5	2061.5	
	REF: AMM 32-30-10	AFL					53		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-30/425 (s)	EXAMINE ELECTRO MECHANICAL LANDING GEAR EXTENSION AND RETRACTION MECHNAISM - EXAMINE ALL COMPONENTS AND THEIR ATTACHMENTS IN THE NOSE AND MAIN LANDING GEAR COMPARTMENTS						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 32-30/426	FUNCTION TEST TIME DELAY RELAYS AND POWER CONTACTORS - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS	12	+10%/-10%		-1	24-OCT-2019	31-OCT-2020	29-NOV-2020
		HRS/MSC	2000				61.5	2061.5	
	REF: See Workcard	AFL					53		
+ 32-30/429	CHECK MAIN LANDING GEAR SPRING STRUT - LOOSEN AND MOVE THE SPRING STRUT COVER TO EXAMINE THE SPRINGS - ELECTRO MECHANICAL LANDING GEAR ONLY								
		MOS	12	+10%/-10%		-1	24-OCT-2019	31-OCT-2020	29-NOV-2020
		HRS/MSC	2000				61.5	2061.5	
	REF: AMM 32-10-06	AFL					53		
+ 32-30/435	DISCARD LEFT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
		MOS		+500/-500					
		HRS/MSC							
DISCARD	REF: See Workcard	AFL	12000	+500/-500			0	12000	12500
+ 32-30/435	DISCARD NOSE LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
		MOS		+500/-500					
		HRS/MSC							
DISCARD	REF: See Workcard	AFL	12000	+500/-500			0	12000	12500
+ 32-30/435	DISCARD RIGHT MAIN LANDING GEAR ELECTRO-MECHANICAL ACTUATORS ANTI-ROTATION PADS								
		MOS		+500/-500					
		HRS/MSC							
DISCARD	REF: See Workcard	AFL	12000	+500/-500			0	12000	12500
+ 32-30/442	EXAMINE LEFT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS								
		MOS	72				23-OCT-2018	31-OCT-2024	
		HRS/MSC					0		
	REF: See Workcard	AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-30/442	EXAMINE RIGHT MAIN LANDING GEAR ACTUATOR TOP AND BOTTOM ATTACHMENT BOLTS AND NUTS	MOS	72				23-OCT-2018	31-OCT-2024	
	REF: See Workcard	HRS/MSC					0		
		AFL					0		
+ 32-40/171 (s)	EXAMINE MAINWHEELS. ROTATE WHEELS, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			61.5		
		AFL					53		
+ 32-40/172 (s)	EXAMINE MAINWHEEL TIRES AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
	REF: AMM 12-10-04	HRS/MSC	300	+10%/-10%			61.5		
		AFL					53		
+ 32-40/173 (s)	EXAMINE NOSEWHEEL. ROTATE WHEEL, MAKE SURE BEARING MOVEMENT IS SMOOTH AND FREE AND NO EXCESSIVE PLAY EXISTS						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	600	+10%/-10%			61.5		
		AFL					53		
+ 32-40/174 (s)	EXAMINE NOSEWHEEL TIRE AND CHECK TIRE PRESSURE						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
	REF: AMM 12-10-04	HRS/MSC	300	+10%/-10%			61.5		
		AFL					53		
+ 32-40/175 (s)	EXAMINE BRAKE SYSTEM - APPLY THE PARKING BRAKE. EXAMINE THE BRAKE UNITS. MAKE SURE THAT PAD WEAR INDICATORS PROTRUDE FROM HOUSING.						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	300	+10%/-10%			61.5		
		AFL					53		
+ 32-40/176 (s)	CHECK FLUID RESERVOIR AND REPLENISH IF NECESSARY						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
	REF: AMM 12-10-02	HRS/MSC	300	+10%/-10%			61.5		
		AFL					53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-50/404	EXAMINE - NLG STEERING MECHANISM								
32.230	REF: AMM 32-50-00	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
320005	PILOT LH BRAKE MASTER CYLINDER								
32.130	959.47.51.131 6335 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320010	PILOT RH BRAKE MASTER CYLINDER								
32.130	959.47.51.131 6381 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320015	PARK BRAKE VALVE								
32.140	959.47.51.121 3146 REF: AMM 32-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320020	NOSE WHEEL								
32.150	959.56.02.302 1831 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320023 (s)	LEFT MAIN LANDING GEAR TIRE								
32.160	025-350-0 9035S00309 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:3 N:0 N:0			24-OCT-2019 61.5 53		
320025	SHIMMY DAMPER ASSY								
32.100	532.20.12.215 SI-0548 REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320030	COPILOT LH BRAKE MASTER CYLINDER								
32.120	959.47.51.131 6383 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320035	COPILOT RH BRAKE MASTER CYLINDER								
32.120	959.47.51.131 6395 REF: AMM 32-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320040	NOSE FOLDING STRUT SPRING PACK ASSY								
32.080	532.20.12.305 SI-0157 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320045	NOSE LANDING GEAR STRUT ASSY								
32.090	532.20.12.044 SI-1198 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320055	RIGHT SHOCK ABSORBER ASSY								
32.060	532.10.12.230 SI-1042 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320060	LH BRAKE ASSY								
32.050	959.56.01.517 3745 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320065	INNER LEFT WHEEL & COVER ASSY								
32.110	959.56.01.503 3974 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320066	OUTER LEFT WHEEL & COVER ASSY								
32.205	959.56.01.503 3994 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320080	LEFT SHOCK ABSORBER ASSY								
32.060	532.10.12.230 SI-1046 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320085	RH BRAKE ASSY								
32.050	959.56.01.517 3750 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320090	INNER RIGHT WHEEL & COVER ASSY								
32.110	959.56.01.503 3982 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320091	OUTER RIGHT WHEEL & COVER ASSY								
32.210	959.56.01.503 4002 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320104	NOSE LANDING GEAR 72A74-01 "UP" PROXIMITY SWITCH								
32.170	973.30.33.116 7109 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320105	MAIN LANDING GEAR 72A74-01 RH "UP" PROXIMITY SWITCH								
32.175	973.30.33.116 7181 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320115	NOSE LANDING GEAR 72A74-01 "DOWN" PROXIMITY SWITCH								
32.170	973.30.33.116 7123 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320120	MAIN LANDING GEAR 72A74-01 LH "UP" PROXIMITY SWITCH								
32.175	973.30.33.116 7114 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320140	INTERMEDIATE CABLE ASSY								
	959.56.01.816 00432 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320140	MAIN GEAR CABLE ASSY 959.56.01.814 00356 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320140	NOSE GEAR CABLE ASSY 959.56.01.815 00418 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320145	EXTENSION GEAR EMERGENCY HANDLE 959.56.01.838 00457 REF: AMM 32-30-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320150	FRONT HIGH CURRENT RELAY 974.09.26.112 1062 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320150	REAR HIGH CURRENT RELAY 974.09.26.112 1065 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320155	LEFT HAND SPRING PACK ASSY 532.34.12.120 723 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320155	RIGHT HAND SPRING PACK ASSY 532.34.12.120 725 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
320160	MLG L/H WOW NLG UP SWITCH ASSY 532.69.21.026 3053 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320160	MLG R/H WOW NLG UP SWITCH ASSY 532.69.21.026 3064 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
CHAPTER 33 LIGHTS									
+ 33-40/177 (s)	OPERATIONAL TEST EXTERIOR LIGHTING PKG 3 REF: AMM 33-40-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 33-41/178 (s)	EXAMINE LANDING LIGHTS PKG 3 REF: AMM 33-41-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 33-42/179 (s)	EXAMINE TAXI LIGHTS PKG 3 REF: AMM 33-42-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 33-43/180 (s)	EXAMINE NAVIGATION AND STROBE LIGHTS PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 33-44/181 (s)	EXAMINE RECOGNITION LIGHTS (IF INSTALLED) PKG 3 REF: AMM 33-44-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 33-46/182 (s)	EXAMINE BEACON LIGHTS (IF INSTALLED) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330005	DIM UNIT								
33.080	975.02.15.205 4115 REF: AMM 33-10-04	MOS HRS/MSC AFL	O/C	R:6 R:0 R:0			17-FEB-2020 94.8 70		
330010	DE-ICE LIGHT ASSY								
33.010	972.87.67.111 4230990 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
330025	TOP SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	972.87.87.347 200967-6-13 REF: AMM 33-46-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
330030	BOTTOM SIDE ANTI COLLISION RED LIGHT ASSY								
33.040	972.87.87.347 200967-6-10 REF: AMM 33-46-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
330040	LEFT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.344 203728-3-27 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
330045	RH WING POWER SUPPLY UNIT								
33.070	972.87.87.179 200967-2-4 REF: AMM 33-43-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
330050	RIGHT HAND WING TIP WARNING LIGHT ASSEMBLY								
33.030	972.87.87.345 202849-5-11 REF: AMM 33-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
330070	NOSE LANDING GEAR TAXI LIGHT								
33.090	972.87.69.430 200723-1-1 REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
330075	L/H 1X0005287-10 LANDING LIGHT									
33.090	972.87.69.432 200725-3-28 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
330076	R/H 1X0005287-10 LANDING LIGHT									
33.110	972.87.69.432 202849-2-3 REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
330085	LEFT HAND RECOGNITION LED LIGHT									
	972.87.69.431 200966-2-16 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
330085	RIGHT HAND RECOGNITION LED LIGHT									
	972.87.69.431 200966-2-2 REF: AMM 33-44-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
CHAPTER 34 NAVIGATION										
+ 34-00/183 (s)	EXAMINE COMMUNICATIONS AND NAVIGATION ANTENNAS						PKG			
	PKG 7	MOS	24	+10%/-10%			23-OCT-2018			
		HRS/MSC	2400	+10%/-10%			0			
	REF: GENERIC NO REF	AFL					0			
+ 34-00/184 (s)	EXAMINE COCKPIT INSTRUMENTS AND AVIONIC EQUIPMENT						PKG			
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019			
		HRS/MSC	300	+10%/-10%			61.5			
	REF: GENERIC NO REF	AFL					53			
+ 34-11/185 (s)	EXAMINE PITOT TUBE						PKG			
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019			
		HRS/MSC	300	+10%/-10%			61.5			
	REF: GENERIC NO REF	AFL					53			



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-11/186 (s)	EXAMINE STATIC PORTS PKG 3	MOS	12	+10%/-10%			PKG 24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			61.5 53		
+ 34-11/268 (s)	DRAIN PITOT AND STATIC SYSTEM PKG 6	MOS	12	+10%/-10%			PKG 24-OCT-2019		
	REF: AMM 34-11-00	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
+ 34-11/343	INSPECTION/CHECK STATIC PORTS PLATE HEIGHT	MOS	24				23-OCT-2018	31-OCT-2020	
34.565	REF: AMM 34-11-12	HRS/MSC AFL					0 0		
+ 34-11/82	LEAK CHECK STATIC SYSTEM	MOS	24				23-OCT-2018	31-OCT-2020	
34.010	REF: AMM 34-11-00	HRS/MSC AFL					4.4 6		
+ 34-11/CFR	PERFORM LEAK CHECK OF STATIC SYSTEM (14 CFR 91.411)	MOS	24				23-OCT-2018	31-OCT-2020	
	REF: See Workcard	HRS/MSC AFL					4.4 6		
+ 34-21/84	SWING CHECK STANDBY MAGNETIC COMPASS (IF INSTALLED)	MOS	24	+10%/-10%			28-SEP-2018	30-SEP-2020	10-DEC-2020
34.560	REF: AMM 34-21-00	HRS/MSC AFL							
+ 34-25/344	FUNCTIONAL TEST ALTITUDE AND VERTICAL SPEED INDICATION (RVSM)	MOS	24	+10%/-10%			23-OCT-2018	31-OCT-2020	04-JAN-2021
34.570	REF: AMM 34-14-00	HRS/MSC AFL					4.4 6		
+ 34-54/86	FUNCTIONAL TEST TRANSPONDER SYSTEM (SINGLE AND DUAL SYSTEMS)	MOS	24				17-SEP-2018	30-SEP-2020	
34.050	REF: See Workcard	HRS/MSC AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-54/CFR	TEST/INSPECT NO. 1 TRANSPONDER SYSTEM (14 CFR 91.413)	MOS	24				23-OCT-2018	31-OCT-2020	
	REF: GENERIC NO REF	HRS/MSC					0		
		AFL					0		
+ 34-54/CFR	TEST/INSPECT NO. 2 TRANSPONDER SYSTEM (14 CFR 91.413)	MOS	24				23-OCT-2018	31-OCT-2020	
	REF: GENERIC NO REF	HRS/MSC					0		
		AFL					0		
340010	DME/IFF ANTENNA								
34.080	984.81.10.240	MOS		N:0			23-OCT-2018		
	261-128220	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-52-02	AFL		N:0			0		
340020	MARKER ANTENNA								
34.100	984.81.10.260	MOS		N:0			23-OCT-2018		
	101-8633	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-32-01	AFL		N:0			0		
340055	WITH HARM FILTER,KN63 DME								
34.200	985.99.11.101	MOS		N:0			23-OCT-2018		
	42222	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-52-01	AFL		N:0			0		
340075	WX,VERTICAL ANTENNA								
34.370	985.99.11.504	MOS		N:0			23-OCT-2018		
	8667	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-41-12	AFL		N:0			0		
340080	TRANSPONDER DME/IFF ANTENNA								
34.080	984.81.10.240	MOS		N:0			23-OCT-2018		
	261-128221	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-54-03	AFL		N:0			0		
340085	ADF,KA44B ANTENNA								
34.070	985.99.11.167	MOS		N:0			23-OCT-2018		
	KA44B-A95430	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-53-02	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340100	FRONT KA92 ANTENNA								
34.090	985.99.11.200 49311339 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340101	REAR KA92 GPS ANTENNA								
34.090	985.99.11.200 49311512 REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340131	KCM 805 CONFIGURATION MODULE								
34.410	985.99.11.884 21041 REF: AMM 34-25-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340140	RADOME								
34.420	985.79.00.005 730 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340145	ANTENNA,VHF NAV COUPLER								
34.160	984.81.10.412 9408 REF: AMM 23-11-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340155	LEFT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 543-91170 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340160	RIGHT SIDE RAD ALT,S67-2002 ANTENNA								
34.110	984.81.29.101 543-91175 REF: AMM 34-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340161	BOTTOM DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 31314 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340162	TOP DIRECTIONAL KA815 - IHAS ANTENNA								
34.430	985.99.11.869 31620 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340170	ALTIMETER,RADAR,KRA405B TRANSMITTER								
34.310	985.99.11.524 KRA405B-20101 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340207	EGPWS MK VI UNIT								
	985.99.12.017 EMK8-08774 REF: AMM 34-45-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340220	STORMSCOPE WX-500 PROCESSOR								
34.270	985.99.18.006 103971 REF: AMM 34-41-31	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340235	AOA SENSOR RH UNIT								
34.330	975.44.21.424 2058 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340245	CONFIGURATION MODULE INSTLN,ART2000 KIT								
34.490	985.99.11.527 1159 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340246	ART 2000 RADAR								
	985.99.11.539 2702 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340255	AOA SENSOR LH UNIT								
34.330	975.44.21.423 1951 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340265	DME/IFF--ATC DIV. ANTENNA								
34.500	984.81.10.240 261-128222 REF: AMM 34-54-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340280	OUTBOARD KMG 7010 MAGNETOMETER								
34.520	985.99.12.114 KMG7010-5383 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340285	INBOARD KMG 7010 MAGNETOMETER								
34.520	985.99.12.114 KMG7010-5365 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340290	KMH920 TAWS B,TCAS 1 UNIT								
34.545	985.99.11.888 KTA910-3060 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340310	NO. 2 KXP 2290 MODE S TRANSPONDER								
34.540	985.99.12.269 KXP2290A-3860 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340315	NO. 1 KXP 2290 MODE S TRANSPONDER								
34.540	985.99.12.269 KXP2290A-3858 REF: AMM 34-54-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340320	LH OAT SENSOR								
34.525	534.13.12.025 06623 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340325	RH OAT SENSOR								
34.525	534.13.12.025 06618 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340330	KSG 7200 DUAL CHANNEL AD AHRS UNIT								
34.505	985.99.12.272 KSG7200-B3084 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340350	XM RADIO, XMD 157, UNIT								
34.515	985.99.12.303 35638136 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340355	LH NAV/WHITE ANTENNA								
	984.81.10.280 168-12296 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
340357	RH NAV/WHITE ANTENNA								
	984.81.10.280 168-12297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
341035	NO. 1 KGS200,SBAS GNSSU UNIT								
	985.99.12.253 KGS200-3416 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
341037	NO. 2 KGS200,SBAS GNSSU UNIT								
	985.99.12.253 KGS200-3417 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
341039	MAG-3100 MAGNETOMETER								
	985.90.03.058 81047 REF: AMM 34-26-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
341045	ESI-1000 STANDBY SYSTEM								
	975.96.11.247 3695 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 35 OXYGEN									
+ 35-10/187 (s)	CHECK HIGH PRESSURE RELIEF INDICATOR (GREEN DISK) - MAKE SURE THAT IT IS NOT DAMAGE						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 35-10/188 (s)	CHECK OXYGEN SYSTEM CONTENTS						PKG		
	PKG 2	MOS					24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 35-10/269 (s)	EXAMINE OXYGEN PIPELINES AND EQUIPMENT						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 35-10/458 (s)	OPERATIONAL TEST CREW OXYGEN SYSTEM						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 35-00-00	AFL					53		
+ 35-10/6	OXYGEN BOTTLE								
	PN	MOS							
35.010	SN-UNKNOWN	HRS/MSC	N/A						
N/A EQUIPMENT NOT INSTALLED	REF: AMM 35-10-01	AFL							
+ 35-10/6	REAR FUSELAGE OXYGEN CYLINDER								
	957.12.12.212	MOS	180				23-OCT-2018	30-NOV-2032	
	C18020548	HRS/MSC					0		
AIRWORTHINESS	REF: AMM 35-10-01	AFL					0		
	Manufacture Date: 01-NOV-2017								
+ 35-10/7	HYDROSTATIC TEST OXYGEN BOTTLE								
	PN	MOS							
35.010	SN-UNKNOWN	HRS/MSC	N/A						
N/A EQUIPMENT NOT INSTALLED	REF: GENERIC NO REF	AFL							



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10/7	HYDROSTATIC TEST REAR FUSELAGE OXYGEN CYLINDER 957.12.12.212 C18020548 REF: GENERIC NO REF	MOS HRS/MSC AFL	60				01-NOV-2017	30-NOV-2022	
AIRWORTHINESS									
+ 35-20/452	OPERATIONAL TEST PASSENGER OXYGEN (DROP-DOWN MASK) SYSTEM (IF INSTALLED) REF: AMM 35-00-00	MOS HRS/MSC AFL	12 3000	+10%/-10%		-1	24-OCT-2019 61.5 53	31-OCT-2020 3061.5	29-NOV-2020
+ 35-20/453	LAV MASK OVERHAUL 957-12-01-215 D18011110 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			01-DEC-2017	31-DEC-2023	01-JUN-2024
OVERHAUL									
+ 35-20/453	OVERHAUL NO. 1 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 957.12.01.215 D17120605 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			01-JUL-2017	31-JUL-2023	01-JAN-2024
OVERHAUL									
+ 35-20/453	OVERHAUL NO. 2 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 957.12.01.215 D17120622 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			01-DEC-2017	31-DEC-2023	01-JUN-2024
OVERHAUL									
+ 35-20/453	OVERHAUL NO. 3 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 957.12.01.215 D17120637 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			01-DEC-2017	31-DEC-2023	01-JUN-2024
OVERHAUL									
+ 35-20/453	OVERHAUL NO. 4 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY) 957.12.01.215 D17120640 REF: GENERIC NO REF	MOS HRS/MSC AFL	72	+6m/-6m			01-DEC-2017	31-DEC-2023	01-JUN-2024
OVERHAUL									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-20/453	OVERHAUL NO. 5 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72	+6m/-6m			01-DEC-2017	31-DEC-2023	01-JUN-2024
OVERHAUL	D17120642 REF: GENERIC NO REF	HRS/MSC AFL							
+ 35-20/453	OVERHAUL NO. 6 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72	+6m/-6m			01-DEC-2017	31-DEC-2023	01-JUN-2024
OVERHAUL	D18011064 REF: GENERIC NO REF	HRS/MSC AFL							
+ 35-20/453	OVERHAUL NO. 7 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72	+6m/-6m			01-JAN-2018	31-JAN-2024	01-JUL-2024
OVERHAUL	D18011079 REF: GENERIC NO REF	HRS/MSC AFL							
+ 35-20/453	OVERHAUL NO. 8 PASSENGER OXYGEN MASK (CARTRIDGE REPLACEMENT DROP-DOWN MASK PN 957.12.01.215 ONLY)								
	957.12.01.215	MOS	72	+6m/-6m			01-JAN-2018	31-JAN-2024	01-JUL-2024
OVERHAUL	D18011099 REF: GENERIC NO REF	HRS/MSC AFL							
+ 35-20/459	OPERATIONAL TEST OF PASSENGER OXYGEN (PLUG-IN MASK) SYSTEM (IF INSTALLED)								
		MOS					23-OCT-2018		
		HRS/MSC	400	+10%/-10%			0	400	440
	REF: AMM 35-00-00	AFL					0		
+ 35-20/87	INSPECTION/CHECK PASSENGER OXYGEN MASKS								
35.010		MOS	36	+10%/-10%			31-OCT-2018	31-OCT-2021	18-FEB-2022
	REF: AMM 35-20-00	HRS/MSC AFL							
350020	PILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	957.12.01.210	MOS					23-OCT-2018		
	B137181	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350025	COPILOT QUICK DONNING MASK-REGULATOR ASSY								
35.040	957.12.01.210 B137271 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350030	PRESSURE,GAGE,OXYGEN SWITCH								
35.050	973.81.14.401 1707 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350035	CONTR,3-POSITION,37071-03 VALVE								
35.030	963.32.11.102 0661 REF: AMM 35-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350050	OXYGEN GAGE ASSY								
35.060	535.12.12.085 60311 REF: AMM 35-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350055	OXYGEN PRESS TRANSDUCER								
35.070	957.12.01.184 8362-2-296 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350067	OXYGEN SHUT-OFF VALVE								
	957.12.12.232 000247942 REF: AMM 35-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350071	NO. 1 PASSENGER OXYGEN MASK ASSEMBLY								
	957.12.01.215 D17120605 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350072	NO. 2 PASSENGER OXYGEN MASK ASSEMBLY								
	957.12.01.215 D17120622 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
350073	NO. 3 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D17120637 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350074	NO. 4 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D17120640 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350075	NO. 5 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D17120642 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350076	NO. 6 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D18011064 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350077	NO. 7 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D18011079 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350078	NO. 8 PASSENGER OXYGEN MASK ASSEMBLY 957.12.01.215 D18011099 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
350079	LAV MASK 957-12-01-215 D18011110 REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

CHAPTER 45 CENTRAL MAINT SYSTEM



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 45-45/454 (s)	CENTRAL MAINTENANCE SYSTEM - DO A CMC REPORTS-EXPORT FAULT HISTORY - SEND TO LOCAL STORAGE - DOWNLOAD						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 45-45-00	AFL					53		
CHAPTER 46 INFORMATION SYSTEMS									
+ 46-26/320 (s)	OPERATIONAL TEST PILOT AND COPILOT (IF INSTALLED) PFD REVERSIONARY SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: See Workcard	AFL					53		
+ 46-26/321 (s)	OPERATIONAL TEST ADAHRS SENSOR SOURCE SELECT SWITCHES						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 46-30-02	AFL					53		
460105	WIRELESS DATA LOADING DEVICE								
	975.96.32.456	MOS				N:0	23-OCT-2018		
	3023	HRS/MSC	O/C			N:0	0		
	REF: GENERIC NO REF	AFL				N:0	0		
CHAPTER 52 DOORS									
+ 52-10/189 (s)	EXAMINE PASSENGER/CREW DOOR SEAL - CLEAN WITH A DRY CLOTH, EXAMINE AND APPLY P0-9-002 FRENCH CHALK						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 52-10/190 (s)	EXAMINE PASSENGER/CREW DOOR SHOOT BOLTS AND DOOR FRAME FITTINGS						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 52-10/191 (s)	PASSENGER/CREW DOOR HANDLE LOCK PIN - MAKE SURE MOVEMENT IS FREE. LUBRICATE WITH P10-001 AS NECESSARY WHEN OPERATING IN FREEZING CONDITIONS						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10/192 (s)	EXAMINE PASSENGER/CREW DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT						PKG		
	PKG 5	MOS	12	+10%/-10%				24-OCT-2019	
		HRS/MSC	600	+10%/-10%				61.5	
	REF: GENERIC NO REF	AFL						53	
+ 52-10/271 (s)	EXAMINE PASSENGER/CREW DOOR, COUNTERBALANCE AND CABLE SUPPORT BRACKETS						PKG		
	PKG 6	MOS	12	+10%/-10%				24-OCT-2019	
		HRS/MSC	1200	+10%/-10%				61.5	
	REF: GENERIC NO REF	AFL						53	
+ 52-10/348	EXAMINE ALL STRUCTURAL ELEMENTS - PASSENGER/CREW DOOR								
52.070		MOS						23-OCT-2018	
		HRS/MSC	N/A					0	
	REF: AMM 52-10-00	AFL						0	
+ 52-10/405	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR PIANO HINGE								
52.100		MOS						23-OCT-2018	
		HRS/MSC	N/A					0	
	REF: AMM 52-00-01	AFL						0	
+ 52-10/406	EDDY CURRENT INSPECTION - PASSENGER/CREW DOOR SKIN								
52.110		MOS						23-OCT-2018	
		HRS/MSC	N/A					0	
	REF: AMM 52-10-01	AFL						0	
+ 52-10/472	EDDY CURRENT INSPECTION PASSENGER / CREW DOOR SHOOT BOLT FITTING (ONLY IF SB 52-007 PART C IS COMPLIED WITH)								
		MOS						23-OCT-2018	
		HRS/MSC	N/A					0	
	REF: AMM 52-10-06	AFL						0	
+ 52-10/88	EXAMINE PASSENGER/CREW DOOR WITH TRIM REMOVED								
52.010		MOS	48	+10%/-10%				31-OCT-2018	
		HRS/MSC	4000	+10%/-10%				0	
	REF: See Workcard	AFL							
								31-OCT-2022	22-MAR-2023
								4000	4400



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-20/272 (s)	EXAMINE EMERGENCY DOOR (DOOR REMOVED) PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
+ 52-20/273 (s)	EXAMINE EMERGENCY DOOR SEAL - CLEAN WITH A WET CLOTH, DRY AND EXAMINE AND APPLY P09-002 FRENCH CHALK PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
+ 52-20/349	EXAMINE ALL STRUCTURAL ELEMENTS - EMERGENCY DOOR	MOS						23-OCT-2018	
52.080	REF: AMM 52-20-00	HRS/MSC AFL	N/A				0 0		
+ 52-30/193 (s)	EXAMINE CARGO DOOR SEAL - CLEAN WITH A DRY CLOTH, AND APPLY P0-9-002 FRENCH CHALK PKG 5	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			61.5 53		
+ 52-30/194 (s)	EXAMINE CARGO DOOR SHOOT BOLTS, DOOR FRAME FITTINGS AND HOOKS - MAKE SURE THE HOOK ROLLER BUSHES ARE FREE TO ROTATE. FOR ROLLER BUSH WEAR LIMITS REFER TO AMM. PKG 5	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: AMM 52-30-00	HRS/MSC AFL	600	+10%/-10%			61.5 53		
+ 52-30/195 (s)	EXAMINE CARGO DOOR HINGES AND LUBRICATE AS NECESSARY WITH MINIMUM QUANTITY OF P10-001 LUBRICANT PKG 5	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	600	+10%/-10%			61.5 53		
+ 52-30/274 (s)	EXAMINE CARGO DOOR PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-30/350	EXAMINE ALL STRUCTURAL ELEMENTS - CARGO DOOR								
52.090	REF: AMM 52-30-00	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 52-30/407	EDDY CURRENT INSPECTION - CARGO DOOR PIANO HINGE								
52.120	REF: See Workcard	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 52-30/408	EDDY CURRENT INSPECTION - CARGO DOOR SKIN								
52.130	REF: AMM 52-30-01	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 52-30/8	CARGO DOOR LOWER LUG (QTY 3) FITTINGS								
52.020	PN	MOS		N:0			23-OCT-2018		
AIRWORTHINESS	SN-UNKNOWN	HRS/MSC	13000	N:0			0		13000
	REF: AMM 52-30-07	AFL	17000	N:0			0		17000
+ 52-30/89	EXAMINE CARGO DOOR WITH TRIM REMOVED. EXAMINE DOOR HINGE PIN, HINGES AND THE LOCK MECHANISM								
52.030	REF: See Workcard	MOS HRS/MSC AFL	48 4000	+10%/-10% +10%/-10%			31-OCT-2018 0	31-OCT-2022 4000	22-MAR-2023 4400
+ 52-70/275 (s)	OPERATIONAL TEST DOOR WARNING SYSTEM								
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
	REF: AMM 52-70-00	HRS/MSC AFL	1200	+10%/-10%			61.5 53		
520005	PASSENGER DOOR								
52.050	552.05.12.043	MOS		N:0			23-OCT-2018		
	1493M	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
520010	FREIGHT OF 10SERIE DOOR ASSY								
52.040	552.05.12.044	MOS		N:0			23-OCT-2018		
	1495M	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
520015	EMERGENCY 6 SERIE EXIT								
52.060	552.05.12.038 1493M REF: AMM 52-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

CHAPTER 53 FUSELAGE

+ 53-00/196 (s)	EXAMINE FUSELAGE EXTERNAL SURFACE. FOR AIRCRAFT THAT EXPERIENCE STONE DAMAGE TO THE BELLY SKIN, VISUALLY EXAMINE AFFECTED AREAS FOR CRACKS.						PKG		
	PKG 3	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
	REF: GENERIC NO REF								

+ 53-00/276 (s)	EXAMINE REAR PRESSURE BULKHEAD						PKG		
	PKG 7	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			23-OCT-2018 0 0		
	REF: GENERIC NO REF								

+ 53-00/277 (s)	EXAMINE FLOOR TOP AND BOTTOM SURFACE AND SEAT RAILS, AS FAR AS POSSIBLE, WITH CARPET AND FLOOR PANELS IN TASK 06-00/218 REMOVED						PKG		
	PKG 6	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
	REF: GENERIC NO REF								

+ 53-00/278 (s)	EXAMINE BAGGAGE/FREIGHT NET MOUNTING PLATES ATTACHMENT BOLTS AND SURROUNDING STRUCTURE FOR CORROSION						PKG		
	PKG 7	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			23-OCT-2018 0 0		
	REF: GENERIC NO REF								

+ 53-00/279 (s)	EXAMINE BAGGAGE COMPARTMENT						PKG		
	PKG 7	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			23-OCT-2018 0 0		
	REF: GENERIC NO REF								

+ 53-00/280 (s)	EXAMINE REAR FUSELAGE INTERNAL STRUCTURE AS FAR AS POSSIBLE, IN PARTICULAR EXAMINE BATTERY MOUNTING TRAY FOR CORROSION						PKG		
	PKG 6	MOS HRS/MSC AFL	12 1200	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
	REF: GENERIC NO REF								



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/324	STRUCTURAL LIMITATION FUSELAGE AND ASSOCIATED STRUCTURE (POST SB 04-009)	MOS						23-OCT-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A					0	
		AFL						0	
+ 53-00/337 (s)	INSPECTION/CHECK CARRY THROUGH FRAMES 21 AND 24							PKG	
	PKG 6	MOS	12	+10%/-10%				24-OCT-2019	
		HRS/MSC	1200	+10%/-10%				61.5	
	REF: AMM 53-20-02	AFL						53	
+ 53-00/351	UPPER LONGERONS FRAME 10 - EDDY CURRENT INSPECTION								
53.100		MOS						23-OCT-2018	
	REF: AMM 53-10-06	HRS/MSC	N/A					0	
		AFL						0	
+ 53-00/352	FUSELAGE FRAMES 10 TO 16 - EXAMINE ALL STRUCTURAL ELEMENTS								
53.110		MOS						23-OCT-2018	
	REF: AMM 53-10-00	HRS/MSC	N/A					0	
		AFL						0	
+ 53-00/353	FUSELAGE FRAMES 16 TO 36 - EXAMINE ALL STRUCTURAL ELEMENTS								
53.120		MOS						23-OCT-2018	
	REF: AMM 53-20-00	HRS/MSC	N/A					0	
		AFL						0	
+ 53-00/354	EXAMINE ALL STRUCTURAL ELEMENTS - FUSELAGE FRAMES 36 TO 43								
53.130		MOS						23-OCT-2018	
	REF: AMM 53-30-00	HRS/MSC	N/A					0	
		AFL						0	
+ 53-00/355	EXAMINE - ANTENNA STRUCTURE								
53.140		MOS						23-OCT-2018	
	REF: AMM 53-00-00	HRS/MSC	N/A					0	
		AFL						0	
+ 53-00/356	EDDY CURRENT INSPECTION - ANTENNA - BOTTOM FUSELAGE SKIN								
53.150		MOS						23-OCT-2018	
	REF: AMM 53-00-00	HRS/MSC	N/A					0	
		AFL						0	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/357	EDDY CURRENT INSPECTION - ANTENNA - UPPER FUSELAGE SKIN								
53.160		MOS					23-OCT-2018		
	REF: AMM 53-00-00	HRS/MSC	N/A				0		
		AFL					0		
+ 53-00/359	FRAMES 21 AND 24 WING ATTACHMENTS - EDDY CURRENT INSPECTION								
53.180		MOS					23-OCT-2018		
	REF: AMM 57-00-03	HRS/MSC	N/A				0		
		AFL					0		
+ 53-00/360	FRAMES 21 AND 24 SIDE FRAME ATTACHMENTS - EDDY CURRENT INSPECTION								
53.190		MOS					23-OCT-2018		
	REF: AMM 53-20-02	HRS/MSC	N/A				0		
		AFL					0		
+ 53-00/361	FRAMES 41 AND 43 STABILIZER ATTACHMENT - EDDY CURRENT INSPECTION								
53.200		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 53-00/419	EDDY CURRENT INSPECTION - FRAME 40								
53.210		MOS					23-OCT-2018		
	REF: See Workcard	HRS/MSC	N/A				0		
		AFL					0		
+ 53-00/90	EXAMINE FRONT PRESSURE BULKHEAD (WITH INSULATION ON ENGINE AND COCKPIT SIDES REMOVED)								
53.030		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			0	4000	4400
		AFL							
+ 53-00/91	EXAMINE FUSELAGE INTERNAL BOTTOM SURFACE (FRAMES 10,21,24,36 AND FRAMES ADJACENT TO DOORS AND TO EMERGENCY EXIT,WITH INSULATION REMOVED)								
53.040		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			0	4000	4400
		AFL							
+ 53-00/92	EXAMINE REAR PRESSURE BULKHEAD WITH TRIM REMOVED								
53.070		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			0	4000	4400
		AFL							

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00/93	EXAMINE STRUCTURE AROUND WINDOWS								
53.050		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
		HRS/MSC	4000	+10%/-10%			0	4000	4400
	REF: GENERIC NO REF	AFL							
+ 53-00/94	EXAMINE DOOR FRAMES AND EMERGENCY EXIT FRAMES								
53.060		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
		HRS/MSC	4000	+10%/-10%			0	4000	4400
	REF: GENERIC NO REF	AFL							
+ 53-30/342	INSPECTION/CHECK STATIC PORTS CRITICAL AREA								
34.575		MOS	12	+1m/-1m		-1	24-OCT-2019	31-OCT-2020	23-NOV-2020
		HRS/MSC					61.5		
	REF: AMM 53-30-01	AFL					53		
530070	FUSELAGE AB 1003 TEIL1								
53.090	553.05.12.029	MOS					23-OCT-2018		
	1493M	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
CHAPTER 55		STABILIZERS							
+ 55-00/325	STRUCTURAL LIMITATION TAIL STRUCTURE (POST SB 04-009)								
		MOS					23-OCT-2018		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A				0		
		AFL					0		
+ 55-10/197 (s)	EXAMINE HORIZONTAL STABILIZER EXTERNAL SURFACE								
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019	PKG	
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		
+ 55-10/319 (s)	INSPECTION/CHECK HORIZONTAL/VERTICAL STABILIZER ATTACHMENT								
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019	PKG	
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: AMM 55-00-00	AFL					53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-10/415	HORIZONTAL STABILIZER								
55.090	PN	MOS		N:0			23-OCT-2018		
LIFE LIMIT	SN-UNKNOWN	HRS/MSC	25000	N:0			0	25000	
	REF: AMM 55-10-01	AFL	30000	N:0			0	30000	
<hr/>									
+ 55-10/95	EXAMINE HORIZONTAL STABILIZER INTERNAL SURFACES AND HORIZONTAL/VERTICAL STABILIZER INTERFACE (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
		HRS/MSC	4000	+10%/-10%			0	4000	4400
	REF: GENERIC NO REF	AFL							
<hr/>									
+ 55-10/96	EXAMINE VERTICAL STABILIZER INTERNAL SURFACES (AS FAR AS POSSIBLE WITH PANELS REMOVED)								
		MOS	48	+10%/-10%			23-OCT-2018	31-OCT-2022	17-MAR-2023
		HRS/MSC	4000	+10%/-10%			0	4000	4400
	REF: GENERIC NO REF	AFL					0		
<hr/>									
+ 55-20/362	EXAMINE LEFT WING ELEVATOR								
55.100		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 55-20-00	AFL					0		
<hr/>									
+ 55-20/362	EXAMINE RIGHT WING ELEVATOR								
		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 55-20-00	AFL					0		
<hr/>									
+ 55-20/367	EDDY CURRENT INSPECTION - ELEVATOR DRIVE LEVER								
55.110		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 55-20-01	AFL					0		
<hr/>									
+ 55-20/368	EDDY CURRENT INSPECTION - LEFT WING ELEVATOR HINGES								
55.120		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 55-20-01	AFL					0		
<hr/>									
+ 55-20/368	EDDY CURRENT INSPECTION - RIGHT WING ELEVATOR HINGES								
		MOS					23-OCT-2018		
		HRS/MSC	N/A				0		
	REF: AMM 55-20-01	AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-30/198 (s)	EXAMINE VERTICAL STABILIZER EXTERNAL SURFACE SPECIALLY AROUND REAR SPAR TOP RIVETS. PKG 3	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%				61.5	53
+ 55-30/281 (s)	EXAMINE VERTICAL STABILIZER ELECTRICAL BONDING STRAPS PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%				61.5	53
+ 55-30/369	EXAMINE - VERTICAL STABILIZER	MOS						23-OCT-2018	
55.130	REF: AMM 55-30-00	HRS/MSC AFL	N/A					0	0
+ 55-30/370	EDDY CURRENT INSPECTION - VERTICAL STABILIZER MAIN AND REAR SPAR ATTACHMENT TO FUSELAGE	MOS						23-OCT-2018	
55.140	REF: See Workcard	HRS/MSC AFL	N/A					0	0
+ 55-30/371	EDDY CURRENT INSPECTION VERTICAL STABILIZER MAIN ATTACHMENT TO HORIZONTAL STABILIZER	MOS						23-OCT-2018	
55.150	REF: AMM 55-00-00	HRS/MSC AFL	N/A					0	0
+ 55-30/372	EDDY CURRENT INSPECTION VERTICAL STABILIZER PITCH TRIM ACTUATOR FITTING AND ATTACHMENT	MOS						23-OCT-2018	
55.160	REF: AMM 55-30-02	HRS/MSC AFL	N/A					0	0
+ 55-30/420	EDDY CURRENT INSPECTION - VERTICAL STABILIZER FORWARD ATTACHMENT TO FRAME 40	MOS						23-OCT-2018	
55.190	REF: AMM 55-30-03	HRS/MSC AFL	N/A					0	0
+ 55-40/373	EXAMINE - RUDDER	MOS						23-OCT-2018	
55.170	REF: AMM 55-40-00	HRS/MSC AFL	N/A					0	0



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-40/377	EDDY CURRENT INSPECTION - RUDDER HINGES								
55.180		MOS					23-OCT-2018		
	REF: AMM 55-40-05	HRS/MSC	N/A				0		
		AFL					0		
+ 55-40/410	EXAMINE - RUDDER TRIM TAB								
55.200		MOS					23-OCT-2018		
	REF: AMM 55-40-04	HRS/MSC	N/A				0		
		AFL					0		
CHAPTER 56 WINDOWS									
+ 56-10/200 (s)	EXAMINE WINDSHIELD LH AND RH						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 56-00-00	AFL					53		
56-11/12	COCKPIT OUTER SIDE, DV WINDOWS AND CABIN WINDOWS - REPLACE IF CRACKED								
56.020		MOS					23-OCT-2018		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	A/R				0		
		AFL					0		
56-11/13	COCKPIT INNER AND OUTER SIDE, DV WINDOWS AND CABIN WINDOWS- REPLACE IF CHIPPED, CRACKED (ONLY FOR INNER SIDE WINDOWS), CRAZING, SCRATCHED, BUBBLES OR DELAMINATED								
		MOS					23-OCT-2018		
	REF: AMM 56-00-00	HRS/MSC	A/R				0		
		AFL					0		
56-11/14	REPLACE LEFT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)								
	959.81.10.109	MOS					23-OCT-2018		
	17200H1445	HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		
56-11/14	REPLACE RIGHT HAND WINDSHIELD ASSY, (LH) (INNER LAMINATION CRACKED)								
	959.81.10.110	MOS					23-OCT-2018		
	17208H2144	HRS/MSC	A/R				0		
	REF: See Workcard	AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-11/15	LEFT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)								
	959.81.10.109	MOS					23-OCT-2018		
	17200H1445	HRS/MSC	A/R				0		
	REF: GENERIC NO REF	AFL					0		
56-11/15	RIGHT HAND WINDSHIELD ONLY UNPRESSURIZED FLIGHT IS PERMITTED UP TO THE NEXT SCHEDULED INSPECTION PROVIDING IT DOES NOT CAUSE VISUAL PROBLEMS (IF CRACKED IN OUTER LAMINATION)								
	959.81.10.110	MOS					23-OCT-2018		
	17208H2144	HRS/MSC	A/R				0		
	REF: GENERIC NO REF	AFL					0		
+ 56-11/332	INSPECTION/CHECK COCKPIT SIDE WINDOWS								
		MOS	120	+6m/-6m			23-OCT-2018	31-OCT-2028	23-APR-2029
56.100		HRS/MSC	11000	+500/-500			0	11000	11500
	REF: AMM 56-11-02	AFL					0		
+ 56-11/378	WINDSHIELD LH AND RH AND COCKPIT SIDE WINDOWS - EXAMINE WITH WIND-SHIELD AND SIDE WINDOWS REMOVED								
		MOS					23-OCT-2018		
56.110		HRS/MSC	N/A				0		
	REF: See Workcard	AFL					0		
+ 56-20/201 (s)	EXAMINE COCKPIT AND CABIN WINDOWS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: AMM 56-00-00	AFL					53		
560015	SIDE,LH WINDOW								
	959.81.10.111	MOS					23-OCT-2018		
56.090	17184H0137	HRS/MSC	O/C				0		
	REF: AMM 56-11-02	AFL					0		
560020	SIDE,RH WINDOW								
	959.81.10.112	MOS					23-OCT-2018		
56.090	17228H4023	HRS/MSC	O/C				0		
	REF: AMM 56-11-02	AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
560025	RH NO 1 CABIN WINDOW 556.20.12.029 0002848190-012 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560030	RH NO 2 CABIN WINDOW 556.20.12.029 0002848192-004 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560035	RH NO 3 CABIN WINDOW 556.20.12.029 0002848192-005 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560040	RH NO 4 CABIN WINDOW 556.20.12.029 0002848192-010 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560045	RH NO 5 CABIN WINDOW 556.20.12.029 0002848192-009 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560050	LH NO 1 CABIN WINDOW 556.20.12.029 0002848190-011 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560055	LH NO 2 CABIN WINDOW 556.20.12.029 0002848190-010 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
560060	LH NO 3 CABIN WINDOW 556.20.12.029 0002848190-006 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
560065	LH NO 4 CABIN WINDOW									
56.050	556.20.12.029 0002848186-005 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
560070	DV-WINDOW ASSY									
56.030	556.14.12.099 18114H5129 REF: AMM 56-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
561010	LEFT HAND WINDSHIELD ASSY, (LH)									
56.010 AIRWORTHINESS	959.81.10.109 17200H1445 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
561011	RIGHT HAND WINDSHIELD ASSY, (LH)									
56.010 AIRWORTHINESS	959.81.10.110 17208H2144 REF: AMM 56-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0			
CHAPTER 57 WINGS										
+ 57-00/202 (s)	EXAMINE WING EXTERNAL SURFACES						PKG			
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019			
		HRS/MSC	300	+10%/-10%			61.5			
	REF: GENERIC NO REF	AFL					53			
+ 57-00/282 (s)	EXAMINE WING TIP STATIC DISCHARGERS						PKG			
	PKG 7	MOS	24	+10%/-10%			23-OCT-2018			
		HRS/MSC	2400	+10%/-10%			0			
	REF: GENERIC NO REF	AFL					0			
+ 57-00/283 (s)	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT AS FAR AS POSSIBLE WITH PANELS IN TASK 06-00/218 OPENED/REMOVED						PKG			
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019			
		HRS/MSC	1200	+10%/-10%			61.5			
	REF: GENERIC NO REF	AFL					53			



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/284 (s)	EXAMINE WING TO FUSELAGE ATTACHMENTS AS FAR AS POSSIBLE PKG 6	MOS	12	+10%/-10%			PKG	24-OCT-2019	
	REF: GENERIC NO REF	HRS/MSC	1200	+10%/-10%				61.5	
		AFL						53	
+ 57-00/326	STRUCTURAL LIMITATION LEFT WING STRUCTURE (POST SB 04-009)	MOS						23-OCT-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A					0	
		AFL						0	
+ 57-00/326	STRUCTURAL LIMITATION RIGHT WING STRUCTURE (POST SB 04-009)	MOS						23-OCT-2018	
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC	N/A					0	
		AFL						0	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - LEFT WING	MOS						23-OCT-2018	
57.100	REF: AMM 57-00-00	HRS/MSC	N/A					0	
		AFL						0	
+ 57-00/379	EXAMINE ALL STRUCTURAL ELEMENTS RIB 1 TO RIB 20 - RIGHT WING	MOS						23-OCT-2018	
	REF: AMM 57-00-00	HRS/MSC	N/A					0	
		AFL						0	
+ 57-00/380	WING MAIN AND REAR SPAR TO FUSELAGE ATTACHMENT - EDDY CURRENT INSPECTION	MOS						23-OCT-2018	
57.110	REF: See Workcard	HRS/MSC	N/A					0	
		AFL						0	
+ 57-00/382	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS						23-OCT-2018	
57.120	REF: AMM 57-20-10	HRS/MSC	N/A					0	
		AFL						0	
+ 57-00/382	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR AT RIB 8 FLAP ARM ATTACHMENT	MOS						23-OCT-2018	
	REF: AMM 57-20-10	HRS/MSC	N/A					0	
		AFL						0	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/383	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
57.130		MOS					23-OCT-2018		
	REF: AMM 57-20-10	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/383	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES RIB 1 THRU RIB 6								
		MOS					23-OCT-2018		
	REF: AMM 57-20-10	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/384	EDDY CURRENT INSPECTION - LEFT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
57.140		MOS					23-OCT-2018		
	REF: AMM 57-20-05	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/384	EDDY CURRENT INSPECTION - RIGHT WING SPARS AND AUXILIARY STRUCTURE - WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					23-OCT-2018		
	REF: AMM 57-20-05	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/385	EDDY CURRENT INSPECTION - LEFT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
57.150		MOS					23-OCT-2018		
	REF: AMM 57-20-10	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/385	EDDY CURRENT INSPECTION - RIGHT WING REAR SPAR FASTENER HOLES RIB 2 THRU RIB 3								
		MOS					23-OCT-2018		
	REF: AMM 57-20-10	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/412	EXAMINE - WING TIPS								
57.170		MOS					23-OCT-2018		
	REF: AMM 57-33-00	HRS/MSC	N/A				0		
		AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00/413	EDDY CURRENT INSPECTION - LEFT WING SKIN AROUND DRAIN HOLES								
57.180		MOS					23-OCT-2018		
	REF: AMM 57-20-01	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/413	EDDY CURRENT INSPECTION - RIGHT WING SKIN AROUND DRAIN HOLES								
		MOS					23-OCT-2018		
	REF: AMM 57-20-01	HRS/MSC	N/A				0		
		AFL					0		
+ 57-00/427	EDDY CURRENT INSPECTION - LEFT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					23-OCT-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
+ 57-00/427	EDDY CURRENT INSPECTION - RIGHT WING MAIN SPAR FASTENER HOLES STRAP RIB 6								
		MOS					23-OCT-2018		
AIRWORTHINESS	REF: AMM 57-20-10	HRS/MSC	16000				0	16000	
		AFL	22500				0	22500	
+ 57-00/97	EXAMINE WING INTERNAL SURFACES AND FLAP COMPARTMENT (AS FAR AS POSSIBLE WITH ALL WING PANELS REMOVED)								
57.020		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			0	4000	4400
		AFL							
+ 57-00/98	EXAMINE LANDING GEAR COMPARTMENTS (ESPECIALLY MAIN AND REAR SPAR PARTS)								
57.030		MOS	48	+10%/-10%			31-OCT-2018	31-OCT-2022	22-MAR-2023
	REF: GENERIC NO REF	HRS/MSC	4000	+10%/-10%			0	4000	4400
		AFL							
+ 57-00/99	EXAMINE WING TO FUSELAGE ATTACHMENT FITTINGS WITH WINGS REMOVED								
57.040		MOS	120	+6m/-6m			23-OCT-2018	31-OCT-2028	23-APR-2029
	REF: AMM 57-00-00	HRS/MSC	11000	+500/-500			0	11000	11500
		AFL					0		
+ 57-60/393	EXAMINE - RIGHT WING AILERON								
		MOS					23-OCT-2018		
	REF: AMM 57-60-00	HRS/MSC	N/A				0		
		AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60/393	EXAMINE -LEFT WING AILERON								
57.160	REF: AMM 57-60-00	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
+ 57-60/411	EXAMINE - AILERON TRIM TAB								
57.190	REF: AMM 57-60-04	MOS HRS/MSC AFL	N/A				23-OCT-2018 0 0		
570005	AILERON LH 10A SERIE ASSY								
57.050	557.60.12.371 3493 REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
570010	AILERON RH 10A SERIE ASSY								
57.050	557.60.12.372 3493 REF: AMM 57-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
570050	L/H WING								
57.080	557.05.12.049 1494M REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
570055	R/H WING								
57.090	557.05.12.050 1494M REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
CHAPTER 61 PROPELLERS/PROPULSORS									
+ 61-20/286 (s)	EXAMINE PROPELLER GOVERNOR, OVERSPEED GOVERNOR AND BETA CONTROLS						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC AFL	1200	+10%/-10%			61.5 53		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
61PR1	NO. 1 PROPELLER								
61.PR1	HC-E5A-3A SA338 REF: See Workcard	MOS HRS/MSC AFL	PP/C						
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01									
+ 612010	NO. 1 ENGINE - PROPELLER GOVERNOR								
	3049558-01	MOS		N:0			25-JUL-2018		
	21351950	HRS/MSC	3500	+500			0	(3500) 3500	4000
OVERHAUL	REF: EMM 61-20-00	ENC		N:0			0		
+ 612020	NO. 1 ENGINE - OVERSPEED GOVERNOR								
	3079148-01	MOS		N:0			25-JUL-2018		
	21281148	HRS/MSC	3500	+500			0	(3500) 3500	4000
OVERHAUL	REF: GENERIC NO REF	ENC		N:0			0		
PROPELLER NO. 1 Model : HC-E5A-3A Serial # SA338 Part # HC-E5A-3A									
+ 610004	NO. 1 PROPELLER - INSPECTION OF THE DE-ICE SYSTEM								
		MOS	12				01-SEP-2019	30-SEP-2020	
		HRS/MSC	600				50.5	(650.5) 650.5	
	REF: CMM 30-61-80								
+ 610010	NO. 1 PROPELLER - OVERHAUL								
		MOS	72				24-AUG-2018	31-AUG-2024	
		HRS/MSC	4000				0	(4000) 4000	
OVERHAUL	REF: GENERIC NO REF								
+ 610020	NO. 1 PROPELLER - ACCOMPLISH A DETAIL INSPECTION								
		MOS	12				24-OCT-2019	31-OCT-2020	
		HRS/MSC	400				61.5	(461.5) 461.5	
	REF: POM 61-00-47								
+ 610030	NO. 1 PROPELLER - LUBRICATE PROPELLER								
		MOS	12				24-OCT-2019	31-OCT-2020	
		HRS/MSC	400				61.5	(461.5) 461.5	
	REF: POM 61-00-47								



Status Report

PROP.#1: S/N SA338

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 610050	NO. 1 PROPELLER - INSPECT BLADE USING COIN-TAP REF: RMM 61-13-70	MOS HRS/MSC	1200				24-AUG-2018 0	(1200) 1200	
+ 610060	NO. 1 PROPELLER - INSPECT EROSION SHIELD USING COIN-TAP REF: RMM 61-13-70	MOS HRS/MSC	600				24-AUG-2018 0	(600) 600	
611501	NO. 1 PROPELLER - NO. 1 BLADE NC10245B B8747 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			24-AUG-2018 0		
611502	NO. 1 PROPELLER - NO. 2 BLADE NC10245B B8388 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			24-AUG-2018 0		
611503	NO. 1 PROPELLER - NO. 3 BLADE NC10245B B8764 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			24-AUG-2018 0		
611504	NO. 1 PROPELLER - NO. 4 BLADE NC10245B B8762 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			24-AUG-2018 0		
611505	NO. 1 PROPELLER - NO. 5 BLADE NC10245B B8387 REF: GENERIC NO REF	MOS HRS/MSC	O/C	N:0 N:0			24-AUG-2018 0		

CHAPTER 71 POWER PLANT



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/101 (s)	OPERATIONAL TEST POWER PLANT TORQUE LIMITER						PKG		
71.010	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: AMM 71-00-00	AFL					53		
+ 71-00/102 (s)	OPERATIONAL TEST POWER PLANT PERFORMANCE						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: AMM 71-00-00	AFL					53		
+ 71-00/103	PERFORM COMPRESSOR PERFORMANCE RECOVERY WASH								
71.040		MOS					23-OCT-2018		
		HRS/MSC	A/R				0		
	REF: AMM 71-00-00	AFL					0		
+ 71-00/104	PERFORM COMPRESSOR DESALINATION WASH								
		MOS					17-FEB-2020		
		HRS/MSC	A/R				94.8		
	REF: AMM 71-00-00	AFL					70		
+ 71-00/105	PERFORM TURBINE WASH								
		MOS					24-OCT-2019		
		HRS/MSC	A/R				61.5		
	REF: AMM 71-00-00	AFL					53		
+ 71-00/107 (s)	CLEAN ENGINE TORQUE AND STICK PUSHER TORQUE TRANSDUCERS ELECTRICAL CONNECTORS						PKG		
71.030	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: AMM 71-00-03	AFL					53		
+ 71-00/16	ENGINE (PRE SB 04-009) MOUNTING FRAME								
71.050	PN	MOS			N:0		23-OCT-2018		
	SN-UNKNOWN	HRS/MSC	20000		N:0		0		20000
AIRWORTHINESS	REF: AMM 71-00-05	AFL	27000		N:0		0		27000
+ 71-00/17	REPLACE ENGINE MOUNTING FRAME BOLTS, WASHERS AND NUTS								
71.050		MOS					23-OCT-2018		
		HRS/MSC	11000				0		11000
AIRWORTHINESS	REF: GENERIC NO REF	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/204	PERFORM POWER PLANT - POST INSPECTION GROUND RUN TESTS AS NECESSARY TO CLOSE UP INSPECTION PKG 1 ,2,3,4,5,6,7 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 71-00/205 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME AND SHOCKMOUNTS. REPLACE SHOCKMOUNT IF CRACKS IN ELASTOMER ARE MORE THAN 1 IN (25,4 MM) LONG AND/OR 0.06 IN (1,5 MM) DEEP PKG 7 REF: GENERIC NO REF	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 23-OCT-2018 0 0		
+ 71-00/206 (s)	EXAMINE POWER PLANT AND ACCESSORIES. REFER TO P&WC EMM 72-00-00 PERIODIC INSPECTION AND DO THE 100 HOUR AND MINOR INSPECTION ITEMS PKG 1 ,2,3,4,5,6,7 REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 71-00/209 (s)	EXAMINE ENGINE DRAIN MAST AND TANK FOR FUEL LEAKS (NO LEAKS PERMITTED) AND DRAIN (NO EXCESSIVE LEAKS) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 71-00/287	PERFORM POWER PLANT - INSPECTION GROUND RUN - NOTE DEFECTS. PKG 1 ,2,3,4,5,6,7 REF: AMM 71-00-00	MOS HRS/MSC AFL	A/R				PKG 24-OCT-2019 61.5 53		
+ 71-00/301 (s)	EXAMINE ENGINE TUBULAR MOUNTING FRAME FIREWALL ATTACHMENT FITTINGS WITH FIREWALL INSULATION BLANKET REMOVED AS NECESSARY. PKG 7 REF:	MOS HRS/MSC AFL	24 2400	+10%/-10% +10%/-10%			PKG 23-OCT-2018 0 0		
+ 71-00/38	LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY 944.81.21.409 71.063 10954 OVERHAUL REF: AMM 71-00-00	MOS HRS/MSC AFL	3500	N:0 +10%/-10% N:0			23-OCT-2018 0 0	3500 3850	



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-00/38	LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.064	944.81.21.409	MOS		N:0			23-OCT-2018		
OVERHAUL	10963	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
+ 71-00/38	UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY								
71.061	944.81.21.409	MOS		N:0			23-OCT-2018		
OVERHAUL	10957	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
+ 71-00/38	UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY								
71.060	944.81.21.409	MOS		N:0			23-OCT-2018		
OVERHAUL	10956	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
+ 71-00/38	UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY								
71.062	944.81.21.409	MOS		N:0			23-OCT-2018		
OVERHAUL	10962	HRS/MSC	3500	+10%/-10%	N:0		0	3500	3850
	REF: AMM 71-00-00	AFL		N:0			0		
+ 71-00/401	ENGINE MOUNT - MAGNETIC PARTICLE INSPECTION								
71.130		MOS					23-OCT-2018		
	REF: AMM 71-00-05	HRS/MSC	N/A				0		
		AFL					0		
71-00/476 (s)	REVIEW AND COMPLY WITH P&WC AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS AS NECESSARY						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	A/R				61.5		
		AFL					53		
+ 71-10/207 (s)	OPEN AND EXAMINE, ENGINE COWLINGS ENG 43AL AND ENG 43AR AND EXAMINE, PARTICULARLY FOR CONDITION OF RUBBING STRIPS AND FASTENERS. LUBRICATE THE HINGES WITH A MINIMUM OF MATERIAL P10-001						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	A/R				61.5		
		AFL					53		
+ 71-10/208	CLOSE ENGINE COWLINGS ENG 43AL AND ENG 43AR						PKG		
	PKG 1 ,2,3,4,5,6,7	MOS					24-OCT-2019		
	REF: GENERIC NO REF	HRS/MSC	A/R				61.5		
		AFL					53		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710050	(WELDED) ENGINE MOUNT								
71.120	571.20.12.037 159 REF: AMM 71-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
71EN1	NO. 1 ENGINE								
71.EN1	PT6A-67P PCE-RY0904 REF: AMM 71-00-00	MOS HRS/MSC AFL	E/C						
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01									
+ 710011	NO. 1 ENGINE - OVERHAUL								
OVERHAUL	REF: GENERIC NO REF	MOS HRS/MSC ENC	3500	+200			25-JUL-2018 0 0	(3500) 3500	3700
+ 710019 (s)	NO. 1 ENGINE - DO A VISUAL INSPECTION OF THE FIRST-STAGE COMPRESSOR ROTOR WITH A MIRROR OR A BORESCOPE								
	PKG 2	MOS HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 710021	NO. 1 ENGINE - HOT SECTION INSPECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	1750	+250			25-JUL-2018 0 0	(1750) 1750	2000
+ 710031	NO. 1 ENGINE - BORESCOPE HOT SECTION								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	400	+10%/-10%			25-JUL-2018 0 0	(400) 400	440
+ 710041	NO. 1 ENGINE - INSPECT POWER TURBINE BLADES								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	N/A				25-JUL-2018 0 0		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710051	NO. 1 ENGINE - COMPRESSOR WASH PERFORMANCE RECOVERY AND DESALINATION REF: See Workcard	MOS HRS/MSC ENC	100	+10%/-10%		5.2	17-FEB-2020 94.8 70	(200) 200	210
+ 710061	NO. 1 ENGINE - PERFORM ENGINE CONDITION TREND MONITORING (ECTM) REF: EMM 72-00-00	MOS HRS/MSC ENC	100				24-OCT-2019 61.5 53	(161.5) 161.5	
+ 710070 (s)	NO. 1 ENGINE - CHECK FCU MANUAL OVERRIDE SYSTEM FOR STATIC OPERATION PKG 2 REF: EMM 71-00-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
710100	NO. 1 ENGINE - PERFORM CORROSION INHIBITION PROCEDURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
CHAPTER 72 ENGINE									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01									
+ 720010	NO. 1 ENGINE - GAS GENERATOR MODULE OVERHAUL REF: See Workcard	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		25-JUL-2018 0 0	(3500) 3500	4000
+ 720012	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETION AND/OR DEBRIS IN OIL FILTER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
+ 720022	NO. 1 ENGINE - OIL SYSTEM - CHECK OIL LEVEL REF: EMM 72-00-00	MOS HRS/MSC ENC	BF/F				25-JUL-2018 0 0		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720023	NO. 1 ENGINE - CHECK CONDITION AND LOCKING OF OIL FILLER CAP REF: EMM 72-60-00	MOS HRS/MSC ENC	BF/F				25-JUL-2018 0 0		
+ 720025	NO. 1 ENGINE - OVERTEMPERATURE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
+ 720030 (s)	NO. 1 ENGINE - CHECK ALL ACCESSIBLE CONNECTIONS, CLAMPS AND BRACKETS FOR ATTACHMENT PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 720035	NO. 1 ENGINE - OVERTORQUE REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
+ 720040 (s)	NO. 1 ENGINE - CHECK CLAMPS, BRACKETS, TUBES/LINES, LINKAGES FOR CHAFING, CRACKS AND CORROSION PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 720045	NO. 1 ENGINE - HEAVY/HARD LANDING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
+ 720050 (s)	NO. 1 ENGINE - CHECK ACCESSORIES ATTACHMENT AND LINKAGES, AIR, OIL AND FUEL LINES PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 720055	NO. 1 ENGINE - AUDIBLE RUBBING, BINDING OR SCRAPING REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720070 (s)	NO. 1 ENGINE - INSPECT FOR OIL AND FUEL LEAKS AS APPLICABLE PKG 2	MOS					PKG		
	REF: GENERIC NO REF	HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 721015	NO. 1 ENGINE - INADVERTENT CUT-OFF AND RELIGHT DURING TAXI	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 721020	NO. 1 ENGINE - CONTAMINATION OF OIL WITH NON-METALLIC FOREIGN MATERIAL	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 721060	NO. 1 ENGINE - STARTER-GENERATOR REPLACEMENT	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		
+ 721100	NO. 1 ENGINE - PROPELLER SHAFT SEAL - CHECK FOR OIL LEAKS	MOS					25-JUL-2018		
	REF: EMM 72-11-00	HRS/MSC ENC	BF/F				0 0		
+ 722010 (s)	NO. 1 ENGINE - INSPECT THE AIR INLET SCREEN FOR CLEANLINESS PKG 2	MOS					PKG		
	REF: See Workcard	HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 722011	NO. 1 ENGINE - NO. 1 SECOND STAGE REDUCTION PLANET GEAR 3037719	MOS					25-JUL-2018		
	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 722020 (s)	NO. 1 ENGINE - WITH INLET SCREEN REMOVED OR ALTERNATIVELY WITH BORESCOPE, INSPECT COMPRESSOR INLET CASE OVERALL SURFACE AREAS AND STRUTS FOR CORROSION PKG 2 REF: EMM 72-20-00	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 722025	NO. 1 ENGINE - BIRD STRIKE/SOFT MATERIAL INGESTION REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
+ 722030	NO. 1 ENGINE - IMMERSION IN WATER REF: EMM 72-00-00	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
+ 723010	NO. 1 ENGINE - 1ST-STAGE COMPRESSOR ROTOR 3042701 MCAKAXTX031 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		25-JUL-2018 0 0	(24000) 24000	
+ 723020	NO. 1 ENGINE - COMPRESSOR ROTOR SHAFT 3043063 PKAAA766971 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		25-JUL-2018 0 0	(24000) 24000	
+ 723026 (s)	NO. 1 ENGINE - INSPECTION/CHECK GAS GENERATOR CASE EXTERNAL SURFACES, AND FIRESEAL MOUNT RING BRACKETS FOR CRACKS, DISTORTION, AND CORROSION PKG 2 REF: EMM 72-30-04	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 723030	NO. 1 ENGINE - 2ND-STAGE COMPRESSOR ROTOR 3040942 MCAKAXTR045 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	24000		N:0 N:0 N:0		25-JUL-2018 0 0	(24000) 24000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

ENGINE#1: S/N PCE-RY0904

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 723035	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH VOLCANIC ASH OR SMOKE	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
+ 723036 (s)	NO. 1 ENGINE - INSPECTION/CHECK FIRESEAL MOUNT RINGS FOR CRACKS AND ATTACHMENT OF BRACKETS AND SEALS						PKG		
	PKG 2	MOS					24-OCT-2019		
	REF: See Workcard	HRS/MSC	300	+10%/-10%			61.5		
		ENC					53		
+ 723040	NO. 1 ENGINE - 3RD-STAGE COMPRESSOR ROTOR								
	3040933	MOS					25-JUL-2018		
	FRAEPWPD35	HRS/MSC					0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000				0	(24000)	24000
+ 723050	NO. 1 ENGINE - 4TH-STAGE COMPRESSOR ROTOR								
	3040944	MOS					25-JUL-2018		
	EAAE000L889	HRS/MSC					0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000				0	(24000)	24000
+ 723060	NO. 1 ENGINE - CENTRIFUGAL IMPELLER								
	3036898	MOS					25-JUL-2018		
	CRAZAFGE001	HRS/MSC					0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	24000				0	(24000)	24000
+ 723070	NO. 1 ENGINE - PERFORMANCE DETERIORATION								
		MOS					25-JUL-2018		
	REF: See Workcard	HRS/MSC A/R					0		
UNSCHEDULED MAINTENANCE CHECK		ENC					0		
+ 724010	NO. 1 ENGINE - SUSTAINED RUNNING AT OIL TEMPERATURE OUTSIDE LIMITS								
		MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 724015	NO. 1 ENGINE - LOSS OF OIL/OIL PRESSURE OR LOW OIL PRESSURE	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724020	NO. 1 ENGINE - HIGH OIL PRESSURE	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724025	NO. 1 ENGINE - CONTAMINATION BY FIRE EXTINGUISHING AGENTS	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724030	NO. 1 ENGINE - DROPPED ENGINE OR COMPONENT	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724050	NO. 1 ENGINE - MATERIAL INGESTION	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 724055	NO. 1 ENGINE - TEAR OR OPENING FOUND ON MAIN OIL FILTER SECONDARY SCREEN	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 725003	NO. 1 ENGINE - OVERSPEED	MOS						25-JUL-2018	
	REF: EMM 72-00-00	HRS/MSC	A/R				0		
		ENC					0		
+ 725010	NO. 1 ENGINE - COMPRESSOR TURBINE DISK	MOS						25-JUL-2018	
	3053740-01	HRS/MSC		N:0			0		
	YUAB001L518	ENC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	8000	N:0			0	(8000) 8000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725020	NO. 1 ENGINE - REPLACE 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADES	MOS					25-JUL-2018		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC	5000				0 0	(5000) 5000	
+ 725026 (s)	NO. 1 ENGINE - INSPECTION/CHECK EXHAUST DUCT FOR CRACKS AND DISTORTION PKG 2	MOS					24-OCT-2019		
	REF: EMM 72-50-05	HRS/MSC ENC	300	+10%/-10%			61.5 53		
+ 725030	NO. 1 ENGINE - 1ST-STAGE POWER TURBINE DISK 3037312	MOS					25-JUL-2018		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC			N:0 N:0 N:0		0 0 0	(15000) 15000	
+ 725040	NO. 1 ENGINE - 2ND-STAGE POWER TURBINE DISK 3037313	MOS					25-JUL-2018		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC ENC			N:0 N:0 N:0		0 0 0	(15000) 15000	
725122	NO. 1 ENGINE - NO. 1 2ND STAGE POWER TURBINE (3RD STAGE TURBINE) BLADE PN	MOS					25-JUL-2018		
	REF: GENERIC NO REF	HRS/MSC ENC	H/T		N:0 N:0 N:0		0 0 0		
726010	NO. 1 ENGINE - ACCESSORY GEARBOX 3059343-01	MOS					25-JUL-2018		
	REF: GENERIC NO REF	HRS/MSC ENC	O/C		N:0 N:0 N:0		0 0 0		
+ 726020	NO. 1 ENGINE - POWER SECTION MODULE PN	MOS					25-JUL-2018		
OVERHAUL	REF: GENERIC NO REF	HRS/MSC ENC	3500	+500	N:0 N:0 N:0		0 0 0	(3500) 3500	4000
+ 726100	NO. 1 ENGINE - PROPELLER SUDDEN STOPPAGE OR STRIKE	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC ENC	A/R				0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 726120	NO. 1 ENGINE - PROPELLER LIGHTNING STRIKE	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
+ 726130	NO. 1 ENGINE - PROPELLER ELECTRICAL LEADS SHORTING	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
+ 726160	NO. 1 ENGINE - PROPELLER WINDMILLING AFTER IN-FLIGHT SHUTDOWN	MOS					25-JUL-2018		
	REF: EMM 72-00-00	HRS/MSC A/R					0		
		ENC					0		
CHAPTER 73 ENGINE FUEL AND CONTROL									
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01									
+ 731010	NO. 1 ENGINE - FUEL PUMP	MOS					25-JUL-2018		
	3040760	HRS/MSC	3500		N:0		0	(3500)	3500
	016166	ENC			N:0		0		
OVERHAUL	REF: EMM 73-10-02	ENC			N:0		0		
+ 731015	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS					25-JUL-2018		
	REF: See Workcard	HRS/MSC	400	+10%/-10%			0	(400)	400 440
		ENC					0		
+ 731025	NO. 1 ENGINE - LEAK/FUNCTIONAL TEST FUEL MANIFOLD ADAPTER AND NOZZLE ASSEMBLIES (ENGINE NOT ON FUEL NOZZLE IN-SITU CLEANING PROGRAM)	MOS					25-JUL-2018		
	REF: EMM 73-11-05	HRS/MSC	400	+10%/-10%			0	(400)	400 440
		ENC					0		
+ 731030	NO. 1 ENGINE - OVERTORQUE LIMITER	MOS					25-JUL-2018		
	3055748-01	HRS/MSC	3500	+500	N:0		0	(3500)	3500 4000
	C51819	ENC			N:0		0		
OVERHAUL	REF: GENERIC NO REF	ENC			N:0		0		



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731031 (s)	NO. 1 ENGINE - DO A CHECK OF THE FUEL PUMP (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 731035	NO. 1 ENGINE - VISUAL INSPECTION FUEL PUMP TO AGB COVER INTERFACE FOR OIL LEAKAGE AND /OR GASKET MIGRATION REF: EMM 73-10-02	MOS HRS/MSC ENC	1750				25-JUL-2018 0 0	(1750) 1750	
+ 731040	NO. 1 ENGINE - CHECK FUEL PUMP FUEL INLET SCREEN FOR FOREIGN MATTER OR DISTORTION, CLEAN AND REINSTALL, OR INSTALL NEW SCREEN 3040760 016166 REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			25-JUL-2018 0 0	(600) 600	660
+ 731045 (s)	NO. 1 ENGINE - DO A CHECK OF THE OIL-TO-FUEL HEATER (IN-SITU INSPECTION ONLY) FOR INSTALLATION PKG 2 REF: EMM 73-10-01	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 731050	NO. 1 ENGINE - CHECK FUEL PUMP COUPLING IN-SITU FOR FRETTING AND CORROSION 3040760 016166 REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				25-JUL-2018 0 0		
+ 731052	NO. 1 ENGINE - REMOVE FUEL PUMP AND INSPECT THE DRIVE COUPLING AREA AND COVER ACCESSORY GEARBOX SIDE FOR SIGNS OF REDDISH-BROWN (IRON OXIDE) STAINS. IF STAINS ARE OBSERVED RETURN THE FUEL PUMP TO AN APPROVED OVERHAUL FACILITY. REF: EMM 73-10-02	MOS HRS/MSC ENC	N/A				25-JUL-2018 0 0		
+ 731055	NO. 1 ENGINE - REPLACE NO. 1 FUEL PUMP OUTLET FILTER PN-UNKNOWN SN-UNKNOWN REPLACE REF: EMM 73-10-02	MOS HRS/MSC ENC	600	+10%/-10%			24-OCT-2019 61.5 53	(661.5) 661.5	721.5



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731056 (s)	NO. 1 ENGINE - INSPECT PNEUMATIC TUBES AND LINES FOR CRACKS AND DAMAGES ESPECIALLY AT THE END FITTINGS AND JOINTS PKG 2 REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 731060	NO. 1 ENGINE - OIL TO FUEL HEATER 3057249-01 WA57676 REF: EMM 73-10-01	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		25-JUL-2018 0 0	(3500) 3500	4000
+ 731065	NO. 1 ENGINE - EXAMINE FILTER BOWL REF: GENERIC NO REF	MOS HRS/MSC ENC	300	+10%			25-JUL-2018 0 0	(300) 300	330
+ 731070	NO. 1 ENGINE - FLOW DIVIDER/PURGE VALVE 3038472 U0933 REF: EMM 73-10-04	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		25-JUL-2018 0 0	(3500) 3500	4000
+ 731085 (s)	NO. 1 ENGINE - DO A CHECK OF THE DRAIN VALVE (IN-SITU INSPECTION ONLY) OF INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-06	MOS HRS/MSC ENC	300	+10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 731090	NO. 1 ENGINE - FUEL CONTROL UNIT 3119892-10 21320128 REF: EMM 73-20-00 OVERHAUL	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		25-JUL-2018 0 0	(3500) 3500	4000
+ 731091 (s)	NO. 1 ENGINE - DO A CHECK OF THE FLOW DIVIDER (IN-SITU INSPECTION ONLY) FOR INSTALLATION AND LEAKAGE PKG 2 REF: EMM 73-10-04	MOS HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 731095	NO. 1 ENGINE - FUEL CONTROL UNIT (FCU) BELLOWS PN SN-UNKNOWN REF: GENERIC NO REF LIFE LIMIT	MOS HRS/MSC ENC	4000		N:0 N:0 N:0		25-JUL-2018 0 0	(4000) 4000	



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731100	NO. 1 ENGINE - CLEAN P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53	(361.5) 361.5	391.5
+ 731150 (s)	NO. 1 ENGINE - CHECK OUTLET FILTER FOR FOREIGN MATTER OR DISTORTION PKG 2 REF: EMM 73-10-02	MOS HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 731155	NO. 1 ENGINE - FUEL PUMP OUTLET FILTER PN-UNKNOWN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	H/T				24-OCT-2019 61.5 53		
+ 732020 (s)	NO. 1 ENGINE - CHECK FCU FOR INSTALLATION, LINKAGES AND PNEUMATIC LINES PKG 2 REF: EMM 73-20-00	MOS HRS/MSC ENC	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 733020	NO. 1 ENGINE - REPLACE P3 FILTER REF: EMM 73-10-07	MOS HRS/MSC ENC	900	+10%/-10%			25-JUL-2018 0 0	(900) 900	990
+ 733070	NO. 1 ENGINE - CLEAN AND INSPECT P3 FILTER DRAIN VALVE HOUSING ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	300	+10%/-10%			25-JUL-2018 0 0	(300) 300	330
CHAPTER 74	IGNITION								
+ 74-00/288 (s)	OPERATIONAL TEST IGNITION SYSTEM PKG 3 REF: AMM 74-00-00	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01									



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 740010	NO. 1 ENGINE - IGNITION EXCITER 3035889 NNA18250348 REF: EMM 74-10-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		25-JUL-2018 0 0	(3500) 3500	4000
+ 740015	NO. 1 ENGINE - CHECK IGNITION EXCITER FOR INSTALLATION AND CONDITION REF: EMM 74-10-00	MOS HRS/MSC ENC	400	+10%/-10%			24-OCT-2019 61.5 53	(461.5) 461.5	501.5
+ 740025	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION. CHECK FUNCTION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			24-OCT-2019 61.5 53	(461.5) 461.5	501.5
+ 742010	NO. 1 ENGINE - CHECK IGNITION CABLES FOR CHAFING, WEAR AND INSTALLATION REF: EMM 74-20-00	MOS HRS/MSC ENC	400	+10%/-10%			24-OCT-2019 61.5 53	(461.5) 461.5	501.5

CHAPTER 75 AIR
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01

+ 750010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE 3059835-01 AHX1001457 REF: EMM 75-30-00	MOS HRS/MSC ENC	3500	+500	N:0 N:0 N:0		25-JUL-2018 0 0	(3500) 3500	4000
----------	--	-----------------------	------	------	-------------------	--	-----------------------	-------------	------

CHAPTER 76 ENGINE CONTROLS

+ 76-00/210 (s)	EXAMINE ENGINE CONTROLS IN ENGINE COMPARTMENT PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 600	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		
+ 76-00/211 (s)	CHECK BETA SLIP RING CARBON BLOCK - MAKE SURE GAP IS NOT MORE THAN 0.01IN (0.25MM) PKG 3 REF: GENERIC NO REF	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			24-OCT-2019 61.5 53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 76-00/212 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT- CAUTION - DO NOT MOVE PCL INTO THE REVERSE RANGE- PCL- MOVE BETWEEN IDLE AND MAX AND MAKE SURE MOVEMENT FULL AND FREE. CONDITION LEVER- DO THE OPERATIONAL TEST. MANUAL OVERRIDE LEVER- MOVE BETWEEN OFF AND MAX AND MAKE SURE MOVEMENT IS FULL AND FREE. PKG 2	MOS					PKG		
	REF: AMM 76-10-00	HRS/MSC AFL	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 76-00/303 (s)	OPERATIONAL TEST COCKPIT CONTROL QUADRANT - POWER CONTROL, MANUAL OVERRIDE PKG 6	MOS	12	+10%/-10%			PKG		
	REF: See Workcard	HRS/MSC AFL	1200	+10%/-10%			24-OCT-2019 61.5 53		
+ 76-00/304 (s)	EXAMINE COCKPIT CONTROL QUADRANT PKG 3	MOS	12	+10%/-10%			PKG		
	REF: GENERIC NO REF	HRS/MSC AFL	300	+10%/-10%			24-OCT-2019 61.5 53		
+ 76-10/117	FUNCTIONAL TEST PROPELLER FEATHERING MICROSWITCHES	MOS	12	+10%/-10%					
76.010	REF: AMM 76-10-02	HRS/MSC AFL	3000	+10%/-10%	7		24-OCT-2019 61.5 53	31-OCT-2020 3061.5	06-DEC-2020 3361.5
760015	MANUAL OVERRIDE CABLE ASSY. 941.94.11.417	MOS							
76.020	00216 REF: AMM 76-20-00	HRS/MSC AFL	O/C				23-OCT-2018 0 0		
760020	CONDITION CABLE ASSY. 941.94.11.418	MOS							
76.030	00234 REF: GENERIC NO REF	HRS/MSC AFL	O/C				23-OCT-2018 0 0		
760025	POWER CONTROL CABLE ASSY. 941.94.11.419	MOS							
76.040	00230 REF: AMM 76-10-04	HRS/MSC AFL	O/C				23-OCT-2018 0 0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 761011	NO. 1 ENGINE - INSPECT ENGINE CONTROL LINKAGES								
		MOS	12	+30d/-10%			24-OCT-2019	31-OCT-2020	
		HRS/MSC	300	+10%/-10%			61.5	(361.5) 361.5	371.5
	REF: EMM 72-00-00	ENC							

CHAPTER 77 ENGINE INDICATING

770005	TRQ,IPT-51DFP-1000-70D TRANSDUCER								
	975.21.15.206	MOS			N:0		23-OCT-2018		
77.010	8475-4-284	HRS/MSC	O/C		N:0		0		
	REF: AMM 77-40-03	AFL			N:0		0		
770025	DIFFERENTIAL PRESSURE TRANSDUCER								
	975.21.15.219	MOS			N:0		23-OCT-2018		
	10908055	HRS/MSC	O/C		N:0		0		
	REF: GENERIC NO REF	AFL			N:0		0		

ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01

771010	NO. 1 ENGINE - T5 THERMOCOUPLE WIRING HARNESS								
	3043825-01	MOS			N:0		25-JUL-2018		
	NRA103891	HRS/MSC	O/C		N:0		0		
	REF: EMM 77-20-01	ENC			N:0		0		

CHAPTER 78 EXHAUST

+ 78-00/214 (s)	EXAMINE EXHAUST STUBS						PKG		
	PKG 3	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	300	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		

CHAPTER 79 OIL

+ 79-00/422 (s)	OPERATIONAL TEST OIL FILLER CAP / DIPSTICK						PKG		
	PKG 5	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	600	+10%/-10%			61.5		
	REF: AMM 79-30-06	AFL					53		
+ 79-20/289 (s)	EXAMINE ENGINE OIL COOLER. MAKE SURE OUTLET DOOR HAS FULL AND FREE MOVEMENT						PKG		
	PKG 6	MOS	12	+10%/-10%			24-OCT-2019		
		HRS/MSC	1200	+10%/-10%			61.5		
	REF: GENERIC NO REF	AFL					53		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-20/290 (s)	OPERATIONAL TEST OIL SYSTEM CHIP DETECTOR INDICATION SYSTEM PKG 3 REF: AMM 79-30-01	MOS HRS/MSC AFL	12 300	+10%/-10% +10%/-10%			PKG 24-OCT-2019 61.5 53		
+ 79-20/43 79.010 OVERHAUL	OIL COOLER 968.32.14.102 T1855 REF: AMM 79-20-02	MOS HRS/MSC AFL	3500	+10%/-10%	N:0 N:0 N:0		23-OCT-2018 0 0	3500	3850
790005 79.020	TEMPERATURE BULB 975.11.20.101 237287 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-OCT-2018 0 0		
790020 79.030	PRESSURE,GAGE SWITCH 973.81.14.305 1773 REF: AMM 79-30-04	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-OCT-2018 0 0		
790025 79.040	THERMAL ACTUATOR 978.73.01.002 2093 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-OCT-2018 0 0		
ENGINE NO. 1 Model : PT6A-67P Serial # PCE-RY0904 Part # 3072955-01									
701020	NO. 1 ENGINE - CONTAMINATION OF OILWITH NON-METALLIC FOREIGN MATERIAL REF: GENERIC NO REF	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		
790021 DISCARD	NO. 1 ENGINE - SERVICING OF OIL SYSTEM REF: GENERIC NO REF	MOS HRS/MSC ENC	A/R				25-JUL-2018 0 0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

ENGINE#1: S/N PCE-RY0904

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790031	NO. 1 ENGINE - CHECK MAGNETIC CHIP DETECTOR	MOS	12	+30d/-10%			24-OCT-2019	31-OCT-2020	23-NOV-2020
	REF: EMM 79-20-02	HRS/MSC	300	+10%/-10%			61.5	(361.5) 361.5	391.5
		ENC					53		
+ 790040	NO. 1 ENGINE - BRIDGE CHECK MAGNETIC CHIP DETECTOR	MOS	12	+1m/-1m		-1	24-OCT-2019	31-OCT-2020	23-NOV-2020
	REF: EMM 79-20-02	HRS/MSC	600	+10%/-10%			61.5	(661.5) 661.5	721.5
		ENC					53		
+ 790050	NO. 1 ENGINE - REPLACE OIL FILTER ELEMENT	MOS					25-JUL-2018		
	REF: EMM 79-20-02	HRS/MSC	900	+10%/-10%			0	(900) 900	990
		ENC					0		
+ 790060	NO. 1 ENGINE - INSPECT CLEAN OIL FILTER ELEMENT AND SECONDARY SCREEN	MOS					24-OCT-2019		
	REF: EMM 79-20-02	HRS/MSC	300				61.5	(361.5) 361.5	
		ENC					53		
+ 790070	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP INLET SCREEN	MOS					25-JUL-2018		
	REF: EMM 72-60-00	HRS/MSC	1000	+10%/-10%			0	(1000) 1000	1100
		ENC					0		
+ 790080	NO. 1 ENGINE - PERFORM AN OIL SAMPLE	MOS					25-JUL-2018		
	REF: EMM 79-20-02	HRS/MSC	N/A				0		
		ENC					0		
790081	NO. 1 ENGINE - PERFORM OIL ANALYSIS TECHNOLOGY SAMPLING	MOS	12				24-OCT-2019	31-OCT-2020	
	PKG 2	HRS/MSC	300	+10%/-10%			61.5	(361.5) 361.5	391.5
	REF: EMM 72-00-00	ENC					53		
+ 790091 (s)	NO. 1 ENGINE - INSPECT FUEL AND OIL LINES FOR LEAKS	MOS					PKG		
	PKG 2	HRS/MSC	300	+10%/-10%			24-OCT-2019		
	REF: GENERIC NO REF	ENC					61.5		
							53		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

ENGINE#1: S/N PCE-RY0904

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

104 HRS, 79 ENC

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 790093 (s)	NO. 1 ENGINE - CHECK SCAVENGE OIL PUMP HOUSING FOR LEAKS PKG 2	MOS	300	+10%/-10%			PKG 24-OCT-2019 61.5		
	REF: GENERIC NO REF	ENC					53		
792030	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 975.21.15.214	MOS					25-JUL-2018		
	8389-7-617	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	ENC					0		
CHAPTER 91 -									
240120	BATTERY EXT POWER JUNCTION BOX								
90.005	974.03.38.152	MOS					23-OCT-2018		
	1120	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910010	LEFT HD POWER JCT BOX								
	974.03.38.144	MOS					23-OCT-2018		
	1114	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910015	KBT 300 TTP BUS RES, A-157 TERMINAL								
90.015	985.99.12.117	MOS					23-OCT-2018		
	KBT300-4745	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910020	KBT 300 TTP BUS RES, A-175 TERMINAL								
90.025	985.99.12.117	MOS					23-OCT-2018		
	KBT300-4747	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		
910025	KBT 300 TTP BUS RES, A-174 TERMINAL								
90.020	985.99.12.117	MOS					23-OCT-2018		
	KBT300-4755	HRS/MSC	O/C				0		
	REF: GENERIC NO REF	AFL					0		



Status Report

PC-12/47E S/N 1828 (N151MV): 104 HRS, 79 AFL as of 11-Aug-2020

Owner/Operator: LATITUDE 33 AVIATION, LLC

Report Date: 11-AUG-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
910035	CO-PILOT RIGHT HD POWER,FE1549R JUNCTION BOX								
90.030	974.03.38.145 993 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		
910040	KBT 300 TTP BUS RES, A-156 TERMINAL								
90.010	985.99.12.117 KBT300-4740 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-OCT-2018 0 0		