



Status Report

PHENOM 300

S/N 50500281 N419PJ

OWNER: LATITUDE 33 AVIATION, LLC
ADDRESS: 2056 PALOMAR AIRPORT ROAD
CARLSBAD CA 92011

OPERATOR: LATITUDE 33 AVIATION, LLC
ADDRESS: 2056 PALOMAR AIRPORT ROAD
CARLSBAD CA 92011

OFFICE:
FAX: 760-278-2168

OFFICE:
FAX: 760-278-2168

ANALYST: ANDREY KORSUKOV
EMAIL: AKORSUKOV@CAMPSYSTEMS.COM

514-636-2020 (OFFICE)
514-636-7866 (FAX)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

FILTER CRITERIA : Spl. Reqs:INCLUDE;PN/SN-UNKNOWN Components:INCLUDE;Task Type:PACKAGE, COMPONENT, SERVICE

AIRCRAFT	SERIAL / REGNO: 50500281/N419PJ	MODEL: PHENOM 300	MANUFACTURER: EMBRAER
CERTIFICATION DATE: 29-APR-2015		LAST ACTUALS: 1813.6 A/C HRS as of 28-FEB-2023 1035 AFL as of 28-FEB-2023	
ENGINE NO. 1	SERIAL / PART: PCE-DG0533/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 17-DEC-2014 0 ENG. HRS 0 A/C HRS 0 ENC		LAST ACTUALS: 1813.6 ENG. HRS as of 28-FEB-2023 1035 ENC as of 28-FEB-2023	
ENGINE NO. 2	SERIAL / PART: PCE-DG0534/A3072913-01	MODEL: PW535E	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 17-DEC-2014 0 ENG. HRS 0 A/C HRS 0 ENC		LAST ACTUALS: 1813.6 ENG. HRS as of 28-FEB-2023 1035 ENC as of 28-FEB-2023	

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z210-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:87
Z210-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:87
Z220-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service ATA:--
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-41-00							PKG:84
Z220-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-41-00							PKG:87
Z230-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service ATA:--
	MOS	14-Apr-20	120 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-42-00							PKG:87
Z230-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87
Z240-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-42-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z240-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION							Service ATA:--
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-42-00							PKG:84
Z310-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION							Service ATA:--
	MOS	14-Apr-20	120 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-43-00							PKG:87
Z310-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-43-00							PKG:87
Z320-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-43-00							PKG:87
Z320-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION							Service ATA:--
	MOS	14-Apr-20	120 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-43-00							PKG:87
Z330-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:87
Z330-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z340-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service ATA:--
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-44-00							PKG:84
Z340-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-44-00							PKG:87
Z410-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z410-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z430-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service ATA:--
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
	PROC. REF: AMM 05-46-00							PKG:87
Z430-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE							Service ATA:--
	MOS	14-Apr-20	120 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-46-00							PKG:87
Z500-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:--
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
	PROC. REF: AMM 05-45-00							PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA GENERAL								
Z500-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS							Service ATA:--
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
				PROC. REF: AMM 05-45-00				PKG:84
Z700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE MAIN LANDING GEAR BAY							Service ATA:--
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
				PROC. REF: AMM 05-47-00				PKG:84
ATA 00 - INFORMATION								
00-CUS-0701 ^U	RENEWAL OF AIRCRAFT REGISTRATION							Service ATA:00
	MOS		36		30-Apr-24 (M)		426 d	
	HRS							
	AFL							
E53E-160530	NO. 1 ENGINE - REVIEW PW535E MM REV 11.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
				PROC. REF: RCF E53E				
E53E-160530	NO. 2 ENGINE - REVIEW PW535E MM REV 11.0							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	ENC							
				PROC. REF: RCF E53E				
EM55-160520	REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
				PROC. REF: RCF EM55-160520				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-160705								
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-160705-1								
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-160822								
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-161022								
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-161122								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-161122-1								
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55-161202								
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18							Service ATA:00
	MOS/MSC	EFF	-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55								
EM55-190218A	REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF EM55								
EM55-210514-ALS	REVIEW EMBRAER PHENOM 300 - AMM - CHAPTER 04- REV. 14, DATED MAY 14TH, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM55-211103-SMR	REVIEW EMBRAER PHENOM 300 - AMM 2757, SMR REV. 04, DATED NOV 3, 2021							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-220505-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED MAY 05/2022 FOR EMBRAER PHENOM 300							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-220630-CAMP ADJUSTMENT	REVIEW EMBRAER EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED JUN 30, 2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF -								
EM55-220812-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED AUG 12/2022 FOR MODEL EMB-505 - PHENOM 300							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-221017-AWL	REVIEW EMB-505 - PHENOM 300 AMM - PART IV - AIRWORTHINESS LIMITATIONS (AWL) REV 1 DATED OCT 17/2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 00 - INFORMATION								
EM55-221103-SMR	REVIEW EMB-505 - PHENOM 300 AMM - PART III - SCHEDULE MAINTENANCE REQUIREMENTS (SMR) REV 5 DATED NOV 03/2022							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-230201-CAMP ADJUSTMENT	REVIEW EMB-505 - PHENOM 300 CAMP ADJUSTMENT, DATED FEB 01, 2023							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
EM55-230216-CAMP ADJUSTMENT	REVIEW CAMP ADJUSTMENT FORM DATED FEB 16/2023 FOR EMB-505 - PHENOM 300							Service ATA:00
	MOS/MSC		-					REQUIREMENT CHANGE FORMS
	HRS							
	AFL							
PROC. REF: RCF 00								
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-01	800 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)	Adj 21.9	2000	2030	186.4 (+30)	
	AFL	679						
PROC. REF: SMR 05-30-01								PKG:1
05-30-10	1600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	28-Dec-18						
	HRS	1178.1	1600 (+30/-30)	Adj 21.9	2800	2830	986.4 (+30)	
	AFL	679						
PROC. REF: SMR 05-30-10								PKG:10
05-30-20	2400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)		2400	2430	586.4 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-20								PKG:20

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-40	3200 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)		3200	3230	1386.4 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-40								PKG:40
05-30-42	3200 FH/60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	14-Apr-20	60 (+1m/-1m)	Adj 15d	29-Apr-25	29-May-25	790 d (+30)	
	HRS	1483.9	3200 (+30/-30)		4683.9	4713.9	2870.3 (+30)	
	AFL	855						
PROC. REF: SMR 05-30-42								PKG:42
05-30-50	5600 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)		5600	5630	3786.4 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-50								PKG:50
05-30-60	6400 FH MAINTENANCE PACKAGE							Package ATA:05
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)		6400	6430	4586.4 (+30)	
	AFL	0						
PROC. REF: SMR 05-30-60								PKG:60
05-30-80	12 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	30-Apr-22	12 (+1m/-1m)	Adj -1d	29-Apr-23	29-May-23	59 d (+30)	
	HRS	1728.6						
	AFL	989						
PROC. REF: SMR 05-30-80								PKG:80
05-30-81	24 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	26-May-21	24 (+1m/-1m)	Adj -27d	29-Apr-23	29-May-23	59 d (+30)	
	HRS	1601.5						
	AFL	928						
PROC. REF: SMR 05-30-81								PKG:81

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-30-82	36 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	26-May-21	36 (+1m/-1m)	Adj -27d	29-Apr-24	29-May-24	425 d (+30)	
	HRS	1601.5						
	AFL	928						
PROC. REF: SMR 05-30-82								PKG:82
05-30-83	48 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	01-May-19	48 (+1m/-1m)	Adj -2d	29-Apr-23	29-May-23	59 d (+30)	
	HRS	1230						
	AFL	711						
PROC. REF: SMR 05-30-83								PKG:83
05-30-84	60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	14-Apr-20	60 (+1m/-1m)	Adj 15d	29-Apr-25	29-May-25	790 d (+30)	
	HRS	1483.9						
	AFL	855						
PROC. REF: SMR 05-30-84								PKG:84
05-30-87	120 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	29-Apr-15	120 (+1m/-1m)		29-Apr-25	29-May-25	790 d (+30)	
	HRS	0						
	AFL	0						
PROC. REF: SMR 05-30-87								PKG:87
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE							Package ATA:05
	MOS	29-Apr-15	T:120 (+1m/-1m)		29-Apr-25	29-May-25	790 d (+30)	
	HRS	0						
	AFL	0						
PROC. REF: SMR 05-30-90								PKG:90
05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-805	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-805	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-810	NO. 1 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-810	NO. 2 ENGINE - ENGINE IMMERSION IN WATER							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-811	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-811	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-812	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-812	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-813	NO. 1 ENGINE - LOSS OF OIL							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							
05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 05-50-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS								
05-50-00-210-823	NO. 1 ENGINE - FUEL CONTAMINATION							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-823	NO. 2 ENGINE - FUEL CONTAMINATION							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-824	NO. 1 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE							Service ATA:05
	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
05-50-00-210-824	NO. 2 ENGINE - TAKE-OFF POWER TIME EXCEEDANCE							Service ATA:05
	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 05-50-00								
051254	NO. 1 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	30-Apr-22	12 (+30d)	Adj -1d	29-Apr-23	29-May-23	59 d (+30)	
	HRS	1728.6	800 (+10%)		(2528.6) 2528.6	2608.6	715 (+80)	
	ENC	989						
PROC. REF: MM 05-20-00								
								PKG:1
051254	NO. 2 ENGINE - 800 HOURS/ 12 MONTHS INSPECTION							Package ATA:05
	MOS	30-Apr-22	12 (+30d)	Adj -1d	29-Apr-23	29-May-23	59 d (+30)	
	HRS	1728.6	800 (+10%)		(2528.6) 2528.6	2608.6	715 (+80)	
	ENC	989						
PROC. REF: MM 05-20-00								
								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 05 - TIME LIMITS/MAINTENANCE CHECKS									
H140-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service	ATA:05
	MOS		120 (+1m/-1m)						
	HRS								
	AFL								
	PROC. REF: AMM 05-42-00								PKG:87
H242-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE							Service	ATA:05
	MOS	29-Apr-15	120 (+1m/-1m)						
	HRS	0							
	AFL	0							
	PROC. REF: AMM 05-42-00								PKG:87
H430-001 ^S	INTERNAL DETAILED INSPECTION OF ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS							Service	ATA:05
	MOS	14-Apr-20	60 (+1m/-1m)						
	HRS	1483.9							
	AFL	855							
	PROC. REF: AMM 05-46-00								PKG:84
H700-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS							Service	ATA:05
	MOS	14-Apr-20	60 (+1m/-1m)						
	HRS	1483.9							
	AFL	855							
	PROC. REF: AMM 05-47-00								PKG:84
H700-002 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR AND NOSE LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS							Service	ATA:05
	MOS	14-Apr-20	60 (+1m/-1m)						
	HRS	1483.9							
	AFL	855							
	PROC. REF: AMM 05-47-00								PKG:84
H700-003 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING							Service	ATA:05
	MOS	14-Apr-20	60 (+1m/-1m)						
	HRS	1483.9							
	AFL	855							
	PROC. REF: AMM 05-47-00								PKG:84
ATA 21 - AIR CONDITIONING									
21-01-01	RH INSC ILLUM PANEL							Component	ATA:21
PN:441-42629-002	MOS/MSC	29-Apr-15	O/C	TSN 0					

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
SN:1191	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-01-01, AMM 21-01-01								
21-20-01	AVIONICS BLOWER							Component ATA:21
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-07, AMM 31-41-07								
21-20-02	AVIONICS/DISPLAY COOLING FAN							Component ATA:21
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-02, AMM 31-61-02								
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY							Component ATA:21
PN:1300250-9	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:814	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY							Component ATA:21
PN:1300250-9	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:818	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-21-01, AMM 21-21-01								
21-20-05	GROUND COOLING FAN							Component ATA:21
PN:1133660-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:396	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-05, AMM 21-23-05								
21-21-02-001 ^S	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02								
								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-21-02-001 ^S	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-21-02							PKG:60	
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR							Component ATA:21
PN:100000-77	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:28816	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-23-03	RAM AIR VALVE							Component ATA:21
PN:505-18030-405	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000834333	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-23-03, AMM 21-23-03								
21-23-03-002 ^S	OPERATIONAL CHECK OF RAM AIR VALVE							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-03							PKG:60	
21-23-03-003 ^S	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 21-23-03							PKG:1	
21-23-04-001 ^S	OPERATIONAL CHECK OF RAM AIR CHECK VALVES							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-23-04							PKG:60	
21-23-05-001 ^S	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	1600 (+30/-30)					
	AFL	679						
PROC. REF: AMM 21-23-05							PKG:10	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-24-01-001 ^S	OPERATIONAL CHECK OF IFE COOLING FAN							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-24-01							PKG:60
21-31-00-002 ^S	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
	PROC. REF: AMM 21-31-00							PKG:1
21-31-00-003 ^S	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE)							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
	PROC. REF: AMM 21-31-00							PKG:1
21-31-00-004 ^S	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-31-00							PKG:50
21-31-00-005 ^S	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 21-31-00							PKG:50
21-31-01	(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT							Component ATA:21
PN:2119286-9	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2119286-00985	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 21-31-01, AMM 21-31-01							
21-31-01-001	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU)							Service ATA:21
PN:2119286-9	MOS	29-Apr-15						
SN:2119286-00985	HRS	0	5600 (+30/-30)	6000 (M)	6030	4186.4 (+30)		
	AFL	0						
	PROC. REF: AMM 21-31-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-31-02	OUTFLOW VALVE							Component ATA:21
PN:103922-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:103922-00284	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-02, AMM 21-31-02								
21-31-02-001	RESTORATION (REPAIR) OF OUTFLOW VALVE							Service ATA:21
PN:103922-1	MOS	29-Apr-15						
SN:103922-00284	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 21-31-02								
21-31-03	NEGATIVE PRESSURE RELIEF (NPR) VALVE							Component ATA:21
PN:130664-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:34163-0640	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-03, AMM 21-31-03								
21-31-03-001 ^S	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-03								
PKG:50								
21-31-04	PRESSURE RELIEF (PRV) VALVE							Component ATA:21
PN:103918-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:103918-00368	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-31-04, AMM 21-31-04								
21-31-04-001 ^S	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-31-04								
PKG:50								
21-41-01	BHS SHUT-OFF VALVE							Component ATA:21
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-01, AMM 21-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-41-04	RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS							Component ATA:21
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-41-04, AMM 21-41-04								
21-52-01	VCS COMPRESSOR DRIVE MODULE							Component ATA:21
PN:1133640-5	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01								
21-52-01-002	DISCARD OF COMPRESSOR DRIVE MODULE BELT							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	2000 (+30/-30)		3178.1	3208.1	1364.5 (+30)	
	AFL	679						
PROC. REF: AMM 21-52-01								
21-52-01-003 ^S	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 21-52-01								
21-52-01-004	RESTORATION (OVERHAUL) COMPRESSOR							Service ATA:21
PN:1133640-5	MOS	29-Apr-15						
SN:439	HRS	0	2000 (+30/-30)		2000	2030	186.4 (+30)	
	AFL	0						
PROC. REF: AMM 21-52-01								
21-52-02	CDM COMPRESSOR MODULE							Component ATA:21
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-01, AMM 21-52-01								
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE							Component ATA:21
PN:1133860-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-03, AMM 21-52-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-03-001 ^S		GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES						Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 21-52-03								PKG:1
21-52-04		FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER						Component ATA:21
PN:1133850-104	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:121	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-04, AMM 21-52-04, AMM 21-52-04, AMM 21-52-04								
21-52-05		COMPRESSOR DRIVE MODULE BELT						Component ATA:21
PN:PN	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
21-52-06-001 ^S		SERVICING OF VCS REFRIGERANT FLUID						Service ATA:21
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 12-17-00								PKG:80
21-52-08		AIR CONDITION CONDENSER ASSEMBLY						Component ATA:21
PN:1133760-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:379	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-08, AMM 21-52-08								
21-52-08-001 ^S		GENERAL VISUAL INSPECTION OF VCS CONDENSER						Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	1600 (+30/-30)					
	AFL	679						
PROC. REF: AMM 21-52-08								PKG:10
21-52-09		AIR CONDITION MIX FLOW CONDENSER FAN						Component ATA:21
PN:1133720-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:404	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-09, AMM 21-52-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-52-10	AIR CONDITION BLEED AIR HEAT EXCHANGER							Component ATA:21
PN:1320260-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:376	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-52-10, AMM 21-52-10								
21-61-00-001 ^S	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM							Service ATA:21
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 21-61-00								PKG:1
21-61-01	ECS TEMPERATURE CONTROLLER							Component ATA:21
PN:1300670-6	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00398	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-01, AMM 21-61-01								
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2800	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2807	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-03, AMM 21-61-03								
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2885	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-04, AMM 21-61-04								
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH							Component ATA:21
PN:1300450-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2795	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 21-61-05, AMM 21-61-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 21 - AIR CONDITIONING								
21-61-06-001 ^S	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR							Service ATA:21
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 21-61-06								PKG:60
ATA 22 - AUTO FLIGHT								
22-11-00	GMC 715 GUIDANCE PANEL							Component ATA:22
PN:011-01430-00	MOS/MSC	30-Apr-22	O/C	TSR 0				
SN:15900714	HRS	1728.6		TSR 0				
	AFL	989		TSR 0				
PROC. REF: AMM 22-11-01, AMM 22-11-01								
22-11-00-001	FUNCTIONAL CHECK AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
	MOS	27-Apr-22	12 (+30d/-30d)	Adj -26d	01-Apr-23	01-May-23	31 d (+30)	AIRWORTHINESS
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
	MOS	27-Apr-22	12 (+30d/-30d)	Adj -26d	01-Apr-23	01-May-23	31 d (+30)	AIRWORTHINESS
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO							Service ATA:22
	MOS	27-Apr-22	12 (+30d/-30d)	Adj -26d	01-Apr-23	01-May-23	31 d (+30)	AIRWORTHINESS
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 22-11-00								
22-11-00-001	FUNCTIONAL CHECK TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO							Service ATA:22
	MOS	27-Apr-22	12 (+30d/-30d)	Adj -26d	01-Apr-23	01-May-23	31 d (+30)	AIRWORTHINESS
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 22-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-00-002 ^S		LUBRICATION OF SERVO ACTUATORS					Service	ATA:22
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 22-11-00								PKG:80
22-11-00-003 ^S		DETAILED INSPECTION OF AUTOPILOT SERVO CABLE					Service	ATA:22
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 22-11-00								PKG:42
22-11-01		TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO					Component	ATA:22
PN:011-00877-21	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1A0006378	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-02		AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO					Component	ATA:22
PN:011-00878-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1A1011984	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-02		ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO					Component	ATA:22
PN:011-00878-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1A1011933	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-02		RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO					Component	ATA:22
PN:011-00878-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1A1011926	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-02, AMM 22-11-02								
22-11-03		AILERON GSM 86 AUTOPILOT SERVO MOUNT					Component	ATA:22
PN:011-01904-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1GK012553	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-03, AMM 22-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 22 - AUTO FLIGHT								
22-11-06 ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT								Component ATA:22
PN:011-01904-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1GK012390	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-06, AMM 22-11-06								
22-11-09 RUDDER GSM 86 AUTOPILOT SERVO MOUNT								Component ATA:22
PN:011-01904-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1GK012513	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-09, AMM 22-11-09								
22-11-12 TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT								Component ATA:22
PN:011-01904-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1GK012534	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 22-11-12, AMM 22-11-12								
ATA 23 - COMMUNICATIONS								
23-10-01 VHF ANTENNA								Component ATA:23
PN:S65-8280-41	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:322-4047	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-11-01 PS440 HF CONTROL DISPLAY UNIT								Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-01, AMM 23-11-01								
23-11-02 REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER								Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-02, AMM 23-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-11-03	KPA 1052 POWER AMPLIFIER							Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-03, AMM 23-11-03								
23-11-04	HF ANTENNA COUPLER							Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-11-04, AMM 23-11-04								
23-12-02	BOTTOM VHF 2 ANTENNA							Component ATA:23
PN:S65-8280-41	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:322-4055	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-12-02, AMM 23-12-02								
23-21-01	SELCAL CSD DECODER							Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-21-01, AMM 23-21-01								
23-50-01	LEFT GMA 1347D AUDIO PANEL							Component ATA:23
PN:011-01257-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:17108020	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-01, AMM 23-51-01								
23-50-02	COPILOT HEADSET							Component ATA:23
PN:026-55-999-0131	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00202911	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-13-07, AMM 44-13-07								
23-50-02	PILOT HEADSET							Component ATA:23
PN:026-55-999-0131	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00202914	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-13-07, AMM 44-13-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-50-03	LH CONSOLE COCKPIT HAND MICROPHONE							Component ATA:23
PN:85-03-12369-04	MOS/MSC	28-Mar-19	O/C	TSN 0				
SN:524881	HRS	1216.8		TSN 0				
	AFL	700		TSN 0				
PROC. REF: GENERIC NO REF								
23-50-04	COCKPIT SPEAKER							Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-02, AMM 23-51-02								
23-50-05	CDVR MICROPHONE							Component ATA:23
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-07, AMM 31-31-07								
23-51-00-001 ^S	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE							Service ATA:23
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 23-51-00								PKG:40
23-51-01	RIGHT GMA 1347D AUDIO PANEL							Component ATA:23
PN:011-01257-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:17105022	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-01, AMM 23-51-01								
23-51-05	LEFT CONTROL PANEL							Component ATA:23
PN:441-40943-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0507	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-05, AMM 23-51-05								
23-51-05	RIGHT CONTROL PANEL							Component ATA:23
PN:441-40943-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0508	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-51-05, AMM 23-51-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 23 - COMMUNICATIONS								
23-61-00-001 ^S	FUNCTIONAL CHECK OF STATIC DISCHARGERS							Service ATA:23
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 23-61-00								PKG:83
ATA 24 - ELECTRICAL POWER								
24-01-01	LEFT CONSOLE CONTROL PANEL							Component ATA:24
PN:441-40929-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0635	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-01-01, AMM 24-01-01								
24-31-01	NO. 1 ENGINE STARTER/GENERATOR							Component ATA:24
PN:400SG180Q	MOS/MSC	21-Nov-19	O/C	TSO 0				
SN:S00662XL	HRS	1463.8		TSO 0				
	AFL	842		TSO 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01								
24-31-01	NO. 2 ENGINE STARTER/GENERATOR							Component ATA:24
PN:400SG180Q	MOS/MSC	21-Nov-19	O/C	TSO 0				
SN:S01027XL	HRS	1463.8		TSO 0				
	AFL	842		TSO 0				
PROC. REF: AMM 24-31-01, AMM 24-31-01								
24-31-01-001	NO. 1 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service ATA:24
PN:400SG180Q	MOS	21-Nov-19						
SN:S00662XL	HRS	1463.8	800 (+30/-30)	2663.8 (M)	2693.8	850.2 (+30)		
	AFL	842						
PROC. REF: AMM 24-31-01								
24-31-01-001	NO. 2 ENGINE STARTER/GENERATOR - RESTORATION (OVERHAUL) OF STARTER GENERATOR ON EMBRAER 505 ACFT WITH STARTER GENERATOR PN MG103C-4 OR PN 400SG180Q SERIES OR POST-MOD SB 505-24-0017							Service ATA:24
PN:400SG180Q	MOS	21-Nov-19						
SN:S01027XL	HRS	1463.8	800 (+30/-30)	2663.8 (M)	2693.8	850.2 (+30)		
	AFL	842						
PROC. REF: AMM 24-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)							Service ATA:24
PN:400SG180Q	MOS/MSC		N/A					
SN:S00662XL	HRS							
	AFL							
PROC. REF: AMM 24-31-01								
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)							Service ATA:24
PN:400SG180Q	MOS/MSC		N/A					
SN:S01027XL	HRS							
	AFL							
PROC. REF: AMM 24-31-01								
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG550-12A	MOS/MSC	04-Feb-16	O/C	TSN 0				
SN:55031	HRS	268.5		TSN 0				
	AFL	158		TSN 0				
PROC. REF: AMM 24-31-02, AMM 24-31-02								
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT							Component ATA:24
PN:GCSG550-12A	MOS/MSC	04-Feb-16	O/C	TSN 0				
SN:55030	HRS	268.5		TSN 0				
	AFL	158		TSN 0				
PROC. REF: AMM 24-31-02, AMM 24-31-02								
24-31-07-001 ^S	RESTORATION (CLEANING) OF LH SHUNT GENERATOR							Service ATA:24
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: AMM 24-31-07								
								PKG:84
24-31-07-001 ^S	RESTORATION (CLEANING) OF RH SHUNT GENERATOR							Service ATA:24
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: AMM 24-31-07								
								PKG:84
24-36-01	AFT MAIN BATTERY							Component ATA:24
PN:7638-48P	MOS/MSC	30-Apr-22	H/T	TSN 1				
SN:G03139621	HRS	1728.6		TSN 0				
	AFL	989		TSN 0				
PROC. REF: AMM 24-36-01, AMM 24-36-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-01	FORWARD MAIN BATTERY							Component ATA:24
PN:7639-34	MOS/MSC	11-Oct-22	H/T	TSN 3				
SN:G03157243	HRS	1795.6		TSN 0				
	AFL	1024		TSN 0				
PROC. REF: AMM 24-36-01, AMM 24-36-01								
24-36-01-003	DISCARD AFT MAIN BATTERY							Service ATA:24
PN:7638-48P	MOS	30-Apr-22	24 (+1m/-1m)	TAC 1	31-Mar-24	30-Apr-24	396 d (+30)	LIFE LIMIT
SN:G03139621	HRS	1728.6		TAC 0				
	AFL	989	600 (+30/-30)	TAC 0	1589	1619	554 (+30)	
PROC. REF: AMM 24-36-01								
24-36-01-003	DISCARD FORWARD MAIN BATTERY							Service ATA:24
PN:7639-34	MOS	11-Oct-22	24 (+1m/-1m)		11-Oct-24	11-Nov-24	590 d (+31)	LIFE LIMIT
SN:G03157243	HRS	1795.6						
	AFL	1024	600 (+30/-30)		1624	1654	589 (+30)	
PROC. REF: AMM 24-36-01								
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015)							Service ATA:24
PN:7638-48P	MOS/MSC		N/A					
SN:G03139621	HRS							
	AFL							
PROC. REF: GENERIC NO REF								
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015)							Service ATA:24
PN:7639-34	MOS/MSC		N/A					
SN:G03157243	HRS							
	AFL							
PROC. REF: GENERIC NO REF								
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015)							Service ATA:24
PN:7638-48P	MOS	30-Apr-22	T:12 (+1m/-1m)		30-Apr-23	31-May-23	60 d (+31)	
SN:G03139621	HRS	1728.6						
	AFL	989						
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 24 - ELECTRICAL POWER								
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015)							Service ATA:24
PN:7639-34	MOS	11-Oct-22	T:12 (+1m/-1m)		11-Oct-23	11-Nov-23	224 d (+31)	
SN:G03157243	HRS	1795.6						
	AFL	1024						
PROC. REF: GENERIC NO REF								
24-36-02-001 ^S	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2)							Service ATA:24
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 24-36-02								
PKG:60								
24-54-05	28 VDC / 115 VAC STATIC INVERTER							Component ATA:24
PN:AS-24-0026-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0678	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-54-05, AMM 24-54-05								
24-65-00	W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE							Component ATA:24
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-02, AMM 24-65-02								
24-65-01	LEFT POWER DISTRIBUTION BOX							Component ATA:24
PN: SX7EG20-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0327	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-01, AMM 24-65-01								
24-65-02	RIGHT POWER DISTRIBUTION BOX							Component ATA:24
PN: SX7EG21-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-02, AMM 24-65-02								
24-65-04	NOSE POWER DISTRIBUTION BOX							Component ATA:24
PN: SX7EG22-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0314	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 24-65-04, AMM 24-65-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-11-01	COPILOT SEAT							Component ATA:25
PN:1419-04HE	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:763-1419	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01	PILOT SEAT							Component ATA:25
PN:1419-03HE	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:762-1419	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-11-01, AMM 25-11-01								
25-11-01-001 ^S	DETAILED INSPECTION COPILOT SEAT							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-11-01								
25-11-01-001 ^S	DETAILED INSPECTION PILOT SEAT							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-11-01								
25-11-01-002 ^S	DETAILED INSPECTION OF COCKPIT SEAT BELTS							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-11-01								
25-21-01	PAX 1 - RH AFT FACE SEAT							Component ATA:25
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01	PAX 2 - LH AFT FACE SEAT							Component ATA:25
PN:403174-25CDDGEH	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:57861	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-01	PAX 3 - RH AFT FACE SEAT							Component ATA:25
PN:403174-26CDDGEH	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:57863	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01	PAX 6 - LH FWD FACE SEAT							Component ATA:25
PN:403174-27CDDGEH	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:57864	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01	PAX 7 - RH FWD FACE SEAT							Component ATA:25
PN:403174-28CDDGEH	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:57865	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER SEATS							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-01								
							PKG:20	
25-21-01-002 ^S	DETAILED INSPECTION OF PASSENGER SEAT BELTS							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-01								
							PKG:20	
25-21-02	DIVAN							Component ATA:25
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-02, AMM 25-21-02								
25-21-02-001 ^S	DETAILED INSPECTION DIVAN							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-02								
							PKG:40	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-02-002 ^S	DETAILED INSPECTION DIVAN SEAT BELTS							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-21-02								PKG:40
25-21-03	PAX 4 - LH FWD FACE SEAT							Component ATA:25
PN:403174-25CDDGEH	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:57860	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-03	PAX 5 - RH FWD FACE SEAT							Component ATA:25
PN:403174-26CDDGEH	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:57862	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-01, AMM 25-21-01								
25-21-04	(DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY							Component ATA:25
PN:508358-415	MOS/MSC	26-Aug-21	O/C	TSN 0				
SN:A08OCT20-67	HRS	1658.4		TSN 0				
	AFL	953		TSN 0				
PROC. REF: AMM 25-21-04, AMM 25-21-04								
25-21-04-001	RESTORATION (REPAIR) OF SEAT BELT AIRBAG ELECTRONIC MODULE ASSEMBLY (EMA) - NOTE: REPLACE THE EMA (ELECTRONIC MODULE ASSEMBLY) INTERNAL BATTERY							Service ATA:25
PN:508358-415	MOS	26-Aug-21	84		08-Oct-27 (M)		1682 d	
SN:A08OCT20-67	HRS	1658.4						
	AFL	953						
PROC. REF: AMM 25-21-04, AMM 25-21-04								
25-21-04-002	DISCARD OF SEAT BELT AIRBAG INFLATOR GAS CYLINDER							Service ATA:25
PN:PN	MOS	01-Aug-14	120		01-Aug-24		519 d	LIFE LIMIT
SN:UNKNOWN	HRS	0						
	AFL							
PROC. REF: AMM 25-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-21-04-003	DETAILED VISUAL INSPECTION OF SEAT BELT AIRBAG ASSEMBLY							Service ATA:25
PN:PN	MOS	26-May-21	48 (+1m/-1m)	Adj -27d	29-Apr-25	29-May-25	790 d (+30)	
SN:UNKNOWN	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 25-21-04								
25-21-04-004	OPERATIONAL CHECK OF SEAT BELT AIRBAG ASSEMBLY							Service ATA:25
PN:PN	MOS	26-May-21	48 (+1m/-1m)	Adj -27d	29-Apr-25	29-May-25	790 d (+30)	
SN:UNKNOWN	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 25-21-04								
25-21-10	AIRBAG CYLINDER INFLATOR, ACH COLD							Component ATA:25
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
25-21-11	DIVAN SEAT BELT AIRBAG ASSEMBLY							Component ATA:25
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-21-04, AMM 25-21-04								
25-43-01-001 ^S	DETAILED VISUAL INSPECTION BELTED TOILET UNIT							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-43-02								
PKG:40								
25-43-01-002 ^S	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT							Service ATA:25
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 25-43-02								
PKG:40								
25-60-01	EMERGENCY LOCATOR TRANSMITTER							Component ATA:25
PN:S1821502-02	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LX1100115090	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-60-03	ELT ANTENNA							Component ATA:25
PN:S65-8282-406	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:401-2550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-03, AMM 25-61-03								
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY							Component ATA:25
PN:S1820506-01	MOS/MSC	20-Oct-20	H/T	TSN 0				
SN:20230195	HRS	1531.4		TSN 0				
	AFL	894		TSN 0				
PROC. REF: AMM 25-61-01, AMM 25-61-01								
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM							Service ATA:25
PN:S1821502-02	MOS	27-Apr-22	12	Adj -13d	14-Apr-23		44 d	
SN:LX1100115090	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 25-61-00								
25-61-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY LOCATOR TRANSMITTER							Service ATA:25
PN:S1821502-02	MOS	27-Apr-22	12	Adj -13d	14-Apr-23		44 d	
SN:LX1100115090	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 25-61-00								
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY							Service ATA:25
PN:S1820506-01	MOS/MSC	20-Oct-20	DUE		01-May-27 (M)		1522 d	LIFE LIMIT
SN:20230195	HRS	1531.4						
	AFL	894						
PROC. REF: AMM 25-61-04								
25-61-05	CS144-A ELT/NAV INTERFACE MODULE							Component ATA:25
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-61-05, AMM 25-61-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-01	FIRST AID KIT							Component ATA:25
PN:PN	MOS/MSC	26-Aug-21	H/T	TSN 0				
SN:UNKNOWN	HRS	1658.4		TSN 0				
	AFL	953		TSN 0				
PROC. REF: GENERIC NO REF								
25-62-01-001	VISUAL CHECK FIRST AID KIT							Service ATA:25
PN:PN	MOS/MSC	06-Oct-22	DUE		31-Aug-23 (M)		183 d	
SN:UNKNOWN	HRS							
	AFL							
PROC. REF: AMM 25-62-01								
25-62-02	COPILOT LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2650871	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 1 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680226	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 2 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680227	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 3 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680228	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 4 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680239	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02	NO. 5 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680229	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 6 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680241	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 7 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680231	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	NO. 8 PASSENGER LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680240	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	PILOT LIFE VEST							Component ATA:25
PN:66601-505	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2650852	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02	TOILET PAX LIFE VEST							Component ATA:25
PN:66601-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:L2680242	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 25-62-02, AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST							Service ATA:25
	MOS	01-Sep-14	120		01-Sep-24		550 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST							Service ATA:25
	MOS	01-Sep-14	120		01-Sep-24		550 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-02-001	RESTORATION (OVERHAUL) OF TOILET LIFE VEST							Service ATA:25
	MOS	01-Oct-14	120		01-Oct-24		580 d	OVERHAUL
	HRS							
	AFL							
PROC. REF: AMM 25-62-02								
25-62-04-001 ^S	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER							Service ATA:25
	MOS	26-May-21	24 (+1m/-1m)					
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 25-62-04								
PKG:81								
25-66-01	LIFE RAFT							Component ATA:25
PN:1015FASA-331-1-101	MOS/MSC	09-Nov-22	O/C	TSN 0				
SN:10SA-00247	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 25 - EQUIPMENT/FURNISHINGS								
25-66-01-001	RESTORATION LIFE RAFT (OVERHAUL)							Service ATA:25
PN:1015FASA-331-1-101	MOS/MSC	09-Nov-22	DUE		01-Oct-25 (M)		945 d	
SN:10SA-00247	HRS							
	AFL							
PROC. REF: AMM 25-66-01								
25-66-CUS-001 ^U	GENERAL VISUAL INSPECTION OF LIFE RAFT							Service ATA:25
PN:1015FASA-331-1-101	MOS	09-Nov-22	12		09-Nov-23		253 d	
SN:10SA-00247	HRS							
	AFL							
25-66-CUS-002 ^U	RENEW LIFE RAFT ELT REGISTRATION							Service ATA:25
PN:1015FASA-331-1-101	MOS/MSC		DUE		15-Nov-24 (M)		625 d	
SN:10SA-00247	HRS							
	AFL							
ATA 26 - FIRE PROTECTION								
26-11-01	LEFT ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-51-565/215C-5.1M	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:49751	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01								
26-11-01	RIGHT ENGINE FIRE DETECTOR							Component ATA:26
PN:3951-51-565/215C-5.1M	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:49755	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-11-01, AMM 26-11-01								
26-11-01-001 ^S	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	28-Dec-18						
	HRS	1178.1	1600 (+30/-30)					
	AFL	679						
PROC. REF: AMM 26-11-01								
								PKG:10

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-11-01-001 ^S	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	28-Dec-18						
	HRS	1178.1	1600 (+30/-30)					
	AFL	679						
	PROC. REF: AMM 26-11-01							PKG:10
26-11-01-002 ^S	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
	PROC. REF: AMM 26-11-01							PKG:1
26-11-01-002 ^S	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR							Service ATA:26
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
	PROC. REF: AMM 26-11-01							PKG:1
26-15-01	MODEL 602 SMOKE DETECTOR							Component ATA:26
PN:8930-223B60L014	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:23981	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 26-15-01, AMM 26-15-01							
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE							Component ATA:26
PN:33000073-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:70481A1	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 26-21-03, AMM 26-21-03							
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL							Service ATA:26
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	2400 (+30/-30)		2400	2430	586.4 (+30)	
	AFL	0						
	PROC. REF: AMM 26-21-00							
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL							Component ATA:26
PN:441-42702-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0584	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 26-21-01, AMM 26-21-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-03-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHER BOTTLE							Service ATA:26
PN:33000073-1	MOS	01-Aug-14	120		01-Aug-24		519 d	AIRWORTHINESS
SN:70481A1	HRS							
	AFL							
PROC. REF: AMM 26-21-03								
26-21-05-001 ^S	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS)							Service ATA:26
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-21-05								
PKG:20								
26-21-07	NO. 1 CARTRIDGE							Component ATA:26
PN:30903962-1	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:1823RH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07	NO. 2 CARTRIDGE							Component ATA:26
PN:30903963-1	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:0631RH	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-21-07, AMM 26-21-07								
26-21-07-001	DISCARD NO. 1 CARTRIDGE							Service ATA:26
PN:30903962-1	MOS	01-Sep-14	120		01-Sep-24		550 d	LIFE LIMIT
SN:1823RH	HRS							
	AFL							
Manufacture Date:: 01-Sep-14 PROC. REF: AMM 26-21-07								
26-21-07-001	DISCARD NO. 2 CARTRIDGE							Service ATA:26
PN:30903963-1	MOS	01-Sep-14	120		01-Sep-24		550 d	LIFE LIMIT
SN:0631RH	HRS							
	AFL							
PROC. REF: AMM 26-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-21-09-001 ^S	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING							Service ATA:26
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 26-21-09								PKG:20
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:RT-A1200	MOS/MSC	27-Apr-18	H/T	TSN 0				
SN:Y-501331	HRS	1013.5		TSN 0				
	AFL	579		TSN 0				
PROC. REF: AMM 26-24-01, AMM 26-24-01								
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER							Component ATA:26
PN:RT-A1200	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:Y-499700	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 26-24-01, AMM 26-24-01								
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	25-Apr-22	12	Adj -11d	14-Apr-23		44 d	
SN:Y-501331	HRS							
	AFL							
PROC. REF: AMM 26-24-01								
26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	25-Apr-22	12	Adj -11d	14-Apr-23		44 d	
SN:Y-499700	HRS							
	AFL							
PROC. REF: AMM 26-24-01								
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	01-Jan-17	144		01-Jan-29		2133 d	LIFE LIMIT
SN:Y-501331	HRS							
	AFL							
PROC. REF: AMM 26-24-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 26 - FIRE PROTECTION								
26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
PN:RT-A1200	MOS	01-Oct-14	144		01-Oct-26		1310 d	LIFE LIMIT
SN:Y-499700	HRS							
	AFL							
Manufacture Date:: 01-Oct-14 PROC. REF: AMM 26-24-01								
26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 26-24-01								
26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER							Service ATA:26
	MOS/MSC		N/A					
	HRS							
	AFL							
PROC. REF: AMM 26-24-01								
ATA 27 - FLIGHT CONTROLS								
27-001	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS/MSC	29-Apr-15	N/A					
SN:0599	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-001	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS/MSC	29-Apr-15	N/A					
SN:0024	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-002	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS/MSC	29-Apr-15	N/A					
SN:1173	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-002	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS/MSC	29-Apr-15	N/A					
SN:1182	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-003	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS/MSC	29-Apr-15	N/A					
SN:1178	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-003	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS/MSC	29-Apr-15	N/A					
SN:1186	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-004	ROLL TRIM ACTUATOR							Component ATA:27
PN:470500-1005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0300	HRS	0	12000	TSN 0	12000		10186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-02, AMM 27-14-02								
27-005	YAW TRIM ACTUATOR							Component ATA:27
PN:470600-1005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0299	HRS	0	12000	TSN 0	12000		10186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-02, AMM 27-24-02								
27-006	PITCH TRIM ACTUATOR							Component ATA:27
PN:467500-1003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0306	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-41-01, AMM 27-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-007	LEFT SPOILER ACTUATOR							Component ATA:27
PN:456800-1003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0580	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02								
27-007	RIGHT SPOILER ACTUATOR							Component ATA:27
PN:456800-1003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0581	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-64-01, AMM 27-64-01, AMM 27-64-02, AMM 27-64-02								
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-70-01, AMM 27-70-01								
27-009	RUDDER BOOSTER ACTUATOR							Component ATA:27
PN:9125-3	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0242T	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-23-02, AMM 27-23-02								
27-01-01	LEFT CONTROL WHEEL							Component ATA:27
PN:83912139	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00864	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01								
27-01-01	RIGHT CONTROL WHEEL							Component ATA:27
PN:83912141	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00824	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-01, AMM 27-01-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-01-02	LH PEDAL ASSEMBLY							Component ATA:27
PN:505-15420-427	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000833145	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-02, AMM 27-01-02								
27-01-02	RH PEDAL ASSEMBLY							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-01-02, AMM 27-01-02								
27-01-03-001 ^S	LUBRICATION OF ROTARY BALL SPLINE							Service ATA:27
	MOS	26-May-21	24 (+1m/-1m)					
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 12-21-00								
PKG:81								
27-010	LEFT TOGGLE LINK							Component ATA:27
PN:456870-1001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0654	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-65-02, AMM 27-65-02								
27-010	RIGHT TOGGLE LINK							Component ATA:27
PN:456870-1001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0666	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-65-02, AMM 27-65-02								
27-011	STICK PUSHER ACTUATOR							Component ATA:27
PN:9124-1	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0309T	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-36-02, AMM 27-36-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-012	POWER DRIVE UNIT							Component ATA:27
PN:467700-1003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0330	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-07, AMM 27-51-07								
27-013	LEFT FLAP POSITION SENSOR UNIT							Component ATA:27
PN:457310-1001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0646	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-013	RIGHT FLAP POSITION SENSOR UNIT							Component ATA:27
PN:457310-1001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:0572	HRS	0	35000	TSN 0	35000		33186.4	
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-03, AMM 27-53-03								
27-014	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS/MSC	29-Apr-15	N/A					
SN:SSW0570	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	29-Apr-15						LIFE LIMIT
SN:SSW1151	HRS	0	35000		35000		33186.4	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	29-Apr-15						LIFE LIMIT
SN:SSW1156	HRS	0	35000		35000		33186.4	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-014	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS/MSC	29-Apr-15	N/A					
SN:SSW0581	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	29-Apr-15						LIFE LIMIT
SN:SSW1157	HRS	0	35000		35000		33186.4	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-014	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS	29-Apr-15						LIFE LIMIT
SN:SSW1165	HRS	0	35000		35000		33186.4	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD LEFT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS	29-Apr-15						LIFE LIMIT
SN:SSW0570	HRS	0	35000		35000		33186.4	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD LEFT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	N/A					
SN:SSW1151	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	N/A					
SN:SSW1156	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-015	DISCARD RIGHT CENTER FLAP FLEXIBLE 2 SHAFT							Service ATA:27
PN:457360-1007	MOS	29-Apr-15						LIFE LIMIT
SN:SSW0581	HRS	0	35000		35000		33186.4	
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	N/A					
SN:SSW1157	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-015	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT							Service ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	N/A					
SN:SSW1165	HRS	0						
	AFL	0						
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-016	DISCARD LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS	29-Apr-15						LIFE LIMIT
SN:0599	HRS	0	7200		7200		5386.4	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-016	DISCARD RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475100-1013	MOS	29-Apr-15						LIFE LIMIT
SN:0024	HRS	0	7200		7200		5386.4	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-017	DISCARD LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS	29-Apr-15						LIFE LIMIT
SN:1173	HRS	0	7200		7200		5386.4	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-017	DISCARD RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-2013	MOS	29-Apr-15						LIFE LIMIT
SN:1182	HRS	0	7200		7200		5386.4	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-018	DISCARD LEFT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS	29-Apr-15						LIFE LIMIT
SN:1178	HRS	0	7200		7200		5386.4	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-018	DISCARD RIGHT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
PN:475000-1013	MOS	29-Apr-15						LIFE LIMIT
SN:1186	HRS	0	7200		7200		5386.4	
	AFL	0						
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL							Component ATA:27
PN:462900-1015	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0808	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-03-01, AMM 27-03-01								
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL							Component ATA:27
PN:462900-1015	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0809	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-03-01, AMM 27-03-01								
27-03-01-002 ^S	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-03-01								
								PKG:50

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-03-01-003 ^S	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-03-01							PKG:50	
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	4586.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-03-01								
27-04-01	TRIM ACTUATOR CONTROLLER							Component ATA:27
PN:475200-1009	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0342	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-04-01, AMM 27-04-01								
27-04-01-001 ^S	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01							PKG:50	
27-04-01-002 ^S	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-04-01							PKG:50	
27-11-00	AILERON CABLES ASSY.							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-02, AMM 27-11-02								
27-11-00-001 ^S	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 27-11-00							PKG:42	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-11-01	LEFT AILERON							Component ATA:27
PN:505-14717-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841196	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-01, AMM 27-11-01								
27-11-01	RIGHT AILERON							Component ATA:27
PN:505-14718-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841197	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-11-01, AMM 27-11-01								
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION							Service ATA:27
	MOS	26-May-21	60 (+1m/-1m)	Adj -29d	27-Apr-26	27-May-26	1153 d (+30)	
	HRS	1601.5	3200 (+30/-30)		4801.5	4831.5	2987.9 (+30)	
	AFL	928						
PROC. REF: AMM 27-11-02								
27-11-02-001(INITIAL)	FUNCTION CHECK OF AILERON CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	29-Apr-15	-					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-11-02								
27-11-02-002 ^S	DETAILED INSPECTION OF AILERON CONTROL CABLES							Service ATA:27
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 27-11-02								
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	4186.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-14-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	4586.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-14-02								
27-14-03	LEFT AILERON TAB							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-14-03, AMM 27-14-03								
27-21-00	RUDDER CABLES ASSY.							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-21-02, AMM 27-21-02								
27-21-00-001 ^S	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 27-21-00								
								PKG:42
27-21-01	RUDDER ASSEMBLY							Component ATA:27
PN:505-39084-413	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841194	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-21-01, AMM 27-21-01								
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION							Service ATA:27
	MOS	26-May-21	60 (+1m/-1m)	Adj -29d	27-Apr-26	27-May-26	1153 d (+30)	
	HRS	1601.5	3200 (+30/-30)		4801.5	4831.5	2987.9 (+30)	
	AFL	928						
PROC. REF: AMM 27-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-21-02-001(INITIAL)		FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION - INITIAL 12 MOS CHECK						Service ATA:27
	MOS/MSC	29-Apr-15	-					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-21-02								
27-21-02-002 ^S		DETAILED INSPECTION OF RUDDER CONTROL CABLES						Service ATA:27
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 27-21-02								
PKG:42								
27-23-00-001 ^S		OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM						Service ATA:27
	MOS	28-Dec-18						
	HRS	1178.1	1600 (+30/-30)					
	AFL	679						
PROC. REF: AMM 27-23-00								
PKG:10								
27-24-02-001		FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH						Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6000 (+30/-30)		6000	6030	4186.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-24-03								
27-24-02-002		DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM						Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	4586.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-24-02								
27-24-03		RUDDER TRIM TAB						Component ATA:27
PN:505-10450-409	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000839621	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-24-03, AMM 27-24-03								
27-26-01		VENTRAL RUDDER						Component ATA:27
PN:505-07540-417	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000838744	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-26-01, AMM 27-26-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-00	ELEVATOR CABLES ASSY							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-02, AMM 27-31-02								
27-31-00-001 ^S	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS							Service ATA:27
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 27-31-00								
								PKG:42
27-31-01	LEFT ELEVATOR							Component ATA:27
PN:505-11082-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841185	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-01	RIGHT ELEVATOR							Component ATA:27
PN:505-11082-402	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841187	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-01, AMM 27-31-01								
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION							Service ATA:27
	MOS	26-May-21	60 (+1m/-1m)	Adj -29d	27-Apr-26	27-May-26	1153 d (+30)	
	HRS	1601.5	3200 (+30/-30)		4801.5	4831.5	2987.9 (+30)	
	AFL	928						
PROC. REF: AMM 27-31-02								
27-31-02-001(INITIAL)	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION - INITIAL 12 MOS CHECK							Service ATA:27
	MOS/MSC	29-Apr-15	-					
	HRS	0						
	AFL	0						
PROC. REF: AMM 27-31-02								
27-31-02-002 ^S	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES							Service ATA:27
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9	3200 (+30/-30)					
	AFL	855						
PROC. REF: AMM 27-31-02								
								PKG:42

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-31-03	LEFT ELEVATOR TAB							Component ATA:27
PN:505-11084-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000840878	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03, AMM 27-31-03								
27-31-03	RIGHT ELEVATOR TAB							Component ATA:27
PN:505-11084-402	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000839351	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-31-03, AMM 27-31-03								
27-31-03-001 ^S	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-31-03								PKG:50
27-31-03-002 ^S	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-31-03								PKG:50
27-36-03-001 ^S	OPERATIONAL CHECK OF PUSHER CUTOUT SWITCH							Service ATA:27
	MOS	01-May-19						
	HRS	1230	1600 (+30/-30)					
	AFL	711						
PROC. REF: AMM 27-36-03								PKG:10
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6400 (+30/-30)	6400	6430	4586.4 (+30)		
	AFL	0						
PROC. REF: AMM 27-41-01								
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6000 (+30/-30)	6000	6030	4186.4 (+30)		
	AFL	0						
PROC. REF: AMM 27-40-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-41-01-003 ^S	LUBRICATION OF PITCH TRIM ACTUATOR							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 12-21-00							PKG:83	
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	4586.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-41-01								
27-41-01-005 ^S	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 12-18-00							PKG:83	
27-41-01-006 ^S	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-41-01							PKG:50	
27-43-02	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL							Component ATA:27
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 27-51-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-001 ^S	LUBRICATION OF FLAP ACTUATORS BALL SCREWS							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 12-21-00								PKG:83
27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								
27-51-01-002	DETAILED INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								
27-51-01-002	DETAILED INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								
27-51-01-002	DETAILED INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								
27-51-01-002	DETAILED INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-002	DETAILED INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	7200 (+30/-30)		7200	7230	5386.4 (+30)	
	AFL	0						
PROC. REF: AMM 27-51-01								
27-51-01-005 ^S	SERVICING OF FLAP ACTUATOR GEAR BOXES							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 12-18-00								
PKG:83								
27-51-01-900-801-01	LEFT NO. 3 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475100-1013	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:0599	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-02	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475100-1013	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:0024	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-03	LEFT NO. 2 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-2013	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:1173	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-04	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-2013	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:1182	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-01-900-801-05	LEFT NO. 1 INBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-1013	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:1178	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-01-900-801-06	RIGHT NO. 1 INBOARD FLAP ACTUATOR							Component ATA:27
PN:475000-1013	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:1186	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-01, AMM 27-51-01								
27-51-05	LEFT INBOARD FLAP							Component ATA:27
PN:505-14358-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000842001	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-05	LEFT OUTBOARD FLAP							Component ATA:27
PN:505-14359-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841952	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-05	RIGHT INBOARD FLAP							Component ATA:27
PN:505-14358-402	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841954	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-05	RIGHT OUTBOARD FLAP							Component ATA:27
PN:505-14359-402	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000841468	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-04, AMM 27-51-04, AMM 27-51-05, AMM 27-51-05								
27-51-06-001 ^S	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 12-21-00								
PKG:83								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-001 ^S	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-001 ^S	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-001 ^S	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-001 ^S	LUBRICATION RIGHT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-001 ^S	LUBRICATION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 12-21-00							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION LEFT CENTER FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 27-51-06							PKG:83
27-51-06-002 ^S	DETAILED VISUAL INSPECTION LEFT OUTBOARD FLAP FLEXIBLE SHAFT							Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
	PROC. REF: AMM 27-51-06							PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-002 ^S		DETAILED VISUAL INSPECTION LH INBOARD FLAP FLEXIBLE SHAFT						Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 27-51-06								PKG:83
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RH INBOARD FLAP FLEXIBLE SHAFT						Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 27-51-06								PKG:83
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RIGHT CENTER FLAP FLEXIBLE SHAFT						Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 27-51-06								PKG:83
27-51-06-002 ^S		DETAILED VISUAL INSPECTION RIGHT OUTBOARD FLAP FLEXIBLE SHAFT						Service ATA:27
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 27-51-06								PKG:83
27-51-06-900-801-01		RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SSW1165	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-51-06-900-801-02		RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SSW1157	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-51-06-900-801-03		LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT						Component ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SSW1156	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-06, AMM 27-51-06								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-51-06-900-801-04	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT							Component ATA:27
PN:457360-1005	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SSW1151	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-51-06-900-801-05	LEFT CENTER FLAP FLEXIBLE 2 SHAFT							Component ATA:27
PN:457360-1007	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SSW0570	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-51-06-900-801-06	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT							Component ATA:27
PN:457360-1007	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SSW0581	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-51-06, AMM 27-51-06								
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER							Component ATA:27
PN:780501-9	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1589	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-53-01, AMM 27-53-01								
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS-INTERNAL							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 27-64-00								
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 27-64-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL							Service ATA:27
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 7 27-64-00								
27-65-00-001 ^S	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-60-00								
PKG:60								
27-65-01-001 ^S	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU)							Service ATA:27
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 27-65-00								
PKG:60								
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR							Component ATA:27
PN:456896-1001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:134359	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-01, AMM 27-66-01								
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR							Component ATA:27
PN:456896-1001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:134360	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-01, AMM 27-66-01								
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR							Component ATA:27
PN:456897-1001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:136638	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-02, AMM 27-66-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 27 - FLIGHT CONTROLS								
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR							Component ATA:27
PN:456897-1001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:136640	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 27-66-02, AMM 27-66-02								
ATA 28 - FUEL								
28-11-00-001 ^S	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS							Service ATA:28
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 28-11-00								PKG:80
28-11-05	LEFT WING WATER DRAIN VALVE							Component ATA:28
PN:L83A13-628	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J00290	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-11-05	RIGHT WING WATER DRAIN VALVE							Component ATA:28
PN:L83A13-628	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J00280	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-05, AMM 28-11-05								
28-11-07	LEFT WING DUMP VALVE							Component ATA:28
PN:V98A32-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J12614	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07								
28-11-07	RIGHT WING DUMP VALVE							Component ATA:28
PN:V98A32-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J12620	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-11-07, AMM 28-11-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-12-01-001 ^S	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA							Service ATA:28
	MOS	14-Apr-20						
	HRS	1483.9	800 (+30/-30)					
	AFL	855						
PROC. REF: AMM 28-12-01								PKG:1
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J02378	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03								
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE							Component ATA:28
PN:L87-19-001P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J16043	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-12-03, AMM 28-12-03								
28-12-03-001 ^S	OPERATIONAL CHECK LEFT FLOAT VENT VALVE							Service ATA:28
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03								PKG:60
28-12-03-001 ^S	OPERATIONAL CHECK RIGHT FLOAT VENT VALVE							Service ATA:28
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-12-03								PKG:60
28-21-01	LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								
28-21-01	RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE							Component ATA:28
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-01, AMM 28-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-02	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE							Component ATA:28
PN:P99C25-606P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G35760	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-02	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE							Component ATA:28
PN:P99C25-606P2	MOS/MSC	01-May-19	O/C					
SN:G97192	HRS	1230						
	AFL	711						
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-03	LEFT WING DC AUXILIARY BOOST PUMP CANISTER							Component ATA:28
PN:C93R25-606P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G36260	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-03	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER							Component ATA:28
PN:C93R25-606P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G36263	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-03, AMM 28-21-03								
28-21-05	LEFT WING JET PUMP FEED LINE							Component ATA:28
PN:T99A19-602	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G29996	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-05	RIGHT WING JET PUMP FEED LINE							Component ATA:28
PN:T99A19-602	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G29998	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-05, AMM 28-21-05								
28-21-07	LEFT 0.75 SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J08766	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-07	RIGHT 0.75 SHUTOFF VALVE							Component ATA:28
PN:B97-15-601	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J08769	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM							Service ATA:28
	MOS	29-Apr-22						AIRWORTHINESS
	HRS	1728.6	800 (+30/-30)		2528.6	2558.6	715 (+30)	
	AFL	989						
PROC. REF: AMM 28-21-07								
28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM							Service ATA:28
	MOS	29-Apr-22						AIRWORTHINESS
	HRS	1728.6	800 (+30/-30)		2528.6	2558.6	715 (+30)	
	AFL	989						
PROC. REF: AMM 28-21-07								
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR							Component ATA:28
PN:D97C00-644P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:C701943	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-08	LEFT WING 28 VDC SOV ACTUATOR							Component ATA:28
PN:D97C00-644P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:C701945	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR							Component ATA:28
PN:D97C00-644P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:C701956	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-07, AMM 28-21-07								
28-21-09	LEFT WING SCAVENGER JET PUMP							Component ATA:28
PN:T99A19-603	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G27415	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-09, AMM 28-21-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-21-09	RIGHT WING SCAVENGER JET PUMP							Component ATA:28
PN:T99A19-603	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G29726	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-09, AMM 28-21-09								
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE							Component ATA:28
PN:B97H19-608P2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:H63066	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-10, AMM 28-21-10								
28-21-10-001	OPERATIONAL CHECK OF FUEL XFEED VALVE							Service ATA:28
	MOS	29-Apr-15						
	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 28-21-10								
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE							Component ATA:28
PN:L96-13-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J12563	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE							Component ATA:28
PN:L96-13-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J12573	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-11, AMM 28-21-11								
28-21-13	INSC ILLUM PANEL							Component ATA:28
PN:441-42621-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-21-13, AMM 28-21-13								
28-23-01	REFUEL CONTROL PANEL							Component ATA:28
PN:742388-1-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:742388IN00390	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-01, AMM 28-23-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE							Component ATA:28
PN:L94E31-653P3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J17600	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-03, AMM 28-23-03								
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE							Component ATA:28
PN:L94E31-653P3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:J17610	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-03, AMM 28-23-03								
28-23-04-001 ^S	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER							Service ATA:28
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-23-05								
							PKG:40	
28-23-07	LEFT HIGH LEVEL SENSOR							Component ATA:28
PN:722860-2-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0822	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-07, AMM 28-23-07								
28-23-07	RIGHT HIGH LEVEL SENSOR							Component ATA:28
PN:722860-2-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0821	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-07, AMM 28-23-07								
28-23-09	FUEL PORT AND CAP							Component ATA:28
PN:K97-63-613	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:G09638	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-23-09, AMM 28-23-09								
28-41-01	NO. 1 LEFT PROBE							Component ATA:28
PN:765896-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765896IN000663	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-01	NO. 1 RIGHT PROBE							Component ATA:28
PN:765896-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765896IN000665	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 LEFT PROBE							Component ATA:28
PN:765873-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765873IN00717	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 2 RIGHT PROBE							Component ATA:28
PN:765873-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765873IN00719	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 3 LEFT PROBE							Component ATA:28
PN:765874-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765874IN00704	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 3 RIGHT PROBE							Component ATA:28
PN:765874-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765874IN00705	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 LEFT PROBE							Component ATA:28
PN:765875-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765875IN00686	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								
28-41-01	NO. 4 RIGHT PROBE							Component ATA:28
PN:765875-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:765875IN00684	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-01, AMM 28-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 28 - FUEL								
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT							Component ATA:28
PN:738742-1-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:738790IN00814	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-41-05, AMM 28-41-05								
28-43-01	TEMPERATURE SENSOR							Component ATA:28
PN:798840-1-0	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:04117	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-43-01, AMM 28-43-01								
28-43-01-001 ^S	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR							Service ATA:28
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 28-43-01								
PKG:60								
28-45-01	LEFT PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1267	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01								
28-45-01	RIGHT PRESSURE SWITCH							Component ATA:28
PN:D98C07-611	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1272	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 28-45-01, AMM 28-45-01								
ATA 29 - HYDRAULIC POWER								
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR							Component ATA:29
PN:3032763-003	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:MX780887	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:3032249-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:MX782684	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02								
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP							Component ATA:29
PN:3032249-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:MX782791	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-01, AMM 29-12-01, AMM 29-12-02, AMM 29-12-02								
29-12-02-001 ^S	VISUAL CHECK OF MANIFOLD/ RESERVOIR							Service ATA:29
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 29-12-02								PKG:80
29-12-02-002 ^S	OPERATIONAL CHECK LEFT EDP CHECK VALVE							Service ATA:29
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 29-10-00								PKG:50
29-12-02-002 ^S	OPERATIONAL CHECK RIGHT EDP CHECK VALVE							Service ATA:29
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 29-10-00								PKG:50
29-15-03	HYDRAULIC ACCUMULATOR							Component ATA:29
PN:11172-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:11172-0054	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-03, AMM 29-15-03								
29-15-03-001 ^S	SERVICING OF HYDRAULIC ACCUMULATOR							Service ATA:29
PN:11172-2	MOS	30-Apr-22	12 (+1m/-1m)					
SN:11172-0054	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 12-13-00								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 29 - HYDRAULIC POWER								
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE							Component ATA:29
PN:3032428-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:AA492485	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-04, AMM 29-15-04								
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE							Component ATA:29
PN:3032428-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:AA492486	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-04, AMM 29-15-04								
29-15-04-001	OPERATIONAL CHECK NO. 1 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE							Service ATA:29
PN:3032428-001	MOS	01-May-19	48 (+30d/-30d)	Adj -2d	29-Apr-23	29-May-23	59 d (+30)	AIRWORTHINESS
SN:AA492485	HRS	1230	3200 (+30/-30)		4430	4460	2616.4 (+30)	
	AFL	711						
PROC. REF: AMM 29-15-04								
29-15-04-001	OPERATIONAL CHECK NO. 2 FSOV FIRE SHUT OFF VALVE ENGINE HYDRAULIC SHUT-OFF VALVE							Service ATA:29
PN:3032428-001	MOS	01-May-19	48 (+30d/-30d)	Adj -2d	29-Apr-23	29-May-23	59 d (+30)	AIRWORTHINESS
SN:AA492486	HRS	1230	3200 (+30/-30)		4430	4460	2616.4 (+30)	
	AFL	711						
PROC. REF: AMM 29-15-04								
29-15-05	PRIORITY VALVE							Component ATA:29
PN:2217-0001-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00289	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-15-05, AMM 29-15-05								
29-31-02-001 ^S	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE							Service ATA:29
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 29-31-02								
ATA 30 - ICE AND RAIN PROTECTION								
30-01-01	MD INSC ILLUM PANEL							Component ATA:30
PN:441-43234-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1169	HRS	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
	AFL	0		TSN 0				
PROC. REF: AMM 30-01-01, AMM 30-01-01								
30-12-00-001 ^S	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-10-00								
PKG:60								
30-12-01-001 ^S	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-12-01								
PKG:60								
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE							Component ATA:30
PN:RYLB-53534-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-02, AMM 30-12-02								
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE							Component ATA:30
PN:RYLB-53534-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0287	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-02, AMM 30-12-02								
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8145-6-310	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8145-6-327	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8145-6-297	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8172-1-221	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8145-6-320	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-485F-1000-50G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8145-6-284	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-12-05, AMM 30-12-05, AMM 30-12-05, AMM 30-12-05								
30-12-05-001 ^S	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-12-05								PKG:60
30-12-05-001 ^S	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-12-05								PKG:60
30-12-05-002 ^S	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-12-05								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-12-05-002 ^S	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-12-05								PKG:60
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE							Component ATA:30
PN:10030295	MOS/MSC	04-Feb-16	O/C	TSN 0				
SN:0001128	HRS	268.5		TSN 0				
	AFL	158		TSN 0				
PROC. REF: AMM 30-21-01, AMM 30-21-01								
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE							Component ATA:30
PN:10030295	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000578	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-01, AMM 30-21-01								
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-477F-1000-100GMOS/MSC		29-Apr-15	O/C	TSN 0				
SN:8172-5-127	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02, AMM 30-21-02								
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER							Component ATA:30
PN:APTE-477F-1000-100GMOS/MSC		29-Apr-15	O/C	TSN 0				
SN:8178-8-588	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-21-02, AMM 30-21-02								
30-21-02-001	FUNCTIONAL CHECK OF LEFT ENGINE ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-02-001	FUNCTIONAL CHECK OF RIGHT ENGINE ANTI-ICING PRESSURE TRANSDUCER							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 30-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-21-02-720-801-A	TROUBLE SHOOTING ENGINE OPERATING PROBLEMS - ENGINE ANTI-ICING PRESSURE TRANSDUCER FUNCTIONAL CHECK							Service ATA:30
	MOS/MSC	29-Apr-15	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	AFL	0						
PROC. REF: AMM 30-21-02								
30-21-03-001 ^S	BORESCOPE INSPECTION OF PICCOLO TUBE							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-21-03								
								PKG:50
30-21-04-001 ^S	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS							Service ATA:30
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 30-21-00								
								PKG:20
30-31-00-002	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING							Service ATA:30
	MOS	26-May-21	24 (+1m/-1m)	Adj -37d	19-Apr-23	19-May-23	49 d (+30)	
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 30-30-00								
								PKG:81
30-41-01-002 ^S	DISCARD OF WINDSHIELD RAIN REPELLENT COATING							Service ATA:30
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 30-41-01								
								PKG:80
30-41-01-003 ^S	FUNCTIONAL CHECK OF RAIN REPELLENT COATING (RRC) LAYER ON WINDSHIELD SURFACE							Service ATA:30
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 30-41-01								
								PKG:80

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 30 - ICE AND RAIN PROTECTION								
30-42-00-001 ^S		OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM						Service ATA:30
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 30-42-00								PKG:1
30-42-01		LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL						Component ATA:30
PN:EPM-112-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:02729	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-42-01		RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL						Component ATA:30
PN:EPM-112-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:02775	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 30-42-01, AMM 30-42-01								
30-81-02		LEFT NOSE ICE DETECTOR						Component ATA:30
PN:0871LM3-1	MOS/MSC	27-Apr-18	O/C	TSR 1				
SN:0787	HRS	1013.5		TSR 0				
	AFL	579		TSR 0				
PROC. REF: AMM 30-81-02, AMM 30-81-02								
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-30-02		CVDR ACCELEROMETER						Component ATA:31
PN:3001-01-111	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0914-DTU4249	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-05, AMM 31-31-05								
31-30-03		REAR CVDR IMPACT SWITCH						Component ATA:31
PN:5930-4-000	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:6763	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-04, AMM 31-31-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-31-00-002	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER)							Service ATA:31
	MOS	30-Apr-22	12 (+1m/-1m)	Adj -1d	29-Apr-23	29-May-23	59 d (+30)	
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 31-31-00								PKG:80
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER							Component ATA:31
PN:2100-3083-50	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:001017510	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-01, AMM 31-31-01								
31-31-03	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON							Component ATA:31
PN:266-E0305-00	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:SD44403	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-03, AMM 31-31-03								
31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY							Service ATA:31
PN:266-E0305-00	MOS/MSC	05-Aug-20	DUE		15-Apr-27 (M)		1506 d	LIFE LIMIT
SN:SD44403	HRS	1517.87						
	AFL	884						
PROC. REF: AMM 31-31-03								
31-31-09	CVDR CONTROL PANEL							Component ATA:31
PN:441-42635-003	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0586	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-31-09, AMM 31-31-09								
31-33-01	FDR - FLIGHT DATA RECORDER							Component ATA:31
PN:2100-2044-00	MOS/MSC	27-Apr-18	O/C	TSR 6				
SN:000830204	HRS	1013.5		TSR 0				
	AFL	579		TSR 0				
PROC. REF: AMM 31-33-01, AMM 31-33-01								
31-33-03	FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON							Component ATA:31
PN:266-E5542-00	MOS/MSC	27-Apr-18	H/T					
SN:ULB017291	HRS	1013.5						
	AFL	579						
PROC. REF: AMM 31-33-03, AMM 31-33-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-33-03-001	DISCARD FDR/ULB - FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON BATTERY (NOTE: FOR AIRCRAFT WITH FDR INSTALLED)							Service ATA:31
PN:266-E5542-00	MOS/MSC	27-Apr-18	DUE		01-Aug-24 (M)		519 d	LIFE LIMIT
SN:ULB017291	HRS	1013.5						
	AFL	579						
PROC. REF: AMM 31-33-03								
31-33-04	FORWARD CVDR IMPACT SWITCH							Component ATA:31
PN:5930-4-000	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:6631	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-04, AMM 31-33-04								
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Component ATA:31
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-05, AMM 31-33-05								
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Component ATA:31
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-33-05, AMM 31-33-05								
31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Service ATA:31
	MOS/MSC	29-Apr-15	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 31-33-05								
31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER							Service ATA:31
	MOS/MSC	29-Apr-15	N/A					
	HRS	0						
	AFL	0						
PROC. REF: AMM 31-33-05								
31-40-01	LH DCU UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:16906190	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01, AMM 31-41-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-40-01	RH DCU UNIT							Component ATA:31
PN:011-01457-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:16906193	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-01, AMM 31-41-01								
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-01105-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1HQ011904	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05								
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT							Component ATA:31
PN:011-01105-20	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1HQ011907	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-05, AMM 31-41-05, AMM 31-41-05								
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL							Component ATA:31
PN:441-42627-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1277	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
31-42-00-001 ^S	OPERATIONAL CHECK OF HSDB SWITCH REVERSION							Service ATA:31
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-42-00								PKG:60
31-50-01	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:46719328	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:46719166	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT							Component ATA:31
PN:011-00831-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:46719119	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-41-03, AMM 31-41-03								
31-61-00-001 ^S	OPERATIONAL CHECK MFD FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-61-00								PKG:40
31-61-00-001 ^S	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-61-00								PKG:40
31-61-00-001 ^S	OPERATIONAL CHECK PFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE)							Service ATA:31
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)					
	AFL	0						
PROC. REF: AMM 31-61-00								PKG:40
31-61-01	MFD (MULTI-FUNCTION FLIGHT DISPLAY)							Component ATA:31
PN:011-01440-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:18T006402	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01								
31-61-01	PFD 1 (PRIMARY FLIGHT DISPLAY)							Component ATA:31
PN:011-01440-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:18T006473	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 31 - INDICATING/RECORDING SYSTEMS								
31-61-01	PFD 2 (PRIMARY FLIGHT DISPLAY)							Component ATA:31
PN:011-01440-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:18T006479	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-01, AMM 31-61-01								
31-61-05	TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY							Component ATA:31
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-05, AMM 31-61-05								
31-61-06	NO. 1 BARO INSC ILLUMINATED PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-06, AMM 31-61-06								
31-61-06	NO. 2 BARO INSC ILLUMINATED PANEL							Component ATA:31
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 31-61-06, AMM 31-61-06								
ATA 32 - LANDING GEAR								
32-00-00-001 ^S	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR POLYURETHANE FILMS							Service ATA:32
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 32-00-20								
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING							Component ATA:32
PN:2317-1201-503	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540677/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING							Component ATA:32
PN:2317-1201-504	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1546167/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-003	LEFT PINTLE PIN							Component ATA:32
PN:2317-1101-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540349/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-003	RIGHT PINTLE PIN							Component ATA:32
PN:2317-1101-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540349/006	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-004	LEFT PINTLE PIN							Component ATA:32
PN:2317-1102-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1542544/008	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-004	RIGHT PINTLE PIN							Component ATA:32
PN:2317-1102-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1542544/011	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE							Component ATA:32
PN:2317-1103-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541520/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE							Component ATA:32
PN:2317-1103-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541520/002	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE							Component ATA:32
PN:2317-1107-005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1518508/001	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		14265	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE							Component ATA:32
PN:2317-1107-005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1518508/008	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		14265	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN							Component ATA:32
PN:2317-1109-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541525/013	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN							Component ATA:32
PN:2317-1109-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541527/002	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT							Component ATA:32
PN:2317-1126-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540545/017	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT							Component ATA:32
PN:2317-1126-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540545/018	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-10-00	LEFT MAIN LANDING GEAR							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
32-10-00	RIGHT MAIN LANDING GEAR							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-00								
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY							Component ATA:32
PN:2317-1100-405	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00274	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY							Component ATA:32
PN:2317-1100-406	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY							Component ATA:32
PN:2317-1500-405	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00279	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY							Component ATA:32
PN:2317-1500-406	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00281	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:2317-1502-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1543288/001	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		14265	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE							Component ATA:32
PN:2317-1502-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1543288/002	HRS	0		TSN 0				
	AFL	0	15300	TSN 0	15300		14265	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE							Component ATA:32
PN:2317-1503-005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1538228/003	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE							Component ATA:32
PN:2317-1503-005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1538228/006	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT							Component ATA:32
PN:2317-1509-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1519879/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT							Component ATA:32
PN:2317-1509-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1519879/004	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-104	LEFT MAIN LANDING GEAR TRAILING ARM							Component ATA:32
PN:2317-1513-501	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1544102/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM							Component ATA:32
PN:2317-1513-502	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541749/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN							Component ATA:32
PN:2317-1505-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540468/008	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN							Component ATA:32
PN:2317-1505-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540468/015	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-04, AMM 32-11-04								
32-11-00-001 ^S	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR							Service ATA:32
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 32-11-00								PKG:80
32-11-00-003	LUBRICATION OF MAIN LANDING GEAR							Service ATA:32
	MOS	26-Apr-22	12 (+1m/-1m)	Adj -12d	14-Apr-23	14-May-23	44 d (+30)	
	HRS	1728.6						
	AFL	989	650 (+30/-30)		1639	1669	604 (+30)	
PROC. REF: AMM 12-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-01-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-11-01-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - STRUT ASSY (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - LOCKING ACTUATOR (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-11-02-900-801-05	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Component ATA:32
PN:2117-3001-003	MOS/MSC		H/T	TSN 0				
SN:1551311/010	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-06	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Component ATA:32
PN:2117-3001-003	MOS/MSC		H/T	TSN 0				
SN:1541222/007	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-02-900-801-07	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:2117-3027-901	MOS/MSC		H/T	TSN 0				
SN:13049	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-08	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Component ATA:32
PN:2117-3027-901	MOS/MSC		H/T	TSN 0				
SN:11019	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-13	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:2117-3019-003	MOS/MSC		H/T	TSN 0				
SN:1538134/003	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-14	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Component ATA:32
PN:2117-3019-003	MOS/MSC		H/T	TSN 0				
SN:1538133/008	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-15	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:2117-3007-003	MOS/MSC		H/T	TSN 0				
SN:1534419/001	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-02-900-801-16	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Component ATA:32
PN:2117-3007-003	MOS/MSC		H/T	TSN 0				
SN:1551227/014	HRS			TSN 0				
	AFL	EFF		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-11-03-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)	29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL	
	HRS							
	AFL	EFF	12000 (+30/-30)	12000 *	12030	10965 (+30)		
PROC. REF: AMM 32-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-11-03-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - SHOCK ABSORBER (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-11-03-004	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER							Service ATA:32
	MOS	25-Apr-22	12 (+1m/-1m)	Adj -11d	14-Apr-23	14-May-23	44 d (+30)	
	HRS	1728.6						
	AFL	989	650 (+30/-30)		1639	1669	604 (+30)	
PROC. REF: AMM 12-14-02								
32-11-04-001	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (LH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-11-04-002	RESTORATION (OVERHAUL) OF MAIN LANDING GEAR - TRAILING ARM (RH)							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-11-00								
32-20-01	NOSE LANDING GEAR							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-00								
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER							Component ATA:32
PN:2317-3000-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00598	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER							Component ATA:32
PN:2317-3000-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00599	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:2317-3011-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1553282/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER							Component ATA:32
PN:2317-3011-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1545722/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:2317-3021-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541535/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE							Component ATA:32
PN:2317-3021-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1548430/001	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2317-3001-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541532/015	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING							Component ATA:32
PN:2317-3001-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541532/009	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT							Component ATA:32
PN:2317-3004-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1548912/009	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT							Component ATA:32
PN:2317-3004-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1548912/005	HRS	0		TSN 0				
	AFL	0	16800	TSN 0	16800		15765	
PROC. REF: AMM 32-11-03, AMM 32-11-03								
32-21-00-001 ^S	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR							Service ATA:32
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 32-21-00								PKG:80
32-21-00-003	LUBRICATION OF NOSE LANDING GEAR							Service ATA:32
	MOS	27-Apr-22	12 (+1m/-1m)	Adj -13d	14-Apr-23	14-May-23	44 d (+30)	
	HRS	1728.6						
	AFL	989	650 (+30/-30)		1639	1669	604 (+30)	
PROC. REF: AMM 12-21-00								
32-21-01-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - STRUT ASSY							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-21-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-02	NLG RETRACTION ACTUATOR							Component ATA:32
PN:2117-1000-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00094	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-02, AMM 32-21-02								
32-21-03	NLG DOWNLOCK ACTUATOR							Component ATA:32
PN:2117-2000-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00295	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-03, AMM 32-21-03								
32-21-04-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - LOCKING STAY							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-21-00								
32-21-05-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - SHOCK ABSORBER							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-21-00								
32-21-05-004	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER							Service ATA:32
	MOS	27-Apr-22	12 (+1m/-1m)	Adj -13d	14-Apr-23	14-May-23	44 d (+30)	
	HRS	1728.6						
	AFL	989	650 (+30/-30)		1639	1669	604 (+30)	
PROC. REF: AMM 12-14-03								
32-21-06-005 ^S	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER							Service ATA:32
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 32-21-06								
PKG:80								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-21-09-001	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR - DRAG BRACE ASSY							Service ATA:32
	MOS	EFF	120 (+1m/-1m)		29-Apr-25 *	29-May-25	790 d (+30)	OVERHAUL
	HRS							
	AFL	EFF	12000 (+30/-30)		12000 *	12030	10965 (+30)	
PROC. REF: AMM 32-21-00								
32-23-03	NLG DOOR - TORQUE TUBE ASSEMBLY							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR							Component ATA:32
PN:2117-3000-409	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00600	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR							Component ATA:32
PN:2117-3000-409	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00513	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER							Component ATA:32
PN:2117-3034-501	MOS			TSN 0				LIFE LIMIT
SN:1548220/001	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER							Component ATA:32
PN:2117-3034-501	MOS			TSN 0				LIFE LIMIT
SN:1515015/001	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-302	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS/MSC	29-Apr-15	N/A					
SN:1541222/007	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-302	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS/MSC	29-Apr-15	N/A					
SN:1551311/010	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-303	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS/MSC	29-Apr-15	N/A					
SN:13049	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-303	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS/MSC	29-Apr-15	N/A					
SN:11019	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:2117-3008-901	MOS			TSN 0				LIFE LIMIT
SN:76450/0015	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD							Component ATA:32
PN:2117-3008-901	MOS			TSN 0				LIFE LIMIT
SN:75014/0025	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:2117-3009-007	MOS			TSN 0				LIFE LIMIT
SN:1555334/014	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON							Component ATA:32
PN:2117-3009-007	MOS			TSN 0				LIFE LIMIT
SN:1497137/010	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-306	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS/MSC	29-Apr-15	N/A					
SN:1538133/008	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-306	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS/MSC	29-Apr-15	N/A					
SN:1538134/003	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-307	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS/MSC	29-Apr-15	N/A					
SN:1534419/001	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-307	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS/MSC	29-Apr-15	N/A					
SN:1551227/014	HRS	0						
	AFL	0						
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:2117-3011-001	MOS			TSN 0				LIFE LIMIT
SN:1544259/015	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP							Component ATA:32
PN:2117-3011-001	MOS			TSN 0				LIFE LIMIT
SN:1507924/004	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:2117-3013-001	MOS			TSN 0				LIFE LIMIT
SN:1550531/006	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING							Component ATA:32
PN:2117-3013-001	MOS			TSN 0				LIFE LIMIT
SN:1519831/003	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-31-01	LANDING GEAR CONTROL LEVER							Component ATA:32
PN:827101-7	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1208	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-01, AMM 32-31-01								
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE							Component ATA:32
PN:7342-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0299T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-04, AMM 32-31-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-31-05	LH MLG UPLOCK BOX ASSY							Component ATA:32
PN:2617-1000-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00442	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-05, AMM 32-31-05								
32-31-05	NLG UPLOCK BOX ASSY							Component ATA:32
PN:2617-1000-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00439	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-05, AMM 32-31-05								
32-31-05	RH MLG UPLOCK BOX ASSY							Component ATA:32
PN:2617-1000-402	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00282	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-31-05, AMM 32-31-05								
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT							Component ATA:32
PN:2117-3015-001	MOS			TSN 0				LIFE LIMIT
SN:1548330/008	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT							Component ATA:32
PN:2117-3015-001	MOS			TSN 0				LIFE LIMIT
SN:1510200/009	HRS			TSN 0				
	AFL	EFF	12000	TSN 0	12007 *		10972	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:MTMKS14ALGA1	MOS			TSN 0				LIFE LIMIT
SN:00464	HRS			TSN 0				
	AFL	EFF	10500	TSN 0	10507 *		9472	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END							Component ATA:32
PN:MTMKS14ALGA1	MOS			TSN 0				LIFE LIMIT
SN:00427	HRS			TSN 0				
	AFL	EFF	10500	TSN 0	10507 *		9472	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-312	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS	29-Apr-15						LIFE LIMIT
SN:13049	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-312	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER							Service ATA:32
PN:2117-3027-901	MOS	29-Apr-15						LIFE LIMIT
SN:11019	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT							Component ATA:32
PN:PN	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	28000	TSN 0	28000		26965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT							Component ATA:32
PN:PN	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0	28000	TSN 0	28000		26965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-314	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS	29-Apr-15						LIFE LIMIT
SN:1538133/008	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-314	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN							Service ATA:32
PN:2117-3019-003	MOS	29-Apr-15						LIFE LIMIT
SN:1538134/003	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-315	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS	29-Apr-15						LIFE LIMIT
SN:1534419/001	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-315	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE							Service ATA:32
PN:2117-3007-003	MOS	29-Apr-15						LIFE LIMIT
SN:1551227/014	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-316	DISCARD LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS	29-Apr-15						LIFE LIMIT
SN:1541222/007	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-316	DISCARD RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON							Service ATA:32
PN:2117-3001-003	MOS	29-Apr-15						LIFE LIMIT
SN:1551311/010	HRS	0						
	AFL	0	12000		12000		10965	
PROC. REF: AMM 32-11-02, AMM 32-11-02								
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM							Service ATA:32
	MOS	26-May-21	24 (+30d/-30d)	Adj -27d	29-Apr-23	29-May-23	59 d (+30)	AIRWORTHINESS
	HRS	1601.5	1600 (+30/-30)		3201.5	3231.5	1387.9 (+30)	
	AFL	928						
PROC. REF: AMM 32-35-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES							Service ATA:32
	MOS	26-May-21	24 (+30d/-30d)	Adj -27d	29-Apr-23	29-May-23	59 d (+30)	AIRWORTHINESS
	HRS	1601.5	1600 (+30/-30)		3201.5	3231.5	1387.9 (+30)	
	AFL	928						
PROC. REF: AMM 32-35-00								
32-35-02	CENTER FUSELAGE FREE FALL VALVE							Component ATA:32
PN:7343-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0289T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-35-02, AMM 32-35-02								
32-400	NOSE LANDING GEAR SHOCK STRUT							Component ATA:32
PN:2317-5100-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00288	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT							Component ATA:32
PN:2310-1144-005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:00249	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT							Component ATA:32
PN:2310-1173-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540012/009	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-06, AMM 32-21-06								
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN							Component ATA:32
PN:2317-5105-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541466/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-01, AMM 32-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN							Component ATA:32
PN:2317-5105-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1545466/012	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING							Component ATA:32
PN:2317-5301-503	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1542992/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-11-01, AMM 32-11-01								
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER							Component ATA:32
PN:2117-4000-403	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:00300	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-06, AMM 32-21-06								
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE							Component ATA:32
PN:2317-5101-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540020/006	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-01, AMM 32-21-01								
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK							Component ATA:32
PN:2317-5201-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1545445/019	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK							Component ATA:32
PN:2317-5201-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1545445/005	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-07, AMM 32-21-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN							Component ATA:32
PN:2317-6003-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1528159/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE							Component ATA:32
PN:2310-1165-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1548248/010	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-41-00	BRAKE CONTROL UNIT							Component ATA:32
PN:DAP00100-10	MOS/MSC	19-Apr-17	O/C					
SN:343400431	HRS	682.6						
	AFL	388						
PROC. REF: AMM 32-41-01, AMM 32-41-01								
32-41-00-001 ^S	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM							Service ATA:32
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-00								PKG:50
32-41-01	BRAKE CONTROL UNIT TRAY							Component ATA:32
PN:DAP00134-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1100	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-01, AMM 32-41-01								
32-41-02	LH BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:Q3008	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:132517	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02								
32-41-02	RH BRAKE PEDAL TRANSDUCER							Component ATA:32
PN:Q3008	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:132518	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-02, AMM 32-41-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-41-02-001 ^S		OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-02								PKG:60
32-41-02-001 ^S		OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-41-02								PKG:60
32-41-02-002 ^S		FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	14-Apr-20						
	HRS	1483.9	1600 (+30/-30)					
	AFL	855						
PROC. REF: AMM 32-41-02								PKG:10
32-41-02-002 ^S		FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER						Service ATA:32
	MOS	14-Apr-20						
	HRS	1483.9	1600 (+30/-30)					
	AFL	855						
PROC. REF: AMM 32-41-02								PKG:10
32-41-06		LH MLG WHEEL SPEED TRANSDUCER						Component ATA:32
PN:DAP00103-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:019NR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06								
32-41-06		RH MLG WHEEL SPEED TRANSDUCER						Component ATA:32
PN:DAP00103-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:017NR	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-06, AMM 32-41-06								
32-41-07		BRAKE CONTROL MODULE						Component ATA:32
PN:DAP00101-02	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:42MK	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-41-07, AMM 32-41-07								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN							Component ATA:32
PN:57675-1	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:00727	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT							Component ATA:32
PN:2310-1183-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:00210	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-07, AMM 32-21-07								
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK							Component ATA:32
PN:2317-5191-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1550786/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-01, AMM 32-21-01, AMM 32-23-03, AMM 32-23-03								
32-43-00-001 ^S	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM							Service ATA:32
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-43-00								PKG:50
32-43-01-001 ^S	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM							Service ATA:32
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 32-43-00								PKG:50
32-43-02	PRESSURE SWITCH							Component ATA:32
PN:DAP00108-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:010NP	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 29-12-03, AMM 29-12-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR							Component ATA:32
PN:DAP00106-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:289	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-04, AMM 32-43-04								
32-43-05	EMERGENCY/PARKING BRAKE VALVE							Component ATA:32
PN:DAP00107-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:037NQ	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-02								
32-43-06	PRESSURE TRANSDUCER							Component ATA:32
PN:DAP00109-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8067-12-36	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-06, AMM 32-43-06								
32-43-08	THERMAL RELIEF VALVE							Component ATA:32
PN:DAP00110-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:301	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-08, AMM 32-43-08								
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE							Component ATA:32
PN:DAP00202-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:365	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-02, AMM 32-43-02								
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE							Component ATA:32
PN:2216-0001-401	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00627	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-43-11, AMM 32-43-11								
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE							Service ATA:32
	MOS	29-Apr-22						AIRWORTHINESS
	HRS	1728.6	800 (+30/-30)		2528.6	2558.6	715 (+30)	
	AFL	989						
PROC. REF: AMM 32-43-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-00	LH MAIN WHEEL AND TIRE ASSY							Component ATA:32
PN:505-19517-611	MOS/MSC	24-Feb-22	O/C	TSO 0				
SN:5086UA	HRS	1703.8		TSO 0				
	AFL	977		TSO 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-00	NOSE WHEEL AND TIRE ASSY							Component ATA:32
PN:505-19601-401	MOS/MSC	14-Apr-20	O/C	TSR 0				
SN:5082JS	HRS	1483.9		TSR 0				
	AFL	855		TSR 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-00	RH MAIN WHEEL AND TIRE ASSY							Component ATA:32
PN:505-19517-611	MOS/MSC	30-Apr-22	O/C	TSR 0				
SN:5082NW	HRS	1728.6		TSR 0				
	AFL	989		TSO 165, TSR 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-01	LEFT MAIN WHEEL							Component ATA:32
PN:PN	MOS/MSC	24-Feb-22	O/C	TSO 0				
SN:5086UA	HRS	1703.8		TSO 0				
	AFL	977		TSO 0				
PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-01	RIGHT MAIN WHEEL							Component ATA:32
PN:DA900098-02	MOS/MSC	30-Apr-22	O/C	TSR 0				
SN:5082NW	HRS	1728.6		TSR 0				
	AFL	989		TSO 165, TSR 0				
PROC. REF: AMM 32-45-01, AMM 32-45-01								
32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY							Service ATA:32
PN:PN	MOS/MSC	24-Feb-22	T/C					
SN:5086UA	HRS	1703.8						
	AFL	977	1500 (+30/-30)		2477	2507	1442 (+30)	
PROC. REF: AMM 32-45-00								
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY							Service ATA:32
PN:DA900098-02	MOS	30-Apr-22						
SN:5082NW	HRS	1728.6						
	AFL	989	T:1500 (+30/-30)	TAC 165	2324	2354	1289 (+30)	
PROC. REF: AMM 32-45-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-02	LEFT MAIN WHEEL TIRE							Component ATA:32
PN:258K63-2	MOS/MSC	24-Feb-22	O/C	TSN 0				
SN:13170494	HRS	1703.8		TSN 0				
	AFL	977		TSN 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-02	RIGHT MAIN WHEEL TIRE							Component ATA:32
PN:258K63-2	MOS/MSC	30-Apr-22	O/C	TSN 0				
SN:13170488	HRS	1728.6		TSN 0				
	AFL	989		TSN 0				
PROC. REF: AMM 32-45-02, AMM 32-45-02								
32-45-03	LH MLG HUB CAP							Component ATA:32
PN:DAP00131-02	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:62NK	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-03, AMM 32-45-03								
32-45-03	RH MLG HUB CAP							Component ATA:32
PN:DAP00131-02	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:58NK	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-45-03, AMM 32-45-03								
32-45-11	NOSE WHEEL							Component ATA:32
PN:DAP00099-02	MOS/MSC	14-Apr-20	O/C	TSR 0				
SN:5082JS	HRS	1483.9		TSR 0				
	AFL	855		TSR 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11								
32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY							Service ATA:32
PN:DAP00099-02	MOS							
SN:5082JS	HRS							
	AFL		T:1500 (+30/-30)	1500	1530	465 (+30)		
PROC. REF: AMM 32-45-00								
32-45-12	NOSE TIRE							Component ATA:32
PN:156K23B1	MOS/MSC	07-Aug-17	O/C	TSN 0				
SN:70102826	HRS	773.7		TSN 0				
	AFL	444		TSN 0				
PROC. REF: AMM 32-45-11, AMM 32-45-11								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-45-21	LH MLG CARBON BRAKE ASSY							Component ATA:32
PN:DAP00097-04	MOS/MSC	07-Aug-17	O/C	TSR 2				
SN:129KQ	HRS	773.7		TSR 0				
	AFL	444		TSR 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-45-21	RH MLG CARBON BRAKE ASSY							Component ATA:32
PN:DAP00097-04	MOS/MSC	07-Aug-17	O/C	TSO 1				
SN:5068NV	HRS	773.7		TSO 0				
	AFL	444		TSO 0				
PROC. REF: AMM 32-45-21, AMM 32-45-21								
32-500	NOSE LANDING GEAR SHOCK ABSORBER							Component ATA:32
PN:2317-5170-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00293	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK							Component ATA:32
PN:2317-5227-501	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1547716/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: GENERIC NO REF								
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING							Component ATA:32
PN:2317-5113-005	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541549/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: GENERIC NO REF								
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER							Component ATA:32
PN:2317-5237-501	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1535213/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-600	NOSE LANDING GEAR DRAG BRACE							Component ATA:32
PN:2317-6000-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00291	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-601	NOSE LANDING GEAR UPPER DRAG BRACE							Component ATA:32
PN:2317-6114-501	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541979/001	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-602	NOSE LANDING GEAR LOWER DRAG BRACE							Component ATA:32
PN:2317-6201-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1528387/004	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN							Component ATA:32
PN:2317-6001-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540751/002	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN							Component ATA:32
PN:2317-6001-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1540749/003	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-09, AMM 32-21-09								
32-604	NOSE LANDING GEAR DRAG BRACE PIN							Component ATA:32
PN:2317-6003-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1515572/006	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-09, AMM 32-21-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-01	LH WING PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:38430	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:38415	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 NLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:38436	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:38432	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 2 NLG PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:38601	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH							Component ATA:32
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-61-01	RH WING PROXIMITY SWITCH							Component ATA:32
PN:80-057-01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:38428	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
32-700	NOSE LANDING GEAR LOCKING STAY							Component ATA:32
PN:2317-6500-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-701	NOSE LANDING GEAR UPPER LOCKING STAY							Component ATA:32
PN:2317-6521-003	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1541576/007	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-702	NOSE LANDING GEAR LOWER LOCKING STAY							Component ATA:32
PN:2317-6531-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1552520/005	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-04, AMM 32-21-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 32 - LANDING GEAR								
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT							Component ATA:32
PN:2310-1734-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1543265/016	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT							Component ATA:32
PN:2310-1734-001	MOS	29-Apr-15		TSN 0				LIFE LIMIT
SN:1543265/015	HRS	0		TSN 0				
	AFL	0	11200	TSN 0	11200		10165	
PROC. REF: AMM 32-21-04, AMM 32-21-04								
ATA 33 - LIGHTS								
33-01-01	OVERHEAD LIGHTS CONTROL PANEL							Component ATA:33
PN:441-43246-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1218	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-01-01, AMM 33-01-01								
33-12-01	COCKPIT DIMMER							Component ATA:33
PN:81-01760-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0672	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-01, AMM 33-12-01								
33-12-02	INSC ILLUM - TEST PANEL							Component ATA:33
PN:441-42631-003	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-12-02, AMM 33-12-02								
33-13-01	LH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY							Component ATA:33
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-13-01	RH WING POSITION,28VDC,RED COLOR,TYPE LED,WING TIP LIGHT ASSY							Component ATA:33
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
33-31-02	NOSE (WITH/WITHOUT FDR) W001,ELECTRICAL HARNESS							Component ATA:33
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
33-42-01	LH LWR FWD TAXI LIGHT ASSY							Component ATA:33
PN:81017-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000343	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01, AMM 33-42-01								
33-42-01	RH LWR FWD TAXI LIGHT ASSY							Component ATA:33
PN:81017-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000455	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-42-01, AMM 33-42-01								
33-47-01	LEFT LANDING LIGHT ASSY							Component ATA:33
PN:81017-5	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000321	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-47-01, AMM 33-47-01								
33-47-01	RIGHT LANDING LIGHT ASSY							Component ATA:33
PN:81017-6	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000326	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-47-01, AMM 33-47-01								
33-48-00	LEFT NO. 1 NAVIGATION LIGHT							Component ATA:33
PN:84004-7	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000691	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-48-00	LEFT NO. 2 NAVIGATION LIGHT							Component ATA:33
PN:84075-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000141	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT							Component ATA:33
PN:84004-7	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000688	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT							Component ATA:33
PN:84075-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000174	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-48-01, AMM 33-48-01, AMM 33-48-02, AMM 33-48-02								
33-48-00-001	DISCARD LEFT NO. 1 NAVIGATION LIGHT							Service ATA:33
PN:84004-7	MOS	29-Apr-15						
SN:000691	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								
33-48-00-001	DISCARD LEFT NO. 2 NAVIGATION LIGHT							Service ATA:33
PN:84075-1	MOS	29-Apr-15						
SN:000141	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								
33-48-00-001	DISCARD RIGHT NO. 1 NAVIGATION LIGHT							Service ATA:33
PN:84004-7	MOS	29-Apr-15						
SN:000688	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-48-00-001	DISCARD RIGHT NO. 2 NAVIGATION LIGHT							Service ATA:33
PN:84075-2	MOS	29-Apr-15						
SN:000174	HRS	0	12000 (+30/-30)		12000	12030	10186.4 (+30)	
	AFL	0						
PROC. REF: AMM 33-48-00								
33-48-00-002 ^S	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT							Service ATA:33
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								
PKG:20								
33-48-00-002 ^S	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT							Service ATA:33
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								
PKG:20								
33-48-00-002 ^S	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT							Service ATA:33
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								
PKG:20								
33-48-00-002 ^S	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT							Service ATA:33
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-48-00								
PKG:20								
33-49-00	NO. 1 STROBE LIGHT							Component ATA:33
PN:84036-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000355	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02								
33-49-00	NO. 2 STROBE LIGHT							Component ATA:33
PN:84036-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:000358	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-49-01, AMM 33-49-01, AMM 33-49-02, AMM 33-49-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-49-00-001	DISCARD NO. 1 STROBE LIGHT							Service ATA:33
PN:84036-3	MOS	29-Apr-15						
SN:000355	HRS	0	8000 (+30/-30)		8000	8030	6186.4 (+30)	
	AFL	0						
PROC. REF: AMM 33-49-00								
33-49-00-001	DISCARD NO. 2 STROBE LIGHT							Service ATA:33
PN:84036-4	MOS	29-Apr-15						
SN:000358	HRS	0	8000 (+30/-30)		8000	8030	6186.4 (+30)	
	AFL	0						
PROC. REF: AMM 33-49-00								
33-49-00-002 ^S	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT							Service ATA:33
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-49-00								PKG:20
33-49-00-002 ^S	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT							Service ATA:33
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 33-49-00								PKG:20
33-52-01	LH REAR EMERGENCY LIGHT BATTERY							Component ATA:33
PN:7450LS-00	MOS/MSC	11-Oct-22	O/C	TSN 14				
SN:005068	HRS	1783.9						
	AFL	1018						
PROC. REF: AMM 33-52-01, AMM 33-52-01								
33-52-01	RH FWD EMERGENCY LIGHT BATTERY							Component ATA:33
PN:6450LS-00	MOS/MSC	14-Apr-20	O/C					
SN:000980	HRS	1483.9						
	AFL	855						
PROC. REF: AMM 33-52-01, AMM 33-52-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service ATA:33
PN:7450LS-00	MOS	11-Oct-22	12	TAC 1	11-Sep-23		194 d	
SN:005068	HRS	1783.9						
	AFL	1018						
PROC. REF: AMM 33-52-01								
33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY)							Service ATA:33
PN:6450LS-00	MOS	25-Apr-22	12	Adj -11d	14-Apr-23		44 d	
SN:000980	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 33-52-01								
33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY)							Service ATA:33
PN:7450LS-00	MOS/MSC		N/A					
SN:005068	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY)							Service ATA:33
PN:6450LS-00	MOS/MSC		N/A					
SN:000980	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY							Service ATA:33
PN:7450LS-00	MOS/MSC		N/A					
SN:005068	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY							Service ATA:33
PN:6450LS-00	MOS/MSC		N/A					
SN:000980	HRS							
	AFL							
PROC. REF: AMM 33-52-01								
33-52-05	SELF-ILLUMINATED UNIT							Component ATA:33
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 33-52-05, AMM 33-52-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 33 - LIGHTS								
33-52-17-001 ^S	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED)							Service ATA:33
	MOS	01-May-19						
	HRS	1230	1600 (+30/-30)					
	AFL	711						
PROC. REF: AMM 33-52-17								PKG:10
ATA 34 - NAVIGATION								
34-00-01 ^U	ACSS TRANSPONDER							Component ATA:34
PN:7510700-951	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:RCE02123	HRS	0		TSN 0				
	AFL	0		TSN 0				
34-00-02	TRANSPONDER RF RELAY							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
34-00-03	NO.1 IASP SMART PROBE							Component ATA:34
PN:2015L-4B	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0737	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-07, AMM 34-15-07								
34-00-03	NO.2 IASP SMART PROBE							Component ATA:34
PN:2015L-4B	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0742	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-15-07, AMM 34-15-07								
34-00-04	SD CARD DATABASE							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
34-10-01	RADIO ALTIMETER							Component ATA:34
PN:066-01153-0101	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:KRA405B-15881	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-02, AMM 34-31-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA							Component ATA:34
PN:S67-2002-45	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:553-6648	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-02, AMM 34-31-02								
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA							Component ATA:34
PN:S67-2002-45	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:553-6649	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-31-02, AMM 34-31-02								
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT							Component ATA:34
PN:C16786DA01	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:C16786012259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-11-01, AMM 34-11-01								
34-11-00-001	FUNCTIONAL CHECK OF (IESI) INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001)							Service ATA:34
PN:C16786DA01	MOS	26-May-21	24 (+1m/-1m)	Adj -26d	30-Apr-23	31-May-23	60 d (+31)	
SN:C16786012259	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 34-11-00								
34-11-02	PITOT/STATIC PROBE							Component ATA:34
PN:0856UT4	MOS/MSC	01-May-19	O/C	TSN 49				
SN:289336	HRS	1230		TSN 1230				
	AFL	711		TSN 711				
PROC. REF: AMM 34-11-02, AMM 34-11-02								
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001)							Service ATA:34
PN:0856UT4	MOS	26-May-21	24 (+1m/-1m)	Adj -26d	30-Apr-23	31-May-23	60 d (+31)	
SN:289336	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 34-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-15-00-001	FUNCTIONAL CHECK OF AIR DATA SYSTEM							Service ATA:34
	MOS	26-May-21	24 (+1m/-1m)	Adj -37d	19-Apr-23	19-May-23	49 d (+30)	
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 34-15-00								PKG:81
34-15-00-002	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS							Service ATA:34
	MOS	30-Apr-19	60 (+1m/-1m)	Adj -11d	19-Apr-24	19-May-24	415 d (+30)	
	HRS	1230						
	AFL	711						
PROC. REF: AMM 34-15-00								PKG:84
34-15-00-003	DETAILED INSPECTION OF IASP							Service ATA:34
	MOS	26-May-21	24 (+1m/-1m)	Adj -37d	19-Apr-23	19-May-23	49 d (+30)	
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 34-15-07								PKG:81
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM							Component ATA:34
PN:011-00868-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:42026753	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-01, AMM 34-21-01								
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM							Component ATA:34
PN:011-00868-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:42026761	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-01, AMM 34-21-01								
34-20-02	LEFT MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1CM013580	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-02, AMM 34-21-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-20-02	RIGHT MAGNETOMETER							Component ATA:34
PN:011-00870-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1CM013575	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-21-02, AMM 34-21-02								
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE LH WING MAGNETOMETER							Service ATA:34
PN:011-00870-10	MOS	29-Apr-15	36 (+1m/-1m)					
SN:1CM013580	HRS	0						
	AFL	0						
PROC. REF: AMM 34-21-02								
34-21-00-001 ^S	FUNCTIONAL CHECK MAGNETIC INTERFERENCE CHECK ON THE RH WING MAGNETOMETER							Service ATA:34
PN:011-00870-10	MOS	29-Apr-15	36 (+1m/-1m)					
SN:1CM013575	HRS	0						
	AFL	0						
PROC. REF: AMM 34-21-02								
34-23-00	MAGNETIC COMPASS							Component ATA:34
PN:KCA0120W	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:BL6630714	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-23-01, AMM 34-23-01								
34-23-00-001 ^S	FUNCTIONAL CHECK MAGNETIC COMPASS OF STANDBY COMPASS							Service ATA:34
PN:KCA0120W	MOS	26-May-21	36 (+1m/-1m)	Adj -25d				
SN:BL6630714	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 34-23-00								
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA							Component ATA:34
PN:S65-247170	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:173-4301	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03								
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE							Component ATA:34
PN:S65-247170	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:173-4294	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-03, AMM 34-32-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-40-01 GDL-69A SATELLITE WEATHER AND RADIO RECEIVER								Component ATA:34
PN:011-00987-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:47768191	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-57-01, AMM 34-57-01								
34-40-02 AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA								Component ATA:34
PN:013-00245-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:12210	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02								
34-40-02 FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA								Component ATA:34
PN:013-00245-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:12209	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-02, AMM 34-56-02, AMM 34-56-02								
34-40-03 WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA								Component ATA:34
PN:011-00883-20	MOS/MSC	28-Oct-15	O/C	TSO 1				
SN:47204512	HRS	180.5		TSO 0				
	AFL	103		TSO 0				
PROC. REF: AMM 34-42-01, AMM 34-42-01								
34-40-04 TCAS II UNIT								Component ATA:34
PN:9003500-55905	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:TSE02785	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-01, AMM 34-43-01								
34-40-05 TCAS II TOP ANTENNA								Component ATA:34
PN:7514060-902	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:ANE44617	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-05, AMM 34-43-05								
34-43-02 LOWER TCAS L BAND ANTENNA								Component ATA:34
PN:S65-5366-7L	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:261-105861	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-43-02, AMM 34-43-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:261-117253	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02								
34-50-02	TOP XPDR L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:261-116985	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-02, AMM 34-52-02								
34-50-03	KN 63 DISTANCE MEASURING UNIT							Component ATA:34
PN:066-01070-0001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:37737	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-01, AMM 34-51-01								
34-50-05	PHASING COUPLER							Component ATA:34
PN:SSPD-113-10	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:7948	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-01, AMM 34-32-01								
34-50-06	MARKER BEACON ANTENNA							Component ATA:34
PN:S35-1000-2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:102-10978	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-04, AMM 34-32-04								
34-50-07	MARKER BEACON ANTENNA SPLITTER							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-05, AMM 34-32-05								
34-50-08	VOR/LOC/GS ANTENNA SPLITTER							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-02, AMM 34-32-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-50-09	VOR/LOC/GS ANTENNA RF CABLE							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-32-02, AMM 34-32-02								
34-50-10	GSR 56 IRIDIUM UNIT							Component ATA:34
PN:011-02268-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1NZ006124	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-01, AMM 23-15-01								
34-50-11	IRIDIUM SATCOM ANTENNA							Component ATA:34
PN:S67-1575-109	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:430-13996	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-15-03, AMM 23-15-03								
34-50-12	GDL 59 DATALINK MANAGEMENT UNIT							Component ATA:34
PN:011-01746-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1EJ005572	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-23-01, AMM 23-23-01								
34-50-13	WI-FI - DATALINK ANTENNA							Component ATA:34
PN:S65-5366-71S	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:258-3688	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 23-23-03, AMM 23-23-03, AMM 44-31-09, AMM 44-31-09, AMM 44-32-11, AMM 44-32-11								
34-50-14	ADF ANTENNA							Component ATA:34
PN:622-7383-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:43P47G	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-02, AMM 34-53-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-50-15	ADF UNIT							Component ATA:34
PN:622-7382-101	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4KGLC	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01, AMM 34-53-01								
34-51-02	NO. 1 DME L BAND ANTENNA							Component ATA:34
PN:S65-5366-7L	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:261-117289	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-51-02, AMM 34-51-02								
34-52-00	NO. 1 TRANSPONDER							Component ATA:34
PN:NXT-600	MOS/MSC	01-May-19	O/C	TSN 0				
SN:NXE05296	HRS	1230		TSN 0				
	AFL	711		TSN 0				
PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-00	NO. 2 TRANSPONDER							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-01, AMM 34-52-01								
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM							Service ATA:34
PN:NXT-600	MOS	14-May-21	24	Adj -14d	30-Apr-23		60 d	
SN:NXE05296	HRS							
	AFL							
PROC. REF: AMM 34-52-00								
34-52-04	LOWER COAXIAL UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-04, AMM 34-52-04								
34-52-04	UPPER COAXIAL UNIT							Component ATA:34
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-52-04, AMM 34-52-04								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 34 - NAVIGATION								
34-53-01	ADF MOUNTING TRAY							Component ATA:34
PN:622-5212-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:44068T	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-53-01, AMM 34-53-01								
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL							Component ATA:34
PN:011-01428-00	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:194005836	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 34-61-03, AMM 34-61-03								
ATA 35 - OXYGEN								
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE							Service ATA:35
	MOS	26-May-21	36 (+30d/-30d)	Adj -27d	29-Apr-24	29-May-24	425 d (+30)	AIRWORTHINESS
	HRS	1601.5	2400 (+30/-30)		4001.5	4031.5	2187.9 (+30)	
	AFL	928						
PROC. REF: AMM 35-00-00								
35-01-00-001 ^S	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION							Service ATA:35
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: AMM 35-01-02								
PKG:84								
35-01-02	OXYGEN CYLINDER TRANSDUCER							Component ATA:35
PN:4441125-000	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8114-9-327	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-02, AMM 35-01-02								
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH							Component ATA:35
PN:P24151	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0377	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-05, AMM 35-01-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-01-06	OXYGEN SYSTEM CONTROL PANEL							Component ATA:35
PN:441-40945-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0650	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-06, AMM 35-01-06								
35-01-07	COCKPIT SENSOR							Component ATA:35
PN:P24099	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0677	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-07, AMM 35-01-07								
35-01-08	PAX LOW PRESSURE OXYGEN SYSTEM SWITCH							Component ATA:35
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
35-01-09	ALTITUDE COMPENSATING REGULATOR							Component ATA:35
PN:4421135-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00550	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-09, AMM 35-01-09								
35-01-10	LOW PRESSURE OXYGEN VALVE							Component ATA:35
PN:4421132-109	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00662	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-01-10, AMM 35-01-10								
35-02-01	OXYGEN CYLINDER							Component ATA:35
PN:4441122-050	MOS/MSC	01-May-19	H/T	TSR 0				
SN:0064-826	HRS	1230		TSN 1280, TSR 0				
	AFL	711		TSR 0				
PROC. REF: AMM 35-02-01, AMM 35-02-01								
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER REGULATOR							Service ATA:35
PN:4441122-050	MOS	04-Jan-19	60		04-Jan-24		309 d	
SN:0064-826	HRS							
	AFL							
PROC. REF: AMM 35-02-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-02-01-003	DISCARD OF OXYGEN CYLINDER							Service ATA:35
PN:4441122-050	MOS		180		01-Aug-23 (M)		153 d	LIFE LIMIT
SN:0064-826	HRS							
	AFL							
PROC. REF: AMM 35-02-01								
35-02-05	OXYGEN PRESSURE REGULATOR							Component ATA:35
PN:PN	MOS/MSC	01-May-19	O/C					
SN:UNKNOWN	HRS	1230						
	AFL	711						
PROC. REF: GENERIC NO REF								
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX							Service ATA:35
	MOS	27-Apr-22	12 (+30d/-30d)	Adj 2d	29-Apr-23	29-May-23	59 d (+30)	AIRWORTHINESS
	HRS	1728.6	800 (+30/-30)		2528.6	2558.6	715 (+30)	
	AFL	989						
PROC. REF: AMM 35-11-02								
35-11-01	COPILOT OXYGEN MASK STOWAGE BOX							Component ATA:35
PN:1186F6-23	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:01280	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-01	PILOT OXYGEN MASK STOWAGE BOX							Component ATA:35
PN:1186F6-23	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:01281	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-11-01, AMM 35-11-01								
35-11-02	LEFT CREW OXYGEN MASK							Component ATA:35
PN:174232-93	MOS/MSC	01-Oct-20	O/C	TSN 12				
SN:46933	HRS	1531.4		TSN 0				
	AFL	894		TSN 0				
PROC. REF: AMM 35-11-02, AMM 35-11-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 35 - OXYGEN									
35-11-02	RIGHT CREW OXYGEN MASK							Component	ATA:35
PN:174232-93	MOS/MSC	01-Oct-20	O/C	TSN 12					
SN:46934	HRS	1531.4		TSN 0					
	AFL	894		TSN 0					
PROC. REF: AMM 35-11-02, AMM 35-11-02									
35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK							Service	ATA:35
PN:174232-93	MOS	11-Oct-22	24 (+1m/-1m)	Adj -10d	01-Oct-24	01-Nov-24	580 d (+31)		
SN:46933	HRS	1795.6							
	AFL	1024							
PROC. REF: AMM 35-11-02									
35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK							Service	ATA:35
PN:174232-93	MOS	11-Oct-22	24 (+1m/-1m)	Adj -10d	01-Oct-24	01-Nov-24	580 d (+31)		
SN:46934	HRS	1795.6							
	AFL	1024							
PROC. REF: AMM 35-11-02									
35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK							Service	ATA:35
PN:174232-93	MOS	01-Oct-20	72 (+1m/-1m)	TAC 12	01-Oct-25	01-Nov-25	945 d (+31)		
SN:46933	HRS	1531.4	3600 (+30/-30)	TAC 0	5131.4	5161.4	3317.8 (+30)		
	AFL	894		TAC 0					
PROC. REF: AMM 35-11-02									
35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK							Service	ATA:35
PN:174232-93	MOS	01-Oct-20	72 (+1m/-1m)	TAC 12	01-Oct-25	01-Nov-25	945 d (+31)		
SN:46934	HRS	1531.4	3600 (+30/-30)	TAC 0	5131.4	5161.4	3317.8 (+30)		
	AFL	894		TAC 0					
PROC. REF: AMM 35-11-02									
35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK							Service	ATA:35
PN:174232-93	MOS/MSC	N/A							
SN:46933	HRS								
	AFL								
PROC. REF: AMM 35-11-02									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK							Service ATA:35
PN:174232-93	MOS/MSC		N/A					
SN:46934	HRS							
	AFL							
PROC. REF: AMM 35-11-02								
35-11-04-001 ^S	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED)							Service ATA:35
	MOS	26-May-21	36 (+1m/-1m)					
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 35-11-04								
PKG:82								
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE							Service ATA:35
	MOS	26-May-21	36 (+30d/-30d)	Adj -27d	29-Apr-24	29-May-24	425 d (+30)	AIRWORTHINESS
	HRS	1601.5	2400 (+30/-30)		4001.5	4031.5	2187.9 (+30)	
	AFL	928						
PROC. REF: AMM 35-21-00								
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE							Service ATA:35
	MOS	26-May-21	36 (+30d/-30d)	Adj -27d	29-Apr-24	29-May-24	425 d (+30)	AIRWORTHINESS
	HRS	1601.5	2400 (+30/-30)		4001.5	4031.5	2187.9 (+30)	
	AFL	928						
PROC. REF: AMM 35-21-00								
35-21-01	AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:4411071-112	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4411071-012-00383	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:4411072-112	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4411072-012-00874	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:4411072-112	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4411072-012-00879	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:4411072-112	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4411072-012-00880	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER							Component ATA:35
PN:4411072-112	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4411072-012-00881	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01	NO. 5 OXYGEN TWO MASK DEPLOYMENT CONTAINER							Component ATA:35
PN:4411072-112	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:4411072-012-00883	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 35-21-01, AMM 35-21-01								
35-21-01-001 ^S	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS							Service ATA:35
	MOS	26-May-21	36 (+1m/-1m)					
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 35-21-01								PKG:82
35-31-01	PBE - PROTECTIVE BREATHING EQUIPMENT							Component ATA:35
PN:MR-10022NEMB	MOS/MSC	01-Sep-14	H/T	TSN 0				
SN:E1405347	HRS			TSN 0				
	AFL			TSN 0				
PROC. REF: AMM 35-31-01, AMM 35-31-01, AMM 35-31-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 35 - OXYGEN								
35-31-01-001	DISCARD OF PROTECTIVE BREATHING EQUIPMENT (PBE)							Service ATA:35
PN:MR-10022NEMB	MOS	01-Sep-14	126 (+1m/-1m)		01-Mar-25	01-Apr-25	731 d (+31)	LIFE LIMIT
SN:E1405347	HRS							
	AFL							
PROC. REF: AMM 35-31-01								
ATA 36 - PNEUMATIC								
36-00-00-710-801-A	TROUBLE SHOOT ENGINE OPERATING PROBLEMS - PNEUMATIC SYSTEM OPERATIONAL CHECK							Service ATA:36
	MOS/MSC	29-Apr-15	A/R					
	HRS	0						
	AFL	0						
PROC. REF: AMM 36-00-00								
36-01-01	PNEUMATIC INSC ILLUM PANEL							Component ATA:36
PN:441-42633-002	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:1278	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-01-01, AMM 36-01-01								
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:RYLB-53505-5	MOS/MSC	28-Feb-19	O/C					
SN:0053	HRS	1197.7						
	AFL	691						
PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE							Component ATA:36
PN:RYLB-53505-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0290	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-01, AMM 36-11-01								
36-11-01-001 ^S	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-01								
PKG:20								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-01-002 ^S	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION							Service ATA:36
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
	PROC. REF: AMM 36-11-00							PKG:1
36-11-02-001 ^S	DETAILED INSPECTION OF BLEED LINE WATER DRAINS							Service ATA:36
	MOS	26-May-21	24 (+1m/-1m)					
	HRS	1601.5						
	AFL	928						
	PROC. REF: AMM 36-11-02							PKG:81
36-11-03	AMS CONTROLLER							Component ATA:36
PN:SYLZ-53632-205	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0347A	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 36-11-03, AMM 36-11-03							
36-11-04	NO. 1 ENGINE FAN AIR VALVE							Component ATA:36
PN:RYLB-53527-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0579	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 36-11-04, AMM 36-11-04							
36-11-04	NO. 2 ENGINE FAN AIR VALVE							Component ATA:36
PN:RYLB-53527-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0572	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 36-11-04, AMM 36-11-04							
36-11-04-001 ^S	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
	PROC. REF: AMM 36-11-04							PKG:20
36-11-05	LH INCONEL 625 BLEED PRE-COOLER							Component ATA:36
PN:10965000-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:T0272	HRS	0		TSN 0				
	AFL	0		TSN 0				
	PROC. REF: AMM 36-11-05, AMM 36-11-05							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-05	RH INCONEL 625 BLEED PRE-COOLER							Component ATA:36
PN:10964000-105	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:T0271	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-05, AMM 36-11-05								
36-11-06	CROSS BLEED VALVE							Component ATA:36
PN:RYLB-53506-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0285	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-06, AMM 36-11-06								
36-11-06-001 ^S	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION							Service ATA:36
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 36-11-06								
36-11-06-002 ^S	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-06								
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER							Component ATA:36
PN:APTE-479F-1000-200G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8134-8-696	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-07, AMM 36-11-07								
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER							Component ATA:36
PN:APTE-479F-1000-200G	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8134-8-702	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-07, AMM 36-11-07								
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:DTS9478	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:DTS9479	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:DTS9498	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR							Component ATA:36
PN:8TJ107DAJ1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:DTS9500	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 36-11-08, AMM 36-11-08								
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-08								PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-08								PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-08								PKG:60
36-11-08-001 ^S	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR							Service ATA:36
	MOS	29-Apr-15						
	HRS	0	6400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 36-11-08								PKG:60

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 36 - PNEUMATIC								
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS							Service ATA:36
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	6400 (+30/-30)		6400	6430	4586.4 (+30)	
	AFL	0						
PROC. REF: AMM 36-21-01								
ATA 38 - WATER/WASTE								
38-33-00	TOILET ASSY							Component ATA:38
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
38-33-07	WASTE DRAIN VALVE							Component ATA:38
PN:0218-0032-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:223066	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 38-33-07, AMM 38-33-07								
ATA 44 - CABIN SYSTEMS								
44-12-07	3-CHANNEL AUDIO AMPLIFIER							Component ATA:44
PN:0700-005	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14070259	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-12-07, AMM 44-12-07								
44-21-03	DC-DC CONVERTER							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-03, AMM 44-21-03								
44-21-09	IFE INSC ILLUM PANEL							Component ATA:44
PN:441-42725-001	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0261	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-09, AMM 44-21-09								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
44-21-11	XM RECEIVER							Component ATA:44
PN:0500-200	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14090078	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-23-21, AMM 44-23-21, AMM 44-21-11, AMM 44-21-11								
44-21-13	XM HEAD CONTROL							Component ATA:44
PN:0500-300	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14120248	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-13, AMM 44-21-13								
44-21-15	AUDIO VOLUME CONTROLLER							Component ATA:44
PN:0700-008	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14060296	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-15, AMM 44-21-15								
44-21-17	IR RECEIVER WITH CONNECTOR							Component ATA:44
PN:0500-018	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14070269	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-17, AMM 44-21-17								
44-21-19	IR REMOTE CONTROLLER							Component ATA:44
PN:0500-028	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14090090	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-17, AMM 44-21-17								
44-21-21	WIRELESS AUDIO TRANSMITTER							Component ATA:44
PN:0700-009	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14060388	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-21, AMM 44-21-21								
44-21-23	NO. 1 WIRELESS HEADPHONE							Component ATA:44
PN:0500-100	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14020148	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
44-21-23	NO. 2 WIRELESS HEADPHONE							Component ATA:44
PN:0500-100	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14070162	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
44-21-25	HEADPHONE DISTRIBUTION AMPLIFIER							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-25, AMM 44-21-25								
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER							Component ATA:44
PN:0604-003	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14070370	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-22-01, AMM 44-22-01								
44-22-03	NO. 1 10.4 INCH FOLD DOWN MONITOR-							Component ATA:44
PN:1043-308	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:15010148	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-22-03, AMM 44-22-03								
44-32-01	ATG5000 TRANSCEIVER							Component ATA:44
PN:P15864-002	MOS/MSC	19-May-17	O/C	TSR 0				
SN:1586400215797	HRS	714.9		TSR 0				
	AFL	406		TSR 0				
PROC. REF: AMM 44-32-01, AMM 44-32-01								
44-32-03	AIRCELL CONFIGURATION MODULE							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-32-03, AMM 44-32-03								
44-32-05	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-32-05, AMM 44-32-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 44 - CABIN SYSTEMS								
442127-0101	LH NO. 1 AUDIO CONTROL JACK							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11								
442127-0102	RH NO. 2 AUDIO CONTROL JACK							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11								
442127-0103	LH NO. 3 AUDIO CONTROL JACK							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11								
442127-0104	RH NO. 4 AUDIO CONTROL JACK							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11								
442127-0105	LH NO. 5 AUDIO CONTROL JACK							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11								
442127-0106	RH NO. 6 AUDIO CONTROL JACK							Component ATA:44
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 44-21-27, AMM 44-21-27, AMM 44-23-11, AMM 44-23-11								
ATA 52 - DOORS								
52-00-00	KEY LOCK KIT							Component ATA:52
PN:505-09736-901	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:8MA001027CL	HRS	0		TSN 0				
	AFL	0		TSN 0				

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
PROC. REF: GENERIC NO REF								
52-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE							Service ATA:52
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 52-10-00								
PKG:84								
52-10-00-01A	PAX DOOR EQUIPPED MAIN DOOR ASSY							Component ATA:52
PN:505-09910-461	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000837153	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-10-00, AMM 52-10-00								
52-10-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE							Service ATA:52
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 52-10-00								
PKG:84								
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL							Service ATA:52
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 52-10-00								
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL							Service ATA:52
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 52-10-00								
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL							Service ATA:52
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 52-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL							Service ATA:52
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 52-10-00								
52-10-20-001 ^S	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL							Service ATA:52
	MOS	30-Apr-22	12 (+1m/-1m)					
	HRS	1728.6						
	AFL	989						
PROC. REF: AMM 52-10-20								
PKG:80								
52-11-00-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 52-11-00								
PKG:83								
52-11-00-003 ^S	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH							Service ATA:52
	MOS	14-Apr-20						
	HRS	1483.9	800 (+30/-30)					
	AFL	855						
PROC. REF: AMM 52-11-23								
PKG:1								
52-13-00	MAIN DOOR BALANCE ASSY. GEAR SECTOR							Component ATA:52
PN:PN	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-13-01	MAIN DOOR BALANCE ASSY. PINION SHAFT							Component ATA:52
PN:PN	MOS/MSC	29-Apr-15	H/T	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-13-21-001 ^S	DISCARD OF SECTOR GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED)							Service ATA:52
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-21								
PKG:50								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-13-22	MAIN DOOR BALANCING MECHANISM							Component ATA:52
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-13-00, AMM 52-13-00, AMM 52-13-22, AMM 52-13-22								
52-13-22-001	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE							Service ATA:52
PN:PN	MOS/MSC	28-Dec-18	O/C					
SN:UNKNOWN	HRS	1178.1						
	AFL	679						
PROC. REF: AMM 52-13-22								
52-13-22-004	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES							Service ATA:52
	MOS	29-Apr-15						
	HRS	0	3200 (+30/-30)		3200	3230	1386.4 (+30)	
	AFL	0						
PROC. REF: AMM 52-13-22								
52-13-23-001 ^S	DISCARD OF SHAFT PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED)							Service ATA:52
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 52-13-23								PKG:50
52-20-00	EMERGENCY DOOR							Component ATA:52
PN:500-09700-439	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000837746	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
52-20-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE							Service ATA:52
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 52-20-00								PKG:87
52-20-01-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE							Service ATA:52
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 52-20-00, NDT PART 5 52-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL							Service ATA:52
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 52-20-00								
52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL							Service ATA:52
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 52-20-00								
52-20-20-001 ^S	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 52-20-20								PKG:83
52-20-21-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR RUBBER SEAL							Service ATA:52
	MOS	26-May-21	24 (+1m/-1m)					
	HRS	1601.5						
	AFL	928						
PROC. REF: AMM 52-20-21								PKG:81
52-31-20-001 ^S	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM							Service ATA:52
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 52-31-20								PKG:83
52-32-20-001 ^S	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM							Service ATA:52
	MOS	01-May-19	48 (+1m/-1m)					
	HRS	1230						
	AFL	711						
PROC. REF: AMM 52-32-20								PKG:83

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 52 - DOORS								
52-71-20	LOWER PAX DOOR MICRO SWITCH ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-71-20, AMM 52-71-20								
52-71-20	UPPER PAX DOOR MICRO SWITCH ASSEMBLY							Component ATA:52
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 52-71-20, AMM 52-71-20								
ATA 53 - FUSELAGE								
53-00-00-001 ^S	GENERAL VISUAL INSPECTION OF FUSELAGE POLYURETHANE FILMS							Service ATA:53
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 53-00-20								PKG:1
53-05-00-001 ^S	DETAILED INSPECTION OF FUSELAGE DRAINS							Service ATA:53
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: AMM 53-05-00								PKG:84
53-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00								PKG:90
53-10-00-002 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES							Service ATA:53
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00								PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-00-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE							Service ATA:53
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00							PKG:87	
53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-10-00								PKG:90
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-10-00								
53-10-07-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE							Service ATA:53
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 53-10-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS,DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:15000		15000		13186.4	
	AFL	0	T:12000		12000		10965	
PROC. REF: NDT PART 5 53-10-00								
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WEEL STRUCTURE. NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:15000		15000		13186.4	
	AFL	0	T:12000		12000		10965	
PROC. REF: NDT PART 5 53-10-00								
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WEEL STRUCTURE.							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:15000		15000		13186.4	
	AFL	0	T:12000		12000		10965	
PROC. REF: NDT PART 5 53-10-00								
53-14-00	NOSE RADOME							Component ATA:53
PN:5190-102-1	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:634	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 53-14-00, AMM 53-14-00								
53-20-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 53-20-00								
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-05-003 ^S	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-06-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 53-20-00								

PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-06-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	29-Apr-15	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00							PKG:90	
53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL							Service ATA:53
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:8750		8750		6936.4	
	AFL	0	T:7000		7000		5965	
PROC. REF: NDT PART 5 53-20-00								
53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL							Service ATA:53
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-08-002 ^S	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE							Service ATA:53
	MOS	29-Apr-15	60 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00							PKG:90	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-10-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-20-00								PKG:90
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-00-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00					PKG:90			
53-30-00-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00					PKG:90			
53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-02-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00					PKG:90			
53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:12500		12500		10686.4	
	AFL	0	T:10000		10000		8965	
PROC. REF: NDT PART 5 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-04-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								PKG:90
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:10000		10000		8186.4	
	AFL	0	T:8000		8000		6965	
PROC. REF: NDT PART 5 53-30-00								
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:12500		12500		10686.4	
	AFL	0	T:10000		10000		8965	
PROC. REF: NDT PART 5 53-30-00								
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL							Service ATA:53
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-07-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 53 - FUSELAGE								
53-30-07-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00					PKG:90			
53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL							Service ATA:53
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL							Service ATA:53
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 53-30-00								
53-30-08-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46							Service ATA:53
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00					PKG:87			
53-30-08-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46							Service ATA:53
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 53-30-00					PKG:90			
ATA 54 - NACELLES/PYLONS								
54-00-00-001 ^S	GENERAL VISUAL INSPECTION OF PYLON POLYURETHANE FILMS							Service ATA:54
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 54-51-20					PKG:1			

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-00-001 ^S	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE							Service ATA:54
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 54-50-00								PKG:90
54-50-00-002 ^S	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX							Service ATA:54
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 54-52-00, NDT PART 5 54-52-00								PKG:90
54-50-01-01-901	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 54-50-00								
54-50-02-01-901	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 54-50-00								
54-50-03-001 ^S	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE.							Service ATA:54
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 54-52-00								PKG:84
54-50-03-01-901	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 54-52-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 54-52-00								
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 54-52-00								
54-50-05-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES							Service ATA:54
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 54-55-00								PKG:87
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:15000		15000		13186.4	
	AFL	0	T:12000		12000		10965	
PROC. REF: NDT PART 6 54-55-00								
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 54-55-00								
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:15000		15000		13186.4	
	AFL	0	T:12000		12000		10965	
PROC. REF: NDT PART 5 54-55-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 54 - NACELLES/PYLONS								
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL							Service ATA:54
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:15000		15000		13186.4	
	AFL	0	T:12000		12000		10965	
PROC. REF: NDT PART 5 54-55-00								
ATA 55 - STABILIZERS								
55-00-00-001 ^S	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS							Service ATA:55
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 55-00-20								
PKG:1								
55-10-00	HORIZONTAL STABILIZER (COMPLETION)							Component ATA:55
PN:505-10700-413	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000837459	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
55-10-00-001 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-10-00								
PKG:84								
55-10-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-10-00								
PKG:84								
55-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-10-00								
PKG:84								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								PKG:87
55-10-03-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-10-00								PKG:84
55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-04-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-001 ^S	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS							Service ATA:55
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00								PKG:90
55-10-05-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 55-10-00								
55-10-05-02-902	SPECIAL DETAILED INSPECTION (BOREScope) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 55-10-00								
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-08-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-10-00								PKG:84
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-10-09-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE SUPPORT							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00							PKG:87	
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL							Service ATA:55
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL							Service ATA:55
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-10-10-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR TRIM-TAB FITTINGS							Service ATA:55
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-10-00							PKG:90	
55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL							Service ATA:55
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-10-00								
55-20-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00							PKG:87	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-20-00								
55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-20-00								
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-20-00								
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-20-00								
55-20-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-20-00								PKG:87
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 55-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 8 55-20-00								
55-20-04-001	INTERNAL GENERAL VISUAL INSPECTION OF ELEVATOR MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	14-Apr-20	60		14-Apr-25		775 d	ALI
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-20-00, NDT PART 5 55-20-00								
55-20-04-002	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS							Service ATA:55
	MOS	14-Apr-20	60		14-Apr-25		775 d	ALI
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-20-00								
55-22-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB							Service ATA:55
	MOS	29-Apr-15	T:120					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-22-00								PKG:90
55-30-00	VERTICAL STABILIZER							Component ATA:55
PN:505-10100-415	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:0000840891	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
55-30-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-30-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-30-00							PKG:90	
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 55-30-00								
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 55-30-00								
55-30-02-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-30-00							PKG:84	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 55-30-00								
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-03-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								PKG:87
55-30-03-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00, NDT PART 5 55-30-00								PKG:87
55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-04-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-30-00								PKG:84

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-05-002 ^S	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER							Service ATA:55
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-30-00								
55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-30-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING							Service ATA:55
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-30-00								
55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-30-00								
55-40-01-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								

PKG:84

PKG:90

PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-40-00								
55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-40-00								
55-40-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-40-00								
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-40-00								
55-40-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY							Service ATA:55
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-40-00								

PKG:87

PKG:87

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 55 - STABILIZERS								
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL							Service ATA:55
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 55-40-00								
55-40-04-002	INTERNAL GENERAL VISUAL INSPECTION OF RUDDER ADJUSTABLE MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	14-Apr-20	60		14-Apr-25		775 d	ALI
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-40-00								
55-40-04-003	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF RUDDER FIXED MASS-BALANCE WEIGHT AND ATTACHMENTS							Service ATA:55
	MOS	14-Apr-20	60		14-Apr-25		775 d	ALI
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 55-40-00								
55-42-00-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB							Service ATA:55
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 55-42-00								
PKG:90								
ATA 56 - WINDOWS								
56-10-00	LEFT GLASS, HEATED WINDSHIELD ASSY, (LH)							Component ATA:56
PN:NP-195301-3	MOS/MS	29-Apr-15	O/C	TSN 0				
SN:14070H8441	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00								
56-10-00	RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH)							Component ATA:56
PN:NP-195301-4	MOS/MS	29-Apr-15	O/C	TSN 0				
SN:14084H0032	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-11-00, AMM 56-11-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF SIDE WINDOW							Service ATA:56
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 56-12-00								PKG:84
56-10-01-002	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS							Service ATA:56
	MOS	10-Jan-17						
	HRS	606.7	1600 (+30/-30)	Adj -6.7	2200	2230	386.4 (+30)	
	AFL	345						
PROC. REF: AMM 56-10-00								
56-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE							Service ATA:56
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE							Service ATA:56
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE							Service ATA:56
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90
56-10-03-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE							Service ATA:56
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 56-10-00								PKG:90

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-10-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL							Service ATA:56
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 56-10-00								
56-12-00	LEFT ACRYLIC SIDE WINDOW							Component ATA:56
PN:NP-195302-3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14202H2731	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-12-00, AMM 56-12-00								
56-12-00	RIGHT ACRYLIC SIDE WINDOW							Component ATA:56
PN:NP-195302-4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:14165H8955	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-12-00, AMM 56-12-00								
56-20-00	NO. 1 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2202016	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 10 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2323922	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 11 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2323955	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 2 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2267118	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-00	NO. 3 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2313438	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 4 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2313442	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 5 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2313445	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 6 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2313454	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 7 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2313467	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 8 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2318726	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								
56-20-00	NO. 9 WINDOW TRANSPARENCY							Component ATA:56
PN:14024	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2318728	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 56-20-00, AMM 56-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 56 - WINDOWS								
56-20-01-001 ^S	EXTERNAL GENERAL VISUAL INSPECTION OF THE PASSENGER WINDOW PANELS							Service ATA:56
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 56-20-00							PKG:84	
ATA 57 - WINGS								
57-00-00-001 ^S	GENERAL VISUAL INSPECTION OF WINGLET POLYURETHANE FILMS							Service ATA:57
	MOS	28-Dec-18						
	HRS	1178.1	800 (+30/-30)					
	AFL	679						
PROC. REF: AMM 57-35-21							PKG:1	
57-10-00-001 ^S	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX							Service ATA:57
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00							PKG:90	
57-10-00-002 ^S	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN							Service ATA:57
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00							PKG:87	
57-10-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS							Service ATA:57
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-00-00							PKG:87	
57-10-01-01-901	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-02-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR							Service ATA:57
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00					PKG:90			
57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL							Service ATA:57
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-03-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR							Service ATA:57
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00					PKG:90			
57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL							Service ATA:57
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-04-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-20-00					PKG:84			
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL							Service ATA:57
	MOS	29-Apr-15					AIRWORTHINESS	
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-06-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL							Service ATA:57
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-10-00								
57-10-07-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-10-00								
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-11-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-10-00								
PKG:84								
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BOREScope) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-10-00								
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:12500		12500		10686.4	
	AFL	0	T:10000		10000		8965	
PROC. REF: NDT PART 5 57-10-00								
57-50-01-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-50-00								
PKG:84								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-50-00								
57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:11250		11250		9436.4	
	AFL	0	T:9000		9000		7965	
PROC. REF: NDT PART 6 57-50-00								
57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 57-50-00								
57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-50-00								
57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 57-50-00								
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-50-00								
57-50-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-20-00								PKG:84
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 57-50-00								
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-50-00								
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 57-50-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-50-00								
57-52-00-001 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE INBOARD FLAP							Service ATA:57
	MOS	29-Apr-15	T:120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-52-00								
								PKG:90
57-52-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-52-00								
								PKG:84
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-52-00								
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-52-00								
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-52-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:11250		11250		9436.4	
	AFL	0	T:9000		9000		7965	
PROC. REF: NDT PART 6 57-52-00								
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-52-00								
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 57-52-00								
57-53-00-001 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF THE OUTBOARD FLAP							Service ATA:57
	MOS	29-Apr-15	120 (+1m/-1m)					
	HRS	0						
	AFL	0						
PROC. REF: NDT PART 5 57-53-00								PKG:87
57-53-00-002 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-53-00								PKG:84
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-53-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-53-00								
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-53-00								
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:11250		11250		9436.4	
	AFL	0	T:9000		9000		7965	
PROC. REF: NDT PART 6 57-53-00								
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-53-00								
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-53-00								
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BOREScope) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-53-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 6 57-53-00								
57-60-00-001	EXTERNAL DETAILED VISUAL INSPECTION OF THE AILERON							Service ATA:57
	MOS	14-Apr-20	60		14-Apr-25		775 d	ALI
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-60-00								
57-60-00-002 ^S	SPECIAL DETAILED INSPECTION (BOREScope METHOD) OF AILERON AND TAB							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-60-00								
PKG:84								
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BOREScope) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-60-00								
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-60-00								
57-60-01-02-901	DETAILED INSPECTION OF AILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-60-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 57 - WINGS								
57-60-02-01-901	DETAILED INSPECTION OF AILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-60-00								
57-60-02-02-901	DETAILED INSPECTION OF AILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL							Service ATA:57
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:17500		17500		15686.4	
	AFL	0	T:14000		14000		12965	
PROC. REF: NDT PART 5 57-60-00								
57-60-04-001 ^U	INTERNAL DETAILED VISUAL INSPECTION OF AILERON MASS-BALANCE WEIGHTS AND ATTACHMENTS							Service ATA:57
	MOS/MSC	29-Apr-15	O/C					
	HRS	0						
	AFL	0						
57-70-02-001 ^S	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS							Service ATA:57
	MOS	14-Apr-20	60 (+1m/-1m)					
	HRS	1483.9						
	AFL	855						
PROC. REF: NDT PART 5 57-70-00								PKG:84
ATA 70 - STANDARD PRACTICES - ENGINES								
700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION							Service ATA:70
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 70-00-00								
700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION							Service ATA:70
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 70-00-00								
ATA 71 - POWER PLANT								
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS							Service ATA:71
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
	ENC	0						
PROC. REF: MM 70-00-00								
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS							Service ATA:71
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 70-00-00								
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH							Service ATA:71
	DAYS/MSC	29-Apr-15	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH							Service ATA:71
	DAYS/MSC	29-Apr-15	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-160-806	NO. 1 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-160-806	NO. 2 ENGINE - PERFORMANCE RECOVERY WASH							Service ATA:71
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN							Service ATA:71
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 71-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-760-810	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN							Service ATA:71
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-814	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK							Service ATA:71
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-814	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - BLEED VALVE OPERATIONAL CHECK							Service ATA:71
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-817	NO. 1 ENGINE - DOWNLOAD ENGINE DCU DATA							Service ATA:71
	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-817	NO. 2 ENGINE - DOWNLOAD ENGINE DCU DATA							Service ATA:71
	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 71-00-00							
71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	01-Jun-22	12 (+30d)		01-Jun-23	01-Jul-23	92 d (+30)	
	HRS	1749.6	630 (+10%)		(2379.6) 2379.6	2442.6	566 (+63)	
	ENC	999						
	PROC. REF: MM 71-00-00							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)							Service ATA:71
	MOS	01-Jun-22	12 (+30d)		01-Jun-23	01-Jul-23	92 d (+30)	
	HRS	1749.6	630 (+10%)		(2379.6) 2379.6	2442.6	566 (+63)	
	ENC	999						
PROC. REF: MM 71-00-00								
71-11-00-001 ^S	GENERAL VISUAL INSPECTION OF UPPER MID COWL							Service ATA:71
	MOS	29-Apr-15						
	HRS	0	5600 (+30/-30)					
	AFL	0						
PROC. REF: AMM 71-11-00								PKG:50
71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LK0815	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00								
71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LK1691	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LK1675	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA4	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LK0832	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-22-00, AMM 71-22-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LK1718	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR							Component ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:LK1715	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-21-00, AMM 71-21-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT AFT MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA4	MOS/MSC	29-Apr-15	O/C					
SN:LK0815	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C					
SN:LK1691	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE LEFT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C					
SN:LK1675	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT AFT MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA4	MOS/MSC	29-Apr-15	O/C					
SN:LK0832	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT INBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C					
SN:LK1718	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-20-00-001	RESTORATION (OVERHAUL) OF ENGINE RIGHT OUTBOARD MOUNT ASSEMBLY AND ATTACHMENTS							Service ATA:71
PN:LM-475-SA3	MOS/MSC	29-Apr-15	O/C					
SN:LK1715	HRS	0						
	AFL	0						
PROC. REF: AMM 71-20-00								
71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY							Service ATA:71
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:7500		7500		5686.4	
	AFL	0	T:6000		6000		4965	
PROC. REF: AMM 71-20-00								
71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL							Service ATA:71
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:4500		4500		2686.4	
	AFL	0	T:3600		3600		2565	
PROC. REF: NDT PART 5 71-22-00, NDT PART 5 71-22-00								
71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY							Service ATA:71
	MOS	29-Apr-15						AIRWORTHINESS
	HRS	0	T:7500		7500		5686.4	
	AFL	0	T:6000		6000		4965	
PROC. REF: AMM 71-20-00								
71-31-00-001 ^S	DETAILED INSPECTION OF PYLON FIREWALL SEAL							Service ATA:71
	MOS	29-Apr-15						
	HRS	0	2400 (+30/-30)					
	AFL	0						
PROC. REF: AMM 71-31-00								PKG:20
71-60-01	LEFT ENGINE AIR INLET							Component ATA:71
PN:505-43420-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:CPI081	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 71 - POWER PLANT								
71-60-01	RIGHT ENGINE AIR INLET							Component ATA:71
PN:505-43430-403	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:CPI081	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 71-60-01, AMM 71-60-01								
71EN1	NO. 1 ENGINE							Component ATA:71
PN:A3072913-01	MOS/MSC		E/C					
SN:PCE-DG0533	HRS							
WC#: 71.EN1	AFL							
PROC. REF: AMM 71-00-00, AMM 71-00-00								
71EN2	NO. 2 ENGINE							Component ATA:71
PN:A3072913-01	MOS/MSC		E/C					
SN:PCE-DG0534	HRS							
WC#: 71.EN2	AFL							
PROC. REF: AMM 71-00-00, AMM 71-00-00								
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	27-Apr-22	12		27-Apr-23		57 d	
	HRS	1728.6	630		(2358.6) 2358.6		545	
	ENC	989						
PROC. REF: MM 72-00-02								
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION							Service ATA:71
	MOS	27-Apr-22	12		27-Apr-23		57 d	
	HRS	1728.6	630		(2358.6) 2358.6		545	
	ENC	989						
PROC. REF: MM 72-00-02								
ATA 72 - ENGINE								
72-00-00-000-802	NO. 1 ENGINE - DISCARD GAS GENERATOR CASE							Service ATA:72
PN:3076150-01	MOS							
SN:RWA60E689	HRS							
	ENC	EFF	8200		(8200) 8200 *		7165	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-000-802	NO. 2 ENGINE - DISCARD GAS GENERATOR CASE							Service ATA:72
PN:3076150-01	MOS							
SN:RWA60E694	HRS							
	ENC	EFF	8200		(8200) 8200 *		7165	
PROC. REF: GENERIC NO REF								
72-00-00-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-802 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-802 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-212-803 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-803 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-804 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-804 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-805 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-805 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-806 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1
72-00-00-212-806 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
	PROC. REF: MM 72-00-00							PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-212-807 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00							PKG:1	
72-00-00-212-807 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00							PKG:1	
72-00-00-212-808 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00							PKG:1	
72-00-00-212-808 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00							PKG:1	
72-00-00-212-809 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00							PKG:1	
72-00-00-212-809 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00							PKG:1	
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR							Service ATA:72
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR							Service ATA:72
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-280-818	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	26-Nov-14	T:120 (+1m)		26-Nov-24	26-Dec-24	636 d (+30)	
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)							Service ATA:72
	MOS	27-Nov-14	T:120 (+1m)		27-Nov-24	27-Dec-24	637 d (+30)	
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00								
72-00-00-280-820 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-280-820 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES							Service ATA:72
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								PKG:1
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS/MSC	27-Apr-18	BF/F					
	HRS	1013.5						
	ENC	579						
PROC. REF: MM 72-00-00								
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL							Service ATA:72
	MOS/MSC	27-Apr-18	BF/F					
	HRS	1013.5						
	ENC	579						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS							Service ATA:72
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 72-00-00							
72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS							Service ATA:72
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
	PROC. REF: MM 72-00-00							
72-00-01-810-822	NO. 1 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)							Service ATA:72
	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 72-00-01							
72-00-01-810-822	NO. 2 ENGINE - TROUBLE SHOOT ENGINE OPERATING PROBLEMS - FAULT ISOLATION 3 (FIGURE 115)							Service ATA:72
	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
	PROC. REF: MM 72-00-01							
72-00-51-030-002	NO. 1 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER							Service ATA:72
	MOS	EFF						LIFE LIMIT
	HRS	EFF	5000 (+100)		(5000) 5000 *	5100	3186.4 (+100)	
	ENC							
	PROC. REF: MM 72-50-01, MM 72-50-01							
72-00-51-030-002	NO. 2 ENGINE - DISCARD HP TURBINE NUT AND KEYWASHER							Service ATA:72
	MOS	EFF						LIFE LIMIT
	HRS	EFF	5000 (+100)		(5000) 5000 *	5100	3186.4 (+100)	
	ENC							
	PROC. REF: MM 72-50-01, MM 72-50-01							

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
72-60-01-212-801	NO. 1 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES							Service ATA:72
	MOS	26-Nov-14						
	HRS	0	1200 (+100)		(2683.9) 2683.9 (M)	2783.9	870.3 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
72-60-01-212-801	NO. 2 ENGINE - INSPECT THE HYDRAULIC PUMP DRIVESHAFT SPLINES							Service ATA:72
	MOS	27-Nov-14						
	HRS	0	1200 (+100)		(2683.9) 2683.9 (M)	2783.9	870.3 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720010	NO. 1 ENGINE - OVERHAUL							Service ATA:72
	MOS	26-Nov-14						
	HRS	0	5000 (+100)		(5000) 5000	5100	3186.4 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720010	NO. 2 ENGINE - OVERHAUL							Service ATA:72
	MOS	27-Nov-14						
	HRS	0	5000 (+100)		(5000) 5000	5100	3186.4 (+100)	
	ENC	0						
PROC. REF: GENERIC NO REF								
720060	NO. 1 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS	26-Nov-14						
	HRS	0	2500 (+50)		(2500) 2500	2550	686.4 (+50)	
	ENC	0						
PROC. REF: MM 72-00-00								
720060	NO. 2 ENGINE - HOT SECTION INSPECTION							Service ATA:72
	MOS	27-Nov-14						
	HRS	0	2500 (+50)		(2500) 2500	2550	686.4 (+50)	
	ENC	0						
PROC. REF: MM 72-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
721010	NO. 1 ENGINE - GEARBOX							Component ATA:72
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
721010	NO. 2 ENGINE - GEARBOX							Component ATA:72
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
722001	NO. 1 ENGINE - OIL PUMP							Component ATA:72
PN:3073477-02	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:EC01A004A641	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-02, MM 79-20-02								
722001	NO. 2 ENGINE - OIL PUMP							Component ATA:72
PN:3073477-02	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:EC01A004A644	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-02, MM 79-20-02								
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY							Component ATA:72
PN:3073356-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:PKAAA577204	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	30000	TSN 0			28965	
PROC. REF: GENERIC NO REF								
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY							Component ATA:72
PN:3073356-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:PKAAA577202	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	30000	TSN 0			28965	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR							Component ATA:72
PN:3073311-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:A003KBXN	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	15000	TSN 0			13965	
PROC. REF: MM 72-30-01, MM 72-30-01								
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR							Component ATA:72
PN:3073311-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:A003K5H7	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	15000	TSN 0			13965	
PROC. REF: MM 72-30-01, MM 72-30-01								
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR							Component ATA:72
PN:3073292-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:TXA1D3922	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	15000	TSN 0			13965	
PROC. REF: GENERIC NO REF								
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR							Component ATA:72
PN:3073292-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:TXA1D3924	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	15000	TSN 0			13965	
PROC. REF: GENERIC NO REF								
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3072981-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:A003HEPC	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3072981-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:A003HEPD	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3056210-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:EAAD000M773	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR							Component ATA:72
PN:3056210-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:EAAD000M769	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:3075221-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:EDA1426F	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-30-02, MM 72-30-02								
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY							Component ATA:72
PN:3075221-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:EDA1426B	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-30-02, MM 72-30-02								
723060	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING							Component ATA:72
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723060	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY - CYLINDRICAL ROLLER BEARING							Component ATA:72
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY							Component ATA:72
PN:3079617-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:A003KD30	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY							Component ATA:72
PN:3079617-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:A003KLPP	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY							Component ATA:72
PN:3076150-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:RWA60E689	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY							Component ATA:72
PN:3076150-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:RWA60E694	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER							Component ATA:72
PN:3073236-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:A003KLWH	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER							Component ATA:72
PN:3073236-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:A003KLWF	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3052673-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:PKAAA585420	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3052673-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:PKAAA585428	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER							Component ATA:72
PN:3052668-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:AFD00P412	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER							Component ATA:72
PN:3052668-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:AFD00P411	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072571-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UAAE1225	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072571-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UAAE1240	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072572-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UAAE1179	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER							Component ATA:72
PN:3072572-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UAAE1184	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING							Component ATA:72
PN:3052737-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:LPA000016739	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING							Component ATA:72
PN:3052737-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:LPA000016744	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR							Component ATA:72
PN:3072574-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:EAAD000M355	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR							Component ATA:72
PN:3072574-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:EAAD000M828	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723160	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING							Component ATA:72
PN:3052670-02	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FCN406175	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723160	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR BALANCING ASSEMBLY - ANNULAR BALL BEARING							Component ATA:72
PN:3052670-02	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FCN406182	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072280-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:PKAAA583726	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072280-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:PKAAA583723	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723180	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:3052616-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FCN418652	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:3052616-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FCN418647	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723190	NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:3052634-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FCN416287	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
723190	NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING							Component ATA:72
PN:3052634-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FCN416289	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053812-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:A003KKN3	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053812-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:A003KKN2	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053743-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:A003KF5B	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK							Component ATA:72
PN:3053743-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:A003KF5D	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
724001	NO. 1 ENGINE - INNER COMBUSTION LINER							Component ATA:72
PN:3075516-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:A003K6L5	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724001	NO. 2 ENGINE - INNER COMBUSTION LINER							Component ATA:72
PN:3075516-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:A003K03P	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER							Component ATA:72
PN:3075522-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:A003K1NY	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER							Component ATA:72
PN:3075522-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:A003KA96	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-40-01, MM 72-40-01								
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY							Component ATA:72
PN:3075468-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:ACM221879749	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY							Component ATA:72
PN:3075468-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:ACM221879756	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK							Component ATA:72
PN:3053331-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:A003KC8M	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			8965	
PROC. REF: MM 72-50-01, MM 72-50-01								
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK							Component ATA:72
PN:3053331-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:A003KC8R	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	10000	TSN 0			8965	
PROC. REF: MM 72-50-01, MM 72-50-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3052661-01	MOS	26-Nov-14		TSN 0				LIFE LIMIT
SN:A003K50P	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER							Component ATA:72
PN:3052661-01	MOS	27-Nov-14		TSN 0				LIFE LIMIT
SN:A003K8ET	HRS	0		TSN 0				
	ENC	0		TSN 0				
	ACCCYC	0	13500	TSN 0			12465	
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWMT5791	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7542	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7543	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7549	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7560	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7564	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7570	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7572	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7573	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7574	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7578	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWMT5795	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7584	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7595	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7598	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7603	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7604	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7606	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7609	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7612	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7615	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7641	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA0730	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7644	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7647	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7648	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7649	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNC1809	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNC2089	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNC2092	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3873	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3877	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3880	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7534	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3884	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3896	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3897	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3899	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3902	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3904	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3909	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3910	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3923	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3929	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7536	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3940	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3959	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3965	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWND3986	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7514	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7515	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7527	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7533	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7534	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7539	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7537	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7540	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7538	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7540	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNA7541	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7541	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7542	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7543	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7552	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7555	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7557	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7564	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7568	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7572	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:HWNH7573	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK2443	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5445	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5458	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5459	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5460	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5476	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5483	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5508	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8925	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8928	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8935	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5391	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8936	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8942	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8945	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8952	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8962	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8969	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8980	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8981	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8990	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8993	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5400	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK8999	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK9006	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK9012	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK9038	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK9042	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1556	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1561	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1562	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1573	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1590	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5401	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1593	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1599	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1603	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1874	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1881	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1882	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1884	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1886	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1889	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1893	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5418	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1900	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1902	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1906	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1911	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1917	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1920	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM1921	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM7839	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM7843	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM7845	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5426	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM7846	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5428	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5436	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNK5438	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM7850	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM7851	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9335	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9339	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9342	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9347	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9371	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9378	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9382	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE							Component ATA:72
PN:3077471-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:HWNM9414	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3073355-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FCN414867	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3073355-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FCN414866	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:3076552-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:RWA60E698	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-50-03								
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY							Component ATA:72
PN:3076552-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:RWA61E376	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-50-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER							Component ATA:72
PN:3073353-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:MDAA005A525	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER							Component ATA:72
PN:3073353-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:MDAA005A519	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING							Component ATA:72
PN:3053163CL01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:PDAKU9AT01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING							Component ATA:72
PN:3053163CL01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:PDAKU2FC01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING							Component ATA:72
PN:3052361CL01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:PDAKYCYL01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING							Component ATA:72
PN:3052361CL01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:PDAKYECR01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY							Component ATA:72
PN:3073262CL02	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:BHKKEHL01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY							Component ATA:72
PN:3073262CL02	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:BHKLAYK01	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726010	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING							Component ATA:72
PN:3052549-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FCN412103	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1413089	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:AEB0208243	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1413090	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:AEB0208375	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1413095	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:AEB0208381	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1413099	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING							Component ATA:72
PN:3073908-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:AEB0208390	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726060	NO. 1 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING							Component ATA:72
PN:3112368-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1413100	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726060	NO. 2 ENGINE - GEARSHAFT ASSY, ACCESSORY DRIVE FLANGED ROLLER BEARING							Component ATA:72
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY							Component ATA:72
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT							Component ATA:72
PN:3072279-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:RWA55E422	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT							Component ATA:72
PN:3072279-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:RWA55E423	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING							Component ATA:72
PN:3072235-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1416223	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING							Component ATA:72
PN:3072235-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FAA1412822	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:3052605-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:FAA1411178	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING							Component ATA:72
PN:3052605-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:FAA1411176	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING							Component ATA:72
PN:3052550-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:BB0211215	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726120	NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING							Component ATA:72
PN:3052550-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:BB0208158	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072282-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:PKAAA582954	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT							Component ATA:72
PN:3072282-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:PKAAA582953	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3075013-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:KYAA014A299	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3075013-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:KYAA014A300	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3074835-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:KYAA014A521	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-70-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 72 - ENGINE								
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY							Component ATA:72
PN:3074835-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:KYAA014A523	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 72-70-01								
793010	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR							Component ATA:72
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793010	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR							Component ATA:72
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 73 - ENGINE FUEL AND CONTROL								
72-00-00-280-819 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								
								PKG:1
72-00-00-280-819 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 72-00-00								
								PKG:1
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES							Service ATA:73
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES							Service ATA:73
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES							Service ATA:73
	MOS							
	HRS							
	ENC	EFF	9900		(9900) 9900 *		8865	
PROC. REF: MM 73-10-04								
73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES							Service ATA:73
	MOS							
	HRS							
	ENC	EFF	9900		(9900) 9900 *		8865	
PROC. REF: MM 73-10-04								
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	30-Apr-22	12 (+30d)	Adj -24d	06-Apr-23	06-May-23	36 d (+30)	
	HRS	1728.6						
	ENC	989						
PROC. REF: MM 73-10-05								
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT							Service ATA:73
	MOS	30-Apr-22	12 (+30d)	Adj -24d	06-Apr-23	06-May-23	36 d (+30)	
	HRS	1728.6						
	ENC	989						
PROC. REF: MM 73-10-05								
73-10-05-960-801	NO. 1 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
	MOS	28-Dec-18						
	HRS	1178.1	800 (+10%)		(1978.1) 1978.1	2058.1	164.5 (+80)	
	ENC	679						
PROC. REF: MM 73-10-05, MM 73-10-05								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-10-05-960-801	NO. 2 ENGINE - DISCARD THE FUEL FILTER							Service ATA:73
	MOS	28-Dec-18						
	HRS	1178.1	800 (+10%)		(1978.1) 1978.1	2058.1	164.5 (+80)	
	ENC	679						
PROC. REF: MM 73-10-05, MM 73-10-05								
73-10-07-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 73-10-07								
								PKG:1
73-10-07-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 73-10-07								
								PKG:1
73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT							Service ATA:73
PN:3071682-05	MOS							
SN:F81513	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 73-20-01								
73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT							Service ATA:73
PN:3071682-05	MOS							
SN:F81627	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 73-20-01								
73-20-02-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 73-20-02								
								PKG:1

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-02-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 73-20-02								PKG:1
73-20-10-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS							Service ATA:73
PN:3073237-05	MOS							
SN:ADXBA001054	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
73-20-10-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS							Service ATA:73
PN:3073237-05	MOS							
SN:ADXBA001069	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
73-20-20-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES							Service ATA:73
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
73-20-20-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES							Service ATA:73
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:73
	MOS							
	HRS		5000 (+100)		(5000) 5000 (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:73
	MOS							
	HRS		5000 (+100)		(5000) 5000 (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
73-21-01	LEFT FADEC							Component ATA:73
PN:3073593-08	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2014070034	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-21-01, AMM 73-21-01								
73-21-01	RIGHT FADEC							Component ATA:73
PN:3073593-08	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:2014080019	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-21-01, AMM 73-21-01								
73-30-02-212-801 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 73-30-02								PKG:1
73-30-02-212-801 ^S	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR							Service ATA:73
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 73-30-02								PKG:1
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER							Component ATA:73
PN:8TJ300AAB2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:DTT7743	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER							Component ATA:73
PN:8TJ300AAB2	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:DTT8696	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 73-33-01, AMM 73-33-01								
731002	NO. 1 ENGINE - FLOW DIVIDER							Component ATA:73
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731002	NO. 2 ENGINE - FLOW DIVIDER							Component ATA:73
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731005	NO. 1 ENGINE - FUEL FILTER							Component ATA:73
PN:PN	MOS/MSC	28-Dec-18	O/C	TSN 0				
SN:UNKNOWN	HRS	1178.1		TSN 0				
	ENC	679		TSN 0				
PROC. REF: MM 73-10-05								
731005	NO. 2 ENGINE - FUEL FILTER							Component ATA:73
PN:PN	MOS/MSC	28-Dec-18	O/C	TSN 0				
SN:UNKNOWN	HRS	1178.1		TSN 0				
	ENC	679		TSN 0				
PROC. REF: MM 73-10-05								
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA53571	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54031	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54032	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA53572	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA53573	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54003	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54006	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54009	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54013	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54014	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:DEAAA54027	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA53555	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54020	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54023	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA53559	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA53574	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54004	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54007	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54010	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54015	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54017	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY							Component ATA:73
PN:3057135-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:DEAAA54018	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT							Component ATA:73
PN:3073593-08	MOS/MSC	08-Dec-14	O/C	TSN 0				
SN:2014070034	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-03, MM 73-20-03								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT							Component ATA:73
PN:3073593-08	MOS/MSC	08-Dec-14	O/C	TSN 0				
SN:2014080019	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-03, MM 73-20-03								
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU)							Component ATA:73
PN:3071682-05	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:F81513	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-01, MM 73-20-01								
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU)							Component ATA:73
PN:3071682-05	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:F81627	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-01, MM 73-20-01								
732005	NO. 1 ENGINE - N2 SPEED SENSOR							Component ATA:73
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732005	NO. 2 ENGINE - N2 SPEED SENSOR							Component ATA:73
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732006	NO. 1 ENGINE - N1 SPEED SENSOR							Component ATA:73
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732006	NO. 2 ENGINE - N1 SPEED SENSOR							Component ATA:73
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 73 - ENGINE FUEL AND CONTROL								
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:3073237-05	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:ADXBA001054	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02								
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS							Component ATA:73
PN:3073237-05	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:ADXBA001069	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-20-02, MM 73-20-02, MM 73-20-02, MM 73-20-02								
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Component ATA:73
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH							Component ATA:73
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
732040	NO. 1 ENGINE - FUEL SHUT-OFF CABLE							Component ATA:73
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07								
732040	NO. 2 ENGINE - FUEL SHUT-OFF CABLE							Component ATA:73
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-07, MM 73-10-07, MM 73-10-07, MM 73-10-07								
ATA 74 - IGNITION								
74-00-01-750-801 ^S	NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM							Service ATA:74
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
PROC. REF: MM 74-00-01							PKG:1	
74-00-01-750-801 ^S	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM							Service ATA:74
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-00-01							PKG:1	
74-10-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER							Service ATA:74
PN:31J2807-07	MOS	30-Apr-22	12 (+30d)					
SN:NNA13430012	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-10-01							PKG:1	
74-10-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER							Service ATA:74
PN:31J2807-07	MOS	30-Apr-22	12 (+30d)					
SN:NNA14410246	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-10-01							PKG:1	
74-20-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES							Service ATA:74
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-20-01							PKG:1	
74-20-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES							Service ATA:74
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-20-01							PKG:1	
74-20-02-210-801 ^S	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR							Service ATA:74
PN:3070508-01	MOS	30-Apr-22	12 (+30d)					
SN:NSN	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-20-02							PKG:1	

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
74-20-02-210-801 ^S		NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR					Service	ATA:74
PN:3070508-01	MOS	30-Apr-22	12 (+30d)					
SN:NSN	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-20-02								PKG:1
74-20-02-210-801 ^S		NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR					Service	ATA:74
PN:3070508-01	MOS	30-Apr-22	12 (+30d)					
SN:N/A	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-20-02								PKG:1
74-20-02-210-801 ^S		NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR					Service	ATA:74
PN:3070508-01	MOS	30-Apr-22	12 (+30d)					
SN:N/A	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 74-20-02								PKG:1
74-20-02-960-801		NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER					Service	ATA:74
PN:3070508-01	MOS/MSC	27-Apr-18	O/C					
SN:NSN	HRS	1013.5						
	ENC	579						
PROC. REF: MM 74-20-02, MM 74-20-02								
74-20-02-960-801		NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER					Service	ATA:74
PN:3070508-01	MOS/MSC	27-Apr-18	O/C					
SN:NSN	HRS	1013.5						
	ENC	579						
PROC. REF: MM 74-20-02, MM 74-20-02								
74-20-02-960-801		NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER					Service	ATA:74
PN:3070508-01	MOS/MSC	27-Apr-18	O/C					
SN:N/A	HRS	1013.5						
	ENC	579						
PROC. REF: MM 74-20-02, MM 74-20-02								
74-20-02-960-801		NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER					Service	ATA:74
PN:3070508-01	MOS/MSC	27-Apr-18	O/C					
SN:N/A	HRS	1013.5						
	ENC	579						
PROC. REF: MM 74-20-02, MM 74-20-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
741001	NO. 1 ENGINE - EXCITER IGNITION							Component ATA:74
PN:31J2807-07	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:NNA13430012	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-10-01, MM 74-10-01								
741001	NO. 2 ENGINE - EXCITER IGNITION							Component ATA:74
PN:31J2807-07	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:NNA14410246	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 74-10-01, MM 74-10-01								
742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER							Component ATA:74
PN:3070508-01	MOS/MSC	10-Jan-17	O/C					
SN:NSN	HRS	606.7						
	ENC	345						
PROC. REF: MM 74-20-02, MM 74-20-02								
742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER							Component ATA:74
PN:3070508-01	MOS/MSC	10-Jan-17	O/C					
SN:N/A	HRS	606.7						
	ENC	345						
PROC. REF: MM 74-20-02, MM 74-20-02								
742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER							Component ATA:74
PN:3070508-01	MOS/MSC	10-Jan-17	O/C					
SN:NSN	HRS	606.7						
	ENC	345						
PROC. REF: MM 74-20-02, MM 74-20-02								
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER							Component ATA:74
PN:3070508-01	MOS/MSC	10-Jan-17	O/C					
SN:N/A	HRS	606.7						
	ENC	345						
PROC. REF: MM 74-20-02, MM 74-20-02								
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD							Component ATA:74
PN:3127408-02	MOS/MSC	19-Feb-16	O/C	TSN 0				
SN:NNA15510072	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 74 - IGNITION								
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD							Component ATA:74
PN:3127408-01	MOS/MSC	19-Feb-16	O/C	TSN 0				
SN:NNA15510156	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD							Component ATA:74
PN:3127408-01	MOS/MSC	19-Feb-16	O/C	TSN 0				
SN:NNA15500157	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD							Component ATA:74
PN:3127408-02	MOS/MSC	19-Feb-16	O/C	TSN 0				
SN:NNA15520103	HRS			TSN 0				
	ENC			TSN 0				
PROC. REF: MM 74-20-01, MM 74-20-01								
ATA 75 - AIR								
75-30-01-212-801 ^S	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE							Service ATA:75
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 75-30-01								PKG:1
75-30-01-212-801 ^S	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE							Service ATA:75
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 75-30-01								PKG:1
75-30-01-212-802	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR							Service ATA:75
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR							Service ATA:75
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 75-30-01								
75-30-01-212-803	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE							Service ATA:75
PN:3053367-01	MOS							
SN:AHX0500397	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE							Service ATA:75
PN:3053367-01	MOS							
SN:AHX0500378	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE							Component ATA:75
PN:3075987-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:TR7549	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE							Component ATA:75
PN:3075987-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:TR7575	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER							Component ATA:75
PN:3071811-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:1836	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER							Component ATA:75
PN:3071811-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:1835	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-801	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES							Service ATA:75
	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-801	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED AIR SYSTEM INTERCONNECTING TUBES							Service ATA:75
	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-802	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE							Service ATA:75
PN:3075987-01	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
SN:TR7549	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-802	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT INTERCOMPRESSOR BLEED VALVE SERVO VALVE							Service ATA:75
PN:3075987-01	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
SN:TR7575	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01								
75-30-01-960-803	NO. 1 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS/MSC	26-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
SN:1836	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
75-30-01-960-803	NO. 2 ENGINE - ENGINE OPERATING PROBLEMS - REPLACEMENT COMPRESSOR BLEED VALVE AND THE LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS/MSC	27-Nov-14	A/R					UNSCHEDULED MAINTENANCE CHECK
SN:1835	HRS	0						
	ENC	0						
PROC. REF: MM 75-30-01, MM 75-30-01, MM 75-30-01								
75-30-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS							
SN:1836	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
75-30-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER							Service ATA:75
PN:3071811-01	MOS							
SN:1835	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
75-30-20-212-801	NO. 1 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR							Service ATA:75
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
75-30-20-212-801	NO. 2 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR							Service ATA:75
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
750010	NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR							Component ATA:75
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-00-00								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 75 - AIR								
750010	NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR							Component ATA:75
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-00-00								
753002	NO. 1 ENGINE - SERVO COMPUTER							Component ATA:75
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
753002	NO. 2 ENGINE - SERVO COMPUTER							Component ATA:75
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
753010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY							Component ATA:75
PN:3053367-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:AHX0500397	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01								
753010	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY							Component ATA:75
PN:3053367-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:AHX0500378	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 75-30-01								
753020	NO. 1 ENGINE - BOV TORQUE MOTOR							Component ATA:75
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
753020	NO. 2 ENGINE - BOV TORQUE MOTOR							Component ATA:75
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition	
ATA 76 - ENGINE CONTROLS									
76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY							Component	ATA:76
PN:6990010-11	MOS/MSC	29-Apr-15	O/C	TSN 0					
SN:1658	HRS	0	TSN 0						
	AFL	0	TSN 0						
PROC. REF: AMM 76-11-01, AMM 76-11-01									

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 77 - ENGINE INDICATING								
77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	26-May-21	36 (+30d)	Adj -29d	27-Apr-24	27-May-24	423 d (+30)	
	HRS	1601.5	1600 (+100)		(3201.5) 3201.5	3301.5	1387.9 (+100)	
	ENC	928						
PROC. REF: MM 77-20-02								
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM							Service ATA:77
	MOS	26-May-21	36 (+30d)	Adj -29d	27-Apr-24	27-May-24	423 d (+30)	
	HRS	1601.5	1600 (+100)		(3201.5) 3201.5	3301.5	1387.9 (+100)	
	ENC	928						
PROC. REF: MM 77-20-02								
77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT							Service ATA:77
PN:3075878-01	MOS							
SN:14026008	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT							Service ATA:77
PN:3075878-01	MOS							
SN:14025512	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
774001	NO. 1 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:3075878-01	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:14026008	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 77-40-01, MM 77-40-01								
774001	NO. 2 ENGINE - DATA COLLECTION UNIT							Component ATA:77
PN:3075878-01	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:14025512	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 77-40-01, MM 77-40-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 78 - EXHAUST								
78-00-00	LH ENGINE EXHAUST ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
78-00-00	RH ENGINE EXHAUST ASSEMBLY							Component ATA:78
PN:PN	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: GENERIC NO REF								
ATA 79 - OIL								
79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)							Service ATA:79
PN:3052640-04	MOS							
SN:09037887	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE)							Service ATA:79
PN:3052640-04	MOS							
SN:09037885	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-20-01-000-802 ^U	NO. 2 ENGINE - PERFORM ENGINE NO.2 OIL FILTER INSPECTION							Service ATA:79
	MOS/MSC	20-Nov-15	-					
	HRS	202.3						
	ENC	116						
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 79-20-01								
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 79-20-01								
79-20-01-960-801	NO. 1 ENGINE - DISCARD THE OIL FILTER							Service ATA:79
	MOS	28-Dec-18						DISCARD
	HRS	1178.1	800 (+10%)		(1978.1) 1978.1	2058.1	164.5 (+80)	
	ENC	679						
PROC. REF: MM 79-20-01, MM 79-20-01								
79-20-01-960-801	NO. 2 ENGINE - DISCARD THE OIL FILTER							Service ATA:79
	MOS	01-May-19						DISCARD
	HRS	1230	800 (+10%)		(2030) 2030	2110	216.4 (+80)	
	ENC	711						
PROC. REF: MM 79-20-01, MM 79-20-01								
79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP DETECTOR							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 79-30-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP DETECTOR							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: MM 79-30-01								
79-30-01-770-801 ^S	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 79-30-01								PKG:1
79-30-01-770-801 ^S	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR							Service ATA:79
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 79-30-01								PKG:1
79-30-02-210-801 ^S	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH							Service ATA:79
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 79-30-02								PKG:1
79-30-02-210-801 ^S	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH							Service ATA:79
	MOS	30-Apr-22	12 (+30d)					
	HRS	1728.6	800 (+10%)					
	ENC	989						
PROC. REF: MM 79-30-02								PKG:1
79-30-03-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
79-30-03-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
79-30-20-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS)							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
79-30-20-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS)							Service ATA:79
	MOS							
	HRS	EFF	5000 (+100)		(5000) 5000 * (M)	5100	3186.4 (+100)	
	ENC							
PROC. REF: GENERIC NO REF								
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR							Component ATA:79
PN:APTE-478A-1000-270D	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00497	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-05, AMM 79-31-05								
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR							Component ATA:79
PN:APTE-478A-1000-270D	MOS/MSC	29-Apr-15	O/C	TSN 0				
SN:00499	HRS	0		TSN 0				
	AFL	0		TSN 0				
PROC. REF: AMM 79-31-05, AMM 79-31-05								
790000	NO. 1 ENGINE - OIL FILTER							Component ATA:79
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-01, MM 79-20-01								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
790000	NO. 2 ENGINE - OIL FILTER							Component ATA:79
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 79-20-01, MM 79-20-01								
790020	NO. 1 ENGINE - CHANGE OIL							Service ATA:79
	MOS/MSC	26-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00, MM 72-00-00								
790020	NO. 2 ENGINE - CHANGE OIL							Service ATA:79
	MOS/MSC	27-Nov-14	A/R					
	HRS	0						
	ENC	0						
PROC. REF: MM 72-00-00, MM 72-00-00								
792010	NO. 1 ENGINE - TEMPERATURE SENSOR							Component ATA:79
PN:ATS-9-800	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:060214-26	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
792010	NO. 2 ENGINE - TEMPERATURE SENSOR							Component ATA:79
PN:ATS-9-800	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:060214-29	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER							Component ATA:79
PN:3052640-04	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:09037887	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-02, MM 73-10-02								
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER							Component ATA:79
PN:3052640-04	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:09037885	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: MM 73-10-02, MM 73-10-02								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task

Status Report

Model: PHENOM 300 Serial: 50500281 RegNo: N419PJ HRS: 1813.6 AFL: 1035 As Of: 28-Feb-2023

01-Mar-2023 01:00 PM

PN & SN	Unit	C/W	Interval	TSX/Adj.	Next Due (ENG/APU) A/C	Max Limit	Remaining	Disposition
ATA 79 - OIL								
793010	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793010	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR							Component ATA:79
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793020	NO. 1 ENGINE - OIL TANK FILLER CAP							Component ATA:79
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793020	NO. 2 ENGINE - OIL TANK FILLER CAP							Component ATA:79
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS)							Component ATA:79
PN:PN	MOS/MSC	26-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS)							Component ATA:79
PN:PN	MOS/MSC	27-Nov-14	O/C	TSN 0				
SN:UNKNOWN	HRS	0		TSN 0				
	ENC	0		TSN 0				
PROC. REF: GENERIC NO REF								

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task